

REPORT TO THE CITY OF HELENA

Section: Nob Hill Park

September 24, 2015

Legend of Abbreviations

aff...	Above the finished ground
AR...	Accessible Route
CIL...	Change in Level
CFS...	Clear Floor Space
CGS...	Clear Ground Space
EPC...	Elevated Play Component
GLPC...	Ground Level Play Component

Background

The Helena Parks and Recreation staff visited Nob Hill Park to conduct an access audit. The findings are below.

1.1 Parking – not applicable

1.2 Exterior Accessible Route - [CHECKLIST] Landing cross slope 5.4% [NHP12](#), [NHP13](#); CIL along Colonial Ramp 5/8" to 3/4" [NHP8](#), [NHP9](#), [NHP7](#); SE Flare of Colonial ramp 11.9% [NHP4](#), [NHP5](#); cross slope 5.2% [NHP10](#), [NHP11](#); debris in curb ramps [NHP3](#); 2.5" gap by alley along Mendocino [NHP16](#), [NHP17](#); AR cross slope 2.4% [NHP14](#), [NHP15](#), 3.7% [NHP25](#), [NHP26](#), Along Saddle 2.3% [NHP30](#), [NHP31](#), 3.1% [NHP32](#), [NHP33](#); AR running slope Mendocino starting at alley heading north 5.4% [NHP18](#), [NHP19](#), 7.7% [NHP21](#), [NHP22](#), 6.2% [NHP23](#), [NHP24](#); No AR to bridge [NHP34](#), [NHP41](#); no curb ramp at alley heading to bridge [NHP34](#), [NHP39](#); CIL at ends of bridge 1.5" [NHP35](#), and 1.375" [NHP40](#), [NHP41](#)

Recommendations (in the alternative, leave as is and designate other sites in the City as accessible):

- 1.2.1 **Create** a level landing at the top of the curb ramp, 36" deep and as wide as ramp (NHP12, NHP13)
- 1.2.2 **Repair, bevel, or ramp** CIL along AR (NHP8, NHP9, NHP7)
- 1.2.3 **Correct slope** of curb ramp side flares to max 10% (NHP4, NHP5)
- 1.2.4 **Correct** curb ramp cross slope to max 2.08% (NHP10, NHP11)
- 1.2.5 **Establish** protocols for regular and frequent inspection and maintenance of surface from AR (NHP3)
- 1.2.6 **Correct or fill** 2.5" gap along AR (NHP16, NHP17)
- 1.2.7 **Correct or repair** sidewalk cross slope along AR to max 2.08% (NHP14, NHP15, NHP25, NHP26, NHP30, NHP31, NHP32, NHP33)
- 1.2.8 **Correct or repair** sidewalk running slope along AR to max 5% (NHP18, NHP19, NHP21, NHP22, NHP23, NHP24)
- 1.2.9 **Create AR** with crushed and compacted stone or similar outdoor material from parking or sidewalk to bridge (NHP34, NHP41)
- 1.2.10 **Create** a curb ramp to be max running slope 8.33%, max cross slope 2.08%, having a top landing as wide as the ramp and 36" deep and side flares with a max slope 10% (NHP34, NHP39)
- 1.2.11 **Repair, bevel, or ramp** CIL along AR (NHP35, NHP40, NHP41)

Responsible Employee	Progress Towards Completion	Recommended Phase
Amy Teegarden Director 406/447-8462	(insert periodic notes regarding steps taken or work completed)	CITY OPTION

1.3 Playground Designated Entry – not applicable

1.4 Playground Surface/Accessible Route within - not applicable

- 1.5 Transfer System** – not applicable
- 1.6 Ramps** - not applicable
- 1.7 Elevated Play Components** – not applicable
- 1.8 Ground Level Play Components** - not applicable
- 1.9 Sand box/Play tables** - not applicable
- 1.10 Park Site** - not applicable
- 1.11 Shelters/Picnic Areas** – not applicable
- 1.12 Park Buildings** - not applicable
- 1.13 Other** - not applicable

CITY OF HELENA NOB HILL PARK