

Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Barney Park	Helena Citizens Council District 4	1.1.1	Parking	Repaint stalls and access aisles to be 8' and 5' each	\$52.50	each	1	\$52.50	2	Complete
Barney Park	Helena Citizens Council District 4	1.1.2	Parking	Repair or correct slope of parking space and access aisle to max 2.08% in any direction	\$2,187.50	each	1	\$2,187.50	2	Incomplete – will be addressed during reconstruction
Barney Park	Helena Citizens Council District 4	1.1.3	Parking	Resurface stalls and access aisles to eliminate gaps, cracks, and asphalt build up	\$2,000.00	each	1	\$2,000.00	2	Incomplete – will be addressed during reconstruction
Barney Park	Helena Citizens Council District 4	1.1.4	Parking	Add one van parking sign to one accessible stall and repaint stall and access aisle to 11' and 5' or 8' and 8'	\$202.50	each	1	\$202.50	2	Complete
Barney Park	Helena Citizens Council District 4	1.2.1	Exterior Accessible Route	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to all buildings and park site elements	\$48.00	lin ft	100	\$4,800.00	3	One additionbal AR needs to be installed to the playground from the parking lot. All other ARs have been compacted and maintained.
Barney Park	Helena Citizens Council District 4	1.2.2	Exterior Accessible Route	Correct or fill gap along AR	\$68.75	each	1	\$68.75	3	Complete
Barney Park	Helena Citizens Council District 4	1.2.3	Exterior Accessible Route	Correct or repair sidewalk cross slope along AR to max 2.08%	\$87.50	sq ft	75	\$6,562.50	3	Incomplete – will be addressed during reconstruction
Barney Park	Helena Citizens Council District 4	1.2.4	Exterior Accessible Route	Correct or repair sidewalk running slope along AR to max 5%	\$87.50	sq ft	50	\$4,375.00	3	Incomplete – will be addressed during reconstruction
Barney Park	Helena Citizens Council District 4	1.2.5	Exterior Accessible Route	Provide cane detectable warning or bollard at base of drinking fountain along the AR	\$150.00	each	1	\$150.00	3	Incomplete – will be addressed during reconstruction
Barney Park	Helena Citizens Council District 4	1.10.1	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the 3rd base side of ball field	\$48.00	lin ft	50	\$2,400.00	СО	Complete
Barney Park	Helena Citizens Council District 4	1.10.2	Park Site	Correct or repair slope at tennis court gate to max 2.08% in any direction for level CFS	\$87.50	sq ft	25	\$2,187.50	2	Incomplete
Barney Park	Helena Citizens Council District 4	1.10.3	Park Site	Correct or fill gap at tennis court	\$68.75	each	1	\$68.75	2	To be completed in FY22
Barney Park	Helena Citizens Council District 4	1.10.4	Park Site	Resurface basketball courts to eliminate gaps and cracks	\$5,000.00	each	1	\$5,000.00	2	Incomplete
Barney Park	Helena Citizens Council District 4	1.10.5	Park Site	Relocate 20% of garbage cans to be along AR	\$0.00	staff time	0	\$0.00	2	Complete
Barney Park	Helena Citizens Council District 4	1.10.6	Park Site	Replace <u>drinking fountain</u> with a hi-lo bowl fountain	\$3,998.75	each	1	\$3,998.75	2	Drinking fountain has been removed.
Barney Park	Helena Citizens Council District 4	1.10.7	Park Site	Correct or repair slope at drinking fountain to max 2.08% in any direction for level CFS	\$87.50	sq ft	12	\$1,050.00	2	Drinking fountain has been removed.
Barney Park	Helena Citizens Council District 4	1.10.8	Park Site	Replace or add one <u>picnic table</u> with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table as a smart practice	\$800.00	each	1	\$800.00	2	Complete

224.293.6333

wtengineering.com



Cita	UCC Diet	Cito	Type of	Dogger was detice.	Delas/ unit	unit	# of	Total cost	Dhasa	Netes
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Barney Park	Helena Citizens Council District 4	1.11.1	Shelters	Replace 20% of the picnic tables with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around the table as a smart practice	\$800.00	each	1	\$800.00	2	Complete
Barney Park	Helena Citizens Council District 4	1.11.2	Shelters	Repair, bevel or ramp CIL at shelter entry	\$68.75	each	1	\$68.75	2	Complete
Barney Park	Helena Citizens Council District 4	1.11.3	Shelters	Relocate tables to provide turning space	\$0.00	staff time	0	\$0.00	2	Complete
Barney Park	Helena Citizens Council District 4	1.12.1	Doors	For all doors along the public circulation route, <i>repair, bevel, or ramp CIL</i> at door entries to max .25"	\$68.75	inch	3	\$206.25	3	N/A only facility on-site with doors is the restroom, which has been addressed
Barney Park	Helena Citizens Council District 4	1.12.2	Doors	For all doors along the public circulation route, <i>fill</i> and maintain gaps at doorways to max .5"	\$68.75	each	2	\$137.50	3	N/A only facility on-site with doors is the restroom, which has been addressed
Barney Park	Helena Citizens Council District 4	1.12.3	Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	2	\$735.00	3	N/A only facility on-site with doors is the restroom, which has been addressed
Barney Park	Helena Citizens Council District 4	1.12.1	Restrooms	Lower mirrors in both so reflective surface is max 40" aff	\$0.00	staff time	0	\$0.00	3	Incomplete will be addressed during renovation
Barney Park	Helena Citizens Council District 4	1.12.2	Restrooms	Insulate exposed pipes under one sink in both	\$55.00	each	2	\$110.00	3	Incomplete will be addressed during renovation
Barney Park	Helena Citizens Council District 4	1.12.3	Restrooms	Reduce ambulatory stall size in both to 36" wide and 60" deep	\$1,963.75	each	2	\$3,927.50	3	Incomplete will be addressed during renovation
Barney Park	Helena Citizens Council District 4	1.12.4	Restrooms	Remount toilets to 16" to 18" from the side wall to centerline	\$1,306.00	each	2	\$2,612.00	3	Incomplete will be addressed during renovation
Barney Park	Helena Citizens Council District 4	1.12.5	Restrooms	Adjust stall door to be self-closing	\$0.00	staff time	0	\$0.00	3	Incomplete will be addressed during renovation
Barney Park	Helena Citizens Council District 4	1.12.6	Restrooms	Acquire and install stall hardware operable without a tight pinch or grasp in both	\$100.00	each	2	\$200.00	3	Incomplete will be addressed during renovation
Barney Park	Helena Citizens Council District 4	1.12.7	Restrooms	Lower sink in men's to max 34" aff to front of rim	\$1,700.00	each	1	\$1,700.00	3	Incomplete will be addressed during renovation
Barney Park	Helena Citizens Council District 4	1.12.8	Restrooms	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" aff	\$2,127.50	each	1	\$2,127.50	3	Incomplete will be addressed during renovation
Batch Softball Fields	Helena Citizens Council District 4	1.1.1	Parking	Create enough 8' accessible parking stalls based on lot capacity, with one 5' adjacent access aisle, with proper signage and striping	\$1,135.00	each	5	\$5,675.00	СО	The parking lot needs to be reconstructed and is not part of the park property. When it is reconstructed we will work with the property owner to assure compliance.
Batch Softball Fields	Helena Citizens Council District 4	1.1.2	Parking	Repaint stalls and access aisles to be 8' and 5' each	\$52.50	each	1	\$52.50	СО	The parking lot needs to be reconstructed and is not part of the park property. When it is reconstructed we will work with the property owner to assure compliance.



011	Hoo Pivi	0.11	Type of	2	Division in	unit	# of	T. (1)	Black	News
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Batch Softball Fields	Helena Citizens Council District 4	1.1.3	Parking	Add one van parking sign to one accessible stall and repaint stall and access aisle to 11' and 5' or 8' and 8'	\$202.50	each	1	\$202.50	СО	The parking lot needs to be reconstructed and is not part of the park property. When it is reconstructed we will work with the property owner to assure compliance.
Batch Softball Fields	Helena Citizens Council District 4	1.1.4	Parking	Repair or correct slope of parking space and access aisle to max 2.08% in any direction	\$2,187.50	each	1	\$2,187.50	со	The parking lot needs to be reconstructed and is not part of the park property. When it is reconstructed we will work with the property owner to assure compliance.
Batch Softball Fields	Helena Citizens Council District 4	1.1.5	Parking	Resurface accessible stalls with a firm, stable, and slip resistant material	\$2,000.00	each	1	\$2,000.00	со	The parking lot needs to be reconstructed and is not part of the park property. When it is reconstructed we will work with the property owner to assure compliance.
Batch Softball Fields	Helena Citizens Council District 4	1.1.6	Parking	Raise existing accessible parking signs so that lowest end of bottom sign is min 60" aff	\$0.00	staff time	0	\$0.00	СО	The parking lot needs to be reconstructed and is not part of the park property. When it is reconstructed we will work with the property owner to assure compliance.
Batch Softball Fields	Helena Citizens Council District 4	1.1.8	Parking	Connect newly surfaced stalls to an AR to the fields	\$48.00	lin ft	200	\$9,600.00	со	The parking lot needs to be reconstructed and is not part of the park property. When it is reconstructed we will work with the property owner to assure compliance.
Batch Softball Fields	Helena Citizens Council District 4	1.2.1	Exterior Accessible Route	Install compliant detectable warning at transitions from walkways to vehicular ways as a smart practice	\$235.00	each	2	\$470.00	СО	N/A optional repair
Batch Softball Fields	Helena Citizens Council District 4	1.2.2	Exterior Accessible Route	Correct or fill gaps along AR	\$68.75	each	2	\$137.50	СО	Complete
Batch Softball Fields	Helena Citizens Council District 4	1.2.3	Exterior Accessible Route	Correct or repair sidewalk cross slope along AR to max 2.08%	\$87.50	sq ft	50	\$4,375.00	СО	Will be addressed with sidewalk reconstruction
Batch Softball Fields	Helena Citizens Council District 4	1.2.4	Exterior Accessible Route	Correct or repair sidewalk running slope along AR to max 5%	\$87.50	sq ft	25	\$2,187.50	СО	Will be addressed with sidewalk reconstruction
Batch Softball Fields	Helena Citizens Council District 4	1.2.5	Exterior Accessible Route	Provide cane detectable warning or bollard at base of drinking fountain along the AR	\$150.00	each	1	\$150.00	СО	N/A optional repair
Batch Softball Fields	Helena Citizens Council District 4	1.2.6	Exterior Accessible Route	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to all site elements	\$48.00	lin ft	150	\$7,200.00	СО	Complete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Batch Softball Fields	Helena Citizens Council District 4	1.3.1	Playground Entry	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to playground designated entry	\$48.00	lin ft	50	\$2,400.00	со	Complete
Batch Softball Fields	Helena Citizens Council District 4	1.3.2	Playground Entry	Acquire and install intended user signage and mount at designated entry as a smart practice	\$150.00	each	1	\$150.00	СО	Complete
Batch Softball Fields	Helena Citizens Council District 4	1.4.1	Playground Surface	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs	\$7,500.00	each	1	\$7,500.00	2	Complete
Batch Softball Fields	Helena Citizens Council District 4	1.4.2	Playground Surface	Establish protocols for regular and frequent inspection and maintenance of accessible playground surface	\$0.00	staff time	0	\$0.00	СО	On-going
Batch Softball Fields	Helena Citizens Council District 4	1.5.1	Playground Transfer System	Consider adding second transfer system as a smart practice	\$3,550.00	each	1	\$3,550.00	СО	N/A optional repair
Batch Softball Fields	Helena Citizens Council District 4	1.5.2	Playground Transfer System	Correct transfer step riser height to 8" max and uniform	\$250.00	each	1	\$250.00	СО	Complete
Batch Softball Fields	Helena Citizens Council District 4	1.7.1	EPCs	Adjust height of platform decks to max 8" for access to EPCs, in the alternative, install compliant transfer steps	\$1,000.00	each	2	\$2,000.00	СО	Complete
Batch Softball Fields	Helena Citizens Council District 4	1.7.2	EPCs	Leave as is, remaining EPCs as the above correction will meet 50%	\$0.00	n/a	0	\$0.00	СО	Complete
Batch Softball Fields	Helena Citizens Council District 4	1.8.1	GLPCs	See recommendation 1.4.1 for surface corrections	\$0.00	n/a	0	\$0.00	СО	Complete
Batch Softball Fields	Helena Citizens Council District 4	1.8.2	GLPCs	Add 3 more GLPC of 2 types such as climbers, spinners or swings, to meet incentive scoping	\$2,000.00	each	3	\$6,000.00	СО	Complete
Batch Softball Fields	Helena Citizens Council District 4	1.10.1	Park Site	Leave as is ball field 1, 2, and 3 and designate ball field 4 as accessible	\$0.00	staff time	0	\$0.00	СО	To be completed in FY22
Batch Softball Fields	Helena Citizens Council District 4	1.10.2	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to ball field 4 player and spectator seating	\$48.00	lin ft	60	\$2,880.00	со	To be completed in FY22
Batch Softball Fields	Helena Citizens Council District 4	1.10.3	Park Site	Repair, bevel, or ramp CIL at ball field 4 dugout	\$68.75	each	2	\$137.50	СО	To be completed in FY22
Batch Softball Fields	Helena Citizens Council District 4	1.10.4	Park Site	Provide CFS at player seating at ball field 4	\$115.00	each	2	\$230.00	СО	To be completed in FY22
Batch Softball Fields	Helena Citizens Council District 4	1.10.5	Park Site	Relocate 20% of garbage cans to be along AR	\$0.00	staff time	0	\$0.00	СО	Complete
Batch Softball Fields	Helena Citizens Council District 4	1.10.6	Park Site	Replace <u>drinking fountain</u> with a hi-lo bowl fountain	\$3,998.75	each	1	\$3,998.75	СО	Staff to investigate
Batch Softball Fields	Helena Citizens Council District 4	1.12.1	Doors	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	8	\$10,000.00	СО	Incomplete will be addressed during reconstructionreconstructed as part of a larger project.



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Batch Softball Fields	Helena Citizens Council District 4	1.12.2	Doors	For all doors along the public circulation route, correct or repair slope at doorway landing to max 2.08% in any direction for level CFS	\$2,187.50	each	2	\$4,375.00	со	Incomplete will be addressed during reconstructionreconstructed as part of a larger project.
Batch Softball Fields	Helena Citizens Council District 4	1.12.3	Doors	For all doors along the public circulation route, <i>fill</i> and maintain gaps in doorway maneuvering clearance to max .5"	\$68.75	each	1	\$68.75	СО	Incomplete will be addressed during reconstructionreconstructed as part of a larger project.
Batch Softball Fields	Helena Citizens Council District 4	1.12.4	Doors	For all doors along the public circulation route, ramp steps at door entries	\$155.00	inch	10	\$1,550.00	СО	Incomplete will be addressed during reconstructionreconstructed as part of a larger project.
Batch Softball Fields	Helena Citizens Council District 4	1.12.5	Doors	For all doors along the public circulation route, <i>install</i> cement pad at exit to that allows 18" clearance on the latch side, and extend a pathway away from the building for emergency egress	\$875.00	each	1	\$875.00	СО	Incomplete will be addressed during reconstructionreconstructed as part of a larger project.
Batch Softball Fields	Helena Citizens Council District 4	1.12.6	Doors	For all doors along the public circulation route, replace doors with ones having 80" overhead and 32" clear width	\$1,980.00	each	1	\$1,980.00	СО	Incomplete will be addressed during reconstructionreconstructed as part of a larger project.
Batch Softball Fields	Helena Citizens Council District 4	1.12.7	Doors	For all doors along the public circulation route, repair, bevel, or ramp CIL at door entries to max .25"	\$68.75	inch	15	\$1,031.25	СО	Incomplete will be addressed during reconstructionreconstructed as part of a larger project.
Batch Softball Fields	Helena Citizens Council District 4	1.12.8	Doors	For all doors along the public circulation route, <i>fill</i> and maintain gaps at doorways to max .5"	\$68.75	each	1	\$68.75	СО	Incomplete will be addressed during reconstructionreconstructed as part of a larger project.
Batch Softball Fields	Helena Citizens Council District 4	1.12.9	Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	8	\$2,940.00	CO	Incomplete will be addressed during reconstructionreconstructed as part of a larger project.
Batch Softball Fields	Helena Citizens Council District 4	1.12.1	Rooms	Employee only areas permit approach, entry, and exit, relocate obstacles such as tables and chairs to create AR through baseball and mechanical	\$0.00	staff time	0	\$0.00	СО	On-going
Batch Softball Fields	Helena Citizens Council District 4	1.12.2	Rooms	For all other deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	СО	N/A
Batch Softball Fields	Helena Citizens Council District 4	1.12.1	Restrooms	Acquire and mount signage for both, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character	\$150.00	each	2	\$300.00	со	Complete
Batch Softball Fields	Helena Citizens Council District 4	1.12.2	Restrooms	Lower hooks in both accessible stalls to max 48" aff	\$0.00	staff time	0	\$0.00	СО	Complete
Batch Softball Fields	Helena Citizens Council District 4	1.12.3	Restrooms	Insulate exposed pipes under one sink in men's	\$55.00	each	1	\$55.00	СО	Complete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Batch Softball Fields	Helena Citizens Council District 4	1.12.4	Restrooms	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" aff	\$2,127.50	each	1	\$2,127.50	СО	Complete
Batch Softball Fields	Helena Citizens Council District 4	1.12.5	Restrooms	Create a wheelchair accessible stall in place of the ambulatory stall in men's with grab bars and fixtures mounted in correct locations and at correct heights	\$3,936.25	each	1	\$3,936.25	со	Complete
Batch Softball Fields	Helena Citizens Council District 4	1.12.6	Restrooms	Widen women's accessible stalls to min. 60" clear width, 59" depth	\$1,963.75	each	1	\$1,963.75	со	Complete
Batch Softball Fields	Helena Citizens Council District 4	1.12.7	Restrooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" aff in women's	\$1,306.00	each	1	\$1,306.00	со	Complete
Batch Softball Fields	Helena Citizens Council District 4	1.12.8	Restrooms	Remount side grab bar in women's to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff	\$281.25	each	1	\$281.25	СО	Complete
Batch Softball Fields	Helena Citizens Council District 4	1.12.9	Restrooms	Reverse stall door in women's to swing out of the stall	\$300.00	each	1	\$300.00	со	Complete
Batch Softball Fields	Helena Citizens Council District 4	1.12.10	Restrooms	Acquire and install lock hardware on both sides of women's stall door	\$100.00	each	1	\$100.00	СО	Complete
Batch Softball Fields	Helena Citizens Council District 4	1.12.11	Restrooms	Adjust stall door to be self-closing	\$0.00	staff time	0	\$0.00	со	Complete
Batch Softball Fields	Helena Citizens Council District 4	1.12.12	Restrooms	Rehang stall door in women's to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet	\$300.00	each	1	\$300.00	со	Complete
Batch Softball Fields	Helena Citizens Council District 4	1.13.1	Concessions	Replace one of the picnic tables with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around the table as a smart practice	\$800.00	each	1	\$800.00	со	Complete
Batch Softball Fields	Helena Citizens Council District 4	1.13.2	Concessions	Lower 36" wide segment of service counter to max 36" aff	\$785.00	each	1	\$785.00	со	Complete
Batch Softball Fields	Helena Citizens Council District 4	1.13.3	Concessions	Replace menu with one having pictures and lettering of compliant size based on viewing distance as a smart practice	\$100.00	each	1	\$100.00	со	Complete
Batch Softball Fields	Helena Citizens Council District 4	1.13.4	Concessions	Relocate or rearrange storage and supplies to maintain a 36" AR throughout the kitchen work area	\$0.00	staff time	0	\$0.00	со	Complete
Batch Softball Fields	Helena Citizens Council District 4	1.13.5	Concessions	For all other deficits, <i>leave as is</i> , employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	со	N/A
Beattie Park	Helena Citizens Council District 6	1.2.1	Exterior Accessible Route	Create lined cross walk where pedestrian pathway crosses through vehicular traffic as a smart practice	\$262.50	each	1	\$262.50	со	Complete
Beattie Park	Helena Citizens Council District 6	1.2.2	Exterior Accessible Route	Correct curb ramp landing slope to max 2.08%	\$87.50	sq ft	16	\$1,400.00	СО	To be completed in FY23



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Beattie Park	Helena Citizens Council District 6	1.2.3	Exterior Accessible Route	Correct slope of adjacent street surfaces to max 5%	\$87.50	sq ft	25	\$2,187.50	со	To be completed in FY23
Beattie Park	Helena Citizens Council District 6	1.2.4	Exterior Accessible Route	Correct slope of curb ramp side flares to max 10%	\$725.00	each	1	\$725.00	CO	To be completed in FY23
Beattie Park	Helena Citizens Council District 6	1.2.5	Exterior Accessible Route	Install compliant detectable warning at curb ramps as a smart practice	\$235.00	each	1	\$235.00	O	To be completed in FY23
Beattie Park	Helena Citizens Council District 6	1.2.6	Exterior Accessible Route	Resurface AR where deteriorating and at patch	\$80.00	sq ft	50	\$4,000.00	СО	Complete
Beattie Park	Helena Citizens Council District 6	1.2.7	Exterior Accessible Route	Repair, bevel, or ramp CILs along AR	\$68.75	each	1	\$68.75	СО	Complete
Beattie Park	Helena Citizens Council District 6	1.2.8	Exterior Accessible Route	Replace drain grate with one having openings max .5"	\$100.00	each	1	\$100.00	со	Complete
Beattie Park	Helena Citizens Council District 6	1.2.9	Exterior Accessible Route	Correct or repair sidewalk running slope along AR to max 5%	\$87.50	sq ft	25	\$2,187.50	СО	To be completed in FY23
Beattie Park	Helena Citizens Council District 6	1.2.10	Exterior Accessible Route	See 1.10 below for AR recommendations	\$0.00	n/a	0	\$0.00	со	N/A
Beattie Park	Helena Citizens Council District 6	1.10.1	Park Site	Relocate garbage can to be along AR	\$0.00	staff time	0	\$0.00	СО	Complete
Beattie Park	Helena Citizens Council District 6	1.10.2	Park Site	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, add at least one armrest and locate along an AR as a smart practice	\$185.00	each	1	\$185.00	со	Incomplete
Beattie Park	Helena Citizens Council District 6	1.10.3	Park Site	Replace one <u>picnic table</u> with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table as a smart practice	\$800.00	each	1	\$800.00	СО	Complete
Bill Roberts Golf Course	Citywide Facilities	1.1.1	Parking	Create one or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping	\$1,135.00	each	1	\$1,135.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.1.2	Parking	Relocate stalls to be on the shortest AR to the building entry or park features	\$262.50	each	1	\$262.50	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.1.3	Parking	Repaint stalls and access aisles to be 8' and 5' each	\$52.50	each	4	\$210.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.1.4	Parking	Add one van parking sign to one accessible stall and repaint stall and access aisle to 11' and 5' or 8' and 8'	\$202.50	each	1	\$202.50	2	Remodel & New Construction

/



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Bill Roberts Golf Course	Citywide Facilities	1.1.5	Parking	Repair or correct slope of parking space and access aisle to max 2.08% in any direction	\$2,187.50	each	1	\$2,187.50	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.1.6	Parking	Acquire and mount correct fine sign for all stalls per state or local statute	\$150.00	each	4	\$600.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.2.1	Exterior Accessible Route	Repair, bevel, or ramp CIL along AR	\$68.75	each	2	\$137.50	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.2.2	Exterior Accessible Route	Correct or fill gaps along AR	\$68.75	each	3	\$206.25	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.2.3	Exterior Accessible Route	Correct or repair sidewalk running slope along AR to max 5%	\$87.50	sq ft	25	\$2,187.50	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.3.1	Exterior Signage	Mount signage at entrance designating it as accessible	\$150.00	each	1	\$150.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.4.1	Exterior Doors	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of door	\$1,250.00	each	10	\$12,500.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.4.2	Exterior Doors	For all doors along the public circulation route, correct or repair slope at doorway landing to max 2.08% in any direction for level CFS	\$2,187.50	each	5	\$10,937.50	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.4.3	Exterior Doors	For all doors along the public circulation route, repair, bevel, or ramp CIL in doorway maneuvering clearance to max .25"	\$68.75	inch	1	\$68.75	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.4.4	Exterior Doors	No maneuvering clearance at door due to stairs, <i>leave as is,</i> correction is technically infeasible	\$0.00	n/a	0	\$0.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.4.5	Exterior Doors	For all doors along the public circulation route, <i>install</i> cement pad at exit that allows 18" clearance on the latch side, and extend a pathway away from the building for emergency egress	\$875.00	each	2	\$1,750.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.4.6	Exterior Doors	For all doors along the public circulation route, widen doors to 32" for any doors indicated	\$1,980.00	each	3	\$5,940.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.4.7		For all doors along the public circulation route, repair, bevel, or ramp CIL at door entries to max .25"	\$68.75	inch	34	\$2,337.50	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.4.8	Exterior Doors	For all doors along the public circulation route, replace thresholds at exterior doors with ADA thresholds	\$181.25	each	2	\$362.50	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.4.9	Exterior Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	11	\$4,042.50	2	Remodel & New Construction



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Bill Roberts Golf Course	Citywide Facilities	1.4.10	Exterior Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice	\$0.00	staff time	0	\$0.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.4.11	Exterior Doors	For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers	\$0.00	staff time	0	\$0.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.4.12	Exterior Doors	For all doors along the public circulation route, replace doors with ones having sidelight viewing windows max 43" aff	\$990.00	each	1	\$990.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.4.13	Exterior Doors	For employee only doors; make above corrections upon renovation	\$0.00	n/a	0	\$0.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.6.1	Interior Doors - Pro Shop	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	8	\$10,000.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.6.2	Interior Doors - Pro Shop	For all doors along the public circulation route, <i>replace</i> doors with ones having 36" clear width at recessed doors	\$1,980.00	each	1	\$1,980.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.6.3	Interior Doors - Pro Shop	For all doors along the public circulation route, <i>replace</i> doors ones having 32" clear width where indicated	\$1,980.00	each	4	\$7,920.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.6.4	Interior Doors - Pro Shop	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	8	\$2,940.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.6.5	Interior Doors - Pro Shop	For all doors along the public circulation route, <i>inspect, adjust, and maintain</i> 5 lbf to open interior doors	\$0.00	staff time	0	\$0.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.6.6	Interior Doors - Pro Shop	For all doors along the public circulation route, <i>inspect, adjust, and maintain</i> closing speed on door closers	\$0.00	staff time	0	\$0.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.6.7	Interior Doors - Pro Shop	For employee only doors; make above corrections upon renovation	\$0.00	n/a	0	\$0.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.7.1	Interior Accessible Route - Pro Shop	Remove, or relocate storage in CFS at fixtures and operable parts along the AR	\$0.00	staff time	0	\$0.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.7.2	Interior Accessible Route - Pro Shop	Replace drinking fountain with hi-lo bowl	\$3,998.75	each	1	\$3,998.75	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.7.1	Service Counter - Pro Shop	Lower 36" wide segment of service counter to max 36" aff	\$785.00	each	1	\$785.00	2	Remodel & New Construction



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Bill Roberts Golf Course	Citywide Facilities	1.7.1	Public Spaces - Pro Shop	Relocate obstacles to create AR through pro	\$0.00	staff time	0	\$0.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.7.2	Public Spaces - Pro Shop	Repair, bevel or ramp CIL in rooms indicated	\$68.75	inch	3	\$206.25	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.7.3	Public Spaces - Pro Shop	Provide required CFS at drinking fountain	\$115.00	each	1	\$115.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.7.4	Public Spaces - Pro Shop	Lower operating mechanisms into max 48" aff to highest operable part; leave as is if employee only operated	\$0.00	staff time	0	\$0.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.7.5	Public Spaces - Pro Shop	Replace or add one work surface with one allowing knee and toe clearance with the surface max 34"	\$800.00	each	1	\$800.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.8.1	Employee Spaces - Pro Shop	Employee only area permit approach, entry, and exit, <i>relocate obstacles</i> to create AR through back storage, closet, and back desk	\$0.00	staff time	0	\$0.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.8.2	Employee Spaces - Pro Shop	Employee only areas permit approach, entry, and exit, <i>relocate obstacles</i> to create turning space of 60" in storage, back storage, and closet	\$0.00	staff time	0	\$0.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.8.3	Employee Spaces - Pro Shop	For all other deficits, <i>leave as is</i> , employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.10.1	Restrooms - Multiple Users - Pro Shop	Acquire and mount signage for both, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character and provide CFS for approach to sign	\$150.00	each	2	\$300.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.10.2	Restrooms - Multiple Users - Pro Shop	Lower mirrors in both so reflective surface is max 40" aff	\$0.00	staff time	0	\$0.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.10.3	Restrooms - Multiple Users - Pro Shop	Raise sink bowl to provide 27" knee clearance, in the alternative, acquire a shallower model	\$170.00	each	2	\$340.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.10.4	Restrooms - Multiple Users - Pro Shop	Replace faucet controls with lever controls in both	\$525.00	each	2	\$1,050.00	2	Remodel & New Construction



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Bill Roberts Golf Course	Citywide Facilities	1.10.5	Restrooms - Multiple Users - Pro Shop	Insulate exposed pipes under one sink in both	\$55.00	each	2	\$110.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.10.6	Restrooms - Multiple Users - Pro Shop	Create a wheelchair accessible stall in place of the ambulatory stalls with grab bars and fixtures mounted in correct locations and at correct heights in both	\$3,936.25	each	2	\$7,872.50	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.10.7	Restrooms - Multiple Users - Pro Shop	Relocate or recess towel dispensers in both and shelf in women's to not interfere with general circulation path, protrusions can't be greater than 4"	\$250.00	each	2	\$500.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.10.8	Restrooms - Multiple Users - Pro Shop	Relocate garbage in both to provide CFS at paper towels	\$0.00	staff time	0	\$0.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.10.9	Restrooms - Multiple Users - Pro Shop	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" aff	\$2,127.50	each	1	\$2,127.50	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.10.10	Restrooms - Multiple Users - Pro Shop	Provide 36" clear width in women's	\$1,963.75	each	1	\$1,963.75	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.10.11	Restrooms - Multiple Users - Pro Shop	Repair, bevel or ramp CIL in women's	\$68.75	each	1	\$68.75	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.15.1	Interior Signage - Pro Shop	Create template for signs that addresses height of sign, size of characters, location of Braille, and other requirements	\$0.00	staff time	0	\$0.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.15.2	Interior Signage - Pro Shop	Implement a sign revision program throughout the building, discriminating between directional signs and signs for permanent spaces	\$0.00	staff time	0	\$0.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.15.3	Interior Signage - Pro Shop	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door	\$150.00	each	10	\$1,500.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.16.1	Golf	Acquire single rider car with hand controls, swivel seat, entry from either side, low center of gravity, light psi tires, standing seat, and promote the availability of the car to all golfers	\$10,000.00	each	1	\$10,000.00	3	Remodel & New Construction



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit	# of units	Total cost	Phase	Notes
Bill Roberts Golf Course	Citywide Facilities	1.16.2	Golf	Replace portable toilets with ADA compliant models	\$780.00	type each	6	\$4,680.00	3	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.16.3	Golf	Replace 5% of the amenities at each hole with ones reachable from the single rider car and operable without a tight pinch or grasp	\$250.00	each	18	\$4,500.00	3	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.16.4	Golf	Replace 50% but no less than one bench with a compliant bench and on one side, a 30" by 48" concrete or asphalt CFS	\$600.00	each	1	\$600.00	3	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.6.1	Interior Doors - Maintenance Garage and Cart Barn	For all doors along the public circulation route, <i>provide</i> required maneuvering clearance on push and pull side of doors	\$1,250.00	each	2	\$2,500.00	3	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.6.2	Interior Doors - Maintenance Garage and Cart Barn	For all doors along the public circulation route, correct or repair slope at doorway landing to max 2.08% in any direction for level CFS	\$2,187.50	each	1	\$2,187.50	3	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.6.3	Interior Doors - Maintenance Garage and Cart Barn	For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width	\$1,980.00	each	2	\$3,960.00	3	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.6.4	Interior Doors - Maintenance Garage and Cart Barn	For all doors along the public circulation route, <i>repair, bevel, or ramp CILs</i> at door entries to max .25"	\$68.75	inch	4	\$275.00	3	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.6.5	Interior Doors - Maintenance Garage and Cart Barn	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	2	\$735.00	3	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.6.6	Interior Doors - Maintenance Garage and Cart Barn	For all doors along the public circulation route, replace doors with ones having sidelight viewing windows max 43" aff	\$990.00	each	1	\$990.00	3	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.6.7	Interior Doors - Maintenance Garage and Cart Barn	For employee only doors; make above corrections upon renovation	\$0.00	n/a	0	\$0.00	3	Remodel & New Construction



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Bill Roberts Golf Course	Citywide Facilities	1.8.1	Public Spaces - Maintenance Garage and Cart Barn	Remove, or relocate storage in CFS at fixtures and operable parts	\$0.00	staff time	0	\$0.00	3	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.8.2	Public Spaces - Maintenance Garage and Cart Barn	Lower operating mechanisms to max 48" aff to highest operable part; leave as is if employee only operated	\$250.00	each	1	\$250.00	3	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.8.3	Public Spaces - Maintenance Garage and Cart Barn	Replace locker hardware with ADA compliant hardware on designated lockers	\$300.00	each	1	\$300.00	3	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.8.4	Public Spaces - Maintenance Garage and Cart Barn	Designate 5% or no less than 1 locker as accessible, mounting signage having the access symbol and hooks and operating mechanisms max 48" aff	\$300.00	each	1	\$300.00	3	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.9.1	Employee Spaces - Maintenance Garage and Cart Barn	For all deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	3	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.11.1	Restrooms - Maintenance Garage and Cart Barn	Upon renovation, create a single user accessible restroom with grab bars and fixtures mounted in correct locations and at correct heights in both	\$0.00	n/a	0	\$0.00	3	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.6.1	Interior Doors - Restaurant	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	5	\$6,250.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.6.2	Interior Doors - Restaurant	For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width	\$1,980.00	each	5	\$9,900.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.6.3	Interior Doors - Restaurant	For all doors along the public circulation route, repair, bevel, or ramp CILs at door entries to max .25"	\$68.75	inch	3	\$206.25	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.6.4	Interior Doors - Restaurant	For all doors along the public circulation route, repair carpet to prevent tripping hazards	\$100.00	each	3	\$300.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.6.5	Interior Doors - Restaurant	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	7	\$2,572.50	2	Remodel & New Construction



1	1									
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Bill Roberts Golf Course	Citywide Facilities	1.6.6	Interior Doors - Restaurant	For all doors along the public circulation route, remount hardware to be 34" to 48" aff	\$250.00	each	1	\$250.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.6.7	Interior Doors - Restaurant	For all doors along the public circulation route, <i>inspect, adjust, and maintain</i> 5 lbf to open interior doors	\$0.00	staff time	0	\$0.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.6.8	Interior Doors - Restaurant	For all doors along the public circulation route, <i>inspect, adjust, and maintain</i> closing speed on door closers	\$0.00	staff time	0	\$0.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.6.9	Interior Doors - Restaurant	For employee only doors; make above corrections upon renovation	\$0.00	n/a	0	\$0.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.7.1	Interior Accessible Route - Restaurant	Correct riser heights on stairs to consistent height between 4" to 7", leave as is if technically infeasible	\$255.00	each	14	\$3,570.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.7.2	Interior Accessible Route - Restaurant	Install detectable warning strip on top tread of each stairway as a smart practice	\$150.00	each	1	\$150.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.7.3	Interior Accessible Route - Restaurant	Replace handrails with compliant handrails	\$700.00	each	1	\$700.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.8.1	Public Spaces - Restaurant	Remove, or relocate storage in CFS at fixtures and operable parts	\$0.00	staff time	0	\$0.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.8.2	Public Spaces - Restaurant	Lower operating mechanisms to max 48" aff to highest operable part	\$0.00	staff time	0	\$0.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.9.1	Employee Spaces - Restaurant	Employee only area permit approach, entry, and exit, <i>relocate obstacles</i> to create AR through beverage closet, storage, and office	\$0.00	staff time	0	\$0.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.9.2	Employee Spaces - Restaurant	Employee only areas permit approach, entry, and exit, relocate obstacles to create turning space of 60" in beverage closet and storage	\$0.00	staff time	0	\$0.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.9.3	Employee Spaces - Restaurant	For all other deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.11.1	Restrooms - Restaurant	Restroom not accessible, <i>acquire and mount</i> signage directing patrons to accessible restroom upon renovation	\$150.00	each	1	\$150.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.11.2	Restrooms - Restaurant	Create a compliant accessible restroom on the ground floor	\$17,806.25	each	1	\$17,806.25	2	Remodel & New Construction



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Bill Roberts Golf Course	Citywide Facilities	1.12.1	Kitchen - Restaurant	Replace 5% of tables with one allowing knee and toe clearance with surface max 34" aff	\$800.00	each	1	\$800.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.12.2	Kitchen - Restaurant	Lower a 36" portion of the bar and self-serve counter to max 34" aff	\$785.00	each	1	\$785.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.12.3	Kitchen - Restaurant	Replace menu with one having pictures and lettering of compliant size based on viewing distance as a smart practice	\$100.00	each	1	\$100.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.12.4	Kitchen - Restaurant	Relocate or rearrange storage and supplies to maintain a 36" AR and 60" turning space throughout the kitchen work area	\$0.00	staff time	0	\$0.00	2	Remodel & New Construction
Bill Roberts Golf Course	Citywide Facilities	1.12.5	Kitchen - Restaurant	For all other deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	2	Remodel & New Construction
<u>Centennial-</u> <u>Bausch Park</u>	Helena Citizens Council District 3	1.1.1	Parking	Repair or correct slope of parking spaces and access aisles to max 2.08% in any direction at all locations	\$2,187.50	each	13	\$28,437.50	2	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.1.2	Parking	Maintain stalls and access aisles to be free of mud and other debris	\$0.00	staff time	0	\$0.00	2	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.1.3	Parking	Remove asphalt ramp at parking and create a compliant curb cut	\$1,062.50	each	1	\$1,062.50	2	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.1.4	Parking	Acquire and mount correct violation sign for all stalls per state or local statute	\$150.00	each	10	\$1,500.00	2	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.1.5	Parking	Relocate indicated stalls to a location that connects to an AR	\$262.50	each	1	\$262.50	2	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.2.1	Exterior Accessible Route	Compact and maintain crushed stone routes	\$0.00	staff time	0	\$0.00	2	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.2.2	Exterior Accessible Route	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to skate park	\$48.00	lin ft	20	\$960.00	2	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.4.1	Playground Surface	Repair or correct running slope of play area accessible surface to max 5%	\$0.00	staff time	0	\$0.00	3	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.4.2	Playground Surface	Repair or correct cross slope of play area accessible surface to max 2.08%	\$0.00	staff time	0	\$0.00	3	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.4.3	Playground Surface	Repair, bevel or ramp CILs within playground	\$68.75	each	1	\$68.75	3	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.4.4	Playground Surface	Fill and compact EWF surface so that it maintains its accessibility characteristics	\$5,000.00	each	1	\$5,000.00	3	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.4.5	Playground Surface	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces	\$0.00	staff time	0	\$0.00	3	On-going



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Centennial- Bausch Park	Helena Citizens Council District 3	1.4.6	Playground Surface	Establish protocols for regular and frequent inspection and maintenance of accessible playground surface	\$0.00	staff time	0	\$0.00	3	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.8.1	GLPCs	Lower entry point for one swing to 11" to 24" aff	\$0.00	staff time	0	\$0.00	3	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.8.2	GLPCs	Leave as is, remaining GLPCs as the above correction will meet one of each type accessible	\$0.00	n/a	0	\$0.00	3	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.10.1	Park Site	See recommendation 1.2.1 for surface correction on AR to ball field	\$0.00	n/a	0	\$0.00	3	N/A
Centennial- Bausch Park	Helena Citizens Council District 3	1.10.2	Park Site	Provide CFS in ball field dugouts	\$115.00	each	8	\$920.00	3	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.10.3	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to both sides of playing field at 20% of small diamonds	\$48.00	lin ft	375	\$18,000.00	3	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.10.4	Park Site	Replace one portable toilet at each location with compliant model and place along AR	\$780.00	each	5	\$3,900.00	2	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.10.5	Park Site	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches at BMX park, add at least one armrest and locate along an AR as a smart practice	\$115.00	each	6	\$690.00	2	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.10.6	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to both sides of BMX park	\$115.00	each	1	\$115.00	2	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.10.7	Park Site	Relocate bike rack to be along AR	\$0.00	staff time	0	\$0.00	2	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.10.8	Park Site	Replace <u>drinking fountain</u> with a hi-lo bowl fountain	\$3,998.75	each	1	\$3,998.75	2	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.10.9	Park Site	Compact and maintain surface at large and small dog parks	\$0.00	staff time	0	\$0.00	2	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.10.10	Park Site	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches in large and small dog parks, and locate along an AR as a smart practice	\$115.00	each	2	\$230.00	2	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.10.11	Park Site	Replace one picnic table in large dog park with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table as a smart practice	\$800.00	each	2	\$1,600.00	2	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.10.12	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to volleyball	\$48.00	lin ft	30	\$1,440.00	СО	To be completed in FY23



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Centennial- Bausch Park	Helena Citizens Council District 3	1.10.13	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the rock climber	\$48.00	lin ft	25	\$1,200.00	2	To be completed in FY23
Centennial- Bausch Park	Helena Citizens Council District 3	1.10.14	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to both sides of soccer	\$48.00	lin ft	100	\$4,800.00	2	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.10.15	Park Site	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to bench at Old Glory landmark, as a smart practice	\$115.00	each	1	\$115.00	2	To be completed in FY23
Centennial- Bausch Park	Helena Citizens Council District 3	1.10.16	Park Site	Extend AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to skate park	\$48.00	lin ft	10	\$480.00	2	To be completed in FY23
Centennial- Bausch Park	Helena Citizens Council District 3	1.10.17	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the snow cone hut or relocate to be on a firm, stable surface	\$48.00	lin ft	25	\$1,200.00	2	Concession no longer in operation at park
Centennial- Bausch Park	Helena Citizens Council District 3	1.10.18	Park Site	Acquire and install at least one armrest to 20% of existing benches as a smart practice	\$70.00	each	1	\$70.00	2	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.11.1	Shelters	Correct or repair running slopes to shelters to max 5% and compact to prevent water accumulation	\$87.50	sq ft	50	\$4,375.00	3	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.11.2	Shelters	Repair, bevel, or ramp CIL at pavilion	\$68.75	each	1	\$68.75	3	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.11.3	Shelters	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to accessible end of tables	\$48.00	lin ft	25	\$1,200.00	3	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.11.4	Shelters	Replace 20% of the picnic tables in paws park shelter with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around the table as a smart practice	\$800.00	each	1	\$800.00	3	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.11.5	Shelters	Relocate or replace table to provide turning space	\$0.00	staff time	0	\$0.00	3	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.11.6	Shelters	Replace drinking fountain with a hi-lo bowl fountain	\$3,998.75	each	1	\$3,998.75	3	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.11.7	Shelters	Create AR with crushed and compacted stone or similar outdoor material from shelters to shelter amenities	\$48.00	lin ft	50	\$2,400.00	3	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.12.1	Restrooms	Replace portable toilet with compliant model and place along AR	\$780.00	each	1	\$780.00	2	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.13.1	Trails	Compact and maintain crushed stone paths to be firm and stable	\$0.00	staff time	0	\$0.00	3	Complete
Centennial- Bausch Park	Helena Citizens Council District 3	1.13.2	Trails	Correct or repair asphalt pathway cross slope along AR to max 2.08% as a smart practice	\$87.50	sq ft	75	\$6,562.50	3	Complete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Chamber of Commerce	Citywide Facilities	1.1.1	Parking	Repaint stalls and access aisles to be 8' and 5' each	\$52.50	each	3	\$157.50	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.1.2	Parking	Repaint van stall and access aisle to 11' and 5' or 8' and 8'	\$202.50	each	1	\$202.50	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.1.3	Parking	Resurface stalls and access aisles to eliminate gaps and cracks	\$2,000.00	each	3	\$6,000.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.1.4	Parking	See 1.2.2 below for connection to lower level	\$0.00	n/a	0	\$0.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.2.1	Exterior Accessible Route	See 1.2.2 below for creation of an AR to lower level	\$0.00	n/a	0	\$0.00	1	N/A
Chamber of Commerce	Citywide Facilities	1.2.2	Exterior Accessible Route	Create a curb ramp to be max running slope 8.33%, max cross slope 2.08%, having a top landing as wide as the ramp and 36" deep and side flares with a max slope 10% from lower level parking	\$1,062.50	each	1	\$1,062.50	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.2.3	Exterior Accessible Route	Repair, bevel, or ramp CIL at curb ramp	\$68.75	each	1	\$68.75	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.2.4	Exterior Accessible Route	Correct slope of curb ramp side flares to max 10%	\$725.00	each	1	\$725.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.2.5	Exterior Accessible Route	Install compliant detectable warning at curb ramps as a smart practice	\$235.00	each	2	\$470.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.3.1	Exterior Signage	Mount signage at entrance designating it as accessible	\$150.00	each	1	\$150.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.4.1	Exterior Doors	For all doors along the public circulation route, correct or repair slope at doorway landing to max 2.08% in any direction for level CFS	\$2,187.50	each	1	\$2,187.50	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.4.2	Exterior Doors	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	3	\$3,750.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.4.3	Exterior Doors	For all doors along the public circulation route, <i>install</i> pathway approaching entry that extends 18" beyond latch side of door for maneuvering clearance	\$875.00	each	1	\$875.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.4.4	Exterior Doors	For all doors along the public circulation route, repair, bevel, or ramp CIL at door entries to max .25"	\$68.75	inch	3	\$206.25	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.4.5	Exterior Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	2	\$735.00	1	Incomplete corrections to be made in FY23 if retained as city property



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Chamber of Commerce	Citywide Facilities	1.4.6	Exterior Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice	\$0.00	staff time	0	\$0.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.4.7	Exterior Doors	For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers	\$0.00	staff time	0	\$0.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.4.8	Exterior Doors	For all doors along the public circulation route, replace doors with ones having sidelight viewing windows max 43" aff	\$990.00	each	1	\$990.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.4.9	Exterior Doors	Upon renovation ; make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	1	N/A
Chamber of Commerce	Citywide Facilities	1.6.1	Interior Doors	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	20	\$25,000.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.6.2	Interior Doors	For all doors along the public circulation route, replace door with one having 32" clear width	\$1,980.00	each	1	\$1,980.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.6.3	Interior Doors	For all doors along the public circulation route provide CFS in front of power door controls	\$0.00	staff time	0	\$0.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.6.4	Interior Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	2	\$735.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.6.5	Interior Doors	For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors	\$0.00	staff time	0	\$0.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.6.6	Interior Doors	For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers	\$0.00	staff time	0	\$0.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.6.7	Interior Doors	For all doors along the public circulation route, replace doors with ones having sidelight viewing windows max 43" aff	\$990.00	each	11	\$10,890.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.6.8	Interior Doors	For employee only doors; make above corrections <i>upon renovation</i>	\$0.00	n/a	0	\$0.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.7.1	Interior Accessible Route	Provide an AR to all public areas required to be accessible	\$31,165.00	each	1	\$31,165.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.7.2	Interior Accessible Route	Remove, or relocate storage in CFS at fixtures and operable parts along the AR	\$0.00	staff time	0	\$0.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.7.3	Interior Accessible Route	Replace drinking fountain with hi-lo bowl	\$3,998.75	each	2	\$7,997.50	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.7.4	Interior Accessible Route	Lower drinking fountains to correct the height of the spout outlet	\$250.00	each	2	\$500.00	1	Incomplete corrections to be made in FY23 if retained as city property



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Chamber of Commerce	Citywide Facilities	1.7.5	Interior Accessible Route	Provide min 36" CFS at drinking fountains	\$110.00	lin ft	4	\$440.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.7.1	Stairs	Provide visual contrast on leading 2" of each tread	\$20.00	each	14	\$280.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.7.2	Stairs	Install detectable warning strip on top tread of each stairway as a smart practice	\$150.00	each	1	\$150.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.8.1	Public Spaces	Relocate protruding objects in HBAC main room and conference room or place cane detectable warning or bollard at foot of fire extinguisher and screen	\$250.00	each	2	\$500.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.8.2	Public Spaces	Remove, or relocate storage in CFS at fixtures and operable parts	\$0.00	staff time	0	\$0.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.8.3	Public Spaces	Lower operating mechanisms to max 48" aff to highest operable part; leave as is if employee only operated	\$0.00	staff time	0	\$0.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.8.4	Public Spaces	Lower sinks to max 34" aff to front of rim	\$1,700.00	each	1	\$1,700.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.8.5	Public Spaces	Remove under sink cabinets to provide knee and toe clearances under sinks and insulate exposed pipes	\$840.00	each	1	\$840.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.9.1	Employee Spaces	Employee only area permit approach, entry, and exit, relocate obstacles to create AR through rooms indicated	\$0.00	staff time	0	\$0.00	1	Complete
Chamber of Commerce	Citywide Facilities	1.9.2	Employee Spaces	Employee only areas permit approach, entry, and exit, relocate obstacles to create turning space of 60" in rooms indicated	\$0.00	staff time	0	\$0.00	1	Complete
Chamber of Commerce	Citywide Facilities	1.9.3	Employee Spaces	For all other deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	1	N/A
Chamber of Commerce	Citywide Facilities	1.11.1	Restrooms - Upper Level	Acquire and mount signage for both, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character	\$150.00	each	2	\$300.00	2	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.11.2	Restrooms - Upper Level	Insulate exposed pipes under one sink in both	\$55.00	each	2	\$110.00	2	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.11.3	Restrooms - Upper Level	Lower hooks in both accessible stalls to max 48" aff	\$0.00	staff time	0	\$0.00	2	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.11.4	Restrooms - Upper Level	Widen accessible stalls in both to min. 60" clear width, 59" depth	\$1,963.75	each	2	\$3,927.50	2	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.11.5	Restrooms - Upper Level	Remount rear grab bar to behind the toilet, 12" to one side of center and 24" to the other and 33" to 36" aff in both	\$281.25	each	2	\$562.50	2	Incomplete corrections to be made in FY23 if retained as city property



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Chamber of Commerce	Citywide Facilities	1.11.6	Restrooms - Upper Level	Acquire and mount vertical grab bar in both, 18" min in length and mounted so that the bottom is between 39" and 41" from the floor and the centerline between 39" and 41" from rear wall	\$281.25	each	2	\$562.50	2	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.11.7	Restrooms - Upper Level	Adjust stall doors in both to be self-closing	\$0.00	staff time	0	\$0.00	2	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.11.8	Restrooms - Upper Level	Acquire and install exterior stall hardware that is operable without a tight pinch or grasp in both	\$100.00	each	2	\$200.00	2	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.11.9	Restrooms - Upper Level	Replace stall door of accessible stalls in both with ones that swing out	\$300.00	each	2	\$600.00	2	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.11.10	Restrooms - Upper Level	Replace toilet tank in men's with one having flush mechanism on the open side, in the alternative, install an auto flush unit	\$211.25	each	1	\$211.25	2	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.11.11	Restrooms - Upper Level	Lower mirror in women's so reflective surface is max 40" aff	\$0.00	staff time	0	\$0.00	2	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.11.12	Restrooms - Upper Level	Remount toilet paper dispenser in women's to max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	\$0.00	staff time	0	\$0.00	2	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.11.1	Restrooms - Lower Level	Acquire and mount signage for both, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character	\$150.00	each	2	\$300.00	2	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.11.2	Restrooms - Lower Level	Insulate exposed pipes under one sink in both	\$55.00	each	2	\$110.00	2	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.11.3	Restrooms - Lower Level	Lower hooks in both accessible stalls to max 48" aff	\$0.00	staff time	0	\$0.00	2	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.11.4	Restrooms - Lower Level	Remount rear grab bar to behind the toilet, 12" to one side of center and 24" to the other and 33" to 36" aff in both	\$281.25	each	2	\$562.50	2	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.11.5	Restrooms - Lower Level	Acquire and mount vertical grab bar in both, 18" min in length and mounted so that the bottom is between 39" and 41" from the floor and the centerline between 39" and 41" from rear wall	\$281.25	each	2	\$562.50	2	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.11.6	Restrooms - Lower Level	Adjust stall doors in both to be self-closing	\$0.00	staff time	0	\$0.00	2	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.11.7	Restrooms - Lower Level	Acquire and install exterior stall hardware that is operable without a tight pinch or grasp in both	\$100.00	each	2	\$200.00	2	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.11.8	Restrooms - Lower Level	Correct or repair slope to max 5% running and 2.08% cross in both	\$87.50	sq ft	50	\$4,375.00	2	Incomplete corrections to be made in FY23 if retained as city property



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Chamber of Commerce	Citywide Facilities	1.11.9	Restrooms - Lower Level	Replace toilet tank in men's with one having flush mechanism on the open side, in the alternative, install an auto flush unit	\$211.25	each	2	\$422.50	2	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.11.10	Restrooms - Lower Level	Replace stall door of men's accessible stall with one that swings out	\$300.00	each	1	\$300.00	2	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.11.11	Restrooms - Lower Level	Widen accessible stalls in women's to min. 60" clear width, 59" depth	\$1,963.75	each	1	\$1,963.75	2	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.11.12	Restrooms - Lower Level	Remount toilet paper dispenser in women's to max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	\$0.00	staff time	0	\$0.00	2	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.14.1	Alarms	Upon renovation <i>install audible and visual</i> alarms in all rooms and spaces	\$407.50	each	6	\$2,445.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.15.1	Interior Signage	Create template for signs that addresses height of sign, size of characters, location of Braille, and other requirements	\$0.00	staff time	0	\$0.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.15.2	Interior Signage	Implement a sign revision program throughout the building, discriminating between directional signs and signs for permanent spaces	\$0.00	staff time	0	\$0.00	1	Incomplete corrections to be made in FY23 if retained as city property
Chamber of Commerce	Citywide Facilities	1.15.3	Interior Signage	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door	\$150.00	each	6	\$900.00	1	Incomplete corrections to be made in FY23 if retained as city property
Cherry Park	Helena Citizens Council District 5	1.2.1	Exterior Accessible Route	Create lined cross walk where pedestrian pathway crosses through vehicular traffic as a smart practice	\$262.50	each	1	\$262.50	2	Complete
Cherry Park	Helena Citizens Council District 5	1.2.2	Exterior Accessible Route	Create a curb ramp to be max running slope 8.33%, max cross slope 2.08%, having a top landing as wide as the ramp and 36" deep and side flares with a max slope 10% at second street entry	\$1,062.50	each	1	\$1,062.50	2	Incomplete
Cherry Park	Helena Citizens Council District 5	1.2.3	Exterior Accessible Route	Correct slope of adjacent street surfaces to max 5%	\$87.50	sq ft	25	\$2,187.50	2	Complete
Cherry Park	Helena Citizens Council District 5	1.2.4	Exterior Accessible Route	Create 48" CFS at base of diagonal ramp out of vehicular way	\$115.00	each	1	\$115.00	2	Complete
Cherry Park	Helena Citizens Council District 5	1.2.5	Exterior Accessible Route	Install compliant detectable warning at curb ramps as a smart practice	\$235.00	each	2	\$470.00	2	Complete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit	# of	Total cost	Phase	Notes
Site	Helena Citizens	Cite	Exterior	Recommendation	Price/ unit	type	units	Total Cost	Filase	Notes
Cherry Park	Council District 5	1.2.6	Accessible Route	Correct or repair sidewalk running slope along AR to max 5%	\$87.50	sq ft	50	\$4,375.00	2	Complete
Cherry Park	Helena Citizens Council District 5	1.2.7	Exterior Accessible Route	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to all site elements	\$48.00	lin ft	200	\$9,600.00	2	Complete
Cherry Park	Helena Citizens Council District 5	1.3.1	Playground Entry	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to playground designated entry	\$48.00	lin ft	100	\$4,800.00	СО	Complete
Cherry Park	Helena Citizens Council District 5	1.3.2	Playground Entry	Acquire and install intended user signage and mount at designated entry as a smart practice	\$150.00	each	1	\$150.00	со	Complete
Cherry Park	Helena Citizens Council District 5	1.4.1	Playground Surface	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs	\$7,500.00	each	1	\$7,500.00	2	Complete
Cherry Park	Helena Citizens Council District 5	1.7.1	EPCs	Adjust height of platform decks to max 8" for access to EPCs, in the alternative, install compliant transfer steps	\$250.00	each	1	\$250.00	со	Complete
Cherry Park	Helena Citizens Council District 5	1.7.2	EPCs	Leave as is, remaining GLPCs as the above correction will meet incentive scoping	\$0.00	n/a	0	\$0.00	со	Complete
Cherry Park	Helena Citizens Council District 5	1.8.1	GLPCs	See recommendations 1.4.1 for surface corrections	\$0.00	n/a	0	\$0.00	со	Complete
Cherry Park	Helena Citizens Council District 5	1.10.1	Park Site	Replace <u>drinking fountain</u> with a hi-lo bowl fountain	\$3,998.75	each	1	\$3,998.75	2	Complete
Cherry Park	Helena Citizens Council District 5	1.10.2	Park Site	Relocate 20% of garbage cans to be along AR	\$0.00	staff time	0	\$0.00	2	Complete
Cherry Park	Helena Citizens Council District 5	1.10.3	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the horseshoe pit	\$48.00	lin ft	50	\$2,400.00	2	Complete
Cherry Park	Helena Citizens Council District 5	1.10.4	Park Site	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, add at least one armrest and locate along an AR as a smart practice	\$115.00	each	2	\$230.00	2	To be completed in FY23
Cherry Park	Helena Citizens Council District 5	1.11.1	Shelters	Replace 20% of the picnic tables with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around the table as a smart practice	\$800.00	each	1	\$800.00	3	Complete
Cherry Park	Helena Citizens Council District 5	1.11.2	Shelters	Repair, bevel or ramp CIL at shelter entry	\$68.75	each	1	\$68.75	2	Complete
City-County Admin Building	Citywide Facilities	1.1.1	Parking	Create two or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping in other lot	\$1,135.00	each	2	\$2,270.00	1	To be completed in FY22



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
City-County Admin Building	Citywide Facilities	1.1.2	Parking	Repaint van stalls and access aisles to be 11' and 5' or 8' and 8'	\$52.50	each	2	\$105.00	1	To be completed in FY22
City-County Admin Building	Citywide Facilities	1.1.3	Parking	Repair or correct slope of parking spaces and access aisles to max 2.08% in any direction	\$2,187.50	each	17	\$37,187.50	1	To be completed in FY22
City-County Admin Building	Citywide Facilities	1.1.4	Parking	Maintain surface around sewer grate to assure CILs are max .25" and gap max .5"	\$137.50	each	1	\$137.50	1	To be completed in FY22
City-County Admin Building	Citywide Facilities	1.2.1	Exterior Accessible Route	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to site elements	\$48.00	lin ft	200	\$9,600.00	1	N/A site elements no longer in place
City-County Admin Building	Citywide Facilities	1.2.2	Exterior Accessible Route	Assure that amenities along the AR to entry are of an accessible design	\$250.00	each	3	\$750.00	1	To be completed in FY23
City-County Admin Building	Citywide Facilities	1.2.3	Exterior Accessible Route	<i>Install</i> parking stops to prevent parked cars from reducing the AR	\$100.00	each	6	\$600.00	1	To be completed in FY23
City-County Admin Building	Citywide Facilities	1.2.4	Exterior Accessible Route	Relocate benches and bike racks to be along the AR	\$250.00	each	2	\$500.00	1	To be completed in FY23
City-County Admin Building	Citywide Facilities	1.2.1	Stairs - Exterior - Main Entry	Install handrails on both sides of stairway, mounted 34" to 38" aff with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max	\$700.00	each	1	\$700.00	1	Need to assess feasibility of remounting historic brass handrails
City-County Admin Building	Citywide Facilities	1.2.1	Stairs - Exterior - From Inaccessible Lot	Correct tread depth on stairs so they are 11" minimum and consistent, leave as is if technically infeasible	\$288.75	each	14	\$4,042.50	1	To be completed in FY22
City-County Admin Building	Citywide Facilities	1.2.2	Stairs - Exterior - From Inaccessible Lot	Provide visual contrast on leading 2" of each tread	\$20.00	each	14	\$280.00	1	To be completed in FY22
City-County Admin Building	Citywide Facilities	1.2.3	Stairs - Exterior - From Inaccessible Lot	<i>Install</i> detectable warning strip on top tread of each stairway as a smart practice	\$150.00	each	1	\$150.00	1	To be completed in FY22



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
City-County Admin Building	Citywide Facilities	1.2.4	Stairs - Exterior - From Inaccessible Lot	Replace handrails with compliant continuous handrails	\$700.00	each	1	\$700.00	1	To be completed in FY22
City-County Admin Building	Citywide Facilities	1.2.1	Ramps	Provide an intermediate landing in middle of ramp	\$1,250.00	each	1	\$1,250.00	1	N/A technically infeasible
City-County Admin Building	Citywide Facilities	1.2.2	Ramps	Correct or repair slope in landing to max 2.08%	\$87.50	sq ft	25	\$2,187.50	1	N/A technically infeasible
City-County Admin Building	Citywide Facilities	1.2.3	Ramps	<i>Install handrails</i> on both sides of the ramp	\$700.00	each	1	\$700.00	1	ADA parking lot to be relocated to North parking lot in FY22
City-County Admin Building	Citywide Facilities	1.2.4	Ramps	Replace existing handrail with ones that are rounded and/or extend to the ground, with handrail extensions and mounted 34" to 38" aff	\$700.00	each	1	\$700.00	1	ADA parking lot to be relocated to North parking lot in FY22
City-County Admin Building	Citywide Facilities	1.2.5	Ramps	Extend curbs at edges to within 4" of the support rails	\$1,000.00	each	1	\$1,000.00	1	ADA parking lot to be relocated to North parking lot in FY22
City-County Admin Building	Citywide Facilities	1.4.1	Exterior Doors	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	14	\$17,500.00	1	Per SHPO for N. Basement
City-County Admin Building	Citywide Facilities	1.4.2	Exterior Doors	For all doors along the public circulation route, correct or repair slope at doorway landing to max 2.08% in any direction for level CFS	\$2,187.50	each	2	\$4,375.00	1	To be completed in FY23
City-County Admin Building	Citywide Facilities	1.4.3	Exterior Doors	For all doors along the public circulation route, repair, bevel, or ramp CIL in doorway maneuvering clearance to max .25"	\$68.75	each	1	\$68.75	1	To be completed in FY23
City-County Admin Building	Citywide Facilities	1.4.4	Exterior Doors	For all doors along the public circulation route, widen doors to 32" for any doors indicated	\$1,980.00	each	0	\$0.00	1	Per SHPO for W. Entry and N. Entry, respectively
City-County Admin Building	Citywide Facilities	1.4.5	Exterior Doors	For all doors along the public circulation route, repair, bevel, or ramp CIL at door entries to max .25"	\$68.75	inch	1	\$68.75	1	To be completed in FY23
City-County Admin Building	Citywide Facilities	1.4.6	Exterior Doors	For all doors along the public circulation route, replace thresholds at exterior doors with ADA thresholds	\$181.25	each	1	\$181.25	1	To be completed in FY23
City-County Admin Building	Citywide Facilities	1.4.7	Exterior Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	2	\$735.00	1	To be completed in FY22
City-County Admin Building	Citywide Facilities	1.4.8	Exterior Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice	\$0.00	staff time	0	\$0.00	1	To be completed in FY22
City-County Admin Building	Citywide Facilities	1.4.9	Exterior Doors	For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers	\$0.00	staff time	0	\$0.00	1	On-going



			Type of				# of			
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	units	Total cost	Phase	Notes
City-County Admin Building	Citywide Facilities	1.4.10	Exterior Doors	For employee only doors; make above corrections <i>upon renovation</i>	\$0.00	n/a	0	\$0.00	1	N/A
City-County Admin Building	Citywide Facilities	1.5.1	Elevator - Front	Leave as is, noncompliant front elevator; signage posted; if ever renovated, install compliant elevator	\$0.00	n/a	0	\$0.00	1	N/A
City-County Admin Building	Citywide Facilities	1.5.1	Elevator - Back	<i>Install</i> floor designation signage on both jambs at basement level	\$150.00	each	10	\$1,500.00	1	To be completed in FY22
City-County Admin Building	Citywide Facilities	1.5.2	Elevator - Back	Remount handrails to be 32" to 36" aff	\$151.25	each	1	\$151.25	1	To be completed in FY22
City-County Admin Building	Citywide Facilities	1.5.3	Elevator - Back	Leave as is, interior dimension; infeasible to correct	\$0.00	n/a	0	\$0.00	1	N/A
City-County Admin Building	Citywide Facilities	1.6.1	Interior Doors - First Floor	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	32	\$40,000.00	1	To be completed in FY23
City-County Admin Building	Citywide Facilities	1.6.2	Interior Doors - First Floor	No maneuvering clearance at door due to stairs, <i>leave as is,</i> correction is technically infeasible	\$0.00	n/a	0	\$0.00	1	N/A
City-County Admin Building	Citywide Facilities	1.6.3	Interior Doors - First Floor	For all doors along the public circulation route, <i>replace</i> doors ones having 32" clear width where indicated	\$1,980.00	each	0	\$0.00	1	Per SHPO (HI: 148 restroom x2, 103, Hall door health officer, 162 north; TI: 168 restroom x2, 149 north, West interior entrance x3, Basement stairs west, 106 director's door)
City-County Admin Building	Citywide Facilities	1.6.4	Interior Doors - First Floor	For all doors along the public circulation route, repair, bevel, or ramp CILs at door entries to max .25"	\$68.75	inch	2	\$137.50	1	To be completed in FY23
City-County Admin Building	Citywide Facilities	1.6.5	Interior Doors - First Floor	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	35	\$12,862.50	1	Requires consultation with SHPO
City-County Admin Building	Citywide Facilities	1.6.6	Interior Doors - First Floor	For all doors along the public circulation route, <i>inspect, adjust, and maintain</i> 5 lbf to open interior doors	\$0.00	staff time	0	\$0.00	1	On-going
City-County Admin Building	Citywide Facilities	1.6.7	Interior Doors - First Floor	For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers	\$0.00	staff time	0	\$0.00	1	On-going
City-County Admin Building	Citywide Facilities	1.6.8	Interior Doors - First Floor	For all doors along the public circulation route, replace doors with ones having sidelight viewing windows max 43" aff	\$990.00	each	0	\$0.00	1	Per SHPO (HI: 142 Dutch door; TI: west stairwell, west basement stairs)
City-County Admin Building	Citywide Facilities	1.6.9	Interior Doors - First Floor	For employee only doors; make above corrections upon renovation	\$0.00	n/a	0	\$0.00	1	N/A
City-County Admin Building	Citywide Facilities	1.7.1	Interior Accessible Route - First Floor	Correct or repair running slope of AR to max 5%	\$87.50	sq ft	25	\$2,187.50	1	Storage 030



			I							Ι
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
City-County Admin Building	Citywide Facilities	1.7.2	Interior Accessible Route - First Floor	Repair, bevel or ramp CIL along AR	\$68.75	each	1	\$68.75	1	Storage 030
City-County Admin Building	Citywide Facilities	1.7.3	Interior Accessible Route - First Floor	Correct or fill gaps	\$68.75	each	1	\$68.75	1	Storage 030
City-County Admin Building	Citywide Facilities	1.7.4	Interior Accessible Route - First Floor	Relocate obstacles to create 36" AR	\$0.00	staff time	0	\$0.00	1	On-going
City-County Admin Building	Citywide Facilities	1.7.5	Interior Accessible Route - First Floor	Lower operating mechanisms along the interior AR to max 48" aff to the highest operable part	\$250.00	each	1	\$250.00	1	When replacing Fire alarm pull stations
City-County Admin Building	Citywide Facilities	1.7.6	Interior Accessible Route - First Floor	Raise ducts to min 80", or pad object to prevent hazard in overhead clearance	\$110.00	each	1	\$110.00	1	N/A
City-County Admin Building	Citywide Facilities	1.7.7	Interior Accessible Route - First Floor	Relocate protruding objects along the interior AR or place cane detectable warning or bollard at foot of pipes	\$150.00	each	2	\$300.00	1	To be completed in FY22
City-County Admin Building	Citywide Facilities	1.7.8	Interior Accessible Route - First Floor	Mount compliant signage at all doors along the egress route	\$150.00	each	4	\$600.00	1	To be completed in FY22
City-County Admin Building	Citywide Facilities	1.7.1	Service Counter - First Floor	Lower 36" wide segment of service counter to max 36" aff	\$785.00	each	3	\$2,355.00	1	Incomplete
City-County Admin Building	Citywide Facilities	1.7.1	Stairs - Interior - First Floor	Correct riser heights on stairs to consistent height between 4" to 7", leave as is if technically infeasible	\$288.75	each	0	\$0.00	1	Per SHPO (West Entry)
City-County Admin Building	Citywide Facilities	1.7.2	Stairs - Interior - First Floor	Repair nosings to be curved or beveled and extend max 1.5" over the tread	\$60.00	each	0	\$0.00	1	Per SHPO (West Entry)
City-County Admin Building	Citywide Facilities	1.7.3	Stairs - Interior - First Floor	Install detectable warning strip on top tread of each stairway as a smart practice	\$150.00	each	1	\$150.00	1	To be completed in FY23
City-County Admin Building	Citywide Facilities	1.7.4	Stairs - Interior - First Floor	Install handrails on both sides of stairway, mounted 34" to 38" aff with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max	\$700.00	each	3	\$2,100.00	1	To be completed in FY24



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
City-County Admin Building	Citywide Facilities	1.8.1	Public Spaces - First Floor	Relocate obstacles to create AR through rooms indicated	\$0.00	staff time	0	\$0.00	1	On-going
City-County Admin Building	Citywide Facilities	1.8.2	Public Spaces - First Floor	Relocate obstacles to create turning space in rooms indicated	\$0.00	staff time	0	\$0.00	1	On-going
City-County Admin Building	Citywide Facilities	1.8.3	Public Spaces - First Floor	Relocate protruding objects in 113 or place cane detectable warning or bollard at foot of fire extinguisher	\$250.00	each	1	\$250.00	1	To be completed in FY22
City-County Admin Building	Citywide Facilities	1.8.4	Public Spaces - First Floor	Remove, or relocate storage in CFS at fixtures and operable parts	\$0.00	staff time	0	\$0.00	1	To be completed in FY22
City-County Admin Building	Citywide Facilities	1.8.5	Public Spaces - First Floor	Lower operating mechanisms to max 48" aff to highest operable part; leave as is if employee only operated	\$250.00	each	7	\$1,750.00	1	Employee-only operated
City-County Admin Building	Citywide Facilities	1.8.6	Public Spaces - First Floor	Replace or add one work surface with the surface max 34" and allowing knee and toe clearance	\$800.00	each	4	\$3,200.00	1	To be completed in FY22
City-County Admin Building	Citywide Facilities	1.8.7	Public Spaces - First Floor	Lower sink height to max 34" aff	\$1,700.00	each	1	\$1,700.00	1	To be completed in FY23
City-County Admin Building	Citywide Facilities	1.9.1	Employee Spaces - First Floor	Employee only area permit approach, entry, and exit, <i>relocate obstacles</i> to create AR through DMV	\$0.00	staff time	0	\$0.00	1	On-going
City-County Admin Building	Citywide Facilities	1.9.2	Employee Spaces - First Floor	Employee only areas permit approach, entry, and exit, <i>relocate obstacles</i> to create turning space of 60" in 139-B	\$0.00	staff time	0	\$0.00	1	On-going
City-County Admin Building	Citywide Facilities	1.9.3	Employee Spaces - First Floor	For all other deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	1	N/A
City-County Admin Building	Citywide Facilities	1.11.1	Restrooms - Multiple Users - First Floor	Insulate exposed pipes under one sink in both	\$55.00	each	2	\$110.00	1	To be completed in FY22
City-County Admin Building	Citywide Facilities	1.11.2	Restrooms - Multiple Users - First Floor	Replace toilet seat, or re-set or replace toilet to 17" to 19" aff in both	\$1,306.00	each	2	\$2,612.00	1	To be completed in FY23
City-County Admin Building	Citywide Facilities	1.11.3	Restrooms - Multiple Users - First Floor	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff in both	\$281.25	each	2	\$562.50	1	To be completed in FY23



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
City-County Admin Building	Citywide Facilities	1.11.4	Restrooms - Multiple Users - First Floor	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar in both	\$0.00	staff time	0	\$0.00	1	Complete
City-County Admin Building	Citywide Facilities	1.11.5	Restrooms - Multiple Users - First Floor	Remount rear grab bar in men's accessible stall to 33" to 36" aff	\$281.25	each	1	\$281.25	1	To be completed in FY23
City-County Admin Building	Citywide Facilities	1.11.6	Restrooms - Multiple Users - First Floor	Install vertical grab bars in both so bottom is between 39" and 41" from the floor and the centerline between 39" and 41" from rear wall	\$281.25	each	2	\$562.50	1	To be completed in FY23
City-County Admin Building	Citywide Facilities	1.11.7	Restrooms - Multiple Users - First Floor	Install exterior door hardware that is operable without a tight pinch or grasp	\$100.00	each	2	\$200.00	1	Automatic door openers installed
City-County Admin Building	Citywide Facilities	1.11.8	Restrooms - Multiple Users - First Floor	Adjust stall door to be self-closing in women's	\$0.00	staff time	0	\$0.00	1	Complete
City-County Admin Building	Citywide Facilities	1.11.9	Restrooms - Multiple Users - First Floor	Relocate or recess hand dryers to not interfere with general circulation path, protrusions can't be greater than 4" in both	\$250.00	each	2	\$500.00	1	To be completed in FY23
City-County Admin Building	Citywide Facilities	1.11.10	Restrooms - Multiple Users - First Floor	Provide cane detectable warning or bollards at sink in men's	\$150.00	each	1	\$150.00	1	To be completed in FY23
City-County Admin Building	Citywide Facilities	1.11.11	Restrooms - Multiple Users - First Floor	Lower mirror so reflective surface is max 40" aff in men's	\$0.00	staff time	0	\$0.00	1	To be completed in FY23
City-County Admin Building	Citywide Facilities	1.11.12	Restrooms - Multiple Users - First Floor	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" aff	\$2,127.50	each	1	\$2,127.50	1	To be completed in FY23
City-County Admin Building	Citywide Facilities	1.11.13	Restrooms - Multiple Users - First Floor	Replace toilet tank with one having flush mechanism on the open side, in the alternative, install an auto flush unit in men's	\$211.25	each	1	\$211.25	1	Employee-only access
City-County Admin Building	Citywide Facilities	1.11.14	Restrooms - Multiple Users - First Floor	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character at women's	\$0.00	staff time	0	\$0.00	1	To be completed in FY22



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
City-County Admin Building	Citywide Facilities	1.11.15	Restrooms - Multiple Users - First Floor	Lower seat covers in women's to max 48" aff	\$0.00	staff time	0	\$0.00	1	To be completed in FY22
City-County Admin Building	Citywide Facilities	1.11.1	Restrooms - Single Users - First Floor	Single user restrooms not accessible, acquire and mount signage at each directing patrons to accessible multi-user restrooms	\$150.00	each	4	\$600.00	1	To be completed in FY22
City-County Admin Building	Citywide Facilities	1.14.1	Alarms - First Floor	Upon renovation <i>install audible and visual</i> alarms in all rooms and spaces	\$407.50	each	30	\$12,225.00	1	To be completed in FY22
City-County Admin Building	Citywide Facilities	1.15.1	Interior Signage - First Floor	Create template for signs that addresses height of sign, size of characters, location of Braille, and other requirements	\$0.00	staff time	0	\$0.00	1	Complete
City-County Admin Building	Citywide Facilities	1.15.2	Interior Signage - First Floor	Implement a sign revision program throughout the building, discriminating between directional signs and signs for permanent spaces	\$0.00	staff time	0	\$0.00	1	Complete
City-County Admin Building	Citywide Facilities	1.15.3	Interior Signage - First Floor	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door	\$150.00	each	30	\$4,500.00	1	Complete
City-County Admin Building	Citywide Facilities	1.6.1		For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	4	\$5,000.00	1	reverse doors at next remodel for: 218, 209, 207, 205; HI: 232 wall; TI: East exit wall, men's room 227
City-County Admin Building	Citywide Facilities	1.6.2		For all doors along the public circulation route, <i>replace</i> doors ones having 32" clear width where indicated	\$1,980.00	each	0	\$0.00	1	Per SHPO (224 tech closet)
City-County Admin Building	Citywide Facilities	1.6.3	Interior Doors - Second Floor	For all doors along the public circulation route, replace push bar with one that protrudes max 4"	\$367.50	each	1	\$367.50	1	To be completed in FY24
City-County Admin Building	Citywide Facilities	1.6.4		For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	10	\$3,675.00	1	To be completed in FY24
City-County Admin Building	Citywide Facilities	1.6.5		For all doors along the public circulation route, <i>inspect, adjust, and maintain</i> 5 lbf to open interior doors	\$0.00	staff time	0	\$0.00	1	On-going



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
City-County Admin Building	Citywide Facilities	1.6.6		For all doors along the public circulation route, <i>inspect, adjust, and maintain</i> closing speed on door closers	\$0.00	staff time	0	\$0.00	1	On-going
City-County Admin Building	Citywide Facilities	1.6.7		For all doors along the public circulation route, replace doors with ones having sidelight viewing windows max 43" aff	\$990.00	each	1	\$990.00	1	To be completed in FY24
City-County Admin Building	Citywide Facilities	1.6.8	Interior Doors - Second Floor	Upon renovation ; make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	1	N/A
City-County Admin Building	Citywide Facilities	1.7.1	Interior Accessible Route - Second Floor	<i>Widen AR</i> to min 36"	\$110.00	lin ft	4	\$440.00	1	Staff will investigate issue as may be a non-issue
City-County Admin Building	Citywide Facilities	1.7.2	Interior Accessible Route - Second Floor	Remove, or relocate storage in CFS at fixtures and operable parts along the AR	\$0.00	staff time	0	\$0.00	1	On-going
City-County Admin Building	Citywide Facilities	1.7.3	Interior Accessible Route - Second Floor	Relocate protruding objects along the interior AR or place cane detectable warning or bollard at foot of fire extinguishers, counter near IT, and spigot	\$250.00	each	4	\$1,000.00	1	To be completed in FY23
City-County Admin Building	Citywide Facilities	1.7.4	Interior Accessible Route - Second Floor	Replace drinking fountain with hi-lo bowl at each location	\$3,998.75	each	4	\$15,995.00	1	To be completed in FY24
City-County Admin Building	Citywide Facilities	1.7.5	Interior Accessible Route - Second Floor	Adjust drinking fountains to correct the height of the spout outlet and to provide knee clearance at indicated fountains	\$250.00	each	1	\$250.00	1	To be completed in FY24
City-County Admin Building	Citywide Facilities	1.7.1	Service Counter - Second Floor	Lower 36" wide segment of service counters to max 36" aff	\$785.00	each	3	\$2,355.00	1	Complete
City-County Admin Building	Citywide Facilities	1.8.1	Public Spaces - Second Floor	Relocate obstacles to create AR through 230	\$0.00	staff time	0	\$0.00	1	Complete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
City-County Admin Building	Citywide Facilities	1.8.2	Public Spaces - Second Floor	Relocate protruding objects in conference or place cane detectable warning or bollard at foot of paper towel dispenser	\$0.00	staff time	0	\$0.00	1	Employee space
City-County Admin Building	Citywide Facilities	1.8.3	Public Spaces - Second Floor	Ramp steps in rooms indicated	\$155.00	inch	26	\$4,030.00	1	Staff will investigate issue as may be a non-issue
City-County Admin Building	Citywide Facilities	1.8.4	Public Spaces - Second Floor	Remove, or relocate storage in CFS at fixtures and operable parts	\$0.00	staff time	0	\$0.00	1	Complete
City-County Admin Building	Citywide Facilities	1.8.5	Public Spaces - Second Floor	Lower operating mechanisms to max 48" aff to highest operable part; leave as is if employee only operated	\$250.00	each	15	\$3,750.00	1	Employee-only operated
City-County Admin Building	Citywide Facilities	1.8.6	Public Spaces - Second Floor	Replace operable parts with ones not requiring a tight pinch or grasp to operate	\$100.00	each	1	\$100.00	1	To be completed in FY23
City-County Admin Building	Citywide Facilities	1.8.7	Public Spaces - Second Floor	Lower sink height to max 34" aff	\$1,700.00	each	1	\$1,700.00	1	To be completed in FY23
City-County Admin Building	Citywide Facilities	1.9.1	Employee Spaces - Second Floor	Employee only area permit approach, entry, and exit, <i>relocate obstacles</i> to create AR through rooms indicated	\$0.00	staff time	0	\$0.00	1	On-going
City-County Admin Building	Citywide Facilities	1.9.2	Employee Spaces - Second Floor	Employee only areas permit approach, entry, and exit, <i>relocate obstacles</i> to create turning space of 60" in rooms indicated if feasible	\$0.00	staff time	0	\$0.00	1	On-going
City-County Admin Building	Citywide Facilities	1.9.3	Employee Spaces - Second Floor	For all other deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	1	Incomplete
City-County Admin Building	Citywide Facilities	1.11.1	Restrooms - Multiple Users - Second Floor - GIS and IT	Lower mirror so reflective surface is max 40" aff in both	\$0.00	staff time	0	\$0.00	1	To be completed in FY23



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
City-County Admin Building	Citywide Facilities	1.11.2	Restrooms - Multiple Users - Second Floor - GIS and IT	Insulate exposed pipes under one sink in both	\$55.00	each	2	\$110.00	1	To be completed in FY23
City-County Admin Building	Citywide Facilities	1.11.3	Restrooms - Multiple Users - Second Floor - GIS and IT	Enlarge accessible stalls in both to 60" wide and 59" deep	\$1,963.75	each	2	\$3,927.50	1	Incomplete will be addressed during renovation
City-County Admin Building	Citywide Facilities	1.11.4	Restrooms - Multiple Users - Second Floor - GIS and IT	Replace one sink in men's with one providing knee and toe clearance	\$3,168.75	each	1	\$3,168.75	1	To be completed in FY23
City-County Admin Building	Citywide Facilities	1.11.5	Restrooms - Multiple Users - Second Floor - GIS and IT	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character at women's	\$0.00	staff time	0	\$0.00	1	To be completed in FY23
City-County Admin Building	Citywide Facilities	1.11.6	Restrooms - Multiple Users - Second Floor - GIS and IT	Lower operating mechanisms in women's to max 48" to highest operable part	\$250.00	each	1	\$250.00	1	To be completed in FY23
City-County Admin Building	Citywide Facilities	1.11.1	Restrooms - Multiple Users - Second Floor - Women's near Historical Preservation	Restroom not accessible, <i>acquire and mount</i> signage directing patrons to accessible restroom	\$150.00	each	1	\$150.00	1	To be completed in FY23
City-County Admin Building	Citywide Facilities	1.6.1	Interior Doors - Third Floor	For all doors along the public circulation route, ramp steps at door entries	\$155.00	inch	7	\$1,085.00	1	To be completed in FY23



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
City-County Admin Building	Citywide Facilities	1.6.2	Interior Doors - Third Floor	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	0	\$0.00	1	Per SHPO; 26 MC issues will be solved with internal labor at no cost (HI: 322 wall, 321 door, 309 A&B, 302 wall, W. women's RR entry, 341 vault, 346 pull, door 346 to 302, L-3-1 Landing by 326; TI: 340 closet, 314A)
City-County Admin Building	Citywide Facilities	1.6.3	Interior Doors - Third Floor	For all doors along the public circulation route, replace doors ones having 32" clear width where indicated	\$1,980.00	each	15	\$29,700.00	1	See line item 447
City-County Admin Building	Citywide Facilities	1.6.4	Interior Doors - Third Floor	For all doors along the public circulation route, replace push bar with one that protrudes max 4"	\$367.50	each	2	\$735.00	1	See line item 447
City-County Admin Building	Citywide Facilities	1.6.5	Interior Doors - Third Floor	For all doors along the public circulation route, repair, bevel, or ramp CILs at door entries to max .25"	\$68.75	inch	2	\$137.50	1	See line item 447
City-County Admin Building	Citywide Facilities	1.6.6	Interior Doors - Third Floor	For all doors along the public circulation route, replace threshold at interior doors with ADA thresholds	\$181.25	each	2	\$362.50	1	See line item 447
City-County Admin Building	Citywide Facilities	1.6.7	Interior Doors - Third Floor	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	47	\$17,272.50	1	See line item 447
City-County Admin Building	Citywide Facilities	1.6.8	Interior Doors - Third Floor	For all doors along the public circulation route, <i>inspect, adjust, and maintain</i> 5 lbf to open interior doors	\$0.00	staff time	0	\$0.00	1	On-going
City-County Admin Building	Citywide Facilities	1.6.9	Interior Doors - Third Floor	For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers	\$0.00	staff time	0	\$0.00	1	On-going
City-County Admin Building	Citywide Facilities	1.6.10	Interior Doors - Third Floor	For all doors along the public circulation route, replace doors with ones having sidelight viewing windows max 43" aff	\$990.00	each	2	\$1,980.00	1	See line item 447
City-County Admin Building	Citywide Facilities	1.6.11	Interior Doors - Third Floor	Upon renovation; make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	1	N/A
City-County Admin Building	Citywide Facilities	1.7.1	Interior Accesible Route - Third Floor	Lower operating mechanisms along the interior AR to max 48" aff to the highest operable part	\$250.00	each	1	\$250.00	1	Employee-only operated
City-County Admin Building	Citywide Facilities	1.7.2	Interior Accesible Route - Third Floor	Remove, or relocate storage in CFS at fixtures and operable parts along the AR	\$0.00	staff time	0	\$0.00	1	On-going
City-County Admin Building	Citywide Facilities	1.7.3	Interior Accesible Route - Third Floor	Relocate protruding objects along the interior AR or place cane detectable warning or bollard at foot of water spigot and agenda at chambers	\$250.00	each	1	\$250.00	1	To be completed in FY23



										<u> </u>
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
City-County Admin Building	Citywide Facilities	1.7.4	Interior Accesible Route - Third Floor	Replace drinking fountain with hi-lo bowl	\$3,998.75	each	1	\$3,998.75	1	To be completed in FY24
City-County Admin Building	Citywide Facilities	1.7.5	Interior Accesible Route - Third Floor	Lower or raise drinking fountains to correct the height of the spout outlet	\$250.00	each	1	\$250.00	1	To be completed in FY24
City-County Admin Building	Citywide Facilities	1.7.1	Service Counter - Third Floor	Lower 36" wide segment of service counter to max 36" aff	\$785.00	each	1	\$785.00	1	Counter removed
City-County Admin Building	Citywide Facilities	1.7.1	Stairs - Interior - Third Floor	Install handrails on both sides of the ramp	\$700.00	each	2	\$1,400.00	1	To be completed in FY25
City-County Admin Building	Citywide Facilities	1.7.2	Stairs - Interior - Third Floor	Replace handrails with ones that are rounded and/or extend to the ground, with handrail extensions and mounted 34" to 38" aff	\$700.00	each	2	\$1,400.00	1	To be completed in FY25
City-County Admin Building	Citywide Facilities	1.8.1	Public Spaces - Third Floor	Remove, or relocate storage in CFS at fixtures and operable parts	\$0.00	staff time	0	\$0.00	1	On-going
City-County Admin Building	Citywide Facilities	1.8.2	Public Spaces - Third Floor	Lower operating mechanisms to max 48" aff to highest operable part; leave as is if employee only operated	\$250.00	each	2	\$500.00	1	Employee-only operated
City-County Admin Building	Citywide Facilities	1.8.3	Public Spaces - Third Floor	Replace or add one work surface with the surface max 34" aff one providing knee and toe clearance	\$800.00	each	1	\$800.00	1	Counter removed
City-County Admin Building	Citywide Facilities	1.9.1	Employee Spaces - Third Floor	Employee only area permit approach, entry, and exit, relocate obstacles to create AR through rooms indicated	\$0.00	staff time	0	\$0.00	1	On-going
City-County Admin Building	Citywide Facilities	1.9.2	Employee Spaces - Third Floor	Employee only areas permit approach, entry, and exit, relocate obstacles to create turning space of 60" in rooms indicated	\$0.00	staff time	0	\$0.00	1	On-going
City-County Admin Building	Citywide Facilities	1.9.3	Employee Spaces - Third Floor	For all other deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	1	N/A
City-County Admin Building	Citywide Facilities	1.11.1	Restrooms - Multiple Users - Third Floor	Create an accessible stall in each restroom	\$3,936.25	each	2	\$7,872.50	1	Not needed due to remodel of Family RR
City-County Admin Building	Citywide Facilities	1.11.2	Restrooms - Multiple Users - Third Floor	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character at men's	\$0.00	staff time	0	\$0.00	1	Not needed due to remodel of Family RR



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
City-County Admin Building	Citywide Facilities	1.11.3	Restrooms - Multiple Users - Third Floor	Replace one sink with one providing knee and toe clearances in men's and assure hardware is operable without a tight pinch or grasp and insulate pipes	\$1,700.00	each	1	\$1,700.00	1	Not needed due to remodel of Family RR
City-County Admin Building	Citywide Facilities	1.11.1	Restrooms - Multiple Users - Third Floor - Women's Near Stairs	Restroom not accessible, <i>acquire and mount</i> signage directing patrons to accessible restroom	\$150.00	each	1	\$150.00	1	To be completed in FY22
City-County Admin Building	Citywide Facilities	1.11.1	Restrooms - Single Users - Third Floor	Leave as is, restroom exempt	\$0.00	n/a	0	\$0.00	1	Complete
City-County Admin Building	Citywide Facilities	1.6.1	Interior Doors - Fourth Floor	For all doors along the public circulation route, <i>provide</i> required maneuvering clearance on push and pull side of doors	\$1,250.00	each	0	\$0.00	1	Per SHPO; 21 MC issues will be solved with internal labor at no cost (HI: 421, 422, 410, east roof access, 435 w., east men's restroom; TI: Women's RR, 408, stairwell entry rail, stairwell door)
City-County Admin Building	Citywide Facilities	1.6.2	Interior Doors - Fourth Floor	No maneuvering clearance at door due to stairs, leave as is, correction is technically infeasible	\$0.00	n/a	0	\$0.00	1	N/A
City-County Admin Building	Citywide Facilities	1.6.3	Interior Doors - Fourth Floor	For all doors along the public circulation route, replace door with one having 32" clear width	\$1,980.00	each	0	\$0.00	1	Per SHPO (HI: 407-408, 407, 405-409, roof access, west men's room, 401 file, 404-403, 403-402, 446, 443-402, 440-439, 435, Men's restroom east, Engineer's door; TI: Stairwell door)
City-County Admin Building	Citywide Facilities	1.6.4	Interior Doors - Fourth Floor	For all doors along the public circulation route, <i>replace</i> doors with ones having 36" clear width at recessed doors	\$1,980.00	each	2	\$3,960.00	1	Incomplete will be addressed during renovation
City-County Admin Building	Citywide Facilities	1.6.5	Interior Doors - Fourth Floor	For all doors along the public circulation route, replace push bar with one that protrudes max 4"	\$367.50	each	2	\$735.00	1	Incomplete will be addressed during renovation
City-County Admin Building	Citywide Facilities	1.6.6	Interior Doors - Fourth Floor	For all doors along the public circulation route, <i>fill</i> and maintain gaps at doorways to max .5"	\$68.75	each	1	\$68.75	1	Incomplete will be addressed during renovation
City-County Admin Building	Citywide Facilities	1.6.7	Interior Doors - Fourth Floor	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	51	\$18,742.50	1	Incomplete will be addressed during renovation
City-County Admin Building	Citywide Facilities	1.6.8	Interior Doors - Fourth Floor	For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors	\$0.00	staff time	0	\$0.00	1	Incomplete will be addressed during renovation



			1			1				
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
City-County Admin Building	Citywide Facilities	1.6.9	Interior Doors - Fourth Floor	For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers	\$0.00	staff time	0	\$0.00	1	Incomplete will be addressed during renovation
City-County Admin Building	Citywide Facilities	1.6.10	Interior Doors - Fourth Floor	For all doors along the public circulation route, replace doors with ones having sidelight viewing windows max 43" aff	\$990.00	each	2	\$1,980.00	1	Incomplete will be addressed during renovation
City-County Admin Building	Citywide Facilities	1.6.11	Interior Doors - Fourth Floor	Upon renovation; make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	1	N/A
City-County Admin Building	Citywide Facilities	1.8.1	Public Spaces - Fourth Floor	Remove, or relocate storage in CFS at fixtures and operable parts	\$0.00	staff time	0	\$0.00	1	On-going
City-County Admin Building	Citywide Facilities	1.8.2	Public Spaces - Fourth Floor	Lower operating mechanisms to max 48" aff to highest operable part; leave as is if employee only operated	\$250.00	each	1	\$250.00	1	Employee-only operated
City-County Admin Building	Citywide Facilities	1.9.1	Employee Spaces - Fourth Floor	Employee only area permit approach, entry, and exit, relocate obstacles to create AR through rooms indicated	\$0.00	staff time	0	\$0.00	1	On-going
City-County Admin Building	Citywide Facilities	1.9.2	Employee Spaces - Fourth Floor	Employee only areas permit approach, entry, and exit, relocate obstacles to create turning space of 60" in rooms indicated	\$0.00	staff time	0	\$0.00	1	On-going
City-County Admin Building	Citywide Facilities	1.9.3	Employee Spaces - Fourth Floor	For all other deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	1	N/A
City-County Admin Building	Citywide Facilities	1.11.1	Restrooms - Multiple Users - Fourth Floor West	Lower mirror so reflective surface is max 40" aff in both	\$0.00	staff time	0	\$0.00	1	To be completed in FY22
City-County Admin Building	Citywide Facilities	1.11.2	Restrooms - Multiple Users - Fourth Floor West	Replace one sink with one providing knee and toe clearances and insulate exposed pipes in both	\$3,168.75	each	1	\$3,168.75	1	To be completed in FY24
City-County Admin Building	Citywide Facilities	1.11.3	Restrooms - Multiple Users - Fourth Floor West	Lower seat cover dispenser in women's and thermostats in both to max 48" to highest operable part	\$0.00	staff time	0	\$0.00	1	To be completed in FY22
City-County Admin Building	Citywide Facilities	1.11.4	Restrooms - Multiple Users - Fourth Floor West	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights in both	\$3,936.25	each	2	\$7,872.50	1	Individuals are directed by a sign to use 3rd Floor Family Restroom



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
City-County Admin Building	Citywide Facilities	1.11.1	Restrooms - Multiple Users - Fourth Floor - Other Men's	Restroom not accessible, <i>acquire and mount</i> signage directing patrons to accessible restroom	\$150.00	each	2	\$300.00	1	Complete
City-County Admin Building	Citywide Facilities	1.6.1	Interior Doors - Basement	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	23	\$28,750.00	1	Incomplete will be addressed during renovation
City-County Admin Building	Citywide Facilities	1.6.2	Interior Doors - Basement	Leave as is, maneuvering clearance in closet or storage, correction is technically infeasible	\$0.00	n/a	0	\$0.00	1	N/A
City-County Admin Building	Citywide Facilities	1.6.3	Interior Doors - Basement	For all doors along the public circulation route, correct or repair slope at doorway landing to max 2.08% in any direction for level CFS	\$2,187.50	each	2	\$4,375.00	1	Incomplete will be addressed during renovation
City-County Admin Building	Citywide Facilities	1.6.4	Interior Doors - Basement	For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width	\$1,980.00	each	6	\$11,880.00	1	Incomplete will be addressed during renovation
City-County Admin Building	Citywide Facilities	1.6.5	Interior Doors - Basement	For all doors along the public circulation route, repair, bevel, or ramp CILs at door entries to max .25"	\$68.75	inch	9	\$618.75	1	Incomplete will be addressed during renovation
City-County Admin Building	Citywide Facilities	1.6.6	Interior Doors - Basement	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	31	\$11,392.50	1	Incomplete will be addressed during renovation
City-County Admin Building	Citywide Facilities	1.6.7	Interior Doors - Basement	For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors	\$0.00	staff time	0	\$0.00	1	On-going
City-County Admin Building	Citywide Facilities	1.6.8	Interior Doors - Basement	For all doors along the public circulation route, replace doors with ones having sidelight viewing windows max 43" aff	\$990.00	each	9	\$8,910.00	1	Incomplete will be addressed during renovation
City-County Admin Building	Citywide Facilities	1.7.1	Stairs - Interior - Basement	Install handrails on both sides of stairway, mounted 34" to 38" aff with top and bottom extensions and having a 1.25" – 2" in diameter, or a non circular grip that has a perimeter dimension of 4"- 6.25" max	\$700.00	each	2	\$1,400.00	1	To be completed in FY24
City-County Admin Building	Citywide Facilities	1.8.1	Public Spaces - Basement	Relocate protruding objects in break room or place cane detectable warning or bollard at foot of first aid	\$250.00	each	1	\$250.00	1	To be completed in FY22
City-County Admin Building	Citywide Facilities	1.8.2	Public Spaces - Basement	Lower operating mechanisms to max 48" aff to highest operable part; leave as is if employee only operated	\$0.00	staff time	0	\$0.00	1	Employee-only operated
City-County Admin Building	Citywide Facilities	1.9.1	Employee Spaces - Basement	Employee only area permit approach, entry, and exit, relocate obstacles to create AR through rooms indicated	\$0.00	staff time	0	\$0.00	1	On-going



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
City-County Admin Building	Citywide Facilities	1.9.2	Employee Spaces - Basement	Employee only areas permit approach, entry, and exit, <i>relocate obstacles</i> to create turning space of 60" in rooms indicated	\$0.00	staff time	0	\$0.00	1	On-going
City-County Admin Building	Citywide Facilities	1.9.3	Employee Spaces - Basement	For all other deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	1	N/A
City-County Admin Building	Citywide Facilities	1.11.1	Restrooms - Single Users - Basement	Restroom not accessible, <i>acquire and mount</i> signage directing patrons to accessible restroom	\$150.00	each	1	\$150.00	1	Employee-only operated
City-County Admin Building	Citywide Facilities	1.12.1	Kitchen - Basement	For all deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	1	N/A
Civic Center	Citywide Facilities	1.1.1	Parking	Repaint stalls and access aisles to be 8' and 5' each	\$52.50	each	1	\$52.50	3	Complete
Civic Center	Citywide Facilities	1.1.2	Parking	Repair or correct slope of parking spaces and access aisles to max 2.08% in any direction	\$2,187.50	each	5	\$10,937.50	3	Staff to investigate completion status
Civic Center	Citywide Facilities	1.1.3	Parking	Resurface stall to eliminate CIL at manhole cover	\$68.75	each	1	\$68.75	3	Incomplete
Civic Center	Citywide Facilities	1.2.1	Exterior Accessible Route	Create a curb ramp to be max running slope 8.33%, max cross slope 2.08%, having a top landing as wide as the ramp and 36" deep and side flares with a max slope 10% at far stall	\$1,062.50	each	1	\$1,062.50	3	To be completed in FY22
Civic Center	Citywide Facilities	1.2.2	Exterior Accessible Route	Create a level landing, max 2.08% slope, at the top of the curb ramp, 36" deep and as wide as ramp	\$87.50	sq ft	32	\$2,800.00	3	To be completed in FY22
Civic Center	Citywide Facilities	1.2.3	Exterior Accessible Route	Correct curb ramp slope to max 8.33%	\$725.00	each	1	\$725.00	3	To be completed in FY22
Civic Center	Citywide Facilities	1.2.4	Exterior Accessible Route	Repair, bevel, or ramp CIL along AR	\$68.75	each	1	\$68.75	3	To be completed in FY22
Civic Center	Citywide Facilities	1.2.5	Exterior Accessible Route	Correct or fill gaps along AR	\$68.75	each	3	\$206.25	3	To be completed in FY22
Civic Center	Citywide Facilities	1.2.6	Exterior Accessible Route	Correct or repair sidewalk cross slope along AR to max 2.08%	\$87.50	sq ft	75	\$6,562.50	3	To be completed in FY22
Civic Center	Citywide Facilities	1.3.1	Exterior Signage	Mount signage at inaccessible entrances directing patrons in wheelchairs to accessible entrance	\$150.00	each	2	\$300.00	3	Complete



						.,				
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Civic Center	Citywide Facilities	1.3.2	Exterior Signage	Mount signage at entrance designating it as accessible	\$150.00	each	2	\$300.00	3	Complete
Civic Center	Citywide Facilities	1.4.1	Exterior Doors	For all doors along the public circulation route, correct or repair slope at doorway landing to max 2.08% in any direction for level CFS	\$2,187.50	each	2	\$4,375.00	3	To be completed in FY22
Civic Center	Citywide Facilities	1.4.2	Exterior Doors	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	3	\$3,750.00	3	Complete
Civic Center	Citywide Facilities	1.4.3	Exterior Doors	For all doors along the public circulation route, replace doors with ones having 80" overhead and 32" clear width	\$1,980.00	each	4	\$7,920.00	3	Incomplete
Civic Center	Citywide Facilities	1.4.4	Exterior Doors	For all doors along the public circulation route, replace push bars on indicated doors with ones having a profile less than 4"	\$367.50	each	2	\$735.00	3	Complete
Civic Center	Citywide Facilities	1.4.5	Exterior Doors	For all doors along the public circulation route, <i>repair, bevel, or ramp CIL</i> at door entries to max .25"	\$68.75	each	6	\$412.50	3	Incomplete
Civic Center	Citywide Facilities	1.4.6	Exterior Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	5	\$1,837.50	3	Incomplete
Civic Center	Citywide Facilities	1.4.7	Exterior Doors	For all doors along the public circulation route, create level CFS at the power door controls	\$87.50	sq ft	25	\$2,187.50	3	Complete
Civic Center	Citywide Facilities	1.4.8	Exterior Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice	\$0.00	staff time	0	\$0.00	3	On-going
Civic Center	Citywide Facilities	1.4.9	Exterior Doors	For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers	\$0.00	staff time	0	\$0.00	3	On-going
Civic Center	Citywide Facilities	1.4.10	Exterior Doors	For all doors along the public circulation route, replace doors with ones having sidelight viewing windows max 43" aff	\$990.00	each	1	\$990.00	3	To be completed in FY22
Civic Center	Citywide Facilities	1.4.11	Exterior Doors	Upon renovation; make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	3	N/A
Civic Center	Citywide Facilities	1.6.1		For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	11	\$13,750.00	3	Staff to investigate technical feasibility
Civic Center	Citywide Facilities	1.6.2		For all doors along the public circulation route, correct or repair slope at doorway landing to max 2.08% in any direction for level CFS	\$2,187.50	each	1	\$2,187.50	3	Staff to investigate technical feasibility
Civic Center	Citywide Facilities	1.6.3	Interior Doors - Ballroom Side	No maneuvering clearance at door due to stairs, <i>Ieave as is</i> , correction is technically infeasible	\$0.00	n/a	0	\$0.00	3	N/A



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Civic Center	Citywide Facilities	1.6.4		For all doors along the public circulation route, replace doors with ones having 80" overhead and 32" clear width	\$1,980.00	each	12	\$23,760.00	3	Incomplete will be addressed during renovation
Civic Center	Citywide Facilities	1.6.5		For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	8	\$2,940.00	3	Incomplete will be addressed during renovation
Civic Center	Citywide Facilities	1.6.6		For all doors along the public circulation route, <i>inspect, adjust, and maintain</i> 5 lbf to open interior doors as a smart practice	\$0.00	staff time	0	\$0.00	3	On-going
Civic Center	Citywide Facilities	1.6.7		For all doors along the public circulation route, <i>inspect, adjust, and maintain</i> closing speed on door closers	\$0.00	staff time	0	\$0.00	3	On-going
Civic Center	Citywide Facilities	1.6.8		For all doors along the public circulation route, replace doors with ones having sidelight viewing windows max 43" aff	\$990.00	each	2	\$1,980.00	3	Incomplete will be addressed during renovation
Civic Center	Citywide Facilities	1.6.9	Interior Doors - Ballroom Side	Upon renovation ; make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	3	N/A
Civic Center	Citywide Facilities	1.7.1	Stairs - Interior - Ballroom Side	Correct riser heights on stairs to consistent height between 4" to 7", leave as is if technically infeasible	\$288.75	each	59	\$17,036.25	3	Staff to investigate technical feasibility
Civic Center	Citywide Facilities	1.7.2	Stairs - Interior - Ballroom Side	Install kick plates on all stairs or replace with ones having closed risers	\$100.00	each	14	\$1,400.00	3	N/A no open stair risers exist in ballroom
Civic Center	Citywide Facilities	1.7.3	Stairs - Interior - Ballroom Side	Create visual contrast on the leading edge of treads	\$20.00	each	87	\$1,740.00	3	Incomplete
Civic Center	Citywide Facilities	1.7.4	Stairs - Interior - Ballroom Side	<i>Install</i> detectable warning strip on top tread of each stairway as a smart practice	\$150.00	each	7	\$1,050.00	3	Incomplete
Civic Center	Citywide Facilities	1.7.5	Stairs - Interior - Ballroom Side	Correct tread depth on stairs to 11" minimum and consistent, leave as is if technically infeasible	\$288.75	each	56	\$16,170.00	3	Staff to investigate technical feasibility



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of	Total cost	Phase	Notes
Civic Center	Citywide Facilities	1.7.6	Stairs - Interior - Ballroom Side	Replace handrails with ones that are rounded and/or extend to the ground, with handrail extensions and mounted 34" to 38" aff	\$700.00	each	7	\$4,900.00	3	Incomplete
Civic Center	Citywide Facilities	1.7.1	Ramps - Interior - Ballroom Side	Correct running slope of ramps to max 8.33%	\$87.50	sq ft	90	\$7,875.00	3	Staff to investigate technical feasibility
Civic Center	Citywide Facilities	1.7.2	Ramps - Interior - Ballroom Side	Install compliant handrail that is continuous throughout the run, if feasible	\$700.00	each	1	\$700.00	3	Staff to investigate technical feasibility
Civic Center	Citywide Facilities	1.7.3	Ramps - Interior - Ballroom Side	Enlarge landing to be 60" deep and as wide as the ramp	\$1,250.00	each	1	\$1,250.00	3	Staff to investigate technical feasibility
Civic Center	Citywide Facilities	1.7.4	Ramps - Interior - Ballroom Side	Enlarge landing on ramp adjacent to door to 60" by 60" minimum	\$1,250.00	each	1	\$1,250.00	3	Staff to investigate technical feasibility
Civic Center	Citywide Facilities	1.7.5	Ramps - Interior - Ballroom Side	Replace handrails with ones that are rounded and/or extend to the ground, with handrail extensions and mounted 34" to 38" aff	\$700.00	each	1	\$700.00	3	Incomplete
Civic Center	Citywide Facilities	1.8.1	Public Spaces - Ballroom Side	Relocate protruding objects in lower ballroom or place cane detectable warning or bollard at foot of fire extinguisher	\$250.00	each	1	\$250.00	3	Incomplete
Civic Center	Citywide Facilities	1.8.2	Public Spaces - Ballroom Side	Lower operating mechanisms in spaces indicated to max 48" aff to highest operable part; leave as is if employee only operated	\$250.00	each	2	\$500.00	3	Employee-only operated
Civic Center	Citywide Facilities	1.9.1	Employee Spaces - Ballroom Side	Employee only area permit approach, entry, and exit, <i>relocate obstacles</i> to create AR through spaces indicated	\$0.00	staff time	0	\$0.00	3	Employee-only operated
Civic Center	Citywide Facilities	1.9.2	Employee Spaces - Ballroom Side	Employee only areas permit approach, entry, and exit, <i>relocate obstacles</i> to create turning space of 60" in spaces indicated	\$0.00	staff time	0	\$0.00	3	Employee-only operated
Civic Center	Citywide Facilities	1.9.3	Employee Spaces - Ballroom Side	For all other deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	3	N/A



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Civic Center	Citywide Facilities	1.11.1	Restrooms - Multiple Users - Ballroom Side	Insulate exposed pipes under one sink in both	\$55.00	each	2	\$110.00	3	Incomplete
Civic Center	Citywide Facilities	1.11.2	Restrooms - Multiple Users - Ballroom Side	Lower hooks in accessible stalls to max 48" aff in both	\$0.00	staff time	0	\$0.00	3	Complete
Civic Center	Citywide Facilities	1.11.3	Restrooms - Multiple Users - Ballroom Side	Lower changing table to max 34" aff to surface when in open position and max 48" aff to handle when in closed position in women's	\$0.00	staff time	0	\$0.00	3	Incomplete
Civic Center	Citywide Facilities	1.11.4	Restrooms - Multiple Users - Ballroom Side	Remount grab bars in accessible stall to 33" to 36" aff in both	\$281.25	each	2	\$562.50	3	Incomplete
Civic Center	Citywide Facilities	1.11.5	Restrooms - Multiple Users - Ballroom Side	Remount toilet paper dispenser 15" to 48" aff and min 12" above or 1.5" below grab bars in both	\$0.00	staff time	0	\$0.00	3	Incomplete
Civic Center	Citywide Facilities	1.11.6	Restrooms - Multiple Users - Ballroom Side	<i>Install</i> vertical grab bars in accessible stalls in both	\$281.25	each	2	\$562.50	3	Incomplete
Civic Center	Citywide Facilities	1.11.7	Restrooms - Multiple Users - Ballroom Side	Adjust stall door to be self-closing in both	\$0.00	staff time	0	\$0.00	3	Complete
Civic Center	Citywide Facilities	1.11.8	Restrooms - Multiple Users - Ballroom Side	Relocate or recess towel dispenser in both to not interfere with general circulation path, protrusions can't be greater than 4"	\$250.00	each	2	\$500.00	3	Incomplete
Civic Center	Citywide Facilities	1.11.9	Restrooms - Multiple Users - Ballroom Side	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" aff	\$2,127.50	each	1	\$2,127.50	3	Incomplete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Civic Center	Citywide Facilities	1.11.10	Restrooms - Multiple Users - Ballroom Side	Create an ambulatory accessible stall with grab bars and fixtures mounted in correct locations and at correct heights in men's	\$3,936.25	each	1	\$3,936.25	3	Incomplete
Civic Center	Citywide Facilities	1.11.11	Restrooms - Multiple Users - Ballroom Side	Widen accessible stall to min. 60" clear width, 59" depth in men's	\$1,963.75	each	1	\$1,963.75	3	Incomplete
Civic Center	Citywide Facilities	1.11.12	Restrooms - Multiple Users - Ballroom Side	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet in men's	\$300.00	each	1	\$300.00	3	Incomplete
Civic Center	Citywide Facilities	1.11.13	Restrooms - Multiple Users - Ballroom Side	Adjust ambulatory accessible stall to be proper dimension with grab bars and fixtures mounted in correct locations and at correct heights in women's	\$3,936.25	each	1	\$3,936.25	3	Incomplete
Civic Center	Citywide Facilities	1.11.14	Restrooms - Multiple Users - Ballroom Side	Replace toilet seat, or re-set or replace toilet to 17" to 19" aff in women's	\$1,306.00	each	1	\$1,306.00	3	Incomplete
Civic Center	Citywide Facilities	1.11.15	Restrooms - Multiple Users - Ballroom Side	Remount rear grab bar to behind the toilet, 12" to one side of center and 24" to the other and 33" to 36" aff in women's	\$281.25	each	1	\$281.25	3	Incomplete
Civic Center	Citywide Facilities	1.12.1	Kitchen - Ballroom Side	For all deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	3	N/A
Civic Center	Citywide Facilities	1.14.1	Alarms - Ballroom Side	Install audible and visual alarms in rooms and spaces where alarms have been installed since 1992	\$407.50	each	15	\$6,112.50	3	Complete
Civic Center	Citywide Facilities	1.14.2	Alarms - Ballroom Side	Upon renovation <i>install audible and visual</i> alarms in all rooms and spaces	\$373.50	each	10	\$3,735.00	3	Complete
Civic Center	Citywide Facilities	1.15.1	Interior Signage - Ballroom Side	Create template for signs that addresses height of sign, size of characters, location of Braille, and other requirements	\$0.00	staff time	0	\$0.00	3	Incomplete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Civic Center	Citywide Facilities	1.15.2	Interior Signage - Ballroom Side	Implement a sign revision program throughout the building, discriminating between directional signs and signs for permanent spaces	\$0.00	staff time	0	\$0.00	3	Incomplete
Civic Center	Citywide Facilities	1.15.3	Interior Signage - Ballroom Side	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door	\$150.00	each	10	\$1,500.00	3	Incomplete
Civic Center	Citywide Facilities	1.16.1	Fitness - Ballroom Side	Create a 30" by 48" "parking space" next to one of each type of fitness equipment offered in the space	\$0.00	staff time	0	\$0.00	3	Employee-only operated
Civic Center	Citywide Facilities	1.6.1	Interior Doors - Auditorium Side	For all doors along the public circulation route, <i>provide</i> required maneuvering clearance on push and pull side of doors	\$1,250.00	each	31	\$38,750.00	3	Staff to investigate technical feasibility
Civic Center	Citywide Facilities	1.6.2	Interior Doors - Auditorium Side	For all doors along the public circulation route, relocate storage, furniture, and other obstacles to create 60" maneuvering space around doors	\$0.00	staff time	0	\$0.00	3	On-going
Civic Center	Citywide Facilities	1.6.3	Interior Doors - Auditorium Side	For all doors along the public circulation route, correct or repair slope at doorway landing to max 2.08% in any direction for level CFS	\$2,187.50	each	2	\$4,375.00	3	N/A technically infeasible
Civic Center	Citywide Facilities	1.6.4	Interior Doors - Auditorium Side	For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width	\$1,980.00	each	19	\$37,620.00	3	N/A technically infeasible
Civic Center	Citywide Facilities	1.6.5	Interior Doors - Auditorium Side	For all doors along the public circulation route, <i>repair, bevel, or ramp CILs</i> at door entries to max .25"	\$68.75	inch	15	\$1,031.25	3	Incomplete
Civic Center	Citywide Facilities	1.6.6	Interior Doors - Auditorium Side	For all doors along the public circulation route, replace threshold at interior doors with ADA thresholds	\$181.25	each	1	\$181.25	3	Incomplete
Civic Center	Citywide Facilities	1.6.7	Interior Doors - Auditorium Side	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	57	\$20,947.50	3	Incomplete
Civic Center	Citywide Facilities	1.6.8	Interior Doors - Auditorium Side	For all doors along the public circulation route, replace hardware with lever hardware where indicated, mounted 34" to 48" aff	\$250.00	each	3	\$750.00	3	Incomplete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Civic Center	Citywide Facilities	1.6.9	Interior Doors - Auditorium Side	For all doors along the public circulation route, <i>inspect, adjust, and maintain</i> 5 lbf to open interior doors	\$0.00	staff time	0	\$0.00	3	On-going
Civic Center	Citywide Facilities	1.6.10	Interior Doors - Auditorium Side	For all doors along the public circulation route, <i>inspect, adjust, and maintain</i> closing speed on door closers	\$0.00	staff time	0	\$0.00	3	On-going
Civic Center	Citywide Facilities	1.6.11	Interior Doors - Auditorium Side	For employee only doors; make above corrections upon renovation	\$0.00	n/a	0	\$0.00	3	N/A
Civic Center	Citywide Facilities	1.7.1	Interior Accessible Route - Auditorium Side	Provide an AR to all public areas required to be accessible	\$31,165.00	each	1	\$31,165.00	3	Staff to investigate technical feasibility
Civic Center	Citywide Facilities	1.7.2	Interior Accessible Route - Auditorium Side	Correct or repair running slope of AR to max 5%	\$87.50	sq ft	140	\$12,250.00	3	N/A technically infeasible
Civic Center	Citywide Facilities	1.7.3	Interior Accessible Route - Auditorium Side	Lower operating mechanisms along the interior AR to max 48" aff to the highest operable part	\$250.00	each	1	\$250.00	3	Employee-only operated
Civic Center	Citywide Facilities	1.7.4	Interior Accessible Route - Auditorium Side	Raise angled supports to min 80", or pad object to prevent hazard in overhead clearance	\$110.00	each	10	\$1,100.00	3	Staff to investigate technical feasibility
Civic Center	Citywide Facilities	1.7.5	Interior Accessible Route - Auditorium Side	Relocate protruding objects along the interior AR or place cane detectable warning or bollard at foot of protrusions	\$250.00	each	1	\$250.00	3	Incomplete
Civic Center	Citywide Facilities	1.7.6	Interior Accessible Route - Auditorium Side	Replace drinking fountain with hi-lo bowl	\$3,998.75	each	1	\$3,998.75	3	Incomplete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit	# of	Total cost	Phase	Notes
Site	HCC DIST	Cite		Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Civic Center	Citywide Facilities	1.7.7	Interior Accessible Route - Auditorium Side	Mount compliant signage at all doors along the egress route	\$150.00	each	2	\$300.00	3	To be completed in FY23
Civic Center	Citywide Facilities	1.7.8	Interior Accessible Route - Auditorium Side	Lower 36" wide segment of service counter to max 36" aff	\$785.00	each	1	\$785.00	3	Staff to investigate completion status
Civic Center	Citywide Facilities	1.7.1	Stairs - Interior - Auditorium Side	Correct riser heights on stairs to consistent height between 4" to 7", leave as is if technically infeasible	\$288.75	each	28	\$8,085.00	3	Staff to investigate technical feasibility
Civic Center	Citywide Facilities	1.7.2	Stairs - Interior - Auditorium Side	Correct tread depth on stairs to 11" minimum and consistent, leave as is if technically infeasible	\$288.75	each	28	\$8,085.00	3	Staff to investigate technical feasibility
Civic Center	Citywide Facilities	1.7.3	Stairs - Interior - Auditorium Side	Create visual contrast on the leading edge of treads	\$20.00	each	28	\$560.00	3	Incomplete
Civic Center	Citywide Facilities	1.7.4	Stairs - Interior - Auditorium Side	Install detectable warning strip on top tread of each stairway as a smart practice	\$150.00	each	2	\$300.00	3	Incomplete
Civic Center	Citywide Facilities	1.7.5	Stairs - Interior - Auditorium Side	Replace handrails with ones that are rounded and/or extend to the ground, with handrail extensions and mounted 34" to 38" aff	\$70.00	each	2	\$140.00	3	Staff to investigate technical feasibility
Civic Center	Citywide Facilities	1.7.1	Ramps - Interior - Auditorium Side	Correct slope of ramp to max 8.33% where indicated	\$87.50	sq ft	900	\$78,750.00	3	N/A technically infeasible
Civic Center	Citywide Facilities	1.7.2	Ramps - Interior - Auditorium Side	Shorten ramp run to max 30' or a max of 30" rise where indicated	\$155.00	inch	10	\$1,550.00	3	N/A technically infeasible
Civic Center	Citywide Facilities	1.7.3	Ramps - Interior - Auditorium Side	Correct ramp cross slope to max 2.08% where indicated	\$87.50	sq ft	25	\$2,187.50	3	N/A technically infeasible



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Civic Center	Citywide Facilities	1.7.4	Ramps - Interior - Auditorium Side	Create landing minimum 60" deep and as wide as the ramp where indicated	\$1,250.00	each	5	\$6,250.00	3	Staff to investigate technical feasibility
Civic Center	Citywide Facilities	1.7.5	Ramps - Interior - Auditorium Side	Install handrails on both sides of the ramp where indicated	\$700.00	each	4	\$2,800.00	3	Incomplete
Civic Center	Citywide Facilities	1.7.6	Ramps - Interior - Auditorium Side	Replace handrails with ones that are rounded and/or extend to the ground, with handrail extensions and mounted 34" to 38" aff where indicated	\$700.00	each	6	\$4,200.00	3	Incomplete
Civic Center	Citywide Facilities	1.8.1	Public Spaces - Auditorium	Widen AR through auditorium to min 36" clear width	\$110.00	lin ft	2	\$220.00	3	Incomplete
Civic Center	Citywide Facilities	1.8.2	Public Spaces - Auditorium	Relocate protruding objects in spaces indicated or place cane detectable warning or bollard at foot of protrusions	\$250.00	each	6	\$1,500.00	3	Incomplete
Civic Center	Citywide Facilities	1.8.3	Public Spaces - Auditorium	Provide a ramp for access to the stage area in the auditorium	\$155.00	inch	21	\$3,255.00	3	Incomplete
Civic Center	Citywide Facilities	1.8.4	Public Spaces - Auditorium	Correct or repair slope to max 5% running	\$87.50	sq ft	60	\$5,250.00	3	Staff to investigate technical feasibility
Civic Center	Citywide Facilities	1.8.5	Public Spaces - Auditorium	Repair, bevel or ramp CIL in rooms indicated	\$68.75	inch	6	\$412.50	3	Staff to investigate technical feasibility
Civic Center	Citywide Facilities	1.8.6	Public Spaces - Auditorium	Lower operating mechanisms in spaces indicated to max 48" aff to highest operable part; leave as is if employee only operated	\$250.00	each	7	\$1,750.00	3	Employee-only operated
Civic Center	Citywide Facilities	1.9.1	Employee Spaces - Auditoriusm	Employee only area permit approach, entry, and exit, relocate obstacles to create AR through spaces indicated	\$0.00	staff time	0	\$0.00	3	Employee-only operated
Civic Center	Citywide Facilities	1.9.2	Employee Spaces - Auditoriusm	Employee only areas permit approach, entry, and exit, relocate obstacles to create turning space of 60" in spaces indicated	\$0.00	staff time	0	\$0.00	3	Employee-only operated
Civic Center	Citywide Facilities	1.9.3	Employee Spaces - Auditoriusm	For all other deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	3	N/A
Civic Center	Citywide Facilities	1.10.1	Assembly Area - Auditorium Side	Acquire and mount signage, including access symbol, designating specified number of wheelchair seats	\$150.00	each	2	\$300.00	3	Incomplete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Civic Center	Citywide Facilities	1.10.2	Assembly Area - Auditorium Side	Disperse accessible seating throughout the assembly area	\$449.50	each	16	\$7,192.00	3	N/A technically infeasible
Civic Center	Citywide Facilities	1.10.3	Assembly Area - Auditorium Side	Provide ramps for access to new seating, or place along an existing AR	\$4,650.00	each	2	\$9,300.00	3	N/A technically infeasible
Civic Center	Citywide Facilities	1.10.4	Assembly Area - Auditorium Side	Advertise the availability of assisted listening devices, if available, or have resources for acquiring ALDs upon request	\$150.00	each	2	\$300.00	3	Complete
Civic Center	Citywide Facilities	1.10.5	Assembly Area - Auditorium Side	Provide a ramp to access stage area	\$155.00	inch	21	\$3,255.00	3	Incomplete
Civic Center	Citywide Facilities	1.11.1	Restrooms - Multiple Users - Auditorium Side - Lobby Accessible	Insulate exposed pipes under one sink in both	\$55.00	each	2	\$110.00	3	To be completed in FY23
Civic Center	Citywide Facilities	1.11.2	Restrooms - Multiple Users - Auditorium Side - Lobby Accessible	Lower operable parts to max 48" to highest operable part in both	\$0.00	staff time	0	\$0.00	3	Employee-only operated
Civic Center	Citywide Facilities	1.11.3	Restrooms - Multiple Users - Auditorium Side - Lobby Accessible	Remount rear grab bar to behind the toilet, 12" to one side of center and 24" to the other in both	\$281.25	each	2	\$562.50	3	Incomplete
Civic Center	Citywide Facilities	1.11.4	Restrooms - Multiple Users - Auditorium Side - Lobby Accessible	Remount grab bars in accessible stall to 33" to 36" aff in both	\$281.25	each	4	\$1,125.00	3	Incomplete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Civic Center	Citywide Facilities	1.11.5	Restrooms - Multiple Users - Auditorium Side - Lobby Accessible	<i>Install</i> vertical grab bars in accessible stalls in both	\$281.25	each	2	\$562.50	3	Incomplete
Civic Center	Citywide Facilities	1.11.6	Restrooms - Multiple Users - Auditorium Side - Lobby Accessible	Replace stall hardware with hardware operable without a tight pinch or grasp and adjust stall doors to be self-closing in both	\$100.00	each	2	\$200.00	3	Incomplete
Civic Center	Citywide Facilities	1.11.7	Restrooms - Multiple Users - Auditorium Side - Lobby Accessible	Rehang stall door to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet in both	\$300.00	each	2	\$600.00	3	Incomplete
Civic Center	Citywide Facilities	1.11.8	Restrooms - Multiple Users - Auditorium Side - Lobby Accessible	Relocate or recess counters to not interfere with general circulation path in both, protrusions can't be greater than 4"	\$250.00	each	2	\$500.00	3	Incomplete
Civic Center	Citywide Facilities	1.11.9	Restrooms - Multiple Users - Auditorium Side - Lobby Accessible	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" aff	\$2,127.50	each	1	\$2,127.50	3	Incomplete
Civic Center	Citywide Facilities	1.11.10	Restrooms - Multiple Users - Auditorium Side - Lobby Accessible	Adjust ambulatory accessible stall to compliant dimensions with grab bars and fixtures mounted in correct locations and at correct heights in men's	\$3,936.25	each	1	\$3,936.25	3	Incomplete
Civic Center	Citywide Facilities	1.11.11	Restrooms - Multiple Users - Auditorium Side - Lobby Accessible	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff in men's	\$281.25	each	1	\$281.25	3	Incomplete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Civic Center	Citywide Facilities	1.11.12	Restrooms - Multiple Users - Auditorium Side - Lobby Accessible	Create an ambulatory accessible stall with grab bars and fixtures mounted in correct locations and at correct heights in women's	\$3,936.25	each	1	\$3,936.25	3	Incomplete
Civic Center	Citywide Facilities	1.11.13	Restrooms - Multiple Users - Auditorium Side - Lobby Accessible	Remount toilet to 16" to 18" from the side wall to centerline in women's	\$1,306.00	each	1	\$1,306.00	3	Incomplete
Civic Center	Citywide Facilities	1.11.14	Restrooms - Multiple Users - Auditorium Side - Lobby Accessible	Widen accessible stalls to min. 60" clear width, 59" depth in women's	\$1,963.75	each	1	\$1,963.75	3	Incomplete
Civic Center	Citywide Facilities	1.11.15	Restrooms - Multiple Users - Auditorium Side - Lobby Accessible	Relocate baby changing table to have required CFS	\$0.00	staff time	0	\$0.00	3	Incomplete
Civic Center	Citywide Facilities	1.11.1	Restrooms - Multiple Users - Auditorium Side - Lobby Inaccessible	Restroom not accessible, <i>acquire and mount</i> signage directing patrons to accessible restroom	\$150.00	each	2	\$300.00	3	Incomplete
Civic Center	Citywide Facilities	1.11.2	Restrooms - Multiple Users - Auditorium Side - Lobby Inaccessible	Leave as is, remaining deficits, restrooms inaccessible	\$0.00	n/a	0	\$0.00	3	N/A
Civic Center	Citywide Facilities	1.11.1	Restrooms - Single Users - Auditorium Side	Renovate one dressing room to be accessible; having a compliant toilet stall, shower and amenities	\$8,817.50	each	1	\$8,817.50	3	Complete
Civic Center	Citywide Facilities	1.11.2	Restrooms - Single Users - Auditorium Side	Leave as is, second dressing room and mount signage directing patrons with disabilities to the accessible dressing room	\$0.00	n/a	0	\$0.00	3	N/A



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit	# of units	Total cost	Phase	Notes
Site	HCC DIST	Cite		Recommendation	Price/ unit	type	units	Total Cost	Filase	Notes
<u>Clinton Park</u>	Helena Citizens Council District 1	1.2.1	Exterior Accessible Route	Create a level landing at the top of the curb ramp, 36" deep and as wide as ramp	\$87.50	sq ft	16	\$1,400.00	со	Incomplete
Clinton Park	Helena Citizens Council District 1	1.2.2	Exterior Accessible Route	Correct slope of curb ramp side flares to max 10%	\$725.00	each	1	\$725.00	СО	Incomplete
Clinton Park	Helena Citizens Council District 1	1.2.3	Exterior Accessible Route	Correct curb ramp slope to max 8.33%	\$725.00	each	2	\$1,450.00	со	Incomplete
Clinton Park	Helena Citizens Council District 1	1.2.4	Exterior Accessible Route	Correct curb ramp cross slope to max 2.08%	\$725.00	each	1	\$725.00	со	Incomplete
Clinton Park	Helena Citizens Council District 1	1.2.5	Exterior Accessible Route	Install compliant detectable warning at transitions from walkways to vehicular ways as a smart practice	\$235.00	each	2	\$470.00	со	Incomplete
Clinton Park	Helena Citizens Council District 1	1.2.6	Exterior Accessible Route	Repair, bevel, or ramp CIL along AR	\$68.75	each	2	\$137.50	со	Complete
Clinton Park	Helena Citizens Council District 1	1.2.7	Exterior Accessible Route	Correct or fill gaps along AR	\$68.75	each	3	\$206.25	со	Complete
Clinton Park	Helena Citizens Council District 1	1.2.8	Exterior Accessible Route	Correct or repair sidewalk cross slope along AR to max 2.08%	\$87.50	sq ft	25	\$2,187.50	со	Incomplete
Clinton Park	Helena Citizens Council District 1	1.2.9	Exterior Accessible Route	See 1.10 below for AR to park elements	\$0.00	n/a	0	\$0.00	со	Complete
Clinton Park	Helena Citizens Council District 1	1.3.1	Playground Entry	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to swings	\$48.00	lin ft	100	\$4,800.00	со	Complete
Clinton Park	Helena Citizens Council District 1	1.3.2	Playground Entry	Acquire and install intended user signage and mount at designated entry as a smart practice	\$150.00	each	1	\$150.00	СО	Complete
Clinton Park	Helena Citizens Council District 1	1.4.1	Playground Surface	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs	\$7,500.00	each	1	\$7,500.00	2	Complete
Clinton Park	Helena Citizens Council District 1	1.4.2	Playground Surface	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces	\$0.00	staff time	0	\$0.00	со	Complete
Clinton Park	Helena Citizens Council District 1	1.4.3	Playground Surface	Establish protocols for regular and frequent inspection and maintenance of accessible playground surface	\$0.00	staff time	0	\$0.00	со	Complete
Clinton Park	Helena Citizens Council District 1	1.8.1	GLPCs	See recommendation 1.4.1 for surface corrections	\$0.00	n/a	0	\$0.00	СО	Complete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of	Total cost	Phase	Notes
Clinton Park	Helena Citizens Council District 1	1.10.1	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the basketball court player seating and player surface	\$48.00	lin ft	50	\$2,400.00	СО	Complete
Clinton Park	Helena Citizens Council District 1	1.10.2	Park Site	Relocate 20% of garbage cans to be along AR	\$0.00	staff time	0	\$0.00	со	Complete
Clinton Park	Helena Citizens Council District 1	1.10.3	Park Site	Replace or add one <u>picnic table</u> with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table as a smart practice	\$800.00	each	1	\$800.00	со	Complete
Constitution Park	Helena Citizens Council District 3	1.2.1	Exterior Accessible Route	Repair, bevel, or ramp CIL along AR	\$68.75	each	1	\$68.75	СО	Complete
Constitution Park	Helena Citizens Council District 3	1.2.2	Exterior Accessible Route	Repair and reset pavers to eliminate CIL and gaps	\$20.00	sq ft	25	\$500.00	со	Complete
Constitution Park	Helena Citizens Council District 3	1.2.3	Exterior Accessible Route	Correct or fill gaps along AR	\$68.75	each	1	\$68.75	со	Complete
Constitution Park	Helena Citizens Council District 3	1.2.4	Exterior Accessible Route	Correct or repair sidewalk cross slope along AR to max 2.08%	\$87.50	sq ft	25	\$2,187.50	со	Staff to investigate technical feasibility
Constitution Park	Helena Citizens Council District 3	1.2.5	Exterior Accessible Route	Correct or repair sidewalk running slope along AR to max 5%	\$87.50	sq ft	25	\$2,187.50	со	Staff to investigate technical feasibility
Constitution Park	Helena Citizens Council District 3	1.10.1	Park Site	Provide ramped entrance to constitution shelter	\$41.25	inch	88	\$3,630.00	со	Complete
Constitution Park	Helena Citizens Council District 3	1.10.2	Park Site	Replace or add one <u>picnic table</u> with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table as a smart practice	\$800.00	each	1	\$800.00	со	Complete
Cunningham Park	Helena Citizens Council District 1	1.2.1	Exterior Accessible Route	Correct or repair sidewalk cross slope along AR to max 2.08%	\$87.50	sq ft	50	\$4,375.00	СО	Staff to investigate technical feasibility
Cunningham Park	Helena Citizens Council District 1	1.2.2	Exterior Accessible Route	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to site elements	\$48.00	lin ft	200	\$9,600.00	со	Staff to investigate technical feasibility
Cunningham Park	Helena Citizens Council District 1	1.3.1	Playground Entry	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to playground designated entry	\$48.00	lin ft	50	\$2,400.00	со	Complete
Cunningham Park	Helena Citizens Council District 1	1.3.2	Playground Entry	Acquire and install intended user signage and mount at designated entry as a smart practice	\$150.00	each	1	\$150.00	со	Complete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Cunningham Park	Helena Citizens Council District 1	1.4.1	Playground Surface	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs	\$7,500.00	each	1	\$7,500.00	2	Complete
Cunningham Park	Helena Citizens Council District 1	1.4.2	Playground Surface	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces	\$0.00	staff time	0	\$0.00	со	Complete
Cunningham Park	Helena Citizens Council District 1	1.4.3	Playground Surface	Establish protocols for regular and frequent inspection and maintenance of accessible playground surface	\$0.00	staff time	0	\$0.00	СО	Complete
Cunningham Park	Helena Citizens Council District 1	1.5.1	Transfer System	Install descending step on transfer system as a smart practice	\$750.00	each	1	\$750.00	со	Complete
Cunningham Park	Helena Citizens Council District 1	1.8.1	GLPCs	Add three type of GLPCs such as climbers, spinners or rockers, to meet incentive scoping	\$2,000.00	each	3	\$6,000.00	со	Complete
Cunningham Park	Helena Citizens Council District 1	1.10.1	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the basketball courts	\$48.00	lin ft	100	\$4,800.00	со	Complete
Cunningham Park	Helena Citizens Council District 1	1.10.2	Park Site	Relocate 20% of garbage cans to be along AR	\$0.00	staff time	0	\$0.00	СО	Complete
Cunningham Park	Helena Citizens Council District 1	1.11.1	Shelters	Remove at least 36" by 48" portion of benches for adjacent CFS as a smart practice	\$250.00	each	1	\$250.00	co	Complete
Cunningham Park	Helena Citizens Council District 1	1.11.2	Shelters	Replace 20% of the picnic tables with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around the table as a smart practice	\$800.00	each	1	\$800.00	со	Complete
Cunningham Park	Helena Citizens Council District 1	1.11.3	Shelters	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to shelter	\$48.00	lin ft	5	\$240.00	со	Complete
Cunningham Park	Helena Citizens Council District 1	1.11.4	Shelters	Correct or fill gap on shelter interior	\$68.75	each	1	\$68.75	со	Complete
Cunningham Park	Helena Citizens Council District 1	1.11.5	Shelters	Relocate tables to provide turning space in shelter	\$0.00	staff time	0	\$0.00	со	Complete
Donaldson Park	Helena Citizens Council District 7	1.1.1	Parking	Repair or correct slope of parking space and access aisle to max 2.08% in any direction	\$2,187.50	each	2	\$4,375.00	2	Complete
Donaldson Park	Helena Citizens Council District 7	1.1.2	Parking	Reconfigure accessible stalls to avoid requiring pedestrians to cross vehicular way, in the alternative, leave as is with striped crosswalk	\$262.50	each	1	\$262.50	2	Complete
Donaldson Park	Helena Citizens Council District 7	1.2.1	Exterior Accessible Route	Install compliant detectable warning at transitions from walkways to vehicular ways as a smart practice	\$235.00	each	1	\$235.00	2	Incomplete



							1			
			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Donaldson Park	Helena Citizens Council District 7	1.2.2	Exterior Accessible Route	Replace gravel and dirt trails with crushed and compacted stone or similar outdoor material	\$48.00	lin ft	50	\$2,400.00	2	Complete
Donaldson Park	Helena Citizens Council District 7	1.2.3	Exterior Accessible Route	See 1.10 below for AR to site elements	\$0.00	n/a	0	\$0.00	2	N/A
Donaldson Park	Helena Citizens Council District 7	1.10.1	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the first hole of disc golf	\$48.00	lin ft	100	\$4,800.00	2	Incomplete
Donaldson Park	Helena Citizens Council District 7	1.10.2	Park Site	See recommendations 1.2.2 for surface corrections to trail	\$0.00	n/a	0	\$0.00	2	N/A
Donaldson Park	Helena Citizens Council District 7	1.10.3	Park Site	Relocate 20% of garbage cans to be along AR	\$0.00	staff time	0	\$0.00	2	Complete
Donaldson Park	Helena Citizens Council District 7	1.10.4	Park Site	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, add at least one armrest and backrest and locate along an AR as a smart practice	\$115.00	each	2	\$230.00	2	Incomplete
Donaldson Park	Helena Citizens Council District 7	1.10.5	Park Site	Relocate accessible table on an AR with 36" AR around table as a smart practice	\$0.00	staff time	0	\$0.00	2	Complete
Donaldson Park	Helena Citizens Council District 7	1.12.1	Doors	For all doors along the public circulation route, <i>install</i> cement pad at exit that allows 18" clearance on the latch side, and extend a pathway away from the building for emergency egress	\$875.00	each	2	\$1,750.00	2	Employee-only access
Donaldson Park	Helena Citizens Council District 7	1.12.2	Doors	For all doors along the public circulation route, repair, bevel, or ramp CIL at door entries to max .25"	\$68.75	inch	8	\$550.00	2	Employee-only access
Donaldson Park	Helena Citizens Council District 7	1.12.3	Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	2	\$735.00	2	Employee-only access
Donaldson Park	Helena Citizens Council District 7	1.12.4	Doors	For all doors along the public circulation route, remount hardware to be 34" to 48" aff	\$250.00	each	1	\$250.00	2	Employee-only access
Donaldson Park	Helena Citizens Council District 7	1.12.5	Doors	For employee only spaces, make corrections upon renovation	\$0.00	n/a	0	\$0.00	2	Employee-only access
Donaldson Park	Helena Citizens Council District 7	1.12.1	Rooms	Resurface floor with a firm, stable, slip resistant material	\$16.00	sq ft	1188	\$19,008.00	2	Employee-only access
Donaldson Park	Helena Citizens Council District 7	1.12.2	Rooms	For all other deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	2	Employee-only access
Exploration Works	Citywide Facilities	1.2.1	Exterior Accessible Route	Lower operating mechanisms along AR to max 48" aff to highest operable part	\$0.00	staff time	0	\$0.00	1	N/A



			T		1	1				
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Exploration Works	Citywide Facilities	1.2.2	Exterior Accessible Route	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to site elements	\$48.00	lin ft	100	\$4,800.00	1	Incomplete
Exploration Works	Citywide Facilities	1.2.3	Exterior Accessible Route	Repair, bevel, or ramp CIL along AR	\$68.75	each	2	\$137.50	1	Incomplete
Exploration Works	Citywide Facilities	1.2.4	Exterior Accessible Route	Correct or repair sidewalk running slope along AR to max 5%	\$87.50	sq ft	25	\$2,187.50	1	Incomplete
Exploration Works	Citywide Facilities	1.2.5	Exterior Accessible Route	Replace signage along AR with compliant signage	\$150.00	each	2	\$300.00	1	Incomplete
Exploration Works	Citywide Facilities	1.2.1	Stairs - Exterior	Provide contrast on leading 2" of stair treads	\$20.00	each	14	\$280.00	1	Incomplete
Exploration Works	Citywide Facilities	1.2.2	Stairs - Exterior	Install detectable warning strip on top tread of each stairway as a smart practice	\$150.00	each	1	\$150.00	1	Incomplete
Exploration Works	Citywide Facilities	1.4.1	Exterior Doors	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	1	\$1,250.00	1	Incomplete
Exploration Works	Citywide Facilities	1.4.2	Exterior Doors	No maneuvering clearance at door due to stairs, <i>leave as is,</i> correction is technically infeasible	\$0.00	n/a	0	\$0.00	1	N/A
Exploration Works	Citywide Facilities	1.4.3	Exterior Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice	\$0.00	staff time	0	\$0.00	1	N/A
Exploration Works	Citywide Facilities	1.4.4	Exterior Doors	For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers	\$0.00	staff time	0	\$0.00	1	N/A
Exploration Works	Citywide Facilities	1.4.5	Exterior Doors	Upon renovation; make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	1	N/A
Exploration Works	Citywide Facilities	1.5.1	Elevator	Remove or relocate storage in elevator CFS	\$0.00	staff time	0	\$0.00	1	N/A
Exploration Works	Citywide Facilities	1.6.1	Interior Doors	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	14	\$17,500.00	1	Incomplete
Exploration Works	Citywide Facilities	1.6.2	Interior Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	2	\$735.00	1	Incomplete
Exploration Works	Citywide Facilities	1.6.3	Interior Doors	For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors	\$0.00	staff time	0	\$0.00	1	Incomplete
Exploration Works	Citywide Facilities	1.6.4	Interior Doors	Upon renovation ; make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	1	N/A



	1		I			1	1			
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Exploration Works	Citywide Facilities	1.7.1	Interior Accessible Route	Correct or fill gap long AR	\$100.00	each	2	\$200.00	1	Incomplete
Exploration Works	Citywide Facilities	1.7.2	Interior Accessible Route	Raise angled posts to min 80", or pad object to prevent hazard in overhead clearance	\$110.00	each	4	\$440.00	1	Incomplete
Exploration Works	Citywide Facilities	1.7.3	Interior Accessible Route	Replace drinking fountain with hi-lo bowl	\$3,998.75	each	1	\$3,998.75	1	Incomplete
Exploration Works	Citywide Facilities	1.7.4	Interior Accessible Route	Remove or relocate storage at drinking fountain to allow toe clearance	\$0.00	staff time	0	\$0.00	1	N/A
Exploration Works	Citywide Facilities	1.7.5	Interior Accessible Route	Remount drinking fountain to allow knee and toe clearance	\$250.00	each	1	\$250.00	1	Incomplete
Exploration Works	Citywide Facilities	1.7.1	Service Counter	Lower 36" wide segment of service counter to max 36" aff	\$785.00	each	1	\$785.00	1	Incomplete
Exploration Works	Citywide Facilities	1.7.1	Stairs - Interior	Correct riser heights on stairs to consistent height between 4" to 7", leave as is if technically infeasible	\$288.75	each	28	\$8,085.00	1	Incomplete
Exploration Works	Citywide Facilities	1.7.2	Stairs - Interior	Provide contrast on leading 2" of stair treads	\$20.00	each	28	\$560.00	1	Incomplete
Exploration Works	Citywide Facilities	1.7.3	Stairs - Interior	Install detectable warning strip on top tread of each stairway as a smart practice	\$150.00	each	2	\$300.00	1	Incomplete
Exploration Works	Citywide Facilities	1.7.4	Stairs - Interior	<i>Install</i> lowered handrail max 28" and 9" from top rail for children's use as a smart practice	\$700.00	each	2	\$1,400.00	1	Incomplete
Exploration Works	Citywide Facilities	1.8.1	Public Spaces	Relocate obstacles to create AR through robotics room	\$0.00	staff time	0	\$0.00	1	N/A
Exploration Works	Citywide Facilities	1.8.2	Public Spaces	Raise to min 80", or pad object to prevent hazard in overhead clearance to barn in little sky country	\$110.00	each	1	\$110.00	1	Incomplete
Exploration Works	Citywide Facilities	1.8.3	Public Spaces	Relocate protruding objects in gift shop and angled supports or place cane detectable warning or bollard at foot of cashier counter and angled supports	\$250.00	each	3	\$750.00	1	Incomplete
Exploration Works	Citywide Facilities	1.8.4	Public Spaces	Repair, bevel or ramp CIL in rooms indicated	\$68.75	each	1	\$68.75	1	Incomplete
Exploration Works	Citywide Facilities	1.8.5	Public Spaces	Correct or repair slope to max 5% running and 2.08% cross or provide a compliant ramp with handrails	\$87.50	sq ft	25	\$2,187.50	1	Incomplete
Exploration Works	Citywide Facilities	1.8.6	Public Spaces	Correct or fill gaps	\$100.00	each	4	\$400.00	1	Incomplete
Exploration Works	Citywide Facilities	1.8.7	Public Spaces	Remove, or relocate storage in CFS at fixtures and operable parts	\$0.00	staff time	0	\$0.00	1	N/A



			<u> </u>							
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Exploration Works	Citywide Facilities	1.8.8	Public Spaces	Lower operating mechanisms to max 48" aff to highest operable part; leave as is if employee only operated	\$250.00	each	1	\$250.00	1	Incomplete
Exploration Works	Citywide Facilities	1.8.9	Public Spaces	Lower sink heights to max 34" aff	\$1,700.00	each	2	\$3,400.00	1	Incomplete
Exploration Works	Citywide Facilities	1.9.1	Employee Spaces	Employee only area permit approach, entry, and exit, relocate obstacles to create AR through rooms indicated	\$0.00	staff time	0	\$0.00	1	N/A
Exploration Works	Citywide Facilities	1.9.2	Employee Spaces	Employee only areas permit approach, entry, and exit, relocate obstacles to create turning space of 60" in rooms indicated	\$0.00	staff time	0	\$0.00	1	N/A
Exploration Works	Citywide Facilities	1.9.3	Employee Spaces	For all other deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	1	N/A
Exploration Works	Citywide Facilities	1.11.1	Restrooms - Multiple Users - Basement	Acquire and mount signage for both, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character	\$150.00	each	2	\$300.00	1	Incomplete
Exploration Works	Citywide Facilities	1.11.2	Restrooms - Multiple Users - Basement	Lower hooks in both accessible stalls to max 48" aff	\$0.00	staff time	0	\$0.00	1	
Exploration Works	Citywide Facilities	1.11.3	Restrooms - Multiple Users - Basement	Widen accessible stalls to min. 60" clear width, 59" depth	\$1,963.75	each	2	\$3,927.50	1	Incomplete
Exploration Works	Citywide Facilities	1.11.4	Restrooms - Multiple Users - Basement	Remount rear grab bar to behind the toilet, 12" to one side of center and 24" to the other and 33" to 36" aff in both	\$281.25	each	2	\$562.50	1	Incomplete
Exploration Works	Citywide Facilities	1.11.5	Restrooms - Multiple Users - Basement	Adjust stall doors in both to be self-closing	\$0.00	staff time	0	\$0.00	1	N/A
Exploration Works	Citywide Facilities	1.11.6	Restrooms - Multiple Users - Basement	Acquire and install exterior stall hardware that is operable without a tight pinch or grasp in both	\$100.00	each	2	\$200.00	1	Incomplete
Exploration Works	Citywide Facilities	1.11.7	Restrooms - Multiple Users - Basement	Rehang stall doors in both to be max 4" from adjacent stall partition and on the stall wall farthest from the toilet	\$300.00	each	2	\$600.00	1	Incomplete



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Exploration Works	Citywide Facilities	1.11.8	Restrooms - Multiple Users - Basement	Replace women's interior stall hardware with hardware operable without a tight pinch or grasp	\$100.00	each	2	\$200.00	1	Incomplete
Exploration Works	Citywide Facilities	1.11.1	Restrooms - Single Users - Lime Green	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character	\$150.00	each	1	\$150.00	1	Incomplete
Exploration Works	Citywide Facilities	1.11.2	Restrooms - Single Users - Lime Green	Remount toilet to 16" to 18" from the side wall to centerline	\$1,306.00	each	1	\$1,306.00	1	Incomplete
Exploration Works	Citywide Facilities	1.11.3	Lime Green	Replace toilet seat, or re-set or replace toilet to 17" to 19" aff	\$1,306.00	each	1	\$1,306.00	1	Incomplete
Exploration Works	Citywide Facilities	1.11.4	Restrooms - Single Users - Lime Green	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	\$0.00	staff time	0	\$0.00	1	N/A
Exploration Works	Citywide Facilities	1.11.5	Restrooms - Single Users - Lime Green	Lower mirror so reflective surface is max 40" aff	\$0.00	staff time	0	\$0.00	1	N/A
Exploration Works	Citywide Facilities	1.11.6	Restrooms - Single Users - Lime Green	Relocate or recess towel dispenser to not interfere with general circulation path, protrusions can't be greater than 4"	\$250.00	each	1	\$250.00	1	Incomplete
Exploration Works	Citywide Facilities	1.11.7	Restrooms - Single Users - Lime Green	Remove or relocate storage to allow CFS at operable parts	\$0.00	staff time	0	\$0.00	1	N/A
Exploration Works	Citywide Facilities	1.11.1	Restrooms - Single Users - Turquoise	Relocate drinking fountain for CFS at sign	\$250.00	each	1	\$250.00	1	Incomplete
Exploration Works	Citywide Facilities	1.11.2	Restrooms - Single Users - Turquoise	Remount toilets to 16" to 18" from the side wall to centerline	\$1,306.00	each	1	\$1,306.00	1	Incomplete
Exploration Works	Citywide Facilities	1.11.3	Restrooms - Single Users - Turquoise	Replace toilet seat, or re-set or replace toilet to 17" to 19" aff	\$1,306.00	each	1	\$1,306.00	1	Incomplete
Exploration Works	Citywide Facilities	1.11.4	Restrooms - Single Users - Turquoise	Remount grab bars to 33" to 36" aff	\$281.25	each	2	\$562.50	1	Incomplete
Exploration Works	Citywide Facilities	1.11.5	Restrooms - Single Users - Turquoise	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	\$0.00	staff time	0	\$0.00	1	N/A
Exploration Works	Citywide Facilities	1.11.6	Restrooms - Single Users - Turquoise	Lower mirror so reflective surface is max 40" aff	\$0.00	staff time	0	\$0.00	1	N/A



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Exploration Works	Citywide Facilities	1.11.7	Restrooms - Single Users - Turquoise	Relocate or recess towel dispenser and lower to max 48" to not interfere with general circulation path, protrusions can't be greater than 4"	\$250.00	each	1	\$250.00	1	Incomplete
Exploration Works	Citywide Facilities	1.11.8	Restrooms - Single Users - Turquoise	Remove or relocate storage to allow CFS at operable parts	\$0.00	staff time	0	\$0.00	1	N/A
Exploration Works	Citywide Facilities	1.11.1	Restrooms - Single Users - Light Blue	Remount toilet to 16" to 18" from the side wall to centerline	\$1,306.00	each	1	\$1,306.00	1	Incomplete
Exploration Works	Citywide Facilities	1.11.2	Light Blue	Replace toilet seat, or re-set or replace toilet to 17" to 19" aff	\$1,306.00	each	1	\$1,306.00	1	Incomplete
Exploration Works	Citywide Facilities	1.11.3	Light Blue	Remount grab bars to 33" to 36" aff	\$281.25	each	2	\$562.50	1	Incomplete
Exploration Works	Citywide Facilities	1.11.4	Restrooms - Single Users - Light Blue	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	\$0.00	staff time	0	\$0.00	1	N/A
Exploration Works	Citywide Facilities	1.11.5	Restrooms - Single Users - Light Blue	Lower mirror so reflective surface is max 40" aff	\$0.00	staff time	0	\$0.00	1	N/A
Exploration Works	Citywide Facilities	1.11.6	Restrooms - Single Users - Light Blue	Relocate or recess towel dispenser to not interfere with general circulation path, protrusions can't be greater than 4"	\$250.00	each	1	\$250.00	1	Incomplete
Exploration Works	Citywide Facilities	1.11.7	Restrooms - Single Users - Light Blue	Remove or relocate storage to allow CFS at operable parts	\$0.00	staff time	0	\$0.00	1	N/A
Exploration Works	Citywide Facilities	1.11.1	Restrooms - Single Users - Unisex	Replace toilet seat, or re-set or replace toilet to 17" to 19" aff	\$1,306.00	each	1	\$1,306.00	1	Incomplete
Exploration Works	Citywide Facilities	1.11.2	Restrooms - Single Users - Unisex	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	\$0.00	staff time	0	\$0.00	1	N/A
Exploration Works	Citywide Facilities	1.11.3	Restrooms - Single Users - Unisex	Lower mirror so reflective surface is max 40" aff	\$0.00	staff time	0	\$0.00	1	N/A
Exploration Works	Citywide Facilities	1.11.4	Restrooms - Single Users - Unisex	Relocate or recess towel dispenser to not interfere with general circulation path, protrusions can't be greater than 4"	\$250.00	each	1	\$250.00	1	Incomplete
Exploration Works	Citywide Facilities	1.11.5	Restrooms - Single Users - Unisex	Remove or relocate storage to allow CFS at sink	\$0.00	staff time	0	\$0.00	1	N/A



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Exploration Works	Citywide Facilities	1.15.1	Interior Signage	Create template for signs that addresses height of sign, size of characters, location of Braille, and other requirements	\$0.00	staff time	0	\$0.00	1	N/A
Exploration Works	Citywide Facilities	1.15.2	Interior Signage	Implement a sign revision program throughout the building, discriminating between directional signs and signs for permanent spaces	\$0.00	staff time	0	\$0.00	1	N/A
Exploration Works	Citywide Facilities	1.15.3	Interior Signage	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door	\$150.00	each	8	\$1,200.00	1	Incomplete
Exploration Works	Citywide Facilities	1.16.1	Exhibit Spaces	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to music path and garden	\$48.00	lin ft	200	\$9,600.00	1	Incomplete
Exploration Works	Citywide Facilities	1.16.2	Exhibit Spaces	Provide a ramp for access to hurricane	\$155.00	inch	14	\$2,170.00	1	Incomplete
Exploration Works	Citywide Facilities	1.16.3	Exhibit Spaces	Correct or fill gaps	\$100.00	each	1	\$100.00	1	Incomplete
Exploration Works	Citywide Facilities	1.16.4	Exhibit Spaces	Remove, or relocate storage in CFS at fixtures and operable parts or provide ramp for access	\$0.00	staff time	0	\$0.00	1	N/A
Exploration Works	Citywide Facilities	1.16.5	Exhibit Spaces	Replace one table at shape your language and microscope word exhibits with one min 36" wide and allowing knee and toe clearance, max surface at 34"	\$800.00	each	2	\$1,600.00	1	Incomplete
Exploration Works	Citywide Facilities	1.16.6	Exhibit Spaces	Lower or raise operating mechanisms to min 15" or max 48" aff to highest operable part	\$250.00	each	4	\$1,000.00	1	Incomplete
Exploration Works	Citywide Facilities	1.16.7	Exhibit Spaces	Replace operable parts with ones not requiring a tight pinch or grasp to operate	\$100.00	each	20	\$2,000.00	1	Incomplete
Exploration Works	Citywide Facilities	1.16.8	Exhibit Spaces	Relocate protruding objects in water works or place cane detectable warning or bollard at foot of coat hooks	\$250.00	each	1	\$250.00	1	Incomplete
Fire Tower Park	Helena Citizens Council District 1	1.1.1	Parking	Create one or more 8' accessible parking stalls based on lot capacity, with one 5' adjacent access aisle, with proper signage and striping	\$1,135.00	each	1	\$1,135.00	со	Incomplete need to work with adjacent property owner
Fire Tower Park	Helena Citizens Council District 1	1.2.1	Exterior Accessible Route	Install compliant detectable warning at transitions from walkways to vehicular ways as a smart practice	\$235.00	each	1	\$235.00	СО	Incomplete need to work with adjacent property owner



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Fire Tower Park	Helena Citizens Council District 1	1.2.2	Exterior Accessible Route	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to tower; consider an agreement with adjacent apartment complex for access	\$48.00	lin ft	200	\$9,600.00	СО	Incomplete need to work with adjacent property owner
Fire Tower Park	Helena Citizens Council District 1	1.2.3	Exterior Accessible Route	Replace trail surface with crushed and compacted stone or similar outdoor material	\$48.00	lin ft	200	\$9,600.00	СО	Incomplete need to work with adjacent property owner
Fire Tower Park	Helena Citizens Council District 1	1.10.1	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the <u>fire tower</u>	\$48.00	lin ft	200	\$9,600.00	СО	Incomplete need to work with adjacent property owner
Fire Tower Park	Helena Citizens Council District 1	1.10.2	Park Site	Leave as is, stair access, not feasible to correct; consider a video presentation of the tower	\$0.00	n/a	0	\$0.00	СО	N/A
Fire Tower Park	Helena Citizens Council District 1	1.10.3	Park Site	Relocate 20% of garbage cans to be along AR	\$0.00	staff time	0	\$0.00	СО	Complete
Fire Tower Park	Helena Citizens Council District 1	1.10.4	Park Site	Replace or add one picnic table with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table as a smart practice	\$800.00	each	1	\$800.00	СО	Incomplete
HATS Facility	Citywide Facilities	1.1.1	Parking	Repaint stalls and access aisles to be 8' and 5' each	\$52.50	each	1	\$52.50	1	Staff to investigate completion status
HATS Facility	Citywide Facilities	1.1.2	Parking	Repair or correct slope of parking spaces and access aisles to max 2.08% in any direction	\$2,187.50	each	2	\$4,375.00	1	Staff to investigate completion status
HATS Facility	Citywide Facilities	1.2.1	Exterior Accessible Route	Create lined cross walk where pedestrian pathway crosses through vehicular traffic as a smart practice	\$262.50	each	1	\$262.50	1	Staff to investigate completion status
HATS Facility	Citywide Facilities	1.2.2	Exterior Accessible Route	Reinstall detectable warning at curb ramps and transitions from walkways to vehicular ways as a smart practice	\$235.00	each	1	\$235.00	1	Staff to investigate completion status
HATS Facility	Citywide Facilities	1.2.3	Exterior Accessible Route	Repair, bevel, or ramp CIL along AR	\$68.75	each	1	\$68.75	1	Staff to investigate completion status
HATS Facility	Citywide Facilities	1.4.1	Exterior Doors	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$0.00	staff time	1	\$0.00	1	On-going
HATS Facility	Citywide Facilities	1.4.2	Exterior Doors	For all doors along the public circulation route, correct or repair slope at doorway landing to max 2.08% in any direction for level CFS	\$2,187.50	each	2	\$4,375.00	1	N/A technically infeasible
HATS Facility	Citywide Facilities	1.4.3	Exterior Doors	For all doors along the public circulation route, repair, bevel, or ramp CIL at door entries to max .25"	\$68.75	each	4	\$275.00	1	N/A technically infeasible
HATS Facility	Citywide Facilities	1.4.4	Exterior Doors	For all doors along the public circulation route, <i>inspect, adjust, and maintain</i> 8.5 lbf to open exterior doors as a smart practice	\$0.00	staff time	0	\$0.00	1	On-going



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
HATS Facility	Citywide Facilities	1.4.5	Exterior Doors	For all doors along the public circulation route, <i>inspect, adjust, and maintain</i> closing speed on door closers	\$0.00	staff time	0	\$0.00	1	On-going
HATS Facility	Citywide Facilities	1.4.6	Exterior Doors	Upon renovation ; make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	1	N/A
HATS Facility	Citywide Facilities	1.6.1	Interior Doors	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	5	\$6,250.00	1	N/A technically infeasible
HATS Facility	Citywide Facilities	1.6.2	Interior Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	2	\$735.00	1	Incomplete
HATS Facility	Citywide Facilities	1.6.3	Interior Doors	For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors	\$0.00	staff time	0	\$0.00	1	On-going
HATS Facility	Citywide Facilities	1.6.4	Interior Doors	For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers	\$0.00	staff time	0	\$0.00	1	On-going
HATS Facility	Citywide Facilities	1.6.5	Interior Doors	Upon renovation; make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	1	N/A
HATS Facility	Citywide Facilities	1.7.1	Interior Accessible Route	Designate 5% or no less than 1 locker as accessible, mounting signage having the access symbol and hooks and operating mechanisms max 48" aff	\$50.00	each	1	\$50.00	1	Incomplete
HATS Facility	Citywide Facilities	1.7.2	Interior Accessible Route	Replace locker hardware with ADA compliant hardware on designated lockers	\$100.00	each	1	\$100.00	1	Incomplete
HATS Facility	Citywide Facilities	1.8.1	Public Spaces	Lower operating mechanisms to max 48" aff to highest operable part; leave as is if employee only operated	\$250.00	each	3	\$750.00	1	Employee-only operated
HATS Facility	Citywide Facilities	1.9.1	Employee Spaces	Employee only area permit approach, entry, and exit, relocate obstacles to create AR through mechanical and bus storage	\$0.00	staff time	0	\$0.00	1	On-going
HATS Facility	Citywide Facilities	1.9.2	Employee Spaces	Employee only areas permit approach, entry, and exit, relocate obstacles to create turning space of 60" in mechanical	\$0.00	staff time	0	\$0.00	1	On-going
HATS Facility	Citywide Facilities	1.9.3	Employee Spaces	For all other deficits, <i>leave as is</i> , employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	1	N/A
HATS Facility	Citywide Facilities	1.11.1	Restrooms - Multiple Users	Lower hooks in both accessible stalls to max 48" aff	\$0.00	staff time	0	\$0.00	1	Incomplete
HATS Facility	Citywide Facilities	1.11.2	Restrooms - Multiple Users	Acquire and install exterior stall hardware operable without a tight pinch or grasp in both	\$100.00	each	2	\$200.00	1	Incomplete



		I	l			1	1			
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
HATS Facility	Citywide Facilities	1.11.3	Restrooms - Multiple Users	Relocate or recess towel dispensers in both and tampon dispenser in women's to not interfere with general circulation path, protrusions can't be greater than 4"	\$250.00	each	3	\$750.00	1	Incomplete
HATS Facility	Citywide Facilities	1.11.4	Restrooms - Multiple Users	Remount toilet in women's to 16" to 18" from the side wall to centerline	\$1,306.00	each	1	\$1,306.00	1	N/A technically infeasible
HATS Facility	Citywide Facilities	1.11.1	Restrooms - Single Users - Office	Relocate sink to allow CFS	\$1,700.00	each	1	\$1,700.00	1	Employee-only access
HATS Facility	Citywide Facilities	1.11.2	Restrooms - Single Users - Office	Lower soap dispensers to max 44" aff for a forward reach over counter	\$0.00	staff time	0	\$0.00	1	Employee-only access
HATS Facility	Citywide Facilities	1.11.3	Restrooms - Single Users - Office	Remove or relocate garbage can to allow turning space	\$0.00	staff time	0	\$0.00	1	On-going
HATS Facility	Citywide Facilities	1.11.4	Restrooms - Single Users - Office	Relocate or recess tampon dispenser to not interfere with general circulation path, protrusions can't be greater than 4"	\$0.00	each	1	\$0.00	1	Employee-only access
HATS Facility	Citywide Facilities	1.11.1	Restrooms - Single Users - Bus Garage	Lower hook to max 48" aff	\$0.00	staff time	0	\$0.00	1	Incomplete
HATS Facility	Citywide Facilities	1.11.2	Restrooms - Single Users - Bus Garage	Remove or relocate garbage can to allow CFS at toilet	\$0.00	staff time	0	\$0.00	1	On-going
Heritage-Pioneer <u>Park</u>	Helena Citizens Council District 1	1.2.1	Exterior Accessible Route	Repair, bevel, or ramp CIL along AR	\$68.75	each	2	\$137.50	2	Incomplete will be addressed during reconstruction
Heritage-Pioneer Park	Helena Citizens Council District 1	1.2.2	Exterior Accessible Route	Correct or fill gaps along AR	\$68.75	each	3	\$206.25	2	Incomplete will be addressed during reconstruction
Heritage-Pioneer Park	Helena Citizens Council District 1	1.2.3	Exterior Accessible Route	Correct or repair sidewalk cross slope along AR to max 2.08%	\$87.50	sq ft	75	\$6,562.50	2	Incomplete will be addressed during reconstruction
Heritage-Pioneer Park	Helena Citizens Council District 1	1.2.4	Exterior Accessible Route	Correct or repair sidewalk running slope along AR to max 5%	\$87.50	sq ft	100	\$8,750.00	2	Incomplete will be addressed during reconstruction
Heritage-Pioneer Park	Helena Citizens Council District 1	1.2.5	Exterior Accessible Route	Leave as is basketball hoop	\$0.00	n/a	0	\$0.00	2	N/A
Heritage-Pioneer Park	Helena Citizens Council District 1	1.2.6	Exterior Accessible Route	See 1.10 below for AR to site elements	\$0.00	n/a	0	\$0.00	2	N/A



		l				1				
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
	Helena Citizens	Cite		Recommendation	Frice/ unit	type	uiiits	Total cost	Filase	Notes
Heritage-Pioneer Park	Council District 1	1.3.1	Playground Entry	Repair, bevel or ramp CIL at playground entry	\$68.75	inch	2	\$137.50	CO	Complete
Heritage-Pioneer	Helena Citizens		Playground	Correct or repair running slope of designated						
Park	Council District 1	1.3.2	Entry	entry to max 5%	\$87.50	sq ft	25	\$2,187.50	CO	Complete
Heritage-Pioneer Park	Helena Citizens Council District 1	1.3.3	Playground Entry	Acquire and install intended user signage and mount at designated entry as a smart practice	\$150.00	each	1	\$150.00	со	Complete
Heritage-Pioneer Park	Helena Citizens Council District 1	1.4.1	Playground Surface	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs	\$7,500.00	each	1	\$7,500.00	2	Complete
Heritage-Pioneer Park	Helena Citizens Council District 1	1.4.2	Playground Surface	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces	\$0.00	staff time	0	\$0.00	СО	Complete
Heritage-Pioneer Park	Helena Citizens Council District 1	1.4.3	Playground Surface	Establish protocols for regular and frequent inspection and maintenance of accessible playground surface	\$0.00	staff time	0	\$0.00	СО	Complete
Heritage-Pioneer Park	Helena Citizens Council District 1	1.5.1	Transfer System	Consider adding second transfer system as a smart practice	\$3,550.00	each	1	\$3,550.00	СО	Complete
Heritage-Pioneer Park	Helena Citizens Council District 1	1.8.1	GLPCs	See recommendation 1.4.1 for surface corrections	\$0.00	n/a	0	\$0.00	СО	N/A
Heritage-Pioneer Park	Helena Citizens Council District 1	1.8.2	GLPCs	Add one more manipulable GLPC to meet one of each type compliant	\$2,000.00	each	1	\$2,000.00	СО	Complete
Heritage-Pioneer Park	Helena Citizens Council District 1	1.8.3	GLPCs	Lower entry point for one bucket swing to 11" to 24" aff	\$0.00	staff time	0	\$0.00	СО	Complete
Heritage-Pioneer Park	Helena Citizens Council District 1	1.10.1	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the <u>flagpole memorial</u>	\$48.00	lin ft	100	\$4,800.00	2	Incomplete
Heritage-Pioneer Park	Helena Citizens Council District 1	1.10.2	Park Site	Replace <u>drinking fountain</u> with a hi-lo bowl fountain	\$3,998.75	each	1	\$3,998.75	2	Drinking fountain has been removed
Heritage-Pioneer Park	Helena Citizens Council District 1	1.10.3	Park Site	Relocate 20% of garbage cans to be along AR	\$0.00	staff time	0	\$0.00	2	Complete
Heritage-Pioneer Park	Helena Citizens Council District 1	1.10.4	Park Site	Acquire and install at least one armrest to 20% of existing benches as a smart practice	\$70.00	each	2	\$140.00	2	Complete
Heritage-Pioneer Park	Helena Citizens Council District 1	1.10.5	Park Site	Replace 20% of the picnic tables with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around the table as a smart practice	\$800.00	each	2	\$1,600.00	2	Complete
Hill Park	Helena Citizens Council District 3	1.2.1	Exterior Accessible Route	Create a curb ramp to be max running slope 8.33%, max cross slope 2.08%, having a top landing as wide as the ramp and 36" deep and side flares with a max slope 10%	\$1,062.50	each	1	\$1,062.50	со	Complete
Hill Park	Helena Citizens Council District 3	1.2.2	Exterior Accessible Route	Create a level landing at the top of the curb ramp, 36" deep and as wide as ramp	\$87.50	sq ft	16	\$1,400.00	СО	Complete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Hill Park	Helena Citizens Council District 3	1.2.3	Exterior Accessible Route	Correct slope of curb ramp side flares to max 10%	\$725.00	each	2	\$1,450.00	со	Complete
Hill Park	Helena Citizens Council District 3	1.2.4	Exterior Accessible Route	Correct curb ramp slope to max 8.33%	\$725.00	each	1	\$725.00	со	Complete
Hill Park	Helena Citizens Council District 3	1.2.5	Exterior Accessible Route	Install compliant detectable warning at curb ramps as a smart practice	\$235.00	each	2	\$470.00	со	Complete
Hill Park	Helena Citizens Council District 3	1.2.6	Exterior Accessible Route	Repair, bevel, or ramp CIL along AR	\$68.75	each	6	\$412.50	со	Complete
Hill Park	Helena Citizens Council District 3	1.2.7	Exterior Accessible Route	Correct or fill gaps along AR	\$68.75	each	1	\$68.75	СО	Complete
Hill Park	Helena Citizens Council District 3	1.2.8	Exterior Accessible Route	Correct or repair sidewalk cross slope along AR to max 2.08%	\$87.50	sq ft	125	\$10,937.50	СО	Incomplete
Hill Park	Helena Citizens Council District 3	1.2.9	Exterior Accessible Route	Correct or repair sidewalk running slope along AR to max 5%	\$87.50	sq ft	75	\$6,562.50	СО	Incomplete
Hill Park	Helena Citizens Council District 3	1.2.10	Exterior Accessible Route	See 1.10 below for AR to site elements	\$0.00	staff time	0	\$0.00	со	N/A
Hill Park	Helena Citizens Council District 3	1.10.1	Park Site	Replace <u>drinking fountain</u> with a hi-lo bowl fountain	\$3,998.75	each	2	\$7,997.50	со	Complete
Hill Park	Helena Citizens Council District 3	1.10.2	Park Site	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to bench and add at least one armrest and locate along an AR as a smart practice	\$115.00	each	1	\$115.00	СО	Complete
Hill Park	Helena Citizens Council District 3	1.10.3	Park Site	Replace one <u>picnic table</u> with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table as a smart practice	\$800.00	each	1	\$800.00	со	Complete
<u>Janet Park</u>	Helena Citizens Council District 7	1.2.1	Exterior Accessible Route	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the site elements	\$48.00	lin ft	50	\$2,400.00	3	Complete
Janet Park	Helena Citizens Council District 7	1.10.1	Park Site	Replace trail surface with crushed and compacted stone or similar outdoor material	\$48.00	lin ft	500	\$24,000.00	2	Complete
Janet Park	Helena Citizens Council District 7	1.10.2	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the gardens	\$48.00	lin ft	50	\$2,400.00	2	Complete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Janet Park	Helena Citizens Council District 7	1.10.3	Park Site	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches and add at least one armrest and locate along an AR as a smart practice	\$115.00	each	1	\$115.00	2	Complete
Janet Park	Helena Citizens Council District 7	1.10.4	Park Site	Replace or add one <u>picnic table</u> with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table as a smart practice	\$800.00	each	1	\$800.00	2	Complete
Jaycee Park	Helena Citizens Council District 4	1.2.1	Exterior Accessible Route	Correct slope of curb ramp side flares to max 10%	\$725.00	each	1	\$725.00	со	Incomplete
Jaycee Park	Helena Citizens Council District 4	1.2.2	Exterior Accessible Route	Install compliant detectable warning at transitions from walkways to vehicular ways as a smart practice	\$235.00	each	1	\$235.00	СО	Incomplete
Jaycee Park	Helena Citizens Council District 4	1.2.3	Exterior Accessible Route	Correct or repair sidewalk cross slope along AR to max 2.08%	\$87.50	sq ft	25	\$2,187.50	СО	Incomplete
Jaycee Park	Helena Citizens Council District 4	1.2.4	Exterior Accessible Route	Correct or repair sidewalk running slope along AR to max 5%	\$87.50	sq ft	25	\$2,187.50	СО	Incomplete
Jaycee Park	Helena Citizens Council District 4	1.2.5	Exterior Accessible Route	See 1.10 below for AR to site elements	\$0.00	n/a	0	\$0.00	СО	N/A
Jaycee Park	Helena Citizens Council District 4	1.4.1	Playground Surface	Fill and compact EWF surface so that it maintains its accessibility characteristics	\$0.00	each	1	\$0.00	2	Complete
Jaycee Park	Helena Citizens Council District 4	1.4.2	Playground Surface	Establish protocols for regular and frequent inspection and maintenance of accessible playground surface	\$0.00	staff time	0	\$0.00	со	On-going
Jaycee Park	Helena Citizens Council District 4	1.8.1	GLPCs	Lower entry point for one swing to 11" to 24" aff	\$0.00	staff time	0	\$0.00	СО	Complete
Jaycee Park	Helena Citizens Council District 4	1.10.1	Park Site	Relocate 20% of garbage cans to be along AR	\$0.00	staff time	0	\$0.00	СО	Complete
Jaycee Park	Helena Citizens Council District 4	1.10.2	Park Site	Replace one picnic table with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table as a smart practice	\$800.00	each	1	\$800.00	со	Complete
Kay McKenna Park	Helena Citizens Council District 3	1.2.1	Exterior Accessible Route	Create a level landing at the top of the curb ramp, 36" deep and as wide as ramp	\$625.00	each	1	\$625.00	2	To be completed in FY23
Kay McKenna Park	Helena Citizens Council District 3	1.2.2	Exterior Accessible Route	Correct slope of curb ramp side flares to max 10%	\$725.00	each	3	\$2,175.00	2	To be completed in FY23
Kay McKenna Park	Helena Citizens Council District 3	1.2.3	Exterior Accessible Route	Correct curb ramp slope to max 8.33%	\$725.00	each	1	\$725.00	2	To be completed in FY23



						1				
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Kay McKenna Park	Helena Citizens Council District 3	1.2.4	Exterior Accessible Route	Correct curb ramp cross slope to max 2.08%	\$725.00	each	2	\$1,450.00	2	To be completed in FY23
Kay McKenna Park	Helena Citizens Council District 3	1.2.5	Exterior Accessible Route	Install compliant detectable warning at curb ramps as a smart practice	\$235.00	each	3	\$705.00	2	To be completed in FY23
Kay McKenna Park	Helena Citizens Council District 3	1.2.6	Exterior Accessible Route	Repair, bevel, or ramp CIL along AR	\$68.75	each	2	\$137.50	2	To be completed in FY23
Kay McKenna Park	Helena Citizens Council District 3	1.2.7	Exterior Accessible Route	Correct or repair sidewalk cross slope along AR to max 2.08%	\$87.50	sq ft	25	\$2,187.50	2	To be completed in FY23
Kay McKenna Park	Helena Citizens Council District 3	1.2.8	Exterior Accessible Route	Correct or repair sidewalk running slope along AR to max 5%	\$87.50	sq ft	25	\$2,187.50	2	To be completed in FY23
Kay McKenna Park	Helena Citizens Council District 3	1.2.9	Exterior Accessible Route	See 1.10 below for AR to site elements	\$0.00	n/a	0	\$0.00	2	N/A
Kay McKenna Park	Helena Citizens Council District 3	1.3.1	Playground Entry	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to playground designated entry	\$48.00	lin ft	25	\$1,200.00	СО	Complete
Kay McKenna Park	Helena Citizens Council District 3	1.3.2	Playground Entry	Create designated entry by removing 60" portion of play area boundary as a smart practice	\$500.00	each	1	\$500.00	СО	Complete
Kay McKenna Park	Helena Citizens Council District 3	1.4.1	Playground Surface	Repair or correct slope of play area accessible surface to max 5% running and 2.08% cross	\$0.00	staff time	0	\$0.00	СО	Complete
Kay McKenna Park	Helena Citizens Council District 3	1.4.2	Playground Surface	Fill and compact EWF surface so that it maintains its accessibility characteristics	\$5,000.00	each	1	\$5,000.00	2	Complete
Kay McKenna Park	Helena Citizens Council District 3	1.4.3	Playground Surface	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces	\$0.00	staff time	0	\$0.00	со	Complete
Kay McKenna Park	Helena Citizens Council District 3	1.4.4	Playground Surface	Establish protocols for regular and frequent inspection and maintenance of accessible playground surface	\$0.00	staff time	0	\$0.00	СО	Complete
Kay McKenna Park	Helena Citizens Council District 3	1.8.1	GLPCs	Add one more type of GLPCs such as climbers, spinners or rockers, to meet incentive scoping	\$2,000.00	each	1	\$2,000.00	СО	Complete
Kay McKenna Park	Helena Citizens Council District 3	1.10.1	Park Site	Mount directional signage at tennis stair entry and designate other entrance as accessible	\$150.00	each	1	\$150.00	2	Incomplete will be addressed during reconstruction
Kay McKenna Park	Helena Citizens Council District 3	1.10.2	Park Site	Correct or repair slope in tennis gate landing to max 2.08% in any direction for level CFS	\$87.50	sq ft	25	\$2,187.50	2	Incomplete will be addressed during reconstruction



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Kay McKenna Park	Helena Citizens Council District 3	1.10.3	Park Site	Repair, bevel, or ramp CIL at tennis	\$68.75	each	1	\$68.75	2	Incomplete will be addressed during reconstruction
Kay McKenna Park	Helena Citizens Council District 3	1.10.4	Park Site	Resurface area at tennis benches to eliminate depressions, gaps, and cracks	\$80.00	sq ft	25	\$2,000.00	2	Incomplete will be addressed during reconstruction
Kay McKenna Park	Helena Citizens Council District 3	1.10.5	Park Site	Relocate 20% of garbage cans to be along AR	\$0.00	staff time	0	\$0.00	2	Complete
Kay McKenna Park	Helena Citizens Council District 3	1.10.6	Park Site	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches and add at least one armrest and locate along an AR as a smart practice	\$115.00	each	1	\$115.00	2	To be completed in FY23
Kay McKenna Park	Helena Citizens Council District 3	1.10.7	Park Site	Locate accessible picnic table along AR with a 36" AR around table as a smart practice	\$0.00	staff time	0	\$0.00	2	Incomplete
Kay McKenna Park	Helena Citizens Council District 3	1.12.1	Doors	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	1	\$1,250.00	3	Incomplete
Kay McKenna Park	Helena Citizens Council District 3	1.12.1	Rooms	Room too small for access, <i>leave as is</i>	\$0.00	n/a	0	\$0.00	3	N/A
Kay McKenna Park	Helena Citizens Council District 3	1.12.1	Restrooms	Acquire and mount signage for both, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character	\$150.00	each	2	\$300.00	3	Complete
Kay McKenna Park	Helena Citizens Council District 3	1.12.2	Restrooms	Lower mirrors in both so reflective surface is max 40" aff	\$0.00	staff time	0	\$0.00	3	Complete
Kay McKenna Park	Helena Citizens Council District 3	1.12.3	Restrooms	Insulate exposed pipes under one sink in both	\$55.00	each	2	\$110.00	3	Complete
Kay McKenna Park	Helena Citizens Council District 3	1.12.4	Restrooms	Remount toilets in both to 16" to 18" from the side wall to centerline	\$1,306.00	each	2	\$2,612.00	3	To be completed in FY23
Kay McKenna Park	Helena Citizens Council District 3	1.12.5	Restrooms	Remount side grab bars in both to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff	\$281.25	each	2	\$562.50	3	To be completed in FY23
Kay McKenna Park	Helena Citizens Council District 3	1.12.6	Restrooms	Remount rear grab bar to behind the toilet, 12" to one side of center and 24" to the other and 33" to 36" aff in both	\$281.25	each	2	\$562.50	3	To be completed in FY23
Kay McKenna Park	Helena Citizens Council District 3	1.12.7	Restrooms	Acquire and mount vertical grab bars for both, 18" min in length and mounted so that the bottom is between 39" and 41" from the floor and the centerline between 39" and 41" from rear wall	\$281.25	each	2	\$562.50	3	To be completed in FY23
Kay McKenna Park	Helena Citizens Council District 3	1.12.8	Restrooms	Adjust stall door to be self-closing	\$0.00	staff time	0	\$0.00	3	Complete
Kay McKenna Park	Helena Citizens Council District 3	1.12.9	Restrooms	Acquire and mount exterior stall hardware operable without a tight pinch or grasp in both	\$100.00	each	2	\$200.00	3	Complete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Kay McKenna Park	Helena Citizens Council District 3	1.12.10	Restrooms	Relocate or recess hand dryers in both to not interfere with general circulation path, protrusions can't be greater than 4"	\$250.00	each	2	\$500.00	3	Complete
Kay McKenna Park	Helena Citizens Council District 3	1.12.11	Restrooms	Adjust timing of sink faucets in men's to remain on for min 10 seconds	\$0.00	staff time	0	\$0.00	3	Complete
Kay McKenna Park	Helena Citizens Council District 3	1.12.12	Restrooms	Remount toilet paper dispenser in men's max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	\$0.00	staff time	0	\$0.00	3	Complete
Kay McKenna Park	Helena Citizens Council District 3	1.12.13	Restrooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" aff in women's	\$1,306.00	each	1	\$1,306.00	3	Complete
Kindrick-Legion Field	Helena Citizens Council District 5	1.1.1	Parking	Repaint stalls and access aisles to be 8' and 5' each	\$52.50	each	3	\$157.50	2	Incomplete
Kindrick-Legion Field	Helena Citizens Council District 5	1.1.2	Parking	Repair or correct slope of parking spaces and access aisles to max 2.08% in any direction	\$2,187.50	each	6	\$13,125.00	2	Incomplete
Kindrick-Legion Field	Helena Citizens Council District 5	1.1.3	Parking	Relocate first stall to be away from the electrical box	\$262.50	each	1	\$262.50	2	Incomplete
Kindrick-Legion Field	Helena Citizens Council District 5	1.2.1	Exterior Accessible Route	Repair, bevel, or ramp CIL along AR	\$68.75	each	1	\$68.75	2	Complete
Kindrick-Legion Field	Helena Citizens Council District 5	1.2.2	Exterior Accessible Route	Correct or fill gaps along AR	\$137.50	each	1	\$137.50	2	Complete
Kindrick-Legion Field	Helena Citizens Council District 5	1.2.3	Exterior Accessible Route	Correct or repair cross slope along AR to max 2.08%	\$87.50	sq ft	75	\$6,562.50	2	Complete
Kindrick-Legion Field	Helena Citizens Council District 5	1.2.4	Exterior Accessible Route	Correct or repair running slope along AR to max 5%	\$87.50	sq ft	50	\$4,375.00	2	Complete
Kindrick-Legion Field	Helena Citizens Council District 5	1.2.5	Stairs - Exterior	Provide contrast on leading 2" of each stair tread	\$20.00	each	8	\$160.00	2	To be completed in FY22
Kindrick-Legion Field	Helena Citizens Council District 5	1.2.6	Stairs - Exterior	Install detectable warning strip on top tread of each stairway as a smart	\$150.00	each	1	\$150.00	2	To be completed in FY22
Kindrick-Legion Field	Helena Citizens Council District 5	1.2.7	Stairs - Exterior	Install handrails on both sides of stairway, mounted 34" to 38" aff with top and bottom extensions	\$700.00	each	1	\$700.00	2	Complete
Kindrick-Legion Field	Helena Citizens Council District 5	1.2.1	Ramps - Exterior	Repair or bevel CIL along main seating ramp	\$68.75	each	1	\$68.75	2	To be completed in FY23
Kindrick-Legion Field	Helena Citizens Council District 5	1.2.2	Ramps - Exterior	Correct slope of main seating, side ramp, SE bleacher ramps and ramp near entry to max 8.33%	\$87.50	sq ft	270	\$23,625.00	2	To be completed in FY23
Kindrick-Legion Field	Helena Citizens Council District 5	1.2.3	Ramps - Exterior	Correct or repair cross slope of main seating, SE side bleachers, and near entry ramps to max 2.08%	\$87.50	sq ft	270	\$23,625.00	2	To be completed in FY23



			Tymo of			unit	# of			
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# or units	Total cost	Phase	Notes
Kindrick-Legion Field	Helena Citizens Council District 5	1.2.4	Ramps - Exterior	Replace or install handrails on both sides of ramps with ones that are rounded and/or extend to the ground, with handrail extensions and mounted 34" to 38" aff	\$700.00	each	6	\$4,200.00	2	To be completed in FY23
Kindrick-Legion Field	Helena Citizens Council District 5	1.2.5	Ramps - Exterior	Enlarge landing on ramps indicated where directions change to 60" by 60"	\$625.00	each	2	\$1,250.00	2	To be completed in FY23
Kindrick-Legion Field	Helena Citizens Council District 5	1.2.6	Ramps - Exterior	Install rail along bottom edge of ramp that prevents a 4" sphere from passing through at ramp to concession on 1st base line	\$350.00	each	1	\$350.00	2	To be completed in FY23
Kindrick-Legion Field	Helena Citizens Council District 5	1.3.1	Exterior Signage	Mount signage at entrance designating it as accessible	\$150.00	each	1	\$150.00	2	Incomplete
Kindrick-Legion Field	Helena Citizens Council District 5	1.4.1	Exterior Doors	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of door	\$1,250.00	each	19	\$23,750.00	2	Complete
Kindrick-Legion Field	Helena Citizens Council District 5	1.4.2	Exterior Doors	For all doors along the public circulation route, correct or repair slope at doorway landing to max 2.08% in any direction for level CFS	\$2,187.50	each	5	\$10,937.50	2	Complete
Kindrick-Legion Field	Helena Citizens Council District 5	1.4.3	Exterior Doors	For all doors along the public circulation route, replace doors with ones having 80" overhead and 32" clear width	\$1,980.00	each	8	\$15,840.00	2	Complete
Kindrick-Legion Field	Helena Citizens Council District 5	1.4.4	Exterior Doors	For all doors along the public circulation route, <i>repair, bevel, or ramp CIL</i> at door entries to max .25"	\$68.75	inch	84	\$5,775.00	2	Complete
Kindrick-Legion Field	Helena Citizens Council District 5	1.4.5	Exterior Doors	For all doors along the public circulation route, replace thresholds at exterior doors with ADA thresholds	\$181.25	each	3	\$543.75	2	Complete
Kindrick-Legion Field	Helena Citizens Council District 5	1.4.6	Exterior Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	16	\$5,880.00	2	Complete
Kindrick-Legion Field	Helena Citizens Council District 5	1.4.7	Exterior Doors	Upon renovation ; make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	2	N/A
Kindrick-Legion Field	Helena Citizens Council District 5	1.6.1	Interior Doors	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	22	\$27,500.00	2	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.6.2	Interior Doors	For all doors along the public circulation route, replace doors with ones having 80" overhead and 32" clear width	\$1,980.00	each	6	\$11,880.00	2	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.6.3	Interior Doors	For all doors along the public circulation route, <i>repair, bevel, or ramp CIL</i> at door entries to max .25"	\$68.75	inch	2	\$137.50	2	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.6.4	Interior Doors	For all doors along the public circulation route, replace thresholds at exterior doors with ADA thresholds	\$181.25	each	4	\$725.00	2	In progress



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Kindrick-Legion Field	Helena Citizens Council District 5	1.6.5	Interior Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	9	\$3,307.50	2	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.6.6	Interior Doors	Upon renovation ; make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	2	N/A
Kindrick-Legion Field	Helena Citizens Council District 5	1.7.1	Stairs - Interior	Correct riser heights on stairs to consistent height between 4" to 7", leave as is if technically infeasible	\$288.75	each	11	\$3,176.25	2	Incomplete
Kindrick-Legion Field	Helena Citizens Council District 5	1.7.2	Stairs - Interior	Install kick plates or replace stairs with closed risers	\$60.00	each	11	\$660.00	2	Incomplete
Kindrick-Legion Field	Helena Citizens Council District 5	1.7.3	Stairs - Interior	Correct tread depth on stairs to 11" minimum and consistent, leave as is if technically infeasible	\$288.75	each	11	\$3,176.25	2	Incomplete
Kindrick-Legion Field	Helena Citizens Council District 5	1.7.4	Stairs - Interior	Provide visual contrast on leading 2" of treads	\$20.00	each	22	\$440.00	2	Incomplete
Kindrick-Legion Field	Helena Citizens Council District 5	1.7.5	Stairs - Interior	Install detectable warning strip on top tread of each stairway as a smart practice	\$150.00	each	2	\$300.00	2	Incomplete
Kindrick-Legion Field	Helena Citizens Council District 5	1.7.6	Stairs - Interior	Install handrails on both sides of stairway, mounted 34" to 38" aff with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max	\$700.00	each	2	\$1,400.00	2	Incomplete
Kindrick-Legion Field	Helena Citizens Council District 5	1.8.1	Public Spaces	Remove, or relocate storage in CFS at fixtures and operable parts	\$0.00	staff time	0	\$0.00	3	On-going
Kindrick-Legion Field	Helena Citizens Council District 5	1.8.2	Public Spaces	Lower 36" wide segment of service counter to max 36" aff in front office	\$785.00	each	1	\$785.00	3	To be completed in FY23
Kindrick-Legion Field	Helena Citizens Council District 5	1.8.3	Public Spaces	Lower operating mechanisms in front office to max 48" aff to highest operable part; leave as is if employee only operated	\$250.00	each	1	\$250.00	3	To be completed in FY23
Kindrick-Legion Field	Helena Citizens Council District 5	1.9.1	Employee Spaces	Employee only area permit approach, entry, and exit, relocate obstacles to create AR through rooms listed	\$0.00	staff time	0	\$0.00	3	To be completed in FY23
Kindrick-Legion Field	Helena Citizens Council District 5	1.9.2	Employee Spaces	Employee only areas permit approach, entry, and exit, relocate obstacles to create turning space of 60" in rooms listed	\$0.00	staff time	0	\$0.00	3	To be completed in FY23
Kindrick-Legion Field	Helena Citizens Council District 5	1.9.3	Employee Spaces	For all other deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	3	N/A
Kindrick-Legion Field	Helena Citizens Council District 5	1.10.1	Assembly Area	Provide nine designated wheelchair seats with adjacent companion seats in assembly	\$449.50	each	9	\$4,045.50	3	To be completed in FY23
Kindrick-Legion Field	Helena Citizens Council District 5	1.10.2	Assembly Area	Mount signage at bleacher seating designating cutout areas as accessible seating	\$150.00	each	4	\$600.00	3	To be completed in FY23



211		<u></u>	Type of			unit	# of			
Site Kindrick-Legion	HCC Dist Helena Citizens	Cite	correction Assembly	Recommendation Advertise the availability of assisted listening	Price/ unit	type	units	Total cost	Phase	Notes
Field	Council District 5	1.10.3	Area	devices, if available, or have resources for acquiring ALDs upon request	\$150.00	each	5	\$750.00	3	To be completed in FY23
Kindrick-Legion Field	Helena Citizens Council District 5	1.11.1	- Brewers	Acquire and mount signage, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character	\$150.00	each	1	\$150.00	3	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.11.2	Restrooms - Multiple Users - Brewers Locker Room	Lower mirror so reflective surface is max 40" aff	\$0.00	staff time	0	\$0.00	3	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.11.3	Restrooms - Multiple Users - Brewers Locker Room	Replace faucet controls with lever controls	\$525.00	each	1	\$525.00	3	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.11.4	Restrooms - Multiple Users - Brewers Locker Room	Lower urinal so that rim height is max 17" aff	\$1,217.50	each	1	\$1,217.50	3	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.11.5	Restrooms - Multiple Users - Brewers Locker Room	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights	\$3,936.25	each	1	\$3,936.25	3	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.11.1	- Visitor	Acquire and mount signage, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character	\$150.00	each	1	\$150.00	3	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.11.2	- Visitor	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights	\$3,936.25	each	1	\$3,936.25	3	In progress



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Kindrick-Legion Field	Helena Citizens Council District 5	1.11.1	Restrooms - Multiple Users - Main Restroom	Acquire and mount signage, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character at both	\$150.00	each	2	\$300.00	3	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.11.2	Restrooms - Multiple Users - Main Restroom	Lower paper towel dispenser and hand dryers in both to max 48" to highest operable part	\$250.00	each	4	\$1,000.00	3	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.11.3	Restrooms - Multiple Users - Main Restroom	Widen accessible stalls to min. 60" clear width, 59" depth in both	\$1,963.75	each	2	\$3,927.50	3	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.11.4	Restrooms - Multiple Users - Main Restroom	Create an ambulatory accessible stall with grab bars and fixtures mounted in correct locations and at correct heights in both	\$3,936.25	each	2	\$7,872.50	3	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.11.5	Restrooms - Multiple Users - Main Restroom	Relocate or recess towel dispenser and hand dryers to not interfere with general circulation path, protrusions can't be greater than 4"	\$250.00	each	2	\$500.00	3	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.11.6	Restrooms - Multiple Users - Main Restroom	Remount grab bars in women's to the correct wall and height in accessible stall	\$281.25	each	2	\$562.50	3	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.11.1	Restrooms - Multiple Users - Dugout Restrooms	Restroom not accessible, <i>acquire and mount</i> signage directing patrons to accessible restroom	\$150.00	each	2	\$300.00	3	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.11.1	Restrooms - Single Users - Brewers Coach Restroom	Renovate restroom to be an accessible single user restroom	\$17,806.25	each	1	\$17,806.25	3	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.11.2	Restrooms - Single Users - Brewers Coach Restroom	Acquire and mount signage, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character upon renovation	\$150.00	each	1	\$150.00	3	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.11.1	Restrooms - Single Users - Office Restroom	Enlarge restroom to compliant dimension for CFS and turning space	\$1,100.00	lin ft	7	\$7,700.00	3	In progress



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Kindrick-Legion Field	Helena Citizens Council District 5	1.11.2	Restrooms - Single Users - Office Restroom	Acquire and mount signage, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character	\$150.00	each	1	\$150.00	3	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.11.3	Restrooms - Single Users - Office Restroom	Replace L shaped bar with one that extends to 54" on the side wall, and 24" to the open side of the toilet on the rear; mounted 33' to 36" aff	\$281.25	each	2	\$562.50	3	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.11.4	Restrooms - Single Users - Office Restroom	Mount vertical grab bar so bottom is between 39" and 41" from the floor and the centerline between 39" and 41" from rear wall	\$281.25	each	1	\$281.25	3	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.11.5	Restrooms - Single Users - Office Restroom	Lower mirror so reflective surface is max 40" aff	\$0.00	staff time	0	\$0.00	3	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.11.6	Restrooms - Single Users - Office Restroom	Replace faucet controls with lever controls	\$525.00	each	1	\$525.00	3	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.11.7	Restrooms - Single Users - Office Restroom	Insulate exposed pipes under sink	\$55.00	each	1	\$55.00	3	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.11.8	Restrooms - Single Users - Office Restroom	Lower paper towel dispenser to max 48" to highest operable part	\$250.00	each	1	\$250.00	3	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.11.1	Restrooms - Single Users - Legion Restroom	Renovate restroom to be an accessible single user restroom	\$17,806.25	each	1	\$17,806.25	3	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.11.2	Restrooms - Single Users - Legion Restroom	Acquire and mount signage, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character upon renovation	\$150.00	each	1	\$150.00	3	In progress
Kindrick-Legion Field	Helena Citizens Council District 5	1.12.1	Concessions - Home	Lower 36" wide segment of service counter to max 36" aff	\$785.00	each	1	\$785.00	2	Incomplete
Kindrick-Legion Field	Helena Citizens Council District 5	1.12.2	Concessions - Home	Replace menu with one having pictures and lettering of compliant size based on viewing distance as a smart practice	\$100.00	each	1	\$100.00	2	Incomplete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Kindrick-Legion Field	Helena Citizens Council District 5	1.12.3	Concessions - Home	For all other deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	2	Incomplete
Kindrick-Legion Field	Helena Citizens Council District 5	1.12.1	Concessions - Visitor	Lower 36" wide segment of service counter to max 36" aff	\$785.00	each	1	\$785.00	3	Incomplete
Kindrick-Legion Field	Helena Citizens Council District 5	1.12.2	Concessions - Visitor	Replace menu with one having pictures and lettering of compliant size based on viewing distance as a smart practice	\$100.00	each	1	\$100.00	3	Incomplete
Kindrick-Legion Field	Helena Citizens Council District 5	1.12.3	Concessions - Visitor	For all other deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	3	Incomplete
Kindrick-Legion Field	Helena Citizens Council District 5	1.12.1	Concessions - Open Air	Correct or repair slope in CFS of service counter to max 2.08% to be level	\$785.00	each	1	\$785.00	2	Incomplete
Kindrick-Legion Field	Helena Citizens Council District 5	1.12.2	Concessions - Open Air	Replace menu with one having pictures and lettering of compliant size based on viewing distance as a smart practice	\$100.00	each	1	\$100.00	2	Incomplete
Kindrick-Legion Field	Helena Citizens Council District 5	1.12.3	Concessions - Open Air	For all other deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	2	N/A
Kindrick-Legion Field	Helena Citizens Council District 5	1.13.1	Locker Rooms - Brewers	For all deficits for professional players and coaches' locker rooms, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	2	N/A
Kindrick-Legion Field	Helena Citizens Council District 5	1.13.1	Locker Rooms - Visitors	For all deficits for professional players and coaches' locker rooms, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	2	N/A
Kindrick-Legion Field	Helena Citizens Council District 5	1.13.1		For all deficits for officials' locker rooms, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	2	N/A
Kindrick-Legion Field	Helena Citizens Council District 5	1.13.1	Locker Rooms - Reps	Designate 5% or no less than 1 locker as accessible, mounting signage having the access symbol and hooks and operating mechanisms max 48" aff	\$300.00	each	1	\$300.00	2	Lockers have been removed
Kindrick-Legion Field	Helena Citizens Council District 5	1.13.1	Locker Rooms - Legion (Senators)	Designate 5% or no less than 1 locker as accessible, mounting signage having the access symbol and hooks and operating mechanisms max 48" aff	\$300.00	each	1	\$300.00	2	Complete



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Kindrick-Legion Field	Helena Citizens Council District 5	1.13.1	Locker Rooms - Coach Shower	For all deficits for players and coaches' locker rooms, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	2	N/A
Kindrick-Legion Field	Helena Citizens Council District 5	1.14.1	Alarms	Upon renovation <i>install audible and visual</i> alarms in all rooms and spaces	\$407.50	each	18	\$7,335.00	2	Incomplete will be addressed during renovation
Kindrick-Legion Field	Helena Citizens Council District 5	1.15.1	Interior Signage	Create template for signs that addresses height of sign, size of characters, location of Braille, and other requirements	\$0.00	staff time	0	\$0.00	2	Incomplete
Kindrick-Legion Field	Helena Citizens Council District 5	1.15.2	Interior Signage	Implement a sign revision program throughout the building, discriminating between directional signs and signs for permanent spaces	\$0.00	staff time	0	\$0.00	2	Incomplete
Kindrick-Legion Field	Helena Citizens Council District 5	1.15.3	Interior Signage	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door	\$150.00	each	20	\$3,000.00	2	Incomplete
Kindrick-Legion Field	Helena Citizens Council District 5	1.16.1	Park Site	Provide a ramp for access to the VIP area	\$155.00	inch	63	\$9,765.00	2	Incomplete
Kindrick-Legion Field	Helena Citizens Council District 5	1.16.2	Park Site	Replace 5% of the tables in the <u>VIP area</u> with ones of an accessible design	\$800.00	each	3	\$2,400.00	2	Incomplete
Kindrick-Legion Field	Helena Citizens Council District 5	1.16.3	Park Site	Leave as is, upper level in the VIP area and provide same services on new accessible level	\$0.00	n/a	0	\$0.00	2	N/A
Kindrick-Legion Field	Helena Citizens Council District 5	1.16.4	Park Site	Relocate garbage can in <u>VIP area</u> to be on the accessible level	\$0.00	staff time	0	\$0.00	2	Incomplete
Kindrick-Legion Field	Helena Citizens Council District 5	1.16.5	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the warm up areas and batting cages	\$48.00	lin ft	100	\$4,800.00	2	Incomplete
Kindrick-Legion Field	Helena Citizens Council District 5	1.16.6	Park Site	Replace 5% of the tables in the <u>beer garden</u> and <u>picnic area on 1st base side</u> with ones of an accessible design	\$800.00	each	10	\$8,000.00	2	Incomplete
Kindrick-Legion Field	Helena Citizens Council District 5	1.16.7	Park Site	Upon renovation create access to dugout on both sides of the field	\$155.00	inch	98	\$15,190.00	3	Incomplete
<u>Last Chance</u> <u>Pool</u>	Citywide Facilities	1.1.1	Parking	Repaint stalls and access aisles to be 8' and 5' each	\$52.50	each	2	\$105.00	2	Incomplete
Last Chance Pool	Citywide Facilities	1.2.1	Exterior Accessible Route	Correct slope of curb ramp side flares to max 10%	\$725.00	each	1	\$725.00	2	Incomplete



			Turno of				# of			
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# or units	Total cost	Phase	Notes
Last Chance Pool	Citywide Facilities	1.2.2	Exterior Accessible Route	Install compliant detectable warning at curb ramps as a smart practice	\$235.00	each	1	\$235.00	2	Incomplete
Last Chance Pool	Citywide Facilities	1.2.3	Exterior Accessible Route	Repair, bevel, or ramp CIL along AR	\$68.75	each	1	\$68.75	2	Incomplete
Last Chance Pool	Citywide Facilities	1.2.4	Exterior Accessible Route	Correct or fill gaps along AR	\$68.75	each	1	\$68.75	2	Incomplete
Last Chance Pool	Citywide Facilities	1.2.5	Exterior Accessible Route	Correct or repair sidewalk cross slope along AR to max 2.08%	\$87.50	sq ft	75	\$6,562.50	2	Incomplete
Last Chance Pool	Citywide Facilities	1.2.6	Exterior Accessible Route	Correct or repair sidewalk running slope along AR to max 5%	\$87.50	sq ft	25	\$2,187.50	2	Incomplete
Last Chance Pool	Citywide Facilities	1.4.1	Exterior Doors	For all doors along the public circulation route, correct or repair slope at doorway landing to max 2.08% in any direction for level CFS	\$2,187.50	each	3	\$6,562.50	1	Complete
Last Chance Pool	Citywide Facilities	1.4.2	Exterior Doors	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	1	\$1,250.00	1	Complete
Last Chance Pool	Citywide Facilities	1.4.3	Exterior Doors	For all doors along the public circulation route, repair , bevel , or ramp CIL at door entries to max .25"	\$68.75	inch	1	\$68.75	1	Complete
Last Chance Pool	Citywide Facilities	1.4.4	Exterior Doors	For all doors along the public circulation route, <i>fill</i> and maintain gaps at doorways to max .5"	\$68.75	each	2	\$137.50	1	Complete
Last Chance Pool	Citywide Facilities	1.4.5	Exterior Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	5	\$1,837.50	1	Complete
Last Chance Pool	Citywide Facilities	1.4.6	Exterior Doors	For all doors along the public circulation route, remount hardware to be 34" to 48" aff	\$250.00	each	1	\$250.00	1	Complete
Last Chance Pool	Citywide Facilities	1.4.7	Exterior Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice	\$0.00	staff time	0	\$0.00	1	Complete
Last Chance Pool	Citywide Facilities	1.4.8	Exterior Doors	For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers	\$0.00	staff time	0	\$0.00	1	Complete
Last Chance Pool	Citywide Facilities	1.4.9	Exterior Doors	Upon renovation ; make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	1	Complete
Last Chance Pool	Citywide Facilities	1.6.1	Interior Doors	For all doors along the public circulation route, <i>fill</i> and maintain gaps at doorways to max .5"	\$68.75	each	1	\$68.75	2	Complete



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Last Chance Pool	Citywide Facilities	1.8.1	Public Spaces	Relocate protruding objects in both locker rooms or place cane detectable warning or bollard at foot of drinking fountains	\$150.00	each	2	\$300.00	2	Complete
Last Chance Pool	Citywide Facilities	1.8.2	Public Spaces	Remove bench, or relocate hooks for CFS	\$0.00	staff time	0	\$0.00	2	Complete
Last Chance Pool	Citywide Facilities	1.8.3	Public Spaces	Lower operating mechanisms to max 48" aff to highest operable part	\$0.00	staff time	0	\$0.00	2	Complete
Last Chance Pool	Citywide Facilities	1.8.4	Public Spaces	Lower 36" wide segment of service counter to max 36" aff	\$785.00	each	1	\$785.00	2	Complete
Last Chance Pool	Citywide Facilities	1.8.5	Public Spaces	Replace faucet controls with lever controls	\$525.00	each	2	\$1,050.00	2	Complete
Last Chance Pool	Citywide Facilities	1.9.1	Employee Spaces	Employee only area permit approach, entry, and exit, relocate obstacles to create AR through pump room	\$0.00	staff time	0	\$0.00	2	N/A
Last Chance Pool	Citywide Facilities	1.9.2	Employee Spaces	For all other deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	staff time	0	\$0.00	2	N/A
Last Chance Pool	Citywide Facilities	1.11.1	Restrooms - Single Users	Acquire and mount signage for both, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character	\$150.00	each	4	\$600.00	2	Complete
Last Chance Pool	Citywide Facilities	1.11.2	Restrooms - Single Users	Remount toilets in both to 16" to 18" from the side wall to centerline	\$1,306.00	each	2	\$2,612.00	2	Complete
Last Chance Pool	Citywide Facilities	1.11.3	Restrooms - Single Users	Replace toilet tanks in both with one having flush mechanism on the open side, in the alternative, install an auto flush unit	\$211.25	each	2	\$422.50	2	Complete
Last Chance Pool	Citywide Facilities	1.11.4	Restrooms - Single Users	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	\$0.00	staff time	0	\$0.00	2	Complete
Last Chance Pool	Citywide Facilities	1.11.5	Restrooms - Single Users	Lower mirrors in both so reflective surface is max 40" aff	\$0.00	staff time	0	\$0.00	2	Complete
Last Chance Pool	Citywide Facilities	1.11.6	Restrooms - Single Users	Lower sinks in both to max 34" aff to front of rim	\$1,700.00	each	2	\$3,400.00	2	Complete
Last Chance Pool	Citywide Facilities	1.11.7	Restrooms - Single Users	Correct or repair slope in women's to max 5% running and 2.08% cross	\$87.50	sq ft	25	\$2,187.50	2	Complete
Last Chance Pool	Citywide Facilities	1.11.1	Restrooms - Single Users - Boy's Locker Room	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights	\$3,936.25	each	1	\$3,936.25	2	Complete



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Last Chance Pool	Citywide Facilities	1.11.2	Restrooms - Single Users - Boy's Locker Room	Replace one urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" aff	\$2,127.50	each	1	\$2,127.50	2	Complete
Last Chance Pool	Citywide Facilities	1.12.1	Concessions	Lower 36" wide segment of service counter to max 36" aff	\$785.00	each	1	\$785.00	2	Complete
Last Chance Pool	Citywide Facilities	1.12.2	Concessions	Correct or repair slope at service counter to max 2.08% in any direction for level CFS	\$87.50	sq ft	25	\$2,187.50	2	Complete
Last Chance Pool	Citywide Facilities	1.12.3	Concessions	Replace menu with one having pictures and lettering of compliant size based on viewing distance as a smart practice	\$100.00	each	1	\$100.00	2	Complete
Last Chance Pool	Citywide Facilities	1.12.4	Concessions	For all other deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	2	Complete
Last Chance Pool	Citywide Facilities	1.13.1	Locker Rooms - Family Changing	Reduce shower stalls in both, if feasible, to compliant dimensions for a transfer shower of 36" deep by 36" wide with a 36" opening	\$1,963.75	each	2	\$3,927.50	2	Incomplete will be addressed during renovation
Last Chance Pool	Citywide Facilities	1.13.2	Locker Rooms - Family Changing	Lower shower head to max 48" aff	\$333.75	each	2	\$667.50	2	Complete
Last Chance Pool	Citywide Facilities	1.13.3	Locker Rooms - Family Changing	Adjust shower control to be operable with less than 5 lbf	\$0.00	staff time	0	\$0.00	2	Complete
Last Chance Pool	Citywide Facilities	1.13.4	Locker Rooms - Family Changing	Remount shower seat to the correct location and height in the shower	\$250.00	each	2	\$500.00	2	Complete
Last Chance Pool	Citywide Facilities	1.13.1	Locker Rooms - Boy's and Girl's	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" aff	\$600.00	each	2	\$1,200.00	2	Complete
Last Chance Pool	Citywide Facilities	1.13.2	Locker Rooms - Boy's and Girl's	Create accessible shower in each locker room	\$4,881.25	each	2	\$9,762.50	2	Incomplete will be addressed during renovation
Last Chance Pool	Citywide Facilities	1.16.1	Pool	Repair, bevel, or ramp CILs on pool deck to max .25"	\$68.75	each	2	\$137.50	2	Complete
Last Chance Pool	Citywide Facilities	1.16.2	Pool	Correct or repair slopes along the pool deck to 2.08% max cross and 5% max running	\$87.50	sq ft	100	\$8,750.00	2	Complete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Last Chance	Citywide Facilities	1.16.3	Pool	Repair, fill, and maintain gaps on pool deck to	\$68.75	each	1	\$68.75	2	Complete
Pool Last Chance	Citywide Facilities	1.16.4	Pool	max .5" Lower 36" wide segment of service counter to	\$785.00	each	1	\$785.00	2	Incomplete
Pool Last Chance	Citywide i aciiilles	1.10.4	1 001	max 36" aff Leave as is, sloped entry to activity pool and	Ψ100.00	Cacii	'	Ψ705.00		incomplete
Pool	Citywide Facilities	1.16.5	Pool	install a pool lift	\$10,000.00	each	1	\$10,000.00	2	Complete
Last Chance Pool	Citywide Facilities	1.16.6	Pool	Correct or repair running slope of sloped entry to max 8.33%	\$87.50	sq ft	90	\$7,875.00	2	Complete
Last Chance Pool	Citywide Facilities	1.16.7	Pool	Correct riser heights on stairs so they are a consistent height	\$288.75	each	5	\$1,443.75	2	Complete
Last Chance Pool	Citywide Facilities	1.16.8	Pool	Replace or remount handrails to 34" to 38" aff	\$700.00	each	1	\$700.00	2	Staff to investigate completion status
Last Chance Pool	Citywide Facilities	1.16.9	Pool	Correct tread depth on stairs so they are 11" minimum and consistent	\$288.75	each	5	\$1,443.75	2	Staff to investigate completion status
Last Chance Pool	Citywide Facilities	1.16.10	Pool	Remount another handrail at the pool stairs, 20" to 24" from an existing handrail	\$700.00	each	1	\$700.00	2	Staff to investigate completion status
<u>Last Chance</u> <u>Walking Mall</u>	Helena Citizens Council District 1	1.2.1	Exterior Accessible Route	Repair, bevel, or ramp CIL along AR	\$68.75	each	4	\$275.00	2	On-going
Last Chance Walking Mall	Helena Citizens Council District 1	1.2.2	Exterior Accessible Route	Correct or fill gaps along AR	\$68.75	each	10	\$687.50	2	On-going
Last Chance Walking Mall	Helena Citizens Council District 1	1.2.3	Exterior Accessible Route	Repair and reset pavers to eliminate CIL and gaps	\$20.00	sq ft	50	\$1,000.00	2	On-going
Last Chance Walking Mall	Helena Citizens Council District 1	1.2.4	Exterior Accessible Route	Correct or repair sidewalk cross slope along AR to max 2.08%	\$87.50	sq ft	225	\$19,687.50	2	Incomplete
Last Chance Walking Mall	Helena Citizens Council District 1	1.2.5	Exterior Accessible Route	Correct or repair sidewalk running slope along AR to max 5%	\$87.50	sq ft	200	\$17,500.00	2	Staff to investigate technical feasibility
Last Chance Walking Mall	Helena Citizens Council District 1	1.10.1	Park Site	Remount monument signage to 40" min to the text on the sign as a smart practice	\$0.00	staff time	0	\$0.00	2	Complete
Last Chance Walking Mall	Helena Citizens Council District 1	1.10.2	Park Site	Lower dog bags to max 48" aff to highest operable part	\$0.00	staff time	0	\$0.00	2	Complete
Last Chance Walking Mall	Helena Citizens Council District 1	1.10.3	Park Site	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches at bus shelter, and locate along an AR as a smart practice	\$115.00	each	1	\$115.00	2	N/A
Last Chance Walking Mall	Helena Citizens Council District 1	1.10.4	Park Site	Remove a bench at one checkerboard table to allow knee and toe clearance, in the alternative, add a compliant model table	\$250.00	each	1	\$250.00	2	Incomplete
Last Chance Walking Mall	Helena Citizens Council District 1	1.10.5	Park Site	Trolley is not accessible, <i>leave as is, consider</i> adding an alternative experience	\$0.00	staff time	0	\$0.00	2	N/A



						1				
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Last Chance	Helena Citizens	Cite	Correction	Replace drinking fountain with a hi-lo bowl	riice/ uiiit	type	uiiits	Total Cost	Filase	Notes
Walking Mall	Council District 1	1.10.6	Park Site	fountain	\$3,998.75	each	1	\$3,998.75	2	Drinking fountain has been removed
Wanting Man	Courion Blouret 1			Replace 20% of the picnic tables with one with						
Last Chance	Helena Citizens	1.10.7	Park Site	knee and toe clearance, 19" deep at 27" high and	\$800.00	each	2	\$1,600.00	2	Incomplete
Walking Mall	Council District 1	1.10.7	I alk Site	24" deep at 9" high, with a 36" AR around the	φουσ.σσ	Cacii		φ1,000.00	2	incomplete
1 11 6				table as a smart practice						
Law and Justice Center	Cityavida Eggilitica	1.1.1	Parking	Repaint stalls and access aisles to be 8' and 5' each	\$73.50	ooob	1	\$73.50	2	To be completed in EV22
Law and Justice	Citywide Facilities	1.1.1	Parking	Repaint van stalls and access aisles to be 8' and	\$73.50	each	ı	\$73.50		To be completed in FY22
Center	Citywide Facilities	1.1.2	Parking	8' each or 11' and 5' respectively	\$73.50	each	1	\$73.50	2	To be completed in FY22
Contor	Oitywide i doilides	1.1.2	1 diking	o cash of the and o respositively	Ψ10.00	Cuon		ψ10.00		10 be completed in 1 122
Law and Justice				Repair or correct slope of parking spaces and						
Center	Citywide Facilities	1.1.3	Parking	access aisles to max 2.08% in any direction	\$3,062.50	each	1	\$3,062.50	2	Staff to investigate completion status
			Exterior							
Law and Justice			Accessible	Correct or repair sidewalk cross slope along AR		-				
Center	Citywide Facilities	1.2.1	Route	to max 2.08%	\$122.50	sq ft	25	\$3,062.50	2	Incomplete
Law and Justice			Exterior Accessible	Correct or repair aidoually rupping along along						
Center	Citywide Facilities	1.2.2	Route	Correct or repair sidewalk running slope along AR to max 5%	\$122.50	sq ft	25	\$3,062.50	2	Incomplete
Center	Citywide i aciiilles	1.2.2	Noute	Correct tread depth on stairs so they are 11"	Ψ122.50	34 11	20	ψ5,002.50		incomplete
Law and Justice			Stairs -	minimum and consistent, leave as is if technically						
Center	Citywide Facilities	1.2.3	Exterior	infeasible	\$404.25	each	4	\$1,617.00	2	Staff to investigate completion status
Law and Justice			Stairs -	Install contrasting strip along front 2" of each						-
Center	Citywide Facilities	1.2.4	Exterior	tread	\$210.00	each	4	\$840.00	2	Incomplete
Law and Justice			Ramps -	Correct slope of ramp to max 8.33% at both						
Center	Citywide Facilities	1.2.5	Exterior	ramps	\$6,510.00	each	3	\$19,530.00	2	Incomplete
Law and Justice Center	Citywide Facilities	1.2.6	Ramps - Exterior	Correct ramp landing slope to max 2.08% at both ramps	\$404.25	sq ft	75	\$30,318.75	2	Incomplete
Law and Justice	Citywide Facilities	1.2.0	Ramps -	Enlarge landing on ramp where directions	φ404.25	SQ IL	73	φ30,310.73		incomplete
Center	Citywide Facilities	1.2.7	Exterior	change to 60" by 60" at main entry ramp	\$1,750.00	each	1	\$1,750.00	2	Staff to investigate technical feasibility
				Replace handrails with ones that are rounded	+ 1,1 2 2 1 2 2		-	+ 1,1 2 2 1 2 2		
				and/or extend to the ground, with handrail						
Law and Justice			Ramps -	extensions and mounted 34" to 38" aff at both						
Center	Citywide Facilities	1.2.8	Exterior	ramps	\$980.00	each	1	\$980.00	2	Staff to investigate completion status
l l			F. 4	Mount signage at inaccessible entrances						
Law and Justice Center	Citywide Facilities	1.3.1	Exterior	directing patrons in wheelchairs to accessible entrance	\$210.00	each	2	\$420.00	2	To be completed in FY22
Law and Justice	Citywide Facilities	1.3.1	Signage Exterior	Mount signage at entrance designating it as	Φ2 10.00	eacii		Φ420.00		To be completed in F122
Center	Citywide Facilities	1.3.2	Signage	accessible	\$210.00	each	1	\$210.00	2	To be completed in FY22
555.	2.1,11.00		5.3	For all doors along the public circulation route,	72.0.03	55.5.1		\$2.0.03		
Law and Justice				provide required maneuvering clearance on push						
Center	Citywide Facilities	1.4.1	Exterior Doors	and pull side of doors	\$1,750.00	each	1	\$1,750.00	2	Staff to investigate technical feasibility
				For all doors along the public circulation route,						
Law and Justice	0.4	4.40	E.A. S	correct or repair slope at doorway landing to	#0.000.50			#0.000.50	_	Oteff to investigate to the control of
Center	Citywide Facilities	1.4.2	Exterior Doors	max 2.08% in any direction for level CFS	\$3,062.50	each	1	\$3,062.50	2	Staff to investigate technical feasibility



			1					I		
			Tymo of			unit	# of			
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	type	# 01 units	Total cost	Phase	Notes
5110	1100 Dist	Oite	Correction		Trice/ unit	type	units	Total cost	1 Hase	Notes
Law and Justice	O'4	4.40		For all doors along the public circulation route,	CE4450			0544.50	0	Otaff to increasing to the control of a collection
Center	Citywide Facilities	1.4.3	Exterior Doors	remount hardware to be 34" to 48" aff	\$514.50	each	1	\$514.50	2	Staff to investigate technical feasibility
Law and hystics				For all doors along the public circulation route,		ataff				
Law and Justice	O'4			inspect, adjust, and maintain 8.5 lbf to open	#0.00	staff	0	#0.00	0	O i
Center	Citywide Facilities	1.4.4	Exterior Doors	exterior doors as a smart practice	\$0.00	time	0	\$0.00	2	On-going
Law and Justice	O'4	4 4 5		Upon renovation, make above corrections to	#0.00	/	0	#0.00	2	NI/A
Center	Citywide Facilities	1.4.5	Exterior Doors	employee only doors	\$0.00	n/a	U	\$0.00		N/A
Low and Justice				Acquire and mount signs between 48" and 60"						
Law and Justice Center	Citrouida Facilitias	1.5.1	Elevators	aff on both jambs of the elevator opening on each floor at both elevators	\$210.00	aaab	12	\$2,520.00	2	To be completed in EV22
Center	Citywide Facilities	1.5.1	Elevators	lioor at both elevators	\$210.00	each	12	\$2,520.00		To be completed in FY22
				Dragram alayatar aar aydibla aignala at bath						
Law and Justice				Program elevator car audible signals at both elevators to chime once for up and twice for down,						
Center	Citywide Facilities	1.5.2	Elevators	or replace audible chimes with verbal enunciators	\$7,700.00	each	2	\$15,400.00	2	To be completed in FY22
Cerilei	Citywide Facilities	1.5.2	Lievalois	Remount car control buttons on interior of	\$1,100.00	eacii		φ13,400.00		10 be completed in F122
Law and Justice				elevator to max 48" at south elevator, <i>leave as is</i>						
Center	Cityavida Eggilitica	1.5.3	Elevators	,	\$22,391.25	ooob	1	\$22,391.25	2	To be completed in EV22
Cerilei	Citywide Facilities	1.5.5	Elevators	if technically infeasible to change	φ22,391.23	each	- 1	φ22,391.23		To be completed in FY22
Law and Justice				Remount handrails in south elevator to between						
Center	Citywide Facilities	1.5.4	Elevators	32" and 36" aff to the top of the gripping surface	\$565.25	each	1	\$565.25	2	To be completed in FY22
Ceriter	Citywide i adiities	1.5.4	Lievators	Replace hardware on emergency communication	ψ303.23	Cacii	'	ψ303.23		10 be completed in 1 122
Law and Justice				system panel door to be operable without a tight						
Center	Citywide Facilities	1.5.5	Elevators	pinch or grasp	\$70.00	each	1	\$70.00	2	To be completed in FY22
Conto	CityWide I domined	1.0.0	Liovatoro	For all doors along the public circulation route,	Ψ7 0.00	Guon		ψ1 0.00		10 00 0011010100 1111 122
Law and Justice			Interior Doors	provide required maneuvering clearance on push						
Center	Citywide Facilities	1.6.1	Upper Level	and pull side of doors	\$1,250.00	each	8	\$10,000.00	2	Staff to investigate technical feasibility
				For all doors along the public circulation route,	, ,			, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		,
				replace door with one having 32" clear width and						
Law and Justice			Interior Doors	with projections no greater than 40" between 27"						
Center	Citywide Facilities	1.6.2	Upper Level	and 80" aff	\$2,772.00	each	5	\$13,860.00	2	Staff to investigate technical feasibility
				For all doors along the public circulation route,						-
Law and Justice			Interior Doors	replace hardware with lever hardware where						
Center	Citywide Facilities	1.6.3	Upper Level	indicated	\$514.50	each	4	\$2,058.00	2	Incomplete
				For all doors along the public circulation route,						
Law and Justice			Interior Doors	inspect, adjust, and maintain 5 lbf to open		staff				
Center	Citywide Facilities	1.6.4	Upper Level	interior doors	\$0.00	time	0	\$0.00	2	On-going
				For all doors along the public circulation route,						
Law and Justice			Interior Doors	inspect, adjust, and maintain closing speed on		staff				
Center	Citywide Facilities	1.6.5	Upper Level	door closers	\$0.00	time	0	\$0.00	2	On-going
				For all doors along the public circulation route,						
Law and Justice			Interior Doors	replace doors with ones having sidelight viewing						
Center	Citywide Facilities	1.66	Upper Level	windows max 43" aff	\$1,386.00	each	5	\$6,930.00	2	Staff to investigate technical feasibility
Law and Justice				Upon renovation , make above corrections to						
Center	Citywide Facilities	1.6.7	Upper Level	employee only doors	\$0.00	n/a	0	\$0.00	2	N/A



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
			Interior							
			Accessible							
Law and Justice			Route - Upper	Lower operating mechanisms along the interior						
Center	Citywide Facilities	1.7.1	Level	AR to max 48" aff to the highest operable part	\$350.00	each	3	\$1,050.00	2	Incomplete
			Interior							
			Accessible	Relocate protruding objects along the interior						
Law and Justice				AR or place cane detectable warning or bollard at						
Center	Citywide Facilities	1.7.2	Level	foot of counter and first aid	\$350.00	each	2	\$700.00	2	Incomplete
			Service	1						
Law and Justice	O'4	470	Counter -	Lower 36" wide segment of service counter to	¢4 000 00		_	¢0.400.00	0	Otaff to investigate to sharing the cribility
Center	Citywide Facilities	1.7.3	Upper Level	max 36" aff	\$1,099.00	each	2	\$2,198.00	2	Staff to investigate technical feasibility
			Stairs -	Correct riser heights on east, NW entry, and						
Law and Justice			Interior -	NW stairwell stairs to consistent height between 4"						
Center	Citywide Facilities	1.7.4	Upper Level	to 7", leave as is if technically infeasible	\$404.25	each	117	\$47.297.25	2	Staff to investigate technical feasibility
	Only mus r dominos		Stairs -	Provide a contrasting strip on the front 2" of each	ψ101.20			ψ, <u>z</u> σ <u>z</u> σ		otali to invoctigate to similoan roadisinty
Law and Justice			Interior -	stair tread at boiler room, NE door, and NW						
Center	Citywide Facilities	1.7.5	Upper Level	stairwell	\$210.00	each	118	\$24,780.00	2	Incomplete
	•									·
				<i>Install</i> handrails on both sides of stairway at west						
				stairs, east stairs, boiler room, NE door, NW entry						
				door, and NW stairwell, mounted 34" to 38" aff						
				with top and bottom extensions and having a 1.25"						
			Stairs -	– 2" in diameter, or a non-circular grip that has a						
Law and Justice			Interior -	perimeter dimension of 4"- 6.25" max with a min						
Center	Citywide Facilities	1.7.6	Upper Level	gap of 1.5" between handrail and wall	\$980.00	each	18	\$17,640.00	2	Incomplete
Law and Justice			Stairs -	Provide 80" overhead clearance at boiler room						
Center	Citywide Facilities	1.7.7	Interior - Upper Level	stairs if feasible, in the alternative, pad the obstruction to prevent injury	\$1,540.00	each	1	\$1,540.00	2	Incomplete
Cerilei	Citywide Facilities	1.7.7	Ramps -	Dostruction to prevent injury	\$1,540.00	eacii	1	\$1,540.00		incomplete
Law and Justice			Interior -							
Center	Citywide Facilities	1.7.8	Upper Level	Correct slope of ramp to max 8.33%	\$6,510.00	each	1	\$6,510.00	2	Incomplete
					70,0100		_	¥0,010100	_	
			Ramps -	Replace handrails with ones that are rounded						
Law and Justice			Interior -	and/or extend to the ground, with handrail						
Center	Citywide Facilities	1.7.9	Upper Level	extensions and mounted 34" to 38" aff	\$980.00	each	1	\$980.00	2	Staff to investigate technical feasibility
			Ramps -							
Law and Justice	2		Interior -	Install rail along bottom edge of ramp that						
Center	Citywide Facilities	1.7.10	Upper Level	prevents a 4" sphere from passing through	\$525.00	each	1	\$525.00	2	Incomplete
Laurand Iva			Dublic Co.	Relocate protruding objects in 302 24/7 or						
Law and Justice	Cityavido Facilitis	101		place cane detectable warning or bollard at foot of	¢250.00	oceb	4	¢250.00	0	Incomplete
Center	Citywide Facilities	1.8.1	- Upper Level	counter	\$350.00	each	1	\$350.00	2	Incomplete
Law and Justice			Public Spaces							
Center	Citywide Facilities	1.8.2		Leave as is volume knobs, no longer in use	\$0.00	n/a	0	\$0.00	2	N/A
OCITICI	Citywide i aciilles	1.0.2	I Obbei revei	Leave as is volume knows, no longer in use	ψ0.00	11/a	U	ψ0.00		IN/A



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Law and Justice Center	Citywide Facilities	1.8.3	- Upper Level	Lower 36" wide segment of service counter to	\$1.099.00	each	1	\$1,099.00	2	Staff to investigate technical feasibility
Octilei	OityWide Facilities	1.0.0	- Opper Lever	max 30° an	ψ1,033.00	Cacii		Ψ1,033.00		Ctan to investigate technical reasibility
Law and Justice				Replace one table with one having required knee						
Center	Citywide Facilities	1.8.4		and toe clearances Employee only area permit approach, entry, and	\$1,120.00	each	1	\$1,120.00	2	Incomplete
Law and Justice			Employee Spaces -	exit, <i>relocate obstacles</i> to create AR through		staff				
Center	Citywide Facilities	1.9.1	Upper Level	rooms indicated	\$0.00	time	0	\$0.00	2	On-going
			Employee	Employee only areas permit approach, entry, and						
Law and Justice Center	Citywide Facilities	1.9.2	Spaces - Upper Level	exit, <i>relocate obstacles</i> to create turning space of 60" in 306 supplies and 321 office	\$0.00	staff time	0	\$0.00	2	To be completed in EV22
Center	Citywide Facilities	1.9.2	Opper Level	For all other deficits, <i>leave as is,</i> employee work	\$0.00	ume	U	φυ.υυ	2	To be completed in FY22
			Employee	area pursuant to 2010 Standards 106.5 Defined						
Law and Justice			Spaces -	Terms, until an employee with a disability works						
Center	Citywide Facilities	1.9.3	Upper Level	here	\$0.00	n/a	0	\$0.00	2	N/A
			Restrooms -							
			Multiple Users							
Law and Justice	07 11 5 77	, , , ,		Lower mirror in both so reflective surface is max	00.00	staff		# 0.00	0	0.6.
Center	Citywide Facilities	1.11.1	328 and 330	40" aff	\$0.00	time	0	\$0.00	2	Staff to investigate technical feasibility
			Restrooms -							
				Raise sink bowl in both to provide 27" knee						
Law and Justice	Citrovida Facilities	1 44 0		clearance, in the alternative, acquire a shallower	¢2 200 00		2	¢4.760.00	0	Ctaff to investigate to shair all face in ility
Center	Citywide Facilities	1.11.2	328 and 330	model	\$2,380.00	each		\$4,760.00	2	Staff to investigate technical feasibility
			Restrooms -							
			Multiple Users							
Law and Justice Center	Citywide Facilities	1.11.3	- Upper Level - 328 and 330	Insulate exposed pipes under one sink in both	\$77.00	each	2	\$154.00	2	Incomplete
Center	Citywide Facilities	1.11.3	320 and 330	Insulate exposed pipes under one sink in both	\$77.00	eacii		\$154.00		incompiete
			Restrooms -							
			Multiple Users							
Law and Justice Center	Citywide Facilities	1.11.4	- Upper Level 328 and 330	Lower seat covers in ambulatory stalls to max	\$350.00	each	2	\$700.00	2	Incomplete
Cernier	Oitywide Facilities	1.11.4	320 and 330	Create a wheelchair accessible stall with grab	ψ550.00	Cacii		ψ100.00		incomplete
			Restrooms -	bars and fixtures mounted in correct locations and						
				at correct heights; if technically infeasible, leave as						
Law and Justice Center	Citywide Facilities	1.11.5	- Upper Level - 328 and 330	is and mount signage directing users to accessible	\$5,510.75	each	2	\$11,021.50	2	Staff to investigate technical feasibility
Center	Citywide Facilities	1.11.5	1 320 and 330	IESHOUIII	φυ,υτυ./5	each		φ11,021.30		Staff to investigate technical feasibility



1										
			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
			Restrooms -							
Law and Justice			Multiple Users							
	Citywide Facilities	1.11.1	340 and 342	Restrooms not accessible, <i>acquire and mount</i> signage directing patrons to accessible restroom	\$210.00	each	2	\$420.00	2	Incomplete
Ochter	Oitywide i aciiities	1.11.1	040 and 042	signage directing pations to accessible restroom	Ψ2 10.00	Cacii		Ψ+20.00		meompiete
			Restrooms -							
			Multiple Users							
Law and Justice				Add a closer to hall door to prevent it from being						
Center	Citywide Facilities	1.11.2		held open and blocking restroom signage	\$94.00	each	1	\$94.00	2	Incomplete
			Restrooms -	Remount side grab bar to max 12" from the rear						
Law and Justice				wall at the close end and min 54" on the far end,						
	Citywide Facilities	1.11.1	303	and 33" to 36" aff	\$393.75	each	1	\$393.75	2	Incomplete
	,		Restrooms -							
				Remount rear grab bar to behind the toilet, 12"						
Law and Justice				to one side of center and 24" to the other and 33"						
Center (Citywide Facilities	1.11.2	303	to 36" aff	\$393.75	each	1	\$393.75	2	Incomplete
			Restrooms -	Remount toilet paper dispenser max 7" to 9"						
Law and Justice				from front of toilet, 15" to 48" aff and min 12"		staff				
	Citywide Facilities	1.11.3	303	above or 1.5" below grab bar	\$0.00	time	0	\$0.00	2	To be completed in FY22
			Restrooms -	-						·
			Single Users -							
Law and Justice	0		Upper Level -	6 1	# 0.00	staff	_	# 0.00	0	0
Center (Citywide Facilities	1.11.4	303	Lower mirror so reflective surface is max 40" aff Create template for signs that addresses height	\$0.00	time	0	\$0.00	2	Staff to investigate technical feasibility
Law and Justice			Signage -	of sign, size of characters, location of Braille, and		staff				
	Citywide Facilities	1.15.1	1 0	other requirements	\$0.00	time	0	\$0.00	2	Complete
								·		·
				Implement a sign revision program throughout						
Law and Justice	Oit	4 45 0		the building, discriminating between directional	#0.00	staff	0	#0.00	0	Ql-t-
Center (Citywide Facilities	1.15.2	Upper Level	signs and signs for permanent spaces	\$0.00	time	0	\$0.00	2	Complete
				Mount signage at all permanent rooms/spaces						
				having Braille and the international symbol of						
				accessibility, mounted 48" to baseline of lowest						
Law and Justice			Signage -	character and 60" to the baseline of the highest						
Center (Citywide Facilities	1.15.3	Upper Level	character sign and on the latch side of the door	\$210.00	each	18	\$3,780.00	2	Incomplete
Low and Justice			Interior Design	For all doors along the public circulation route,						
Law and Justice Center	Citywide Facilities	1.6.1	Main Level	provide required maneuvering clearance on push and pull side of doors	\$1,750.00	each	15	\$26,250.00	2	Staff to investigate technical feasibility
OCITIEI (Oitywide i adiities	1.0.1	Main Level	and pair side of doors	ψ1,730.00	Cacii	10	Ψ20,230.00		Otan to investigate technical leasibility
Law and Justice			Interior Doors	For all doors along the public circulation route,						
Center	Citywide Facilities	1.6.2	Main Level	replace door with one having 32" clear width	\$2,772.00	each	4	\$11,088.00	2	Staff to investigate technical feasibility



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit	# of units	Total cost	Phase	Notes
Site	HCC DIST	Cite	correction		Price/ unit	type	units	Total cost	Phase	Notes
Law and Justice			Interior Doors	For all doors along the public circulation route, replace hardware with lever hardware where						
Center	Citywide Facilities	1.6.3	Main Level	indicated	\$514.50	each	5	\$2,572.50	2	Incomplete
	Only made i demands			For all doors along the public circulation route,	ψοισ	54511		\$2,0.2.00		
Law and Justice				inspect, adjust, and maintain 5 lbf to open		staff				
Center	Citywide Facilities	1.6.4	Main Level	interior doors	\$0.00	time	0	\$0.00	2	On-going
Law and lustics			Interior Deers	For all doors along the public circulation route,						
Law and Justice Center	Citywide Facilities	1.6.5	Main Level	inspect, adjust, and maintain closing speed on door closers	\$0.00	staff time	0	\$0.00	2	On-going
Ochici	Oitywide i admites	1.0.0	Wall Level	For all doors along the public circulation route,	Ψ0.00	unic		ψ0.00		CH-going
Law and Justice			Interior Doors -	replace doors with ones having sidelight viewing						
Center	Citywide Facilities	1.6.6	Main Level	windows max 43" aff	\$1,386.00	each	7	\$9,702.00	2	Staff to investigate technical feasibility
Law and Justice Center	Citywide Facilities	1.6.7	Main Level	Upon renovation, make above corrections to employee only doors	\$0.00	l n/a	0	\$0.00	2	N/A
Center	Citywide Facilities	1.0.7	Iviain Levei	employee only doors	\$0.00	n/a	0	\$0.00		IN/A
Law and Justice			Public Spaces	Relocate obstacles to create turning space in		staff				
Center	Citywide Facilities	1.8.1		interview room #2 211	\$0.00	time	0	\$0.00	2	To be completed in FY22
				Relocate protruding objects in interview room						
Law and Justice	0, 1, 5, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,	400		#2 211 or place cane detectable warning or	****			4050.00	•	T
Center	Citywide Facilities	1.8.2	- Main Level	bollard at foot of shelf	\$350.00	each	1	\$350.00	2	To be completed in FY22
Law and Justice			Public Spaces							
Center	Citywide Facilities	1.8.3		Leave as is volume knobs, no longer in use	\$0.00	n/a	0	\$0.00	2	N/A
Law and Justice				Replace one table with one having required knee						
Center	Citywide Facilities	1.8.4		and toe clearances Employee only area permit approach, entry, and	\$1,120.00	each	1	\$1,120.00	2	To be completed in FY22
Law and Justice			Employee	exit, <i>relocate obstacles</i> to create AR through		staff				
Center	Citywide Facilities	1.9.1	Level	rooms indicated	\$0.00	time	0	\$0.00	2	On-going
	Onymus r domass		Employee	Employee only areas permit approach, entry, and	Ψ0.00			ψο.σσ		on genig
Law and Justice			Spaces - Main	exit, <i>relocate obstacles</i> to create turning space		staff				
Center	Citywide Facilities	1.9.2	Level	of 60" in rooms indicated	\$0.00	time	0	\$0.00	2	On-going
				For all other deficits, <i>leave as is,</i> employee work						
Law and Justice			Employee	area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works						
Center	Citywide Facilities	1.9.3	Level	here	\$0.00	n/a	0	\$0.00	2	N/A
2211121	,				70.00			70.00		
			Restrooms -							
			Mulitple Users							
Law and Justice	Citavida Facilitis	1 11 1		Restrooms not accessible, <i>acquire and mount</i>	¢240.00	aaak		¢420.00	0	To be completed in EVOC
Center	Citywide Facilities	1.11.1	238 and 240	signage directing patrons to accessible restroom	\$210.00	each	2	\$420.00	2	To be completed in FY22



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
			Restrooms -							
Law and Justice			Mulitple Users	Lower mirror in both so reflective surface is max		staff				
Center	Citywide Facilities	1.11.1	221 and 223		\$0.00	time	0	\$0.00	2	Staff to investigate technical feasibility
	,				75.55			70.00		
			Restrooms -							
				Raise sink bowl in both to provide 27" knee						
Law and Justice	04	4 44 0	- Main Level -	clearance, in the alternative, acquire a shallower	#0 200 00		0	¢4.700.00	0	Career in the standard and the standard for the standard
Center	Citywide Facilities	1.11.2	221 and 223	model	\$2,380.00	each	2	\$4,760.00	2	Staff to investigate technical feasibility
			Restrooms -							
			Mulitple Users							
Law and Justice			- Main Level -							
Center	Citywide Facilities	1.11.3	221 and 223	Insulate exposed pipes under one sink in both	\$77.00	each	2	\$154.00	2	Incomplete
			D t							
			Restrooms - Mulitple Users							
Law and Justice			- Main Level -	Lower seat covers in ambulatory stalls to max						
Center	Citywide Facilities	1.11.4		•	\$350.00	each	2	\$700.00	2	To be completed in FY22
				Create a wheelchair accessible stall with grab						
				bars and fixtures mounted in correct locations and						
				at correct heights; if technically infeasible, leave as						
Law and Justice Center	Citywide Facilities	1.11.5		is and mount signage directing users to accessible restroom	\$5,510.75	each	2	\$11,021.50	2	Staff to investigate technical feasibility
Cerilei	Citywide Facilities	1.11.5	221 and 223	Testiooni	φ5,510.75	eacii		\$11,021.50		Stall to investigate technical leasibility
			Restrooms -							
			Mulitple Users							
Law and Justice			- Main Level -	Relocate shelf to allow minimum clearance at						
Center	Citywide Facilities	1.11.6	221 and 223	men's restroom sign	\$350.00	each	1	\$350.00	2	Incomplete
			Restrooms -	Domestatide week her to make 10" from the year						
Law and Justice			Main Level -	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end,						
Center	Citywide Facilities	1.11.1	205	and 33" to 36" aff	\$393.75	each	1	\$393.75	2	Staff to investigate completion status
			Restrooms -					,		,
				Remount toilet paper dispenser max 7" to 9"						
Law and Justice	a =		Main Level -	from front of toilet, 15" to 48" aff and min 12"		staff				
Center	Citywide Facilities	1.11.2	205	above or 1.5" below grab bar	\$0.00	time	0	\$0.00	2	Staff to investigate completion status
			Restrooms -	Relocate or recess towel dispenser to not						
Law and Justice				interfere with general circulation path, protrusions						
Center	Citywide Facilities	1.11.3	205	can't be greater than 4"	\$350.00	each	1	\$350.00	2	Staff to investigate completion status
				For all doors along the public circulation route,						
Law and Justice				<i>provide</i> required maneuvering clearance on push						
Center	Citywide Facilities	1.6.1	Lower Level	and pull side of doors	\$1,750.00	each	9	\$15,750.00	2	Staff to investigate technical feasibility



Site.	LICC Diet	Cita	Type of	December detion	Deigo/comit	unit	# of	Total acat	Dhasa	Natas
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
				For all doors along the public circulation route,						
Law and Justice	6,, = ,,,,	4.0.0		correct or repair slope at doorway landing to	** ***			* 0.407.50		0. 55
Center	Citywide Facilities	1.6.2	Lower Level	max 2.08% in any direction for level CFS	\$3,062.50	each	3	\$9,187.50	2	Staff to investigate technical feasibility
Law and Justice			Interior Doors -	For all doors along the public circulation route,						
Center	Citywide Facilities	1.6.3	Lower Level	replace door with one having 32" clear width	\$2,772.00	each	2	\$5,544.00	2	Staff to investigate technical feasibility
				For all doors along the public circulation route,						
Law and Justice			Interior Doors -	replace hardware with lever hardware where						
Center	Citywide Facilities	1.6.4	Lower Level	indicated	\$514.50	each	8	\$4,116.00	2	Incomplete
				For all doors along the public circulation route,						
Law and Justice			Interior Doors -	inspect, adjust, and maintain 5 lbf to open		staff				
Center	Citywide Facilities	1.6.5	Lower Level	interior doors	\$0.00	time	0	\$0.00	2	On-going
				For all doors along the public circulation route,						
Law and Justice				inspect, adjust, and maintain closing speed on		staff				
Center	Citywide Facilities	1.6.6	Lower Level	door closers	\$0.00	time	0	\$0.00	2	On-going
				For all doors along the public circulation route,						
Law and Justice			Interior Doors -	replace doors with ones having sidelight viewing						Incomplete will be addressed during
Center	Citywide Facilities	1.6.7	Lower Level	windows max 43" aff	\$1,386.00	each	3	\$4,158.00	2	reconstruction
Law and Justice			Interior Doors -	Leave as is NE entry door clearance, power						
Center	Citywide Facilities	1.6.8	Lower Level	openers installed	\$0.00	n/a	0	\$0.00	2	N/A
Law and Justice				<i>Upon renovation</i> , make above corrections to						
Center	Citywide Facilities	1.6.9	Lower Level	employee only doors	\$0.00	n/a	0	\$0.00	2	N/A
			Employee	Employee only area permit approach, entry, and						
Law and Justice			Spaces -	exit, <i>relocate obstacles</i> to create AR through		staff				
Center	Citywide Facilities	1.9.1	Lower Level	rooms indicated	\$0.00	time	0	\$0.00	2	On-going
			Employee	Employee only areas permit approach, entry, and						
Law and Justice			Spaces -	exit, <i>relocate obstacles</i> to create turning space		staff				
Center	Citywide Facilities	1.9.2	Lower Level	of 60" in rooms indicated	\$0.00	time	0	\$0.00	2	On-going
				For all other deficits, <i>leave as is,</i> employee work						
			Employee	area pursuant to 2010 Standards 106.5 Defined						
Law and Justice			Spaces -	Terms, until an employee with a disability works						
Center	Citywide Facilities	1.9.3	Lower Level	here	\$0.00	n/a	0	\$0.00	2	N/A
			Restrooms -							
			Multiple Users							
Law and Justice	0.1 .1 5			Restroom not accessible, acquire and mount	0040.00			0040.00		T. I
Center	Citywide Facilities	1.11.1	118 and 120	signage directing patrons to accessible restroom	\$210.00	each	1	\$210.00	2	To be completed in FY22
Law and Justice	07 11 5 37	4 40 4	E.,	Create a 36" wide AR to one of each type of	40.00	staff		00.00	0	
Center	Citywide Facilities	1.16.1	Fitness	fitness equipment in the center Create a 30" by 48" "parking space" next to one	\$0.00	time	0	\$0.00	2	Incomplete
Law and Justice				of each type of fitness equipment offered in the		staff				
Center	Citavido Escilitica	1.16.2	Fitness	or each type of fitness equipment offered in the	\$0.00	time	0	\$0.00	2	Employee only energical
Center	Citywide Facilities	1.10.2	Filliess	center	φυ.υυ	unie	U	φυ.υυ	2	Employee-only operated



		l	1							
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Leo Pocha Park	Helena Citizens Council District 1	1.3.1	Playground Entry	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the playground	\$48.00	lin ft	75	\$3,600.00	СО	Complete
Leo Pocha Park	Helena Citizens Council District 1	1.3.2	Playground Entry	Mount signage to designate an entry at play area boundary as a smart practice	\$150.00	each	1	\$150.00	со	Complete
Leo Pocha Park	Helena Citizens Council District 1	1.4.1	Playground Surface	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs	\$7,500.00	each	1	\$7,500.00	2	Complete
Leo Pocha Park	Helena Citizens Council District 1	1.4.2	Playground Surface	Establish protocols for regular and frequent inspection and maintenance of accessible playground surface	\$0.00	staff time	0	\$0.00	СО	On-going
Leo Pocha Park	Helena Citizens Council District 1	1.5.1	Transfer System	See recommendation 1.3.1 for AR correction	\$0.00	n/a	0	\$0.00	СО	N/A
Leo Pocha Park	Helena Citizens Council District 1	1.5.2	Transfer System	Lower platform on transfer system to 11" to 18" aff, in the alternative, add and maintain surface fill level to achieve the same	\$250.00	each	1	\$250.00	СО	Complete
Leo Pocha Park	Helena Citizens Council District 1	1.8.1	GLPCs	See recommendation 1.4.1 for surface corrections	\$0.00	n/a	0	\$0.00	СО	N/A
Leo Pocha Park	Helena Citizens Council District 1	1.8.2	GLPCs	Leave as is, remaining GLPCs as the above correction will meet incentive scoping	\$0.00	n/a	0	\$0.00	со	N/A
Lincoln Park	Helena Citizens Council District 5	1.1.1	Parking	Create one or more 8' accessible parking stalls based on lot capacity, with one 5' adjacent access aisle, with proper signage and striping of a firm, stable, and slip resistant material	\$1,135.00	each	1	\$1,135.00	CO	Incomplete will be addressed during reconstruction
Lincoln Park	Helena Citizens Council District 5	1.2.1	Exterior Accessible Route	Install compliant detectable warning at transitions from walkways to vehicular ways as a smart practice	\$235.00	each	1	\$235.00	со	Incomplete will be addressed during reconstruction
Lincoln Park	Helena Citizens Council District 5	1.2.2	Exterior Accessible Route	Remove or relocate picnic table in AR	\$0.00	staff time	0	\$0.00	со	Complete
Lincoln Park	Helena Citizens Council District 5	1.2.3	Exterior Accessible Route	Correct or repair sidewalk cross slope along AR to max 2.08%	\$87.50	sq ft	25	\$2,187.50	СО	Incomplete will be addressed during reconstruction
Lincoln Park	Helena Citizens Council District 5	1.2.4	Exterior Accessible Route	See 1.10 below for AR to site elements	\$0.00	n/a	0	\$0.00	СО	N/A
Lincoln Park	Helena Citizens Council District 5	1.10.1	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to both sides of ball field and player seating	\$48.00	lin ft	200	\$9,600.00	со	Incomplete
Lincoln Park	Helena Citizens Council District 5	1.10.2	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the horseshoe pits	\$48.00	lin ft	50	\$2,400.00	со	Incomplete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Lincoln Park	Helena Citizens Council District 5	1.10.3	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to both sides of basketball court	\$48.00	lin ft	75	\$3,600.00	со	N/A School District property
Lincoln Park	Helena Citizens Council District 5	1.11.1	Shelters	Replace 20% of the picnic tables with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around the table as a smart practice	\$800.00	each	1	\$800.00	со	Complete
Lincoln Park	Helena Citizens Council District 5	1.11.2	Shelters	Correct or fill gaps on shelter interior	\$68.75	each	2	\$137.50	СО	Complete
Lincoln Park	Helena Citizens Council District 5	1.11.3	Shelters	Create AR with crushed and compacted stone or similar outdoor material from shelter to grill	\$48.00	lin ft	5	\$240.00	со	Incomplete
Lincoln Park	Helena Citizens Council District 5	1.12.1	Doors	For all doors along the public circulation route, <i>install</i> cement pad at exit that allows 18" clearance on the latch side, and extend a pathway away from the building for emergency egress	\$875.00	each	1	\$875.00	СО	To be completed in FY23
Lincoln Park	Helena Citizens Council District 5	1.12.2	Doors	For all doors along the public circulation route, widen doors to 32" for any doors indicated	\$1,980.00	each	4	\$7,920.00	со	Incomplete will be addressed during renovation
Lincoln Park	Helena Citizens Council District 5	1.12.3	Doors	For all doors along the public circulation route, <i>fill</i> and maintain gaps at doorways to max .5"	\$68.75	each	2	\$137.50	СО	Incomplete will be addressed during renovation
Lincoln Park	Helena Citizens Council District 5	1.12.4	Doors	For all doors along the public circulation route, repair, bevel, or ramp CIL at door entries to max .25"	\$68.75	inch	2	\$137.50	со	Incomplete will be addressed during renovation
Lincoln Park	Helena Citizens Council District 5	1.12.5	Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	1	\$367.50	со	Incomplete will be addressed during renovation
Lincoln Park	Helena Citizens Council District 5	1.12.6	Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice	\$0.00	staff time	0	\$0.00	со	On-going
Lincoln Park	Helena Citizens Council District 5	1.12.7	Doors	Upon renovation; make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	СО	N/A
Lincoln Park	Helena Citizens Council District 5	1.12.1	Rooms	Raise air unit to min 80", or pad object to prevent hazard in overhead clearance	\$110.00	each	1	\$110.00	со	Incomplete will be addressed during renovation
Lincoln Park	Helena Citizens Council District 5	1.12.2	Rooms	Lower sink height to max 34" aff	\$1,700.00	each	1	\$1,700.00	СО	Incomplete
Lincoln Park	Helena Citizens Council District 5	1.12.3	Rooms	Replace faucet controls with lever controls	\$525.00	each	1	\$525.00	СО	Incomplete
Lincoln Park	Helena Citizens Council District 5	1.12.1	Restrooms	Create two unisex single user restrooms and designate current men's as accessible	\$35,612.50	each	1	\$35,612.50	СО	Incomplete
Lockey Park	Helena Citizens Council District 6	1.1.1	Parking	Relocate stalls to be on the shortest AR to the building entry or park features	\$262.50	each	1	\$262.50	2	Staff will invesitigate feasibility of on- street designated ADA spaces
Lockey Park	Helena Citizens Council District 6	1.1.2	Parking	Paint stalls and access aisles to be 8' and 8' each	\$52.50	each	1	\$52.50	2	N/A



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
		Oite	COTTCCTION	Add one van parking sign to one accessible stall	T TIOO, UIIIC	i iyee	units	10101 0031	1 11450	110103
Lockey Park	Helena Citizens Council District 6	1.1.3	Parking	and repaint stall and access aisle to 11' and 5' or 8' and 8'	\$202.50	each	1	\$202.50	2	N/A
	Helena Citizens		Exterior							
Lockey Park	Council District 6	1.2.1	Accessible Route	Create a level landing at the top of the curb ramp, 36" deep and as wide as ramp	\$87.50	sq ft	48	\$4,200.00	3	Incomplete
	Halana Citiaana		Exterior	oo deep and de wide de famp						
Lockey Park	Helena Citizens Council District 6	1.2.2	Accessible Route	Correct slope of adjacent street surfaces to max 5%	\$87.50	sq ft	25	\$2,187.50	3	Incomplete will be addressed during reconstruction
	Helena Citizens		Exterior	Install compliant detectable warning at					_	
Lockey Park	Council District 6	1.2.3	Accessible Route	transitions from walkways to vehicular ways as a smart practice	\$235.00	each	2	\$470.00	3	Incomplete
			Exterior	Smart practice						
Lockey Park	Helena Citizens Council District 6	1.2.4	Accessible		\$68.75	each	2	\$137.50	3	Complete
	Council District 6		Route	Repair, bevel, or ramp CIL along AR						
Lockey Park	Helena Citizens	1.2.5	Exterior Accessible	Correct or renair aidowalk areas along AD	\$87.50	sq ft	125	\$10,937.50	3	Incomplete
LOCKEY FAIR	Council District 6	1.2.3	Route	Correct or repair sidewalk cross slope along AR to max 2.08%	φ67.30	Sqit	123	\$10,937.30	3	incomplete
	Helena Citizens		Exterior							
Lockey Park	Council District 6	1.2.6	Accessible	Correct or repair sidewalk running slope along	\$87.50	sq ft	150	\$13,125.00	3	Incomplete
			Route	AR to max 5%						
Lockey Park	Helena Citizens	1.3.1	Playground	Create designated entry by removing 60" portion	\$500.00	each	1	\$500.00	3	Complete
,	Council District 6	,	Entry	of play area boundary as a smart practice	,			•		- '
5 .	Helena Citizens		Playground		* 450.00			* 4 5 0 0 0		
Lockey Park	Council District 6	1.3.2	Entry	Acquire and install intended user signage and mount at designated entry as a smart practice	\$150.00	each	1	\$150.00	3	Complete
				Replace existing surface with an accessible						
Lockey Park	Helena Citizens Council District 6	1.4.1	Playground Surface	surface such as EWF, PIP or tiles, with compliant	\$7,500.00	each	1	\$7,500.00	2	Complete
	Council District 6		Surface	slopes and CILs						
	Helena Citizens		Dlovaround	Frequently inspect and regularly maintain accessible portions of play area surface that are		staff				
Lockey Park	Council District 6	1.4.2	Playground Surface	comprised of loose fill such as EWF so that	\$0.00	time	0	\$0.00	3	Complete
				surface is level with other surfaces						
	Helena Citizens		Playground	Establish protocols for regular and frequent		staff				_
Lockey Park	Council District 6	1.4.3	Surface	inspection and maintenance of accessible	\$0.00	time	0	\$0.00	3	Complete
	Helena Citizens		Playground	playground surface Repair, bevel or ramp CILs within playground				*		_
Lockey Park	Council District 6	1.4.4	Surface	and at playground entry	\$68.75	each	2	\$137.50	3	Complete
Lockey Park	Helena Citizens	1.5.1	Transfer	Consider adding second transfer system as a	\$3,550.00	each	1	\$3,550.00	3	Complete
	Council District 6		System	smart practice	40,000.00	53011	<u> </u>	40,000.00		25
Lockey Park	Helena Citizens Council District 6	1.5.2	Transfer System	Raise platform on transfer system to 11" to 18" aff	\$250.00	each	1	\$250.00	3	Complete
Lockey Park	Helena Citizens	1.8.1	GLPCs	See recommendation 1.4.1 for surface	\$0.00	n/a	0	\$0.00	3	Complete
Lockey Park	Council District 6	1.0.1	GLPUS	corrections	φυ.υυ	п/а	U	φυ.υυ	J	Complete



			Tymo of			unit	# of			
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Lockey Park	Helena Citizens Council District 6	1.8.2	GLPCs	Leave as is, remaining GLPCs as the above correction will meet incentive scoping and one of each type accessible	\$0.00	n/a	0	\$0.00	3	Complete
Lockey Park	Helena Citizens Council District 6	1.10.1	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the <u>ball field</u>	\$48.00	lin ft	75	\$3,600.00	СО	Incomplete
Lockey Park	Helena Citizens Council District 6	1.10.2	Park Site	Extend AR to grill	\$48.00	lin ft	5	\$240.00	2	Incomplete
Lockey Park	Helena Citizens Council District 6	1.10.3	Park Site	Replace or add checkerboard table with surface max 34" aff and allowing knee and toe clearance and place along AR	\$800.00	each	1	\$800.00	2	Incomplete
Lockey Park	Helena Citizens Council District 6	1.10.4	Park Site	Replace drinking fountain with a hi-lo bowl fountain	\$3,998.75	each	1	\$3,998.75	2	Complete
Lockey Park	Helena Citizens Council District 6	1.10.5	Park Site	Remove lock at one gate at tennis courts to open to min 32" and mount signage direction patrons to the accessible entry	\$150.00	each	1	\$150.00	СО	N/A gates are no longer locked
Lockey Park	Helena Citizens Council District 6	1.10.6	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the basketball court play surface	\$48.00	lin ft	25	\$1,200.00	со	Incomplete
Lockey Park	Helena Citizens Council District 6	1.10.7	Park Site	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice	\$115.00	each	1	\$115.00	2	Incomplete
Lockey Park	Helena Citizens Council District 6	1.10.8	Park Site	Adjust bench seat to 17" to 19" bench height as a smart practice	\$250.00	each	1	\$250.00	2	Complete
Lockey Park	Helena Citizens Council District 6	1.10.9	Park Site	Acquire and install at least one armrest to 20% of existing benches as a smart practice	\$70.00	each	1	\$70.00	2	Complete
Lockey Park	Helena Citizens Council District 6	1.10.10	Park Site	Replace one picnic table with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table as a smart practice	\$800.00	each	1	\$800.00	2	Complete
Lockey Park	Helena Citizens Council District 6	1.11.1	Shelters	Replace 20% of the picnic tables with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around the table as a smart practice	\$800.00	each	1	\$800.00	3	Complete
Lockey Park	Helena Citizens Council District 6	1.11.2	Shelters	Leave as is, unused storage; enlarge if renovations occur	\$0.00	n/a	0	\$0.00	3	N/A
Memorial Park	Helena Citizens Council District 5	1.1.1	Parking - Warming House	Relocate stalls to be on the shortest AR to the building entry and park features	\$262.50	each	1	\$262.50	3	Incomplete will be addressed during reconstruction
Memorial Park	Helena Citizens Council District 5	1.1.2	Parking - Warming House	Paint stalls and access aisles to be 8' and 5' each	\$52.50	each	1	\$52.50	3	Incomplete will be addressed during reconstruction



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
	Helena Citizens		Parking -	Add one van parking sign to one accessible stall				_		Incomplete will be addressed during
Memorial Park	Council District 5	1.1.3	Warming House	and repaint stall and access aisle to 11' and 5' or	\$202.50	each	1	\$202.50	3	reconstruction
			Parking -	8' and 8'						
Memorial Park	Helena Citizens Council District 5	1.1.4	Warming	Resurface stalls and access aisles to eliminate	\$2,000.00	each	1	\$2,000.00	3	Incomplete will be addressed during reconstruction
	Council District 5		House	gaps and cracks						Teconstruction
			Exterior Accessible							
Memorial Park	Helena Citizens	1.2.1	Route -		\$87.50	sq ft	16	\$1,400.00	3	Incomplete will be addressed during
Wichional Lank	Council District 5	1.2.1	Warming	Create a level landing at the top of the curb ramp,	ψον.σσ	39 11	'0	Ψ1,400.00		reconstruction
			House	36" deep and as wide as ramp						
			Exterior							
	Helena Citizens	400	Accessible		\$705.00	١.		# 705.00		Incomplete will be addressed during
Memorial Park	Council District 5	1.2.2	Route - Warming	Correct slope of curb ramp side flares to max	\$725.00	each	1	\$725.00	3	reconstruction
			House	10%						
			Exterior							
	Helena Citizens		Accessible							Incomplete will be addressed during
Memorial Park	Council District 5	1.2.3	Route -		\$725.00	each	1	\$725.00	3	reconstruction
	004.10.1 2.04.10.0		Warming House	2						, 555,151, 451,511
			Exterior	Correct curb ramp slope to max 8.33%						
			Accessible							
Memorial Park	Helena Citizens Council District 5	1.2.4	Route -		\$235.00	each	1	\$235.00	3	Incomplete will be addressed during reconstruction
	Council District 5		Warming	Install compliant detectable warning at curb						reconstruction
			House	ramps as a smart practice						
			Exterior Accessible							
Memorial Park	Helena Citizens	1.2.5	Route -		\$68.75	each	2	\$137.50	3	Incomplete will be addressed during
	Council District 5		Warming		,			,		reconstruction
			House	Repair, bevel, or ramp CIL along AR						
			Exterior							
Memorial Park	Helena Citizens	1.2.6	Accessible Route -		\$87.50	sq ft	25	\$2,187.50	3	Incomplete will be addressed during
Wellional Laik	Council District 5	1.2.0	Warming	Correct or repair sidewalk running slope along	ψ07.50	39 11	23	Ψ2,107.30	3	reconstruction
			House	AR to max 5%						
			Stairs -							
Memorial Park	Helena Citizens	1.2.1	Exterior -	Correct tread depth on stairs so they are 11"	\$288.75	each	5	\$1,443.75	3	Incomplete will be addressed during
	Council District 5		Warming House	minimum and consistent, leave as is if technically infeasible				, ,		renovation
			Stairs -	IIIIeasibie						
Managarial D. J	Helena Citizens	400	Exterior -		#00.00		_	#400.00		Incomplete will be addressed during
Memorial Park	Council District 5	1.2.2	Warming	Provide visual contrast on leading 2" of each	\$20.00	each	5	\$100.00	3	renovation
			House	tread on stairs						



		I	1			I				
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Memorial Park	Helena Citizens Council District 5	1.2.3	Stairs - Exterior - Warming House	<i>Install</i> detectable warning strip on top tread of each stairway as a smart practice	\$150.00	each	1	\$150.00	3	Incomplete will be addressed during renovation
Memorial Park	Helena Citizens Council District 5	1.2.4	Stairs - Exterior - Warming House	Replace handrails on both sides of stairway, mounted 34" to 38" aff with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max	\$700.00	each	1	\$700.00	3	Incomplete will be addressed during renovation
Memorial Park	Helena Citizens Council District 5	1.2.1	Ramps - Exterior - Warming House	Correct ramp cross slope to max 2.08%	\$87.50	sq ft	90	\$7,875.00	3	Incomplete will be addressed during renovation
Memorial Park	Helena Citizens Council District 5	1.2.2	Ramps - Exterior - Warming House	Enlarge landing to be 60" deep and as wide as the ramp	\$1,250.00	each	1	\$1,250.00	3	Incomplete will be addressed during renovation
Memorial Park	Helena Citizens Council District 5	1.2.3	Ramps - Exterior - Warming House	Install compliant handrails on both sides of the ramp having min 1.5" clearance between rail and adjacent surface	\$700.00	each	1	\$700.00	3	Incomplete will be addressed during renovation
Memorial Park	Helena Citizens Council District 5	1.4.1	Exterior Doors - Warming House	For all doors along the public circulation route, <i>repair, bevel, or ramp CIL</i> at door entries to max .25"	\$68.75	each	1	\$68.75	3	Incomplete will be addressed during renovation
Memorial Park	Helena Citizens Council District 5	1.4.2	Exterior Doors - Warming House	For all doors along the public circulation route, <i>inspect, adjust, and maintain</i> 8.5 lbf to open exterior doors as a smart practice	\$0.00	staff time	0	\$0.00	3	On-going
Memorial Park	Helena Citizens Council District 5	1.4.3	Exterior Doors - Warming House	For all doors along the public circulation route, <i>inspect, adjust, and maintain</i> closing speed on door closers	\$0.00	staff time	0	\$0.00	3	Incomplete will be addressed during renovation
Memorial Park	Helena Citizens Council District 5	1.4.4	Exterior Doors - Warming House	For all doors along the public circulation route, <i>replace doors</i> with ones having sidelight viewing windows max 43" aff	\$990.00	each	1	\$990.00	3	Incomplete will be addressed during renovation
Memorial Park	Helena Citizens Council District 5	1.4.5	Exterior Doors - Warming House	For employee only doors; make above corrections upon renovation	\$0.00	n/a	0	\$0.00	3	N/A
Memorial Park	Helena Citizens Council District 5	1.6.1	Interior Doors Warming House	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	1	\$1,250.00	3	Incomplete will be addressed during renovation



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Memorial Park	Helena Citizens Council District 5	1.6.2	Interior Doors - Warming House	For all doors along the public circulation route, secure carpet at interior doors	\$100.00	each	2	\$200.00	3	Incomplete will be addressed during renovation
Memorial Park	Helena Citizens Council District 5	1.6.3	Interior Doors Warming House	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	2	\$735.00	3	Incomplete will be addressed during renovation
Memorial Park	Helena Citizens Council District 5	1.6.4	Interior Doors - Warming House	For employee only doors; make above corrections upon renovation	\$0.00	n/a	0	\$0.00	3	N/A
Memorial Park	Helena Citizens Council District 5	1.8.1	Public Spaces - Warming House	Relocate protruding objects in main room or place cane detectable warning or bollard at foot of skate cubbies	\$150.00	each	1	\$150.00	3	Incomplete will be addressed during renovation
Memorial Park	Helena Citizens Council District 5	1.8.2	Public Spaces - Warming House	Lower operating mechanisms to max 48" aff to highest operable part; leave as is if employee only operated	\$250.00	each	1	\$250.00	3	Incomplete will be addressed during renovation
Memorial Park	Helena Citizens Council District 5	1.8.3	Public Spaces - Warming House	Lower sink height to max 34" aff	\$1,700.00	each	1	\$1,700.00	3	Incomplete will be addressed during renovation
Memorial Park	Helena Citizens Council District 5	1.9.1	Employee Spaces - Warming House	Employee only area permit approach, entry, and exit, <i>relocate obstacles</i> to create AR through skate sharpening, lower level, and storage	\$0.00	staff time	0	\$0.00	3	On-going
Memorial Park	Helena Citizens Council District 5	1.9.2	Employee Spaces - Warming House	Employee only areas permit approach, entry, and exit, <i>relocate obstacles</i> to create turning space of 60" in skate sharpening	\$0.00	staff time	0	\$0.00	3	On-going
Memorial Park	Helena Citizens Council District 5	1.9.3	Employee Spaces - Warming House	For all other deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	3	N/A
Memorial Park	Helena Citizens Council District 5	1.11.1	Restrooms - Multiple Users - Warming House	Upon renovation, reconfigure restrooms to have a 36" access aisle, 60" turning space, and a wheelchair stall with grab bars and fixtures mounted in correct locations and at correct heights	\$5,925.00	each	2	\$11,850.00	3	Incomplete will be addressed during renovation
Memorial Park	Helena Citizens Council District 5	1.1.1	Parking - Memorial Park	Repair or correct slope of parking space and access aisle to max 2.08% in any direction	\$2,187.50	each	2	\$4,375.00	3	Incomplete will be addressed during reconstruction



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Memorial Park	Helena Citizens Council District 5	1.1.2	Parking - Memorial Park	Resurface stalls and access aisles to eliminate gaps and cracks	\$2,000.00	each	1	\$2,000.00	3	To be completed in FY23
Memorial Park	Helena Citizens Council District 5	1.1.3	Parking - Memorial Park	Add one van parking sign to one accessible stall and repaint stall and access aisle to 11' and 5' or 8' and 8'	\$202.50	each	1	\$202.50	3	To be completed in FY23
Memorial Park	Helena Citizens Council District 5	1.2.1	Exterior Accessible Route - Memorial Park	Correct slope of curb ramp side flares to max 10%	\$725.00	each	1	\$725.00	3	Incomplete will be addressed during reconstruction
Memorial Park	Helena Citizens Council District 5	1.2.2	Exterior Accessible Route - Memorial Park	Correct curb ramp slope to max 8.33%	\$725.00	each	1	\$725.00	3	Incomplete will be addressed during reconstruction
Memorial Park	Helena Citizens Council District 5	1.2.3	Exterior Accessible Route - Memorial Park	Install compliant detectable warning at transitions from walkways to vehicular ways as a smart practice	\$235.00	each	1	\$235.00	3	Incomplete will be addressed during reconstruction
Memorial Park	Helena Citizens Council District 5	1.2.4	Exterior Accessible Route - Memorial Park	Repair, bevel, or ramp CIL along AR	\$68.75	each	1	\$68.75	3	Complete
Memorial Park	Helena Citizens Council District 5	1.2.5	Exterior Accessible Route - Memorial Park	Correct or fill gaps along AR	\$68.75	each	1	\$68.75	3	Complete
Memorial Park	Helena Citizens Council District 5	1.2.6	Exterior Accessible Route - Memorial Park	Correct or repair sidewalk cross slope along AR to max 2.08%	\$87.50	sq ft	50	\$4,375.00	3	Incomplete
Memorial Park	Helena Citizens Council District 5	1.2.7	Exterior Accessible Route - Memorial Park	Correct or repair sidewalk running slope along AR to max 5%	\$87.50	sq ft	50	\$4,375.00	3	Incomplete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Memorial Park	Helena Citizens Council District 5	1.2.8	Exterior Accessible Route - Memorial Park	See 1.10 below for AR to site elements	\$0.00	n/a	0	\$0.00	3	N/A
Memorial Park	Helena Citizens Council District 5	1.3.1	Playground Entry - Memorial Park	Acquire and install intended user signage and mount at designated entry as a smart practice	\$150.00	each	1	\$150.00	СО	Complete
Memorial Park	Helena Citizens Council District 5	1.4.1	Playground Surface - Memorial Park	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs	\$7,500.00	each	1	\$7,500.00	2	Complete
Memorial Park	Helena Citizens Council District 5	1.4.2	Playground Surface - Memorial Park	Repair, bevel or ramp CILs within playground and at playground entry	\$68.75	each	1	\$68.75	СО	Complete
Memorial Park	Helena Citizens Council District 5	1.4.3	Playground Surface - Memorial Park	Establish protocols for regular and frequent inspection and maintenance of accessible playground surface	\$0.00	staff time	0	\$0.00	СО	Complete
Memorial Park	Helena Citizens Council District 5	1.5.1	Transfer System - Memorial Park	<i>Install</i> transfer supports on 2 to 5 transfer platform	\$750.00	each	1	\$750.00	СО	Complete
Memorial Park	Helena Citizens Council District 5	1.5.2	Transfer System - Memorial Park	<i>Install</i> descending step on 2 to 5 transfer system as a smart practice	\$500.00	each	1	\$500.00	СО	Complete
Memorial Park	Helena Citizens Council District 5	1.5.3	Transfer System - Memorial Park	Consider adding second 5 to 12 transfer system as a smart practice	\$3,550.00	each	1	\$3,550.00	СО	Complete
Memorial Park	Helena Citizens Council District 5	1.5.4	Transfer System - Memorial Park	Lower platform on 5 to 12 transfer system to 11" to 18" aff, in the alternative, add and maintain surface fill level to achieve the same	\$250.00	each	1	\$250.00	со	Complete
Memorial Park	Helena Citizens Council District 5	1.6.1	Playground Ramps - Memorial Park	Inspect ramp segments and adjust or raise segments to achieve ramp slope of max 8.33%	\$1,000.00	each	3	\$3,000.00	со	Complete
Memorial Park	Helena Citizens Council District 5	1.6.2	Playground Ramps - Memorial Park	Replace handrails with compliant handrails	\$700.00	each	1	\$700.00	со	To be completed in FY22



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Memorial Park	Helena Citizens Council District 5	1.8.1	GLPCs - Memorial Park	See recommendation 1.4.1 for surface corrections for both	\$0.00	n/a	0	\$0.00	со	N/A
Memorial Park	Helena Citizens Council District 5	1.8.2	GLPCs - Memorial Park	Leave as is, remaining GLPCs on both as the above correction will meet incentive scoping	\$0.00	n/a	0	\$0.00	СО	N/A
Memorial Park	Helena Citizens Council District 5	1.10.1	Park Site - Memorial Park	Create ramped access to memorial wall	\$155.00	inch	21	\$3,255.00	3	N/A site managed in accordance with an MOU with veteran's group
Memorial Park	Helena Citizens Council District 5	1.10.2	Park Site - Memorial Park	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the swinging benches	\$48.00	lin ft	100	\$4,800.00	3	Incomplete
Memorial Park	Helena Citizens Council District 5	1.10.3	Park Site - Memorial Park	Install rail along bottom edge of flagpole memorial ramp that prevents a 4" sphere from passing through	\$350.00	each	1	\$350.00	3	N/A site managed in accordance with an MOU with veteran's group
Memorial Park	Helena Citizens Council District 5	1.10.4	Park Site - Memorial Park	Correct slope of band shell ramp to max 8.33%	\$87.50	sq ft	180	\$15,750.00	3	Staff to investigate technical feasibility
Memorial Park	Helena Citizens Council District 5	1.10.5	Park Site - Memorial Park	Replace handrails on both sides of ramp at band shell ramp with ones that are rounded and/or extend to the ground, with handrail extensions and mounted 34" to 38" aff	\$700.00	each	1	\$700.00	3	Complete
Memorial Park	Helena Citizens Council District 5	1.10.6	Park Site - Memorial Park	Replace <u>drinking fountain</u> with a hi-lo bowl fountain	\$3,998.75	each	1	\$3,998.75	3	Drinking fountain has been removed
Memorial Park	Helena Citizens Council District 5	1.10.7	Park Site - Memorial Park	Relocate 20% of garbage cans to be along AR	\$0.00	staff time	0	\$0.00	3	Complete
Memorial Park	Helena Citizens Council District 5	1.10.8	Park Site - Memorial Park	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, add at least one armrest and locate along an AR as a smart practice	\$185.00	each	3	\$555.00	3	Complete
Memorial Park	Helena Citizens Council District 5	1.10.9	Park Site - Memorial Park	Raise bench seat to 17" to 19" as a smart practice	\$250.00	each	1	\$250.00	3	Complete
Memorial Park	Helena Citizens Council District 5	1.10.10	Park Site - Memorial Park	Replace 20% of the <u>picnic tables</u> with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around the table as a smart practice	\$800.00	each	4	\$3,200.00	3	Complete
Memorial Park	Helena Citizens Council District 5	1.12.1	Doors - Memorial Park	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	2	\$735.00	3	Complete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Memorial Park	Helena Citizens Council District 5	1.12.1	Restrooms - Memorial Park	Acquire and mount signage for both, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character	\$150.00	each	2	\$300.00	3	Incomplete
Memorial Park	Helena Citizens Council District 5	1.12.2	Restrooms - Memorial Park	Insulate exposed pipes under one sink in both	\$55.00	each	2	\$110.00	3	Complete
Memorial Park	Helena Citizens Council District 5	1.12.3	Restrooms - Memorial Park	Remount side grab bars in both to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff	\$281.25	each	2	\$562.50	3	Complete
Memorial Park	Helena Citizens Council District 5	1.12.4	Restrooms - Memorial Park	Remount rear grab bars in both to behind the toilet, 12" to one side of center and 24" to the other and 33" to 36" aff	\$281.25	each	2	\$562.50	3	Complete
Memorial Park	Helena Citizens Council District 5	1.12.5	Restrooms - Memorial Park	Acquire and mount vertical grab bar for both, min 18" in length and mounted so the bottom is between 39" and 41" from the floor and the centerline between 39" and 41" from rear wall	\$281.25	each	2	\$562.50	3	Complete
Memorial Park	Helena Citizens Council District 5	1.12.6	Restrooms - Memorial Park	Adjust stall doors in both to be self-closing	\$0.00	staff time	0	\$0.00	3	Complete
Memorial Park	Helena Citizens Council District 5	1.12.7	Restrooms - Memorial Park	Acquire and install exterior stall door hardware operable without a tight pinch or grasp in both	\$100.00	each	2	\$200.00	3	Complete
Memorial Park	Helena Citizens Council District 5	1.12.8	Restrooms - Memorial Park	Remount toilet paper dispensers in both max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	\$0.00	staff time	0	\$0.00	3	Complete
Memorial Park	Helena Citizens Council District 5	1.12.9	Restrooms - Memorial Park	Relocate or recess hand dryers in both to not interfere with general circulation path, protrusions can't be greater than 4"	\$250.00	each	2	\$500.00	3	Complete
Memorial Park	Helena Citizens Council District 5	1.12.10	Restrooms - Memorial Park	Lower mirror in women's so reflective surface is max 40" aff	\$0.00	staff time	0	\$0.00	3	Complete
Mount Helena Park - Trailhead	Helena Citizens Council District 1	1.1.1	Parking	Create two or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping	\$1,135.00	each	2	\$2,270.00	со	Complete
Mount Helena Park - Trailhead	Helena Citizens Council District 1	1.10.1	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to trail head	\$48.00	lin ft	50	\$2,400.00	со	Complete
Mount Helena Park - Trailhead	Helena Citizens Council District 1	1.10.2	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to info kiosk	\$48.00	lin ft	50	\$2,400.00	со	Complete
Mount Helena Park - Trailhead	Helena Citizens Council District 1	1.10.3	Park Site	Lower operating mechanisms at info kiosk to max 48" aff to highest operable part	\$250.00	each	1	\$250.00	СО	Staff to investigate completion status



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Mount Helena Park - Trailhead	Helena Citizens Council District 1	1.10.4	Park Site	Relocate 20% of garbage cans to be along AR	\$0.00	staff time	0	\$0.00	со	Complete
Mount Helena Park - Trailhead	Helena Citizens Council District 1	1.10.5	Park Site	Relocate dog waste bag dispenser to be along AR	\$0.00	staff time	0	\$0.00	со	Complete
Mount Helena Park - Trailhead	Helena Citizens Council District 1	1.10.6	Park Site	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along an AR as a smart practice	\$115.00	each	1	\$115.00	со	Staff to investigate completion status
Mount Helena Park - Trailhead	Helena Citizens Council District 1	1.10.7	Park Site	Acquire and install at least one armrest to 20% of existing benches as a smart practice	\$70.00	each	1	\$70.00	со	Complete
Mount Helena Park - Trailhead	Helena Citizens Council District 1	1.10.8	Park Site	Replace or add one <u>picnic table</u> with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table as a smart practice	\$800.00	each	1	\$800.00	со	Complete
Mount Helena Park - Trailhead	Helena Citizens Council District 1	1.12.1	Doors	For all doors along the public circulation route, widen pathway approaching entry to extend 18" beyond latch side of door for maneuvering clearance	\$875.00	each	2	\$1,750.00	СО	Complete
Mount Helena Park - Trailhead	Helena Citizens Council District 1	1.12.2	Doors	For all doors along the public circulation route, repair, bevel, or ramp CIL in doorway maneuvering clearance to max .25"	\$68.75	each	2	\$137.50	со	Complete
Mountain View Park	Helena Citizens Council District 7	1.2.1	Exterior Accessible Route	Correct slope of curb ramp side flares to max 10%	\$725.00	each	4	\$2,900.00	2	Complete
Mountain View Park	Helena Citizens Council District 7	1.2.2	Exterior Accessible Route	Correct or repair sidewalk running slope along AR to max 5%	\$87.50	sq ft	375	\$32,812.50	2	Complete
Mountain View Park	Helena Citizens Council District 7	1.2.3	Exterior Accessible Route	See 1.10 below for AR to site elements	\$0.00	n/a	0	\$0.00	2	N/A
Mountain View Park	Helena Citizens Council District 7	1.3.1	Playground Entry	Repair, bevel or ramp CIL at playground entry	\$68.75	each	1	\$68.75	3	Complete
Mountain View Park	Helena Citizens Council District 7	1.3.2	Playground Entry	Acquire and install intended user signage and mount at designated entry as a smart practice	\$150.00	each	1	\$150.00	3	Complete
Mountain View Park	Helena Citizens Council District 7	1.4.1	Playground Surface	Fill and compact EWF surface so that it maintains its accessibility characteristics	\$5,000.00	each	1	\$5,000.00	2	Complete
Mountain View Park	Helena Citizens Council District 7	1.4.2	Playground Surface	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces	\$0.00	staff time	0	\$0.00	2	Complete
Mountain View Park	Helena Citizens Council District 7	1.4.3	Playground Surface	Establish protocols for regular and frequent inspection and maintenance of accessible playground surface	\$0.00	staff time	0	\$0.00	2	Complete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Mountain View Park	Helena Citizens Council District 7	1.5.1	Transfer System	Raise platform on transfer system to 11" to 18"	\$250.00	each	1	\$250.00	3	Complete
Mountain View Park	Helena Citizens Council District 7	1.10.1	Park Site	Adjust gate at tennis to open to 90 degrees	\$0.00	staff time	0	\$0.00	СО	Complete
Mountain View Park	Helena Citizens Council District 7	1.10.2	Park Site	Widen pathway approaching tennis court gate to extend 18" beyond latch side of door for maneuvering clearance	\$875.00	each	1	\$875.00	со	Complete
Mountain View Park	Helena Citizens Council District 7	1.10.3	Park Site	Correct or repair slope at tennis court gate landing to max 2.08% in any direction for level CFS	\$2,187.50	each	1	\$2,187.50	со	Complete
Mountain View Park	Helena Citizens Council District 7	1.10.4	Park Site	Repair, bevel, or ramp CIL at dog park entry to max .25"	\$68.75	each	1	\$68.75	2	Complete
Mountain View Park	Helena Citizens Council District 7	1.10.5	Park Site	Replace dog park surface with crushed and compacted stone or similar outdoor material	\$1,000.00	each	1	\$1,000.00	2	Complete
Mountain View Park	Helena Citizens Council District 7	1.10.6	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to volleyball	\$48.00	lin ft	40	\$1,920.00	2	Complete
Mountain View Park	Helena Citizens Council District 7	1.10.7	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the first hole at the disc golf course	\$48.00	lin ft	100	\$4,800.00	2	Incomplete
Mountain View Park	Helena Citizens Council District 7	1.10.8	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the horseshoes	\$48.00	lin ft	50	\$2,400.00	2	Complete
Mountain View Park	Helena Citizens Council District 7	1.10.9	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the amphitheater spectator seating	\$48.00	lin ft	25	\$1,200.00	2	Complete
Mountain View Park	Helena Citizens Council District 7	1.10.10	Park Site	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, add at least one armrest and locate along an AR as a smart practice	\$115.00	each	2	\$230.00	2	Complete
Mountain View Park	Helena Citizens Council District 7	1.10.11	Park Site	Relocate <u>picnic table</u> to a location with a 36" AR around table as a smart practice	\$0.00	staff time	0	\$0.00	2	Complete
Nature Park	Helena Citizens Council District 4	1.1.1	Parking	Create one or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping	\$1,135.00	each	1	\$1,135.00	3	Complete
Nature Park	Helena Citizens Council District 4	1.10.1	Park Site	Relocate 20% of garbage cans to be along AR	\$0.00	n/a	0	\$0.00	2	Complete
Neighborhood Center	Citywide Facilities	1.1.1	Parking	Create two or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping	\$1,135.00	each	2	\$2,270.00	2	Complete
Neighborhood Center	Citywide Facilities	1.1.2	Parking	Repaint stalls and add access aisles to be 8' and 5' each	\$52.50	each	3	\$157.50	2	Complete



Site	HCC Dist	Cite	Type of correction	Recommendation	Drice/ unit	unit	# of	Total cost	Phase	Notes
Site	ncc bist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Neighborhood Center	Citywide Facilities	1.1.3	Parking	Repair or correct slope of parking spaces and access aisles to max 2.08% in any direction	\$2,187.50	each	3	\$6,562.50	2	Complete
Neighborhood Center	Citywide Facilities	1.1.4	Parking	Resurface stalls and access aisles to eliminate gaps and cracks	\$2,000.00	each	2	\$4,000.00	2	Complete
Neighborhood Center	Citywide Facilities	1.1.5	Parking	Raise existing accessible parking signs so lowest end of bottom sign is min 60" aff	\$0.00	staff time	0	\$0.00	2	Complete
Neighborhood Center	Citywide Facilities	1.2.1	Exterior Accessible Route	Install compliant detectable warning at transitions from walkways to vehicular ways as a smart practice	\$235.00	each	1	\$235.00	2	Complete
Neighborhood Center	Citywide Facilities	1.2.2	Exterior Accessible Route	Repair, bevel, or ramp CIL along AR	\$68.75	each	1	\$68.75	2	Complete
Neighborhood Center	Citywide Facilities	1.2.3	Exterior Accessible Route	Correct or repair sidewalk cross slope along AR to max 2.08%	\$87.50	sq ft	25	\$2,187.50	2	Complete
Neighborhood Center	Citywide Facilities	1.2.4	Exterior Accessible Route	Correct or repair sidewalk running slope along AR to max 5%	\$87.50	sq ft	25	\$2,187.50	2	Complete
Neighborhood Center	Citywide Facilities	1.2.5	Exterior Accessible Route	Provide cane detectable warning at base of air conditioner along the AR	\$150.00	each	1	\$150.00	2	Complete
Neighborhood Center	Citywide Facilities	1.3.1	Exterior Signage	Mount signage at entrance designating it as accessible	\$150.00	each	1	\$150.00	2	Complete
Neighborhood Center	Citywide Facilities	1.4.1	Exterior Doors	For all doors along the public circulation route, correct or repair slope at doorway landing to max 2.08% in any direction for level CFS	\$2,187.50	each	2	\$4,375.00	2	Complete
Neighborhood Center	Citywide Facilities	1.4.2	Exterior Doors	For all doors along the public circulation route, relocate storage, furniture, and other obstacles to create 60" maneuvering space around doors	\$0.00	staff time	0	\$0.00	2	On-going
Neighborhood Center	Citywide Facilities	1.4.3	Exterior Doors	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	3	\$3,750.00	2	Complete
Neighborhood Center	Citywide Facilities	1.4.4	Exterior Doors	For all doors along the public circulation route, repair, bevel, or ramp CIL at door entries to max .25"	\$68.75	inch	6	\$412.50	2	Complete
Neighborhood Center	Citywide Facilities	1.4.5	Exterior Doors	For all doors along the public circulation route, <i>fill</i> and maintain gaps at doorways to max .5"	\$68.75	each	1	\$68.75	2	Complete
Neighborhood Center	Citywide Facilities	1.4.6	Exterior Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	3	\$1,102.50	2	Complete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Neighborhood Center	Citywide Facilities	1.4.7	Exterior Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice	\$0.00	staff time	0	\$0.00	2	On-going
Neighborhood Center	Citywide Facilities	1.4.8	Exterior Doors	For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers	\$0.00	staff time	0	\$0.00	2	On-going
Neighborhood Center	Citywide Facilities	1.4.9	Exterior Doors	For all doors along the public circulation route, <i>install a power door opener</i> that opens both sets of doors simultaneously, keeping them open for an adequate amount of time to allow patrons entry, in the alternative, relocate second set of doors at least 80" from the first set	\$1,353.75	each	2	\$2,707.50	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.4.10	Exterior Doors	Upon renovation ; make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	2	N/A
Neighborhood Center	Citywide Facilities	1.5.1	Elevator	Remount call buttons to max 48" to the center	\$675.00	each	3	\$2,025.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.5.2	Elevator	Remount handrails to 32" to 36" aff	\$151.25	each	1	\$151.25	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.5.3	Elevator	Replace communication system with one operable without voice communication and adjust operable part to max 5 lbf to use	\$5,668.75	each	1	\$5,668.75	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.5.4	Elevator	Leave as is, interior dimension; infeasible to correct	\$0.00	n/a	0	\$0.00	2	N/A
Neighborhood Center	Citywide Facilities	1.6.1	Interior Doors - Top Floor	For all doors along the public circulation route, relocate storage, furniture, and other obstacles to create 60" maneuvering space around doors	\$0.00	staff time	0	\$0.00	2	On-going
Neighborhood Center	Citywide Facilities	1.6.2	Interior Doors - Top Floor	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	4	\$5,000.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.6.3	Interior Doors - Top Floor	Leave as is, maneuvering clearance in closet or storage, correction is technically infeasible	\$0.00	n/a	0	\$0.00	2	N/A
Neighborhood Center	Citywide Facilities	1.6.4	Interior Doors - Top Floor	For all doors along the public circulation route, replace door with one having 32" clear width	\$1,980.00	each	1	\$1,980.00	2	Incomplete will be addressed during renovation
Neighborhood Center	Citywide Facilities	1.6.5	Interior Doors - Top Floor	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	38	\$13,965.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.6.6	Interior Doors - Top Floor	For all doors along the public circulation route, relocate hardware mounted 34" to 48" aff	\$250.00	each	1	\$250.00	2	Staff to investigate completion status



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Neighborhood Center	Citywide Facilities	1.6.7	Interior Doors - Top Floor	For all doors along the public circulation route, relocate storage, furniture, and other obstacles from CFS at power door controls	\$0.00	staff time	0	\$0.00	2	On-going
Neighborhood Center	Citywide Facilities	1.6.8	Interior Doors - Top Floor	For all doors along the public circulation route, <i>inspect, adjust, and maintain</i> 5 lbf to open interior doors	\$0.00	staff time	0	\$0.00	2	On-going
Neighborhood Center	Citywide Facilities	1.6.9	Interior Doors - Top Floor	For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers	\$0.00	staff time	0	\$0.00	2	On-going
Neighborhood Center	Citywide Facilities	1.6.10	Interior Doors - Top Floor	For all doors along the public circulation route, replace doors with ones having sidelight viewing windows max 43" aff	\$990.00	each	2	\$1,980.00	2	Incomplete will be addressed during renovation
Neighborhood Center	Citywide Facilities	1.6.11	Interior Doors - Top Floor	For employee only doors; make above corrections upon renovation	\$0.00	n/a	0	\$0.00	2	N/A
Neighborhood Center	Citywide Facilities	1.7.1	Interior Accessible Route - Top Floor	See 1.4 above for correction to exterior doors	\$0.00	n/a	0	\$0.00	2	N/A
Neighborhood Center	Citywide Facilities	1.7.2	Interior Accessible Route - Top Floor	Remove and relocate storage to maintain 36" clearance in hallway	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.7.3	Interior Accessible Route - Top Floor	Lower operating mechanisms along the interior AR to max 48" aff to the highest operable part	\$250.00	each	4	\$1,000.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.7.4	Interior Accessible Route - Top Floor	Remove, or relocate storage in CFS at fixtures and operable parts along the AR	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.7.5	Interior Accessible Route - Top Floor	Relocate protruding objects along the interior AR or place cane detectable warning or bollard at foot of protrusions	\$250.00	each	2	\$500.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.7.6	Interior Accessible Route - Top Floor	Replace drinking fountains with hi-lo bowl fountains	\$3,998.75	each	5	\$19,993.75	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.7.7	Interior Accessible Route - Top Floor	Remove or relocate storage in CFS at drinking fountains	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Neighborhood Center	Citywide Facilities	1.7.1	Stairs - Top Floor	Correct riser heights on stairs to consistent height between 4" to 7", leave as is if technically infeasible	\$288.75	each	42	\$12,127.50	2	N/A technically infeasible
Neighborhood Center	Citywide Facilities	1.7.2	Stairs - Top Floor	Install detectable warning strip on top tread of each stairway as a smart practice	\$150.00	each	3	\$450.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.7.3	Stairs - Top Floor	Create visual contrast at leading 2" edge of treads	\$20.00	each	42	\$840.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.7.4	Stairs - Top Floor	Secure carpet on stairs to prevent trip hazard	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.7.5	Stairs - Top Floor	Correct tread depth on stairs to 11" minimum and consistent, leave as is if technically infeasible	\$288.75	each	28	\$8,085.00	2	N/A technically infeasible
Neighborhood Center	Citywide Facilities	1.7.6	Stairs - Top Floor	Install handrails on both sides of stairway, mounted 34" to 38" aff with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max	\$700.00	each	3	\$2,100.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.8.1	Public Spaces - Top Floor	Relocate obstacles to create AR through spaces indicated	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.8.2	Public Spaces - Top Floor	Relocate obstacles to create turning space in spaces indicated	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.8.3	Public Spaces - Top Floor	Relocate protruding objects in spaces indicated or place cane detectable warning or bollard at foot of protrusions	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.8.4	Public Spaces - Top Floor	Remove, or relocate storage in CFS at fixtures and operable parts	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.8.5	Public Spaces - Top Floor	Lower operating mechanisms in spaces indicated to max 48" aff to highest operable part; leave as is if employee only operated	\$250.00	each	4	\$1,000.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.8.6	Public Spaces - Top Floor	Replace operable parts to be operable without a tight pinch or grasp	\$100.00	each	2	\$200.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.8.7	Public Spaces - Top Floor	Replace work surface with one that provides required knee clearance	\$800.00	each	1	\$800.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.8.8	Public Spaces - Top Floor	Lower sink height to max 34" aff	\$1,700.00	each	1	\$1,700.00	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.9.1	Employee Spaces - Top Floor	Employee only area permit approach, entry, and exit, <i>relocate obstacles</i> to create AR through spaces indicated	\$0.00	staff time	0	\$0.00	2	On-going



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Neighborhood Center	Citywide Facilities	1.9.2	Employee Spaces - Top Floor	Employee only areas permit approach, entry, and exit, <i>relocate obstacles</i> to create turning space of 60" in spaces indicated	\$0.00	staff time	0	\$0.00	2	On-going
Neighborhood Center	Citywide Facilities	1.9.3	Employee Spaces - Top Floor	For all other deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	2	N/A
Neighborhood Center	Citywide Facilities	1.11.1	Restrooms - Multiple Users - Top Floor	Restroom not accessible, <i>acquire and mount</i> signage directing patrons to accessible restroom at both until renovated	\$150.00	each	2	\$300.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.11.2	Restrooms - Multiple Users - Top Floor	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character at both	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.11.3	Restrooms - Multiple Users - Top Floor	Lower mirror so reflective surface is max 40" aff in both	\$0.00	staff time	0	\$0.00	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.11.4	Restrooms - Multiple Users - Top Floor	Lower hooks in accessible stalls to max 48" aff in both	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.11.5	Restrooms - Multiple Users - Top Floor	Lower tampon dispenser to max 48" to highest operable part in women's	\$250.00	each	1	\$250.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.11.6	Restrooms - Multiple Users - Top Floor	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights in both	\$3,936.25	each	2	\$7,872.50	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.11.7	Restrooms - Multiple Users - Top Floor	Relocate or recess protrusions to not interfere with general circulation path in both, protrusions can't be greater than 4"	\$250.00	each	2	\$500.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.11.8	Restrooms - Multiple Users - Top Floor	Insulate exposed pipes under one sink in men's	\$55.00	each	1	\$55.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.11.9	Restrooms - Multiple Users - Top Floor	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" aff in men's	\$2,127.50	each	1	\$2,127.50	2	Staff to investigate technical feasibility



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Neighborhood Center	Citywide Facilities	1.11.10	Restrooms - Multiple Users - Top Floor	Raise sink bowl to provide 27" knee clearance, in the alternative, acquire a shallower model in women's	\$1,700.00	each	1	\$1,700.00	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.11.11	Restrooms - Multiple Users - Top Floor	Relocate baby changing table to provide required CFS in women's	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.11.1	Restrooms - Single Users - Top Floor	Restroom not accessible, acquire and mount signage directing patrons to accessible restroom until renovated	\$150.00	each	1	\$150.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.11.2	Restrooms - Single Users - Top Floor	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.11.3	Restrooms - Single Users - Top Floor	Leave as is, lack of clearance around toilet, correction may be technically infeasible	\$0.00	n/a	0	\$0.00	2	N/A
Neighborhood Center	Citywide Facilities	1.11.4	Restrooms - Single Users - Top Floor	Replace toilet seat, or re-set or replace toilet to 17" to 19" aff	\$1,306.00	each	1	\$1,306.00	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.11.5	Restrooms - Single Users - Top Floor	Acquire and mount grab bars of compliant dimension and mounted in correct locations	\$281.25	each	1	\$281.25	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.11.6	Restrooms - Single Users - Top Floor	Replace toilet tank with one having flush mechanism on the open side, in the alternative, install an auto flush unit	\$211.25	each	1	\$211.25	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.11.7	Restrooms - Single Users - Top Floor	Lower mirror so reflective surface is max 40" aff	\$0.00	staff time	0	\$0.00	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.11.8	Restrooms - Single Users - Top Floor	Insulate exposed pipes under sink	\$55.00	each	1	\$55.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.11.9	Restrooms - Single Users - Top Floor	Lower hook to max 48" aff	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.11.10	Restrooms - Single Users - Top Floor	Relocate or recess towel dispenser and cabinet to not interfere with general circulation path, protrusions can't be greater than 4"	\$250.00	each	2	\$500.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.12.1	Kitchen - Top Floor	Relocate tables to provide 36" route throughout	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.12.2	Kitchen - Top Floor	Lower sink heights to max 34" aff	\$1,700.00	each	4	\$6,800.00	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.12.3	Kitchen - Top Floor	Insulate exposed pipes under sinks	\$55.00	each	4	\$220.00	2	Staff to investigate completion status



						Ι	<u> </u>			
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Neighborhood Center	Citywide Facilities	1.12.4	Kitchen - Top Floor	Provide knee clearance at one of each type of sink	\$785.00	each	4	\$3,140.00	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.12.5	Kitchen - Top Floor	Raise oven hood to min 80", or pad object to prevent hazard in overhead clearance	\$250.00	each	1	\$250.00	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.12.6	Kitchen - Top Floor	Replace floor mats with ones that do not have gaps	\$100.00	each	1	\$100.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.12.7	Kitchen - Top Floor	Remount operable parts to be within reach range of max 48" aff	\$250.00	each	1	\$250.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.14.1	Alarms - Top Floor	Install audible and visual alarms in rooms and spaces where alarms have been installed since 1992	\$407.50	each	15	\$6,112.50	2	Incomplete will be addressed during renovation
Neighborhood Center	Citywide Facilities	1.14.2	Alarms - Top Floor	Upon renovation <i>install audible and visual</i> alarms in all rooms and spaces	\$373.50	each	5	\$1,867.50	2	Incomplete will be addressed during renovation
Neighborhood Center	Citywide Facilities	1.15.1	Interior Signage - Top Floor	Create template for signs that addresses height of sign, size of characters, location of Braille, and other requirements	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.15.2	Interior Signage - Top Floor	Implement a sign revision program throughout the building, discriminating between directional signs and signs for permanent spaces	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.15.3	Interior Signage - Top Floor	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door	\$150.00	each	15	\$2,250.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.6.1	Interior Doors - Middle Floor	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	10	\$12,500.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.6.2	Interior Doors - Middle Floor	For all doors along the public circulation route, relocate storage, furniture, and other obstacles to create 60" maneuvering space around doors	\$0.00	staff time	0	\$0.00	2	On-going
Neighborhood Center	Citywide Facilities	1.6.3	Interior Doors - Middle Floor	For all doors along the public circulation route, widen doors to 36" for recessed doors	\$1,980.00	each	1	\$1,980.00	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.6.4	Interior Doors - Middle Floor	For all doors along the public circulation route, widen doors to 32" for any doors indicated	\$1,980.00	each	2	\$3,960.00	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.6.5	Interior Doors - Middle Floor	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	13	\$4,777.50	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.6.6	Interior Doors - Middle Floor	For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors as a smart practice	\$0.00	staff time	0	\$0.00	2	On-going



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Neighborhood Center	Citywide Facilities	1.6.7	Interior Doors - Middle Floor	For all doors along the public circulation route, <i>inspect, adjust, and maintain</i> closing speed on door closers	\$0.00	staff time	0	\$0.00	2	On-going
Neighborhood Center	Citywide Facilities	1.6.8	Interior Doors - Middle Floor	For all doors along the public circulation route, replace doors with ones having sidelight viewing windows max 43" aff	\$99.00	each	5	\$495.00	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.6.9	Interior Doors - Middle Floor	Upon renovation; make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	2	N/A
Neighborhood Center	Citywide Facilities	1.7.1	Stairs - Interior - Middle Floor	Replace handrails with ones with compliant handrail extensions	\$700.00	each	1	\$700.00	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.7.2	Stairs - Interior - Middle Floor	Install lower set of handrails mounted between 20"-28" aff for child usage as a smart practice	\$700.00	each	1	\$700.00	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.8.1	Public Spaces - Middle Floor	Relocate obstacles to create AR through spaces indicated	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.8.2	Public Spaces - Middle Floor	Raise obstructions to min 80", or pad object to prevent hazard in overhead clearance	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.8.3	Public Spaces - Middle Floor	Relocate obstacles to create turning space in preschool storage	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.8.4	Public Spaces - Middle Floor	Relocate protruding objects in spaces indicated or place cane detectable warning or bollard at foot of protrusions	\$250.00	each	3	\$750.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.8.5	Public Spaces - Middle Floor	Secure rugs to prevent trip hazard where indicated	\$100.00	each	5	\$500.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.8.6	Public Spaces - Middle Floor	Repair, bevel or ramp CIL in rooms indicated	\$68.75	each	1	\$68.75	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.8.7	Public Spaces - Middle Floor	Remove, or relocate storage in CFS at fixtures and operable parts	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.8.8	Public Spaces - Middle Floor	Lower operating mechanisms in spaces indicated to max 48" aff to highest operable part; leave as is if employee only operated	\$250.00	each	2	\$500.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.8.9	Public Spaces - Middle Floor	Replace projector pull screen with one that does not require tight pinch or grasp	\$100.00	each	1	\$100.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.8.10	Public Spaces - Middle Floor	Replace one table in preschool rooms with one having an adjustable height for use by a child in a wheelchair	\$800.00	each	4	\$3,200.00	2	Staff to investigate completion status



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Neighborhood Center	Citywide Facilities	1.8.11	Public Spaces - Middle Floor	Lower sink height to max 34" aff	\$1,700.00	each	1	\$1,700.00	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.8.12	Public Spaces - Middle Floor	Remove storage from CFS at sink	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.9.1	Employee Spaces - Middle Floor	Employee only area permit approach, entry, and exit, relocate obstacles to create AR through spaces indicated	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.9.2	Employee Spaces - Middle Floor	Employee only areas permit approach, entry, and exit, relocate obstacles to create turning space of 60" in spaces indicated	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.9.3	Employee Spaces - Middle Floor	For all other deficits, <i>leave as is</i> , employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	2	N/A
Neighborhood Center	Citywide Facilities	1.11.1	Restrooms - Multiple Users - Middle Floor - Preschool Restrooms	Restroom not accessible, <i>acquire and mount</i> signage directing patrons to accessible restroom at both until renovations occur	\$150.00	each	2	\$300.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.11.2	Restrooms - Multiple Users - Middle Floor - Preschool Restrooms	Lower mirror so reflective surface is max 40" aff in both	\$0.00	staff time	0	\$0.00	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.11.3	Restrooms - Multiple Users - Middle Floor - Preschool Restrooms	Raise sink bowl to provide 27" knee clearance, in the alternative, acquire a shallower model in both	\$1,700.00	each	2	\$3,400.00	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.11.4	Restrooms - Multiple Users - Middle Floor - Preschool Restrooms	<i>Insulate exposed pipes</i> under one sink in both	\$55.00	each	2	\$110.00	2	Staff to investigate completion status



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Neighborhood Center	Citywide Facilities	1.11.5	Restrooms - Multiple Users - Middle Floor - Preschool Restrooms	Create a wheelchair accessible stall in place of ambulatory stall with grab bars and fixtures mounted in correct locations and at correct heights in both	\$3,936.25	each	2	\$7,872.50	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.11.6	Restrooms - Multiple Users - Middle Floor - Preschool Restrooms	Widen accessible stall doors to 32" when opened to 90 degrees in both	\$300.00	each	2	\$600.00	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.11.7	Restrooms - Multiple Users - Middle Floor - Preschool Restrooms	Replace stall hardware with hardware operable without a tight pinch or grasp and adjust stall door to be self-closing in both	\$100.00	each	2	\$200.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.11.8	Restrooms - Multiple Users - Middle Floor - Preschool Restrooms	Widen route at turn to min 48" wide for clearance in both	\$1,963.75	each	2	\$3,927.50	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.11.9	Restrooms - Multiple Users - Middle Floor - Preschool Restrooms	Relocate or recess towel dispensers to not interfere with general circulation path in both, protrusions can't be greater than 4"	\$250.00	each	2	\$500.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.11.10	Restrooms - Multiple Users - Middle Floor - Preschool Restrooms	Lower urinal to be mounted at max 17" to rim with flush controls max 48" aff and remove step for CFS	\$1,217.50	each	1	\$1,217.50	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.11.1	Restrooms - Multiple User - Lower Floor	Remove under sink apron to create knee clearance at sinks in both	\$785.00	each	2	\$1,570.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.11.2	Restrooms - Multiple User - Lower Floor	Create a wheelchair accessible stall with grab bars and fixtures mounted in correct locations and at correct heights in both	\$3,936.25	each	2	\$7,872.50	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.11.3	Restrooms - Multiple User - Lower Floor	Relocate or recess towel dispensers to not interfere with general circulation path, protrusions can't be greater than 4" in both	\$250.00	each	2	\$500.00	2	Staff to investigate completion status



			1							
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Neighborhood Center	Citywide Facilities	1.11.4	Restrooms - Multiple User - Lower Floor	Correct or repair slope to max 5% running and 2.08% cross in both	\$87.50	sq ft	50	\$4,375.00	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.11.5	Restrooms - Multiple User - Lower Floor	Replace stall door hardware of ambulatory stall with one that is within reach range in men's	\$100.00	each	1	\$100.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.11.6	Restrooms - Multiple User - Lower Floor	Adjust ambulatory stall to be 36" wide in men's	\$1,963.75	each	1	\$1,963.75	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.11.7	Restrooms - Multiple User - Lower Floor	Replace damaged signage at women's restroom	\$150.00	each	1	\$150.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.11.1	Restrooms - Single Users - Middle Floor	Leave as is, inaccessible restrooms, and mount signage directing patrons to accessible restroom	\$0.00	n/a	0	\$0.00	2	N/A
Neighborhood Center	Citywide Facilities	1.12.1	Kitchen - Middle Floor	Renovate preschool kitchen to provide 40" clear width between counters and fixtures	\$785.00	each	2	\$1,570.00	2	Incomplete will be addressed during renovation
Neighborhood Center	Citywide Facilities	1.12.2	Kitchen - Middle Floor	Lower sink height to max 34" aff	\$1,700.00	each	1	\$1,700.00	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.12.3	Kitchen - Middle Floor	Remove under sink cabinets to provide knee and toe clearances under sinks	\$785.00	each	1	\$785.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.12.4	Kitchen - Middle Floor	Replace oven in preschool kitchen with one having controls on the front panel	\$2,000.00	each	1	\$2,000.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.12.5	Kitchen - Middle Floor	Lower microwave in preschool kitchen to be in reach range max 48" aff	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.12.6	Kitchen - Middle Floor	Replace sink hardware with lever hardware	\$525.00	each	1	\$525.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.12.7	Kitchen - Middle Floor	Remove, or relocate storage at fixtures and operable parts	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.12.8	Kitchen - Middle Floor	Raise oven hood to min 80", or pad object to prevent hazard in overhead clearance	\$250.00	each	1	\$250.00	2	N/A technically infeasible
Neighborhood Center	Citywide Facilities	1.12.9	Kitchen - Middle Floor	Leave as is, steps to boiler room, correction technically infeasible	\$0.00	n/a	0	\$0.00	2	N/A
Neighborhood Center	Citywide Facilities	1.12.10	Kitchen - Middle Floor	Lower hood controls to max 48" aff to highest operable part; leave as is if employee only operated	\$250.00	each	1	\$250.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.6.1	Interior Doors - Lowest Floor	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	1	\$1,250.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.6.2	Interior Doors - Lowest Floor	For all doors along the public circulation route, relocate storage, furniture, and other obstacles to create 60" maneuvering space around doors	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Neighborhood Center	Citywide Facilities	1.6.3	Interior Doors - Lowest Floor	For all doors along the public circulation route, replace doors with ones having 36" clear width at recessed doors	\$1,980.00	each	2	\$3,960.00	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.6.4	Interior Doors - Lowest Floor	For all doors along the public circulation route, replace doors ones having 32" clear width where indicated	\$1,980.00	each	1	\$1,980.00	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.6.5	Interior Doors - Lowest Floor	For all doors along the public circulation route, replace push bar hardware to not project more than 4" into door frame	\$367.50	each	2	\$735.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.6.6	Interior Doors - Lowest Floor	For all doors along the public circulation route, replace hardware with lever hardware where indicated, mounted 34" to 48" aff	\$367.50	each	13	\$4,777.50	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.6.7	Interior Doors - Lowest Floor	For all doors along the public circulation route, <i>inspect, adjust, and maintain</i> 5 lbf to open interior doors	\$0.00	staff time	0	\$0.00	2	On-going
Neighborhood Center	Citywide Facilities	1.6.8	Interior Doors - Lowest Floor	For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers	\$0.00	staff time	0	\$0.00	2	On-going
Neighborhood Center	Citywide Facilities	1.6.9	Interior Doors - Lowest Floor	For employee only doors; make above corrections upon renovation	\$0.00	n/a	0	\$0.00	2	N/A
Neighborhood Center	Citywide Facilities	1.8.1	Public Spaces - Lowest Floor	Relocate obstacles to create AR through spaces indicated	\$0.00	staff time	0	\$0.00	2	On-going
Neighborhood Center	Citywide Facilities	1.8.2	Public Spaces - Lowest Floor	Relocate protruding objects in spaces indicated or place cane detectable warning or bollard at foot of protrusions	\$250.00	each	1	\$250.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.8.3	Public Spaces - Lowest Floor	Lower operating mechanisms in spaces indicated to max 48" aff to highest operable part; leave as is if employee only operated	\$250.00	each	2	\$500.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.9.1	Employee Spaces - Lowest Floor	Employee only area permit approach, entry, and exit, relocate obstacles to create AR through spaces indicated	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.9.2	Employee Spaces - Lowest Floor	Employee only areas permit approach, entry, and exit, relocate obstacles to create turning space of 60" in spaces indicated	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.11.1	Employee Spaces - Lowest Floor	Restroom not accessible, <i>acquire and mount</i> signage directing patrons to accessible restroom at both until renovations occur	\$150.00	each	2	\$300.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.11.2	Employee Spaces - Lowest Floor	Lower mirror so reflective surface is max 40" aff	\$0.00	staff time	0	\$0.00	2	Staff to investigate technical feasibility



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Neighborhood Center	Citywide Facilities	1.11.3	Employee Spaces - Lowest Floor	Raise sink bowl to provide 27" knee clearance, in the alternative, acquire a shallower model in both	\$1,700.00	each	2	\$3,400.00	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.11.4	Employee Spaces - Lowest Floor	Insulate exposed pipes under one sink in both	\$55.00	each	2	\$110.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.11.5	Employee Spaces - Lowest Floor	Create a wheelchair accessible stall in place of ambulatory stall with grab bars and fixtures mounted in correct locations and at correct heights in both	\$3,936.25	each	2	\$7,872.50	2	Staff to investigate technical feasibility
Neighborhood Center	Citywide Facilities	1.11.6	Employee Spaces - Lowest Floor	Lower hooks in stalls to max 48" aff in both	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.11.7	Employee Spaces - Lowest Floor	Relocate or recess towel dispensers to not interfere with general circulation path in both, protrusions can't be greater than 4"	\$250.00	each	2	\$500.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.11.8	Employee Spaces - Lowest Floor	Remount signage on wall, latch side of the door, 48" to baseline of lowest character and 60" to baseline of highest character at women's	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Neighborhood Center	Citywide Facilities	1.11.9	Employee Spaces - Lowest Floor	Lower hook near sink to max 48" aff in women's	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Northwest Park	Helena Citizens Council District 4	1.1.1	Parking	Relocate stalls to be on the shortest AR to the building entry or park features	\$262.50	each	1	\$262.50	СО	Complete
Northwest Park	Helena Citizens Council District 4	1.1.2	Parking	Add one van parking sign to one accessible stall and repaint stall and access aisle to 11' and 5' or 8' and 8'	\$202.50	each	1	\$202.50	СО	Complete
Northwest Park	Helena Citizens Council District 4	1.1.3	Parking	Repair or correct slope of parking space and access aisle to max 2.08% in any direction	\$2,187.50	each	2	\$4,375.00	со	Complete
Northwest Park	Helena Citizens Council District 4	1.1.4	Parking	Maintain stalls and access aisles to be free of dirt, sand, and other debris	\$0.00	staff time	0	\$0.00	СО	Complete
Northwest Park	Helena Citizens Council District 4	1.1.5	Parking	Acquire and mount at appropriate heights and locations accessible parking signs for all the stalls	\$150.00	each	3	\$450.00	со	Complete
Northwest Park	Helena Citizens Council District 4	1.1.6	Parking	Reconfigure accessible stalls to avoid overlap with drive path	\$262.50	each	1	\$262.50	со	Complete
Northwest Park	Helena Citizens Council District 4	1.2.1	Exterior Accessible Route	Maintain curb ramps and AR to be free of debris	\$0.00	staff time	0	\$0.00	СО	Complete



Site	HCC Dist	Cite	Type of	Recommendation	Delas/ unit	unit	# of	Total cost	Phase	Notes
Site	HCC DIST	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Northwest Park	Helena Citizens Council District 4	1.2.2	Exterior Accessible Route	Create a curb ramp to be max running slope 8.33%, max cross slope 2.08%, having a top landing as wide as the ramp and 36" deep and side flares with a max slope 10% at Harwood St.	\$1,062.50	each	1	\$1,062.50	со	Complete
Northwest Park	Helena Citizens Council District 4	1.2.3	Exterior Accessible Route	Re-cut or re-pour curb ramp to be max running slope 8.33%, max cross slope 2.08%, having a top landing as wide as the ramp and 36" deep and side flares max slope 10% at Brady St.	\$725.00	each	1	\$725.00	СО	Complete
Northwest Park	Helena Citizens Council District 4	1.2.4	Exterior Accessible Route	Install compliant detectable warning at curb ramps as a smart practice	\$235.00	each	2	\$470.00	со	Complete
Northwest Park	Helena Citizens Council District 4	1.2.5	Exterior Accessible Route	Replace AR with crushed and compacted stone or similar outdoor material	\$48.00	lin ft	600	\$28,800.00	со	Complete
Northwest Park	Helena Citizens Council District 4	1.2.6	Exterior Accessible Route	Correct or repair sidewalk cross slope along AR to max 2.08%	\$87.50	sq ft	25	\$2,187.50	со	Complete
Northwest Park	Helena Citizens Council District 4	1.2.7	Exterior Accessible Route	See 1.10 below for AR to site elements	\$0.00	n/a	0	\$0.00	со	Complete
Northwest Park	Helena Citizens Council District 4	1.3.1	Playground Entry	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to new designated entry	\$48.00	lin ft	25	\$1,200.00	со	Complete
Northwest Park	Helena Citizens Council District 4	1.3.2	Playground Entry	Create designated entry by mounting signage at border along new AR as a smart practice	\$500.00	each	1	\$500.00	со	Complete
Northwest Park	Helena Citizens Council District 4	1.3.3	Playground Entry	Acquire and install intended user signage and mount at new designated entry as a smart practice	\$150.00	each	1	\$150.00	со	Complete
Northwest Park	Helena Citizens Council District 4	1.4.1	Playground Surface	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs	\$7,500.00	each	1	\$7,500.00	2	Complete
Northwest Park	Helena Citizens Council District 4	1.4.2	Playground Surface	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces	\$0.00	staff time	0	\$0.00	со	Complete
Northwest Park	Helena Citizens Council District 4	1.8.1	GLPCs	See recommendation 1.3.1 for AR correction	\$0.00	n/a	0	\$0.00	СО	Complete
Northwest Park	Helena Citizens Council District 4	1.8.2	GLPCs	Raise entry point for step standing swing to 11" to 24" aff	\$250.00	each	1	\$250.00	СО	Complete
Northwest Park	Helena Citizens Council District 4	1.8.3	GLPCs	Add two more GLPC of at least one new type such as spinners or rockers, to meet incentive scoping	\$2,000.00	each	2	\$4,000.00	со	Complete



		Ι	I	T	<u> </u>		I			
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Northwest Park	Helena Citizens Council District 4	1.10.1	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the ball field east	\$48.00	lin ft	75	\$3,600.00	со	Complete
Northwest Park	Helena Citizens Council District 4	1.10.2	Park Site	Repair, bevel, or ramp CIL at ball field east dugouts	\$155.00	inch	17	\$2,635.00	СО	Complete
Northwest Park	Helena Citizens Council District 4	1.10.3	Park Site	Relocate garbage at in bench CFS at ball field east	\$0.00	staff time	0	\$0.00	СО	Complete
Northwest Park	Helena Citizens Council District 4	1.10.4	Park Site	Leave as is <u>ball field west</u> and designate ball field east as accessible	\$0.00	n/a	0	\$0.00	СО	Complete
Northwest Park	Helena Citizens Council District 4	1.10.5	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the athletic fields	\$48.00	lin ft	100	\$4,800.00	СО	Complete
Northwest Park	Helena Citizens Council District 4	1.10.6	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the concessions	\$48.00	lin ft	200	\$9,600.00	СО	Complete
Northwest Park	Helena Citizens Council District 4	1.10.7	Park Site	Replace portable toilet with compliant model and place along AR	\$780.00	each	1	\$780.00	СО	Complete
Northwest Park	Helena Citizens Council District 4	1.10.8	Park Site	Correct or repair cross slope along walking/jogging path to max 2.08%	\$87.50	sq ft	25	\$2,187.50	СО	Complete
Northwest Park	Helena Citizens Council District 4	1.10.9	Park Site	Replace surface on walking/jogging path with crushed and compacted stone or similar outdoor material	\$10.67	lin ft	3000	\$32,000.00	со	Complete
Northwest Park	Helena Citizens Council District 4	1.10.10	Park Site	Ramp entry to storage shed if used by the public and connect to the AR	\$155.00	inch	6	\$930.00	СО	Complete
Northwest Park	Helena Citizens Council District 4	1.10.11	Park Site	Relocate 20% of garbage cans to be along AR	\$0.00	staff time	0	\$0.00	СО	Complete
Northwest Park	Helena Citizens Council District 4	1.10.12	Park Site	Replace one picnic table with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table as a smart practice	\$800.00	each	1	\$800.00	со	Complete
PA1551:O1788ar king Facilities - 6th Avenue	0" 11 5 1111	444	D 1:	Repaint stalls and access aisles to be 8' and 5' each for standard and 8' and 8' for van stalls in	070.50			0447.00		T. I. I. I. EV00
Garage Parking Facilities - 6th Avenue Garage	Citywide Facilities Citywide Facilities	1.1.1	Parking Parking	each location Relocate van stalls to location within the garage that allows for minimum 98" vertical clearance at stalls and along drive path from entrance and to exit. if feasible	\$73.50 \$283.50	each	3	\$147.00 \$850.50	2	To be completed in FY23 Staff to investigate technical feasibility
Parking Facilities - 6th Avenue Garage	,	1.1.3	Parking	In the alternative to 1.1.2, <i>relocate</i> van accessible stalls to nearby street location with minimal slope and provide compliant curb ramps in close proximity to new stalls	\$0.00	staff time	0	\$0.00	2	Staff will invesitigate feasibility of on- street designated ADA spaces
Parking Facilities - 6th Avenue Garage	Citywide Facilities	1.1.4	Parking	Repair or correct slope of parking spaces and access aisles to max 2.08% in any direction	\$3,062.50	each	12	\$36,750.00	2	Staff to investigate technical feasibility



			ı			1	I		ı	1
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Parking Facilities										
6th Avenue Garage	Citywide Facilities	1.1.5	Parking	Remove ramp from access aisle on upper level	\$6,510.00	each	1	\$6,510.00	2	N/A ramp required for pedestrian bridge
Parking Facilities	Citywide Facilities	1.1.5	Faiking	Remove ramp from access alsie on upper level	φ0,510.00	eacii	-	φ0,510.00		N/A Tamp required for pedestrian bridge
6th Avenue				Raise existing accessible parking signs so lowest		staff				
Garage	Citywide Facilities	1.1.6	Parking	end of bottom sign is min 60" aff	\$0.00	time	0	\$0.00	2	To be completed in FY22
Parking Facilities -				Reconfigure accessible stalls to avoid requiring						
6th Avenue				pedestrians to cross vehicular way, <i>in the</i>						
Garage	Citywide Facilities	1.1.7	Parking	alternative, leave as is with striped crosswalk	\$367.50	each	1	\$367.50	2	To be completed in FY22
Parking Facilities -			Exterior	Install compliant detectable warning at						
6th Avenue			Accessible	transitions from walkways to vehicular ways as a						
Garage	Citywide Facilities	1.2.1	Route	smart practice	\$329.00	each	1	\$329.00	2	Staff to investigate
Parking Facilities -			04	Correct riser heights on stairs so they are a						Ct-ff to invocation to to observe the control of
6th Avenue Garage	Citywide Facilities	1.2.2	Stairs - Exterior	consistent height between 4" to 7"; leave as is if technically infeasible at level one entry	\$283.50	each	5	\$1,417.50	2	Staff to investigate technical feasibility
Parking Facilities	Citywide Facilities	1.2.2	Exterior	Correct tread depth on stairs so they are 11"	\$203.50	eacii	3	\$1,417.50		
6th Avenue			Stairs -	minimum and consistent, leave as is if technically						Staff to investigate technical feasibility
Garage	Citywide Facilities	1.2.3	Exterior	infeasible	\$283.50	each	4	\$1,134.00	2	Ciam to invocagate toominear readization
Parking Facilities	,			Re-install handrails on both sides of level one						
6th Avenue			Stairs -	and level four stairways, mounted 34" to 38" aff						Staff to investigate technical feasibility
Garage	Citywide Facilities	1.2.4	Exterior	with top and bottom extensions	\$980.00	each	4	\$3,920.00	2	
Parking Facilities -			_							
6th Avenue	0	405	Ramps -	0.000	0400 50		0.5	#0.000 F0	0	Staff to investigate technical feasibility
Garage	Citywide Facilities	1.2.5	Exterior	Correct ramp top landing slope to max 2.08% Replace ramp handrails with ones that are	\$122.50	sq ft	25	\$3,062.50	2	
Parking Facilities				continuous, rounded and/or extend to the ground,						
6th Avenue			Ramps -	with handrail extensions and mounted 34" to 38"						Staff to investigate technical feasibility
Garage	Citywide Facilities	1.2.6	Exterior	aff	\$980.00	each	2	\$1,960.00	2	
Parking Facilities	- /			Mount signage at inaccessible entrances	•			, , , , , , , , , , , , , , , , , , , ,		
6th Avenue			Exterior	directing patrons in wheelchairs to accessible						
Garage	Citywide Facilities	1.3.1	Signage	entrance	\$150.00	each	5	\$750.00	2	To be completed in FY22
Parking Facilities										
6th Avenue	0,, 1, 5, 1,,,	4.0.0	Exterior	Mount signage at entrance designating it as	* 450.00			****		T
Garage	Citywide Facilities	1.3.2	Signage	accessible For all doors along the public circulation route,	\$150.00	each	2	\$300.00	2	To be completed in FY22
Parking Facilities - 6th Avenue				provide required maneuvering clearance on push						Staff to investigate technical feasibility
Garage	Citywide Facilities	1.4.1	Exterior Doors	and pull side of doors	\$1,750.00	each	2	\$3,500.00	2	Start to investigate technical reasibility
Parking Facilities	Oity Wido i dointies	1.7.1	LACTO DOOLS	and pair side of doors	ψ1,700.00	Guon		ψ0,000.00		
6th Avenue				No maneuvering clearance at door due to stairs,						N/A
Garage	Citywide Facilities	1.4.2	Exterior Doors	leave as is, correction is technically infeasible	\$0.00	n/a	0	\$0.00	2	
Parking Facilities -										
6th Avenue				For all doors along the public circulation route,						Staff to investigate technical feasibility
Garage	Citywide Facilities	1.4.3	Exterior Doors	ramp steps at door entries	\$96.25	inch	48	\$4,620.00	2	



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Parking Facilities				For all doors along the public circulation route, fill		<u> </u>				
6th Avenue				and maintain gaps in doorway clearances to max						
Garage	Citywide Facilities	1.4.4	Exterior Doors	,	\$96.25	each	1	\$96.25	2	To be completed in FY22
Parking Facilities -				For all doors along the public circulation route,						·
6th Avenue				correct or repair slope at doorway landing to						Staff to investigate technical feasibility
Garage	Citywide Facilities	1.4.5	Exterior Doors	max 2.08% in any direction for level CFS	\$3,062.50	each	3	\$9,187.50	2	
Parking Facilities -				For all doors along the public circulation route,						
6th Avenue				repair, bevel, or ramp CIL at door entries to max						Staff to investigate technical feasibility
Garage	Citywide Facilities	1.4.6	Exterior Doors	.25"	\$96.25	inch	4	\$385.00	2	
Parking Facilities				For all door along the mobile since the second state of the second						
6th Avenue Garage	Citywide Facilities	1 1 0	Exterior Deere	For all doors along the public circulation route, <i>fill</i> and maintain gaps at doorways to max .5"	\$96.25	each	5	\$481.25	2	To be completed in EV22
Parking Facilities	Citywide Facilities	1.4.0	Exterior Doors	For all doors along the public circulation route,	φ90.25	eacii	3	φ401.25		To be completed in FY22
6th Avenue				replace hardware with lever hardware where						
Garage	Citywide Facilities	149	Exterior Doors	•	\$514.50	each	9	\$4,630.50	2	To be completed in FY22
Parking Facilities	onjmus i domuse		2,4,6,1,6,1,2,6,1,6	For all doors along the public circulation route,	ψο :σο	50.5.1	-	ψ 1,000.00	_	
6th Avenue				inspect, adjust, and maintain 8.5 lbf to open		staff				
Garage	Citywide Facilities	1.4.10	Exterior Doors	exterior doors as a smart practice	\$0.00	time	0	\$0.00	2	To be completed in FY22
Parking Facilities -				For all doors along the public circulation route,						
6th Avenue				inspect, adjust, and maintain closing speed on		staff				
Garage	Citywide Facilities	1.4.11	Exterior Doors		\$0.00	time	0	\$0.00	2	To be completed in FY22
Parking Facilities -				For all doors along the public circulation route,						
6th Avenue				replace doors with ones having sidelight viewing						
Garage	Citywide Facilities	1.4.12	Exterior Doors	windows max 43" aff	\$1,386.00	each	3	\$4,158.00	2	To be completed in FY22
Parking Facilities				Management in the second secon						
6th Avenue	Citravida Facilities	1 1 1 2	Exterier Deere	Upon renovation, make above corrections to	\$0.00	2/2	0	¢0.00	2	Frankrian anki anaratad
Garage Parking Facilities	Citywide Facilities	1.4.13	Exterior Doors	employee only doors	\$0.00	n/a	U	\$0.00		Employee-only operated
6th Avenue										
Garage	Citywide Facilities	1.5.1	Elevator	Repair elevator buttons on 3 rd level	\$2,184.00	each	1	\$2,184.00	2	To be completed in FY22
Parking Facilities	ORYWIGO I GOINGOO	1.0.1	Liovator	Troban diovator battorio di di lovo	Ψ2,101.00	Guon		Ψ2,101.00		10 00 0011101000 1111 122
6th Avenue										
Garage	Citywide Facilities	1.5.2	Elevator	Acquire and install visible signage at hoistway	\$15.00	each	8	\$120.00	2	To be completed in FY22
Parking Facilities -										
6th Avenue				Remount floor designation signage on both						
Garage	Citywide Facilities	1.5.3	Elevator	hoistways to 60" to the center	\$150.00	each	2	\$300.00	2	To be completed in FY22
Parking Facilities -										
6th Avenue	o			Add tactile star to main level elevator designation	0.455.55			0.450.00		_ , , , , , _,,,
Garage	Citywide Facilities	1.5.4	Elevator	and floor buttons	\$150.00	each	3	\$450.00	2	To be completed in FY22
Parking Facilities				Lawrence and the control butter to the Call						Stoff to investigate tackning family 11th
6th Avenue	Citywido Essilitica	1.5.5	Eleveter	Lower communication system button to max 54" aff	\$945.00	oach	1	\$945.00	2	Staff to investigate technical feasibility
Garage Parking Facilities -	Citywide Facilities	1.3.5	Elevator	all	φ940.00	each		φ943.00		
6th Avenue				Leave as is, elevator dimensions, infeasible to						N/A
Garage	Citywide Facilities	1.5.6	Elevator	correct until replaced	\$0.00	n/a	0	\$0.00	2	IV/A
Garage	Citywide Facilities	1.5.0	Elevator	correct until replaceu	φυ.υυ	II/a	U	φυ.υυ		



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Parking Facilities				No maneuvering clearance at door due to						NIA
6th Avenue Garage	Citywide Facilities	1.6.1	Interior Doors	stairs/railing, <i>leave as is,</i> correction is technically infeasible	\$0.00	n/a	0	\$0.00	2	N/A
Parking Facilities -	onjmus i demuse			For all doors along the public circulation route,	Ψ0.00	.,,	J	ψ0.00		
6th Avenue	Cityavida Facilitias	160	Interior Deere	replace hardware with lever hardware where	\$514.50	aaab	1	ΦΕ44 F0	2	To be completed in EVO2
Garage Parking Facilities	Citywide Facilities	1.6.2	Interior Doors	For all doors along the public circulation route,	φ 514.50	each	- 1	\$514.50		To be completed in FY22
6th Avenue				inspect, adjust, and maintain 5 lbf to open		staff				
Garage Parking Facilities	Citywide Facilities	1.6.3	Interior Doors	interior doors For all doors along the public circulation route,	\$0.00	time	0	\$0.00	2	To be completed in FY22
6th Avenue				inspect, adjust, and maintain closing speed on		staff				
Garage	Citywide Facilities	1.6.4	Interior Doors	door closers	\$0.00	time	0	\$0.00	2	To be completed in FY22
Parking Facilities - 6th Avenue				For all doors along the public circulation route, replace doors with ones having sidelight viewing						
Garage	Citywide Facilities	1.6.5		windows max 43" aff	\$1,386.00	each	1	\$1,386.00	2	To be completed in FY23
Parking Facilities					. ,					·
6th Avenue Garage	Citywide Facilities	1.7.1		Repair, bevel or ramp CIL to elevator on all levels	\$68.75	inch	24	\$1,650.00	2	Staff to investigate technical feasibility
Parking Facilities	Citywide Facilities	1.7.1		Correct riser heights on all stairs to consistent	φυσ.75	IIICII	24	φ1,050.00		
6th Avenue				height between 4" to 7", leave as is if technically						Staff to investigate technical feasibility
Garage Parking Facilities	Citywide Facilities	1.7.2	Interior	infeasible	\$283.50	each	126	\$35,721.00	2	
6th Avenue			Stairs -	Correct tread depth on stairs to 11" minimum						Staff to investigate technical feasibility
Garage	Citywide Facilities	1.7.3	Interior	and consistent, leave as is if technically infeasible	\$283.50	each	42	\$11,907.00	2	,
				Install handrails on both sides of all stairways,						
				mounted 34" to 38" aff with top and bottom extensions and having a 1.25" – 2" in diameter, or						
Parking Facilities				a non-circular grip that has a perimeter dimension						Staff to investigate technical feasibility
6th Avenue	Citywide Facilities	1.7.4		of 4"- 6.25" max with a min gap of 1.5" between handrail and wall	\$980.00	ooob	24	\$23,520.00	2	
Garage Parking Facilities	Citywide Facilities	1.7.4	Interior	Create template for signs that addresses height	\$980.00	each	24	\$23,320.00		
6th Avenue				of sign, size of characters, location of Braille, and		staff				
Garage	Citywide Facilities	1.15.1	Signage	other requirements	\$0.00	time	0	\$0.00	2	To be completed in FY22
Parking Facilities				Implement a sign revision program throughout						0.50
6th Avenue				the building, discriminating between directional		staff				Staff to investigate technical feasibility
Garage	Citywide Facilities	1.15.2	Signage	signs and signs for permanent spaces	\$0.00	time	0	\$0.00	2	
				Mount signage at all permanent rooms/spaces						
				having Braille and the international symbol of						
Parking Facilities				accessibility, mounted 48" to baseline of lowest						
6th Avenue Garage	Citywide Facilities	1.15.3	Signage	character and 60" to the baseline of the highest character sign and on the latch side of the door	\$150.00	each	16	\$2.400.00	2	Staff to investigate completion status



T T										
			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Parking Facilities										
15th Street Garage	Citywide Facilities	1.1.1	Dorking	Polocoto etall to eliminate column in access cicle	\$73.50	ooob	1	\$73.50	2	To be completed in FY22
Parking Facilities	Citywide Facilities	1.1.1	Parking	Relocate stall to eliminate column in access aisle	\$73.50	each	ı	\$73.50		To be completed in F122
15th Street				Repaint stalls and add access aisles to be 8' and						
Garage	Citywide Facilities	1.1.2	Parking	5' each on 3 rd level	\$73.50	each	2	\$147.00	2	To be completed in FY23
Parking Facilities				Repair or correct slope of parking spaces and						Career in the contract of the
15th Street Garage	Citywide Facilities	1.1.3	Parking	access aisles to max 2.08% in any direction on all levels	\$3,062.50	each	14	\$42,875.00	2	Staff to investigate technical feasibility
Parking Facilities	Citywide i aciiilles	1.1.5	I arking	levels	ψ5,002.50	Cacii	14	ψ42,073.00	2	
15th Street				Raise existing accessible parking signs so lowest		staff				
Garage	Citywide Facilities	1.1.4	Parking	end of bottom sign is min 60" aff	\$0.00	time	0	\$0.00	2	To be completed in FY22
Darking Equilities				Pecentiaure ecoscible stelle to evoid requiring						
Parking Facilities - 15th Street				Reconfigure accessible stalls to avoid requiring pedestrians to cross vehicular way, in the						Staff to investigate technical feasibility
Garage	Citywide Facilities	1.1.5	Parking	alternative, leave as is with striped crosswalk	\$367.50	each	2	\$735.00	2	
Parking Facilities -	•		Exterior							
15th Street	0,, 1, 5, 1,,,		Accessible		** ** **			* 4 04 5 00		Staff to investigate technical feasibility
Garage Parking Facilities	Citywide Facilities	1.2.1	Route Exterior	Correct curb ramp cross slope to max 2.08%	\$1,015.00	each	1	\$1,015.00	2	
15th Street			Accessible							Staff to investigate technical feasibility
Garage	Citywide Facilities	1.2.2	Route	Repair, bevel, or ramp CIL along AR	\$96.25	each	1	\$96.25	2	otan to mit congate toomican roadizmity
Parking Facilities -				Correct riser heights on stairs near street so						
15th Street	0,, 1, 5, 1,,,	4.0.0	Stairs -	they are a consistent height between 4" to 7";	4000 50			*** *** ** ** ** ** ** *		Staff to investigate technical feasibility
Garage Parking Facilities	Citywide Facilities	1.2.3	Exterior	leave as is if technically infeasible	\$283.50	each	52	\$14,742.00	2	
15th Street			Stairs -	<i>Install</i> visual contrast strip on leading 2" of each						
Garage	Citywide Facilities	1.2.4	Exterior	tread on both stairs	\$84.00	each	104	\$8,736.00	2	Staff to investigate completion status
Parking Facilities -				Install handrails on both sides of stairway,						-
15th Street	0,, 1, 5, 1,,,		Stairs -	mounted 34" to 38" aff with correct bottom	****			* 7 040 00		0
Garage Parking Facilities	Citywide Facilities	1.2.5	Exterior	extensions	\$980.00	each	8	\$7,840.00	2	Staff to investigate completion status
15th Street			Exterior	Mount signage at entrance designating it as						
Garage	Citywide Facilities	1.3.1	Signage	accessible	\$150.00	each	2	\$300.00	2	To be completed in FY22
Parking Facilities				For all doors along the public circulation route,						
15th Street Garage	Citywide Facilities	1 1 1	Exterior Deers	correct or repair slope at doorway landing to max 2.08% in any direction for level CFS at entry	\$3,062.50	each	1	\$3,062.50	2	To be completed in FY22
Parking Facilities	Citywide Facilities	1.4.1	LATERIOR DOORS	For all doors along the public circulation route,	ψ5,002.50	Eacil		ψ3,002.30		10 be completed in F122
15th Street				inspect, adjust, and maintain 8.5 lbf to open		staff				
Garage	Citywide Facilities	1.4.2	Exterior Doors	exterior doors as a smart practice	\$0.00	time	0	\$0.00	2	To be completed in FY22
D 11 5 700				Burney design of the sign of						
Parking Facilities - 15th Street				Program elevator car audible signals to chime once for up and twice for down, or replace						Staff to coordinate with contractor on
Garage	Citywide Facilities	1.5.1	Elevator	audible chimes with verbal enunciators at level 1R	\$7,700.00	each	1	\$7,700.00	2	elevator repairs



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
				Repaint stalls and access aisles to be 8' and 5'						
Parking Facilities Getchell Garage	Citywide Facilities	1.1.1	Dorking	each for standard accessible and 8' and 8' for van stalls where noted	\$73.50	ooob	4	\$294.00	2	To be completed in FY23
Getchen Garage	Citywide Facilities	1.1.1	Parking	Stalls where noted	\$73.30	each	4	\$294.00		To be completed in F123
Parking Facilities										
Getchell Garage	Citywide Facilities	1.1.2	Parking	Relocate pipe to eliminate protrusion in van stall	\$1,540.00	each	1	\$1,540.00	2	Staff will investigate completion status
Parking Facilities				Repair or correct slope of parking spaces and						Staff to investigate technical feasibility
Getchell Garage	Citywide Facilities	1.1.3	Parking	access aisles to max 2.08% in any direction	\$3,062.50	each	27	\$82,687.50	2	otali to investigate teorinical leasibility
			J	·						
Parking Facilities		444	Danisia a	Relocate stall from group of three to a location	ф 7 0 го			¢70.50	0	To be completed in EVO2
Getchell Garage	Citywide Facilities	1.1.4	Parking	without drain	\$73.50	each	1	\$73.50	2	To be completed in FY23
Parking Facilities				Raise existing accessible parking signs so lowest		staff				
Getchell Garage	Citywide Facilities	1.1.5	Parking	end of bottom sign is min 60" aff	\$0.00	time	0	\$0.00	2	To be completed in FY22
				Reconfigure accessible stalls to avoid requiring						
Parking Facilities				pedestrians to cross vehicular way, <i>in the</i>						
Getchell Garage	Citywide Facilities	1.1.6	Parking	alternative, leave as is with striped crosswalk	\$367.50	each	4	\$1,470.00	2	To be completed in FY23
5 II 5 III			Exterior	Install compliant detectable warning at curb						
Parking Facilities Getchell Garage	Citywide Facilities	1.2.1	Accessible Route	ramps and transitions from walkways to vehicular ways as a smart practice	\$329.00	each	3	\$987.00	2	Staff to investigate completion status
Octorion Garage	Oitywide i delinies	1.2.1	Exterior	ways as a smart practice	ψ323.00	Cacii	3	ψ301.00		Stall to investigate completion status
Parking Facilities			Accessible							Staff to investigate technical feasibility
Getchell Garage	Citywide Facilities	1.2.2	Route	Repair, bevel, or ramp CIL along AR	\$96.25	each	1	\$96.25	2	
Parking Facilities			Exterior Accessible							
Getchell Garage	Citywide Facilities	1.2.3	Route	Correct or fill gaps and cracks along AR	\$96.25	each	2	\$192.50	2	Staff to investigate completion status
				Correct riser heights on stairs in elevator tower						
Parking Facilities			Stairs -	and end of garage so they are a consistent height between 4" to 7"; leave as is if technically						Staff to investigate technical feasibility
Getchell Garage	Citywide Facilities	1.2.4	Exterior	infeasible	\$283.50	each	80	\$22,680.00	2	
				Correct tread depth on stairs at end of garage so	,			, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
Parking Facilities			Stairs -	they are 11" minimum and consistent, leave as is	4000 50		40	***	•	Staff to investigate technical feasibility
Getchell Garage	Citywide Facilities	1.2.5	Exterior	if technically infeasible	\$283.50	each	40	\$11,340.00	2	
Parking Facilities			Stairs -	<i>Install</i> contrasting strip along front 2" of each						
Getchell Garage	Citywide Facilities	1.2.6	Exterior	tread on all stairs	\$84.00	each	125	\$10,500.00	2	To be completed in FY23
Dadda - E 200			04-:	Install handrails on both sides of stairway at end						Ctoff to investigate to the include for all 199
Parking Facilities Getchell Garage	Citywide Facilities	1.2.7	Stairs - Exterior	of garage, mounted 34" to 38" aff with top and bottom extensions	\$980.00	each	4	\$3,920.00	2	Staff to investigate technical feasibility
Solonon Sarage	City mad i dollidos	1.4.1	LAGIO	2 Storil Onto 100 10	ψυσυ.υυ	54611		ψ0,020.00		
Parking Facilities			Ramps -	Correct slope of ramp to max 8.33% on all ramps						Staff to investigate technical feasibility
Getchell Garage	Citywide Facilities	1.2.8	Exterior	where noted	\$6,510.00	each	5	\$32,550.00	2	



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Parking Facilities Getchell Garage	Citywide Facilities	1.2.9	Ramps - Exterior	Correct ramp landing slope to max 2.08% at elevator stairwell	\$122.50	sq ft	25	\$3,062.50	2	Staff to investigate technical feasibility
Parking Facilities - Getchell Garage	Citywide Facilities	1.2.10	Ramps - Exterior	Enlarge middle landing to be 60" deep and as wide as the ramp at elevator stairwell	\$875.00	sq ft	5	\$4,375.00	2	Staff to investigate technical feasibility
Parking Facilities - Getchell Garage	Citywide Facilities	1.2.11	Ramps - Exterior	<i>Install handrails</i> on both sides of the ramp on the lower and upper level	\$980.00	each	4	\$3,920.00	2	Staff to investigate technical feasibility
Parking Facilities Getchell Garage	Citywide Facilities	1.2.12	Ramps - Exterior	Replace handrails with ones that are rounded and/or extend to the ground, with handrail extensions and mounted 34" to 38" aff at elevator stairwell	\$980.00	each	1	\$980.00	2	Staff to investigate technical feasibility
Parking Facilities Getchell Garage	Citywide Facilities	1.2.13	Ramps - Exterior	Install rail along bottom edge of ramp that prevents a 4" sphere from passing through at elevator stairwell	\$980.00	each	1	\$980.00	2	Staff to investigate technical feasibility
Parking Facilities Getchell Garage	Citywide Facilities	1.3.1	Exterior Signage	Mount signage at inaccessible entrances directing patrons in wheelchairs to accessible entrance	\$150.00	each	2	\$300.00	2	To be completed in FY23
Parking Facilities - Getchell Garage	Citywide Facilities	1.3.2	Exterior Signage	Mount signage at entrance designating it as accessible	\$150.00	each	3	\$450.00	2	To be completed in FY22
Parking Facilities - Getchell Garage	Citywide Facilities	1.4.1		For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,750.00	each	2	\$3,500.00	2	Staff to investigate completion status
Parking Facilities - Getchell Garage	Citywide Facilities	1.4.2	Exterior Doors	For all doors along the public circulation route, correct or repair slope at doorway landing to max 2.08% in any direction for level CFS	\$3,062.50	each	2	\$6,125.00	2	Staff to investigate technical feasibility
Parking Facilities - Getchell Garage	Citywide Facilities	1.4.3	Exterior Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Parking Facilities - Getchell Garage	Citywide Facilities	1.4.4	Exterior Doors		\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Parking Facilities - Getchell Garage	Citywide Facilities	1.4.5	Exterior Doors	For all doors along the public circulation route, replace doors with ones having sidelight viewing windows max 43" aff	\$1,386.00	each	3	\$4,158.00	2	Staff to investigate completion status
Parking Facilities Getchell Garage	Citywide Facilities	1.4.6	Exterior Doors	Upon renovation, make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	2	Employee-only access
Parking Facilities -	Citywide Facilities	1.5.1		Acquire and mount floor designation signage on both hoistways to 60" to the center on upper level	\$150.00	each	2	\$300.00	2	To be completed in FY22



F	Ī			T		ı				1
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
				A #						
Parking Facilities				Adjust communication system compartment to require less than 5 lbf to open and provide an						
Getchell Garage	Citywide Facilities	1.5.2	Elevator	operable part usable without a tight pinch or grasp	\$514.50	each	1	\$514.50	2	To be completed in FY22
J				Adjust re-entry timing so door reopens when an						·
Parking Facilities	0, , , , , , , , , , , , , , , , , , ,	4.50		obstruction passes through and stays open for min		staff		40.00	•	0.50
Getchell Garage	Citywide Facilities	1.5.3	Elevator	20 seconds Create template for signs that addresses height	\$0.00	time	0	\$0.00	2	Staff to coordinate with contractor
Parking Facilities				of sign, size of characters, location of Braille, and		staff				
Getchell Garage	Citywide Facilities	1.15.1	Signage	other requirements	\$0.00	time	0	\$0.00	2	To be completed in FY22
Parking Facilities				Implement a sign revision program throughout the building, discriminating between directional		staff				
Getchell Garage	Citywide Facilities	1.15.2	Signage	signs and signs for permanent spaces	\$0.00	time	0	\$0.00	2	Staff to investigate completion status
_ · _ · _ · _ ·			<u> </u>	J J I	•			,		<u> </u>
				Mount signage at all permanent rooms/spaces						
				having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest						
Parking Facilities				character and 60" to the baseline of the highest						
Getchell Garage	Citywide Facilities	1.15.3	Signage	character sign and on the latch side of the door	\$150.00	each	3	\$450.00	2	Staff to investigate completion status
Parking Facilities - Jackson Street				Panaint stalls and seems sinks to be 9' and 5'						
Garage	Citywide Facilities	1.1.1	Parking	Repaint stalls and access aisles to be 8' and 5' each	\$73.50	each	1	\$73.50	2	To be completed in FY23
	onjmus i demuse		9		ψ. σ.σσ	545		Ψ. σ.σσ		. o 20 completed iii 1 20
Parking Facilities										
Jackson Street	O:4 : : : : : : : :	440	Danisia a	Remount signage to be centered at the head of	#0.00	staff		#0.00	0	T- b
Garage	Citywide Facilities	1.1.2	Parking	accessible stalls	\$0.00	time	0	\$0.00	2	To be completed in FY22
Parking Facilities			Exterior	Install compliant detectable warning at curb						
Jackson Street			Accessible	ramps and transitions from walkways to vehicular						
Garage	Citywide Facilities	1.2.1	Route	ways as a smart practice	\$329.00	each	1	\$329.00	2	Staff to investigate completion status
Parking Facilities				Correct riser heights on stairs so they are a						
Jackson Street			Stairs -	consistent height between 4" to 7"; leave as is if						N/A
Garage	Citywide Facilities	1.2.2	Exterior	technically infeasible where noted	\$283.50	each	14	\$3,969.00	2	
5 II 5 III										
Parking Facilities - Jackson Street			Stairs -	<i>Install</i> contrasting strip along front 2" of each						
Garage	Citywide Facilities	1.2.3	Exterior	tread and repair deterioration	\$210.00	each	28	\$5,880.00	2	Staff to investigate completion status
_					, , , , ,					,
Parking Facilities			64.	Install handrails on both sides of stairway,						
Jackson Street	Citywide Englishes	1.2.4	Stairs -	mounted 34" to 38" aff with top and bottom extensions at center and North stairs	¢090 00	oach	4	\$3,020,00	2	Staff to investigate completion status
Garage	Citywide Facilities	1.2.4	Exterior	JEXICHSIONS ALCENIEL AND NORTH STAIRS	\$980.00	each	4	\$3,920.00	2	Staff to investigate completion status



			I				1			
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Parking Facilities - Jackson Street Garage	Citywide Facilities	1.3.1	Exterior Signage	Mount signage at entrance designating it as accessible	\$150.00	each	2	\$300.00	2	To be completed in FY22
Parking Facilities - Jackson Street Garage	Citywide Facilities	1.4.1		For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,750.00	each	1	\$1,750.00	2	Staff to investigate completion status
Parking Facilities - Jackson Street Garage	Citywide Facilities	1.4.2	Exterior Doors	No maneuvering clearance at door due to stair railing, <i>leave as is</i> , correction is technically infeasible	\$0.00	n/a	2	\$0.00	2	N/A
Parking Facilities - Jackson Street Garage	Citywide Facilities	1.4.3	Exterior Doors	For all doors along the public circulation route, correct or repair slope at doorway landing to max 2.08% in any direction for level CFS	\$3,062.50	each	1	\$3,062.50	2	Staff to investigate technical feasibility
Parking Facilities - Jackson Street Garage	Citywide Facilities	1.4.4	Exterior Doors	For all doors along the public circulation route, assure drain trench doesn't create gaps greater than .5" and slope more than 2%	\$350.00	each	2	\$700.00	2	Staff to investigate technical feasibility
Parking Facilities - Jackson Street Garage	Citywide Facilities	1.4.5	Exterior Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Parking Facilities - Jackson Street Garage	Citywide Facilities	1.4.6	Exterior Doors	For all doors along the public circulation route, <i>inspect, adjust, and maintain</i> closing speed on door closers	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Parking Facilities - Jackson Street Garage	Citywide Facilities	1.4.7	Exterior Doors	For all doors along the public circulation route, replace doors with ones having sidelight viewing windows max 43" aff	\$1,386.00	each	1	\$1,386.00	2	Staff to investigate completion status
Parking Facilities - Jackson Street Garage	Citywide Facilities	1.4.8		Enlarge archway to elevator to min 80" overhead for required clearance	\$1,540.00	each	1	\$1,540.00	2	Staff to investigate technical feasibility
Parking Facilities - Jackson Street Garage	Citywide Facilities	1.4.9	Exterior Doors	Upon renovation, make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	2	Employee-only access
Parking Facilities - Jackson Street Garage	Citywide Facilities	1.5.1	Elevator	Leave as is, handrail citing construction tolerance	\$0.00	n/a	0	\$0.00	2	N/A



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Parking Facilities - Jackson Street Garage	Citywide Facilities	1.15.1	Signage	Create template for signs that addresses height of sign, size of characters, location of Braille, and other requirements	\$0.00	staff time	0	\$0.00	2	To be completed in FY22
Parking Facilities - Jackson Street Garage	Citywide Facilities	1.15.2	Signage	Implement a sign revision program throughout the building, discriminating between directional signs and signs for permanent spaces	\$0.00	staff time	0	\$0.00	2	Staff to investigate completion status
Parking Facilities - Jackson Street Garage	Citywide Facilities	1.15.3	Signage	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door	\$150.00	each	3	\$450.00	2	Staff to investigate technical feasibility
Parking Facilities - Jackson Street Garage	Citywide Facilities	1.16.1	Kiosk	Repair slope in CFS of kiosk operable parts to max 2.08%	\$122.50	sq ft	12	\$1,470.00	2	Staff to investigate technical feasibility
Parking Facilities - Jackson Street Garage	Citywide Facilities	1.16.2	Kiosk	Lower kiosk so operable parts are max 48" aff and display screen is visible from 40" aff	\$350.00	each	1	\$350.00	2	To be completed in FY22
Parking Facilities - Jackson Street Garage	Citywide Facilities	1.16.3	Kiosk	Replace kiosk controls, adding "clear" or "correct" key	\$11,000.00	each	2	\$22.000.00	2	Staff to investigate technical feasibility
Parking Facilities - Jackson Street Garage	Citywide Facilities	1.16.4	Kiosk	Replace kiosk control panel with one having tactile controls and tactile input buttons	\$11,000.00	each	2	\$22,000.00	2	Staff to investigate technical feasibility
Parking Facilities - Medical Arts Garage	Citywide Facilities	1.1.1	Parking	Repaint stalls and access aisles to be 8' and 5' each	\$73.50	each	3	\$220.50	2	To be completed in FY23
Parking Facilities - Medical Arts Garage	Citywide Facilities	1.1.2	Parking	Repair or correct slope of parking spaces and access aisles to max 2.08% in any direction	\$3,062.50	each	6	\$18,375.00	2	Staff to investigate technical feasibility
Parking Facilities - Medical Arts Garage	Citywide Facilities	1.1.3	Parking	Repair surface to eliminate water pooling	\$2,800.00	each	1	\$2,800.00	2	To be completed in FY23



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Parking Facilities - Medical Arts				Raise existing accessible parking signs so lowest		staff				
Garage	Citywide Facilities	1.1.4	Parking	end of bottom sign is min 60" aff	\$0.00	time	0	\$0.00	2	To be completed in FY22
Parking Facilities - Medical Arts	07 11 5 177	404	Exterior Accessible	Install compliant detectable warning at transitions from walkways to vehicular ways as a	4007.50			0007.50	•	0. %
Garage	Citywide Facilities	1.2.1	Route	smart practice	\$367.50	each	1	\$367.50	2	Staff to investigate completion status
Parking Facilities - Medical Arts	a	400	Exterior Accessible		\$70.50			A70.50		Staff to investigate technical feasibility
Garage	Citywide Facilities	1.2.2	Route	Repair, bevel, or ramp CIL along AR	\$73.50	each	1	\$73.50	2	
Parking Facilities - Medical Arts	a		Exterior Accessible		\$70.50			A 70.50		T
Garage	Citywide Facilities	1.2.3	Route	Correct or fill 1" gap along AR	\$73.50	each	1	\$73.50	2	To be completed in FY22
Parking Facilities - Medical Arts Garage	Citywide Facilities	1.2.4	Exterior Accessible Route	Correct or repair sidewalk cross slope along AR to max 2.08%	\$122.50	sq ft	25	\$3,062.50	2	Staff to investigate technical feasibility
Parking Facilities - Medical Arts Garage	Citywide Facilities	1.2.5	Exterior Accessible Route	Correct or repair sidewalk running slope along AR to max 5%	\$122.50	sq ft	25	\$3,062.50	2	Staff to investigate technical feasibility
Parking Facilities - Medical Arts Garage	Citywide Facilities	1.2.6		<i>Install</i> contrasting strip along front 2" of each tread	\$84.00	each	86	\$7,224.00	2	Staff to investigate completion status
Parking Facilities - Medical Arts Garage	Citywide Facilities	1.2.7	Stairs - Exterior	Install handrails on both sides of stairway, mounted 34" to 38" aff with top and bottom extensions	\$980.00	each	4	\$3,920.00	2	Staff to investigate technical feasibility
Parking Facilities - Medical Arts Garage	Citywide Facilities	1.3.1	Exterior Signage	Mount signage at entrance designating it as accessible	\$150.00	each	2	\$300.00	2	To be completed in FY22
Parking Facilities - Medical Arts Garage	Citywide Facilities	1.4.1	Exterior Doors	No maneuvering clearance at door due to stair rail, <i>leave as is,</i> correction is technically infeasible	\$0.00	n/a	0	\$0.00	2	N/A
Parking Facilities - Medical Arts Garage	Citywide Facilities	1.4.2	Exterior Doors	For all doors along the public circulation route, <i>replace hardware</i> with lever hardware where indicated	\$514.50	each	1	\$514.50	2	To be completed in FY22



			I			1				
0.4	Hoo Bird	0.4	Type of	B	5	unit	# of	T. (.)	D	Notes
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Parking Facilities				For all doors along the public circulation route,						
Medical Arts				inspect, adjust, and maintain 8.5 lbf to open		staff				
Garage	Citywide Facilities	1.4.3	Exterior Doors	exterior doors as a smart practice	\$0.00	time	0	\$0.00	2	Staff to investigate completion status
Parking Facilities				For all doors along the public circulation route,						
Medical Arts				replace doors with ones having sidelight viewing						
Garage	Citywide Facilities	1.4.4	Exterior Doors	windows max 43" aff	\$1,386.00	each	1	\$1,386.00	2	Staff to investigate completion status
Parking Facilities										
Medical Arts				<i>Upon renovation</i> , make above corrections to						
Garage	Citywide Facilities	1.4.5	Exterior Doors	employee only doors	\$0.00	n/a	0	\$0.00	2	Employee-only access
Parking Facilities				Create template for signs that addresses height						
Medical Arts				of sign, size of characters, location of Braille, and		staff				
Garage	Citywide Facilities	1.15.1	Signage	other requirements	\$0.00	time	0	\$0.00	2	Staff to investigate completion status
Parking Facilities				Implement a sign revision program throughout						
Medical Arts				the building, discriminating between directional		staff				
Garage	Citywide Facilities	1.15.2	Signage	signs and signs for permanent spaces	\$0.00	time	0	\$0.00	2	Staff to investigate completion status
				Mount signage at all permanent rooms/spaces						
				having Braille and the international symbol of						
Parking Facilities -				accessibility, mounted 48" to baseline of lowest						
Medical Arts	Citavido Eggilitica	1.15.3	Signogo	character and 60" to the baseline of the highest	\$150.00	each	2	\$300.00	2	Staff to investigate completion status
Garage	Citywide Facilities	1.15.5	Signage	character sign and on the latch side of the door	\$150.00	eacn		φ300.00		Stail to investigate completion status
Parking Facilities -										
Medical Arts	Citavida Facilities	1 16 1	Kinak	Replace kiosk controls, adding "clear" or "correct"	¢44 000 00		1	\$11.000.00	2	Ctaff to investigate to shared facelhility
Garage	Citywide Facilities	1.16.1	Kiosk	key Replace kiosk control panel with one having	\$11,000.00	each	-	\$11,000.00		Staff to investigate technical feasibility
				tactile controls and tactile input buttons assuring						
Parking Facilities				numeric keys are in 12 key ascending or						
Medical Arts Garage	Citywide Facilities	1.16.2	Kiosk	descending order with the 5 key being tactilely discernible from the others	\$11,000.00	each	1	\$11,000.00	2	Staff to investigate technical feasibility
Parking Facilities	0.0,		, week	Repaint stalls and access aisles to be 8' and 5'	* 1.1,000.00	54511	·	ψ,σσσ.σσ		Ctain to invocal gate tool in load it out in ly
Lot 1	Citywide Facilities	1.1.1	Parking	each	\$73.50	each	1	\$73.50	2	To be completed in FY23
Parking Facilities				Add one van parking sign to one accessible stall and repaint stall and access aisle to 11' and 5' or						
Lot 1	Citywide Facilities	1.1.2	Parking	8' and 8'	\$283.50	each	1	\$283.50	2	To be completed in FY23
Dadda - 5 200				Barrain ann ann an Airean (
Parking Facilities - Lot 1	Citywide Facilities	1.1.3	Parking	Repair or correct slope of parking spaces and access aisles to max 2.08% in any direction	\$3,062.50	each	1	\$3,062.50	2	To be completed in FY23
Parking Facilities	enjinas i domas		. s.iking	Relocate kiosk to provide required 30" by 48"	\$0,00 <u>2.00</u>	Caon		Ç0,00 <u>2.00</u>	_	70 % COp. 000 m 1 1 20
Lot 1	Citywide Facilities	1.1.4	Parking	clear floor space	\$350.00	each	1	\$350.00	2	To be completed in FY23



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of	Total cost	Phase	Notes
Parking Facilities	1100 Bist	Oite	COTTECTION	Recommendation	T HOE/ UIIIC	type	units	Total cost	1 11436	Hotes
Lot 1	Citywide Facilities	1.2.1	Kiosk	Resurface route to kiosk to be firm and stable	\$50.50	sq ft	24	\$1,212.00	2	To be completed in FY23
Parking Facilities - Lot 1	Citywide Facilities	1.2.2	Kiosk	See 1.1.4 above for relocation of kiosk	\$0.00	n/a	0	\$0.00	2	To be completed in FY23
Parking Facilities	Oitywide i doillies	1.2.2	Riodic	Assure new location provides level CFS with	Ψ0.00	11/4		ψ0.00		To be completed in 1 120
Lot 1	Citywide Facilities	1.2.3	Kiosk	2.08% slope or less Replace kiosk control panel with one having	\$122.50	sq ft	12	\$1,470.00	2	To be completed in FY23
Parking Facilities -				tactile controls, tactile input buttons, speech enabled feature, adding a "clear" or "correct" key and assure numbers are arranged in a 12-key ascending or descending layout with the 5 key						
Lot 1	Citywide Facilities	1.2.4	Kiosk	tactilely discernable from the others Create two or more 8' accessible parking stalls,	\$11,000.00	each	1	\$11,000.00	2	Staff to investigate technical feasibility
Parking Facilities - Lot 2	Citywide Facilities	1.1.1	Parking	with one 5' adjacent access aisle, with proper signage and striping	\$1,589.00	each	2	\$3,178.00	2	To be completed in FY22
Parking Facilities - Lot 2	Citywide Facilities	1.2.1	Kiosk	Correct or repair CIL in CFS of kiosk	\$96.25	each	1	\$96.25	2	Staff to investigate technical feasibility
Parking Facilities -	Oitywide i adiities	1.2.1	Niosk	Repair slope in CFS of kiosk operable parts to	Ψ30.23	Cacii		ψ50.25		otali to investigate technical reasibility
Lot 2	Citywide Facilities	1.2.2	Kiosk	max 2.08%	\$122.50	sq ft	12	\$1,470.00	2	Staff to investigate technical feasibility
Parking Facilities - Lot 2	Citywide Facilities	1.2.3	Kiosk	Replace kiosk control panel with one having tactile controls, tactile input buttons, speech enabled feature, adding a "clear" or "correct" key and assure numbers are arranged in a 12-key ascending or descending layout with the 5 key tactilely discernable from the others	\$11,000.00	each	1	\$11,000.00	2	Staff to investigate technical feasibility
Parking Facilities - Lot 3	Citywide Facilities	1.1.1	Parking	Create one or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping	\$1,589.00	each	1	\$1,589.00	2	To be completed in FY22
Parking Facilities - Lot 3	Citywide Facilities	1.1.2	Parking	Repaint existing stall and access aisle to be 8' and 5' each	\$73.50	each	1	\$73.50	2	To be completed in FY22
Parking Facilities - Lot 3	Citywide Facilities	1.1.3	Parking	Repair or correct slope of parking spaces and access aisles to max 2.08% in any direction	\$3,062.50	each	2	\$6,125.00	2	Staff to investigate technical feasibility
Parking Facilities - Lot 3	Citywide Facilities	1.1.4	Parking	Maintain accessible stalls to be free of debris	\$0.00	staff time	0	\$0.00	2	On-going
Parking Facilities - Lot 3	Citywide Facilities	1.1.5	Parking	Reconfigure accessible stalls to avoid requiring pedestrians to cross vehicular way, in the alternative, leave as is with striped crosswalk	\$367.50	each	1	\$367.50	2	Staff to investigate technical feasibility
Parking Facilities - Lot 3	Citywide Facilities	1.2.1	Kiosk	Correct or repair CIL in CFS of klosk and maintain to be free of debris	\$96.25	each	1	\$96.25	2	To be completed in FY22
Parking Facilities - Lot 3	Citywide Facilities	1.2.2	Kiosk	Repair slope in CFS of kiosk operable parts to max 2.08%	\$122.50	sq ft	12	\$1,470.00	2	To be completed in FY22



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
				Replace kiosk control panel with one having						
				tactile controls, tactile input buttons, speech enabled feature, adding a "clear" or "correct" key						
				and assure numbers are arranged in a 12-key ascending or descending layout with the 5 key						
Parking Facilities				tactilely discernable from the others and assure						
Lot 3	Citywide Facilities	1.2.3	Kiosk	top control in max 48" above the ground	\$11,000.00	each	1	\$11,000.00	2	Staff to investigate technical feasibility
Parking Facilities -				Create five or more 8' accessible parking stalls,						
Lot 4	Citywide Facilities	1.1.1	Parking	with one 5' adjacent access aisle, with proper signage and striping	\$1,589.00	each	5	\$7,945.00	2	Staff to investigate technical feasibility
				Make below corrections to the kiosk closest to the						, ,
Parking Facilities - Lot 4	Citywide Facilities	1.2.1	Kiosk	new accessible stalls; if stalls are dispersed, correct both	\$0.00	n/a	0	\$0.00	2	N/A
Parking Facilities	Citywide i aciiilles	1.2.1	Niosk	Repair slope in CFS of kiosk operable parts to	ψ0.00	II/a	0	ψ0.00		IN/A
Lot 4	Citywide Facilities	1.2.2	Kiosk	max 2.08%	\$122.50	sq ft	1	\$122.50	2	Staff to investigate technical feasibility
				Replace kiosk control panel with one having						
				tactile controls, tactile input buttons, speech						
				enabled feature, adding a "clear" or "correct" key						
				and assure numbers are arranged in a 12-key ascending or descending layout with the 5 key						
Parking Facilities -				tactilely discernable from the others and assure						
Lot 4 Parking Facilities	Citywide Facilities	1.2.3	Kiosk	top control in max 48" above the ground	\$11,000.00	each	1	\$11,000.00	2	Staff to investigate technical feasibility
Lot 5	Citywide Facilities	1.1.1	Parking	Designate one RV stall as accessible and assure it is 20' wide min	\$283.50	each	1	\$283.50	2	To be completed in FY22
Dankin - Facilitia				Demoint steller and access sinks to be 0' and 5'						
Parking Facilities - Lot 5	Citywide Facilities	1.1.2	Parking	Repaint stalls and access aisles to be 8' and 5' each for standard stalls and 8' and 8' for van	\$73.50	each	2	\$147.00	2	To be completed in FY22
Parking Facilities -			Ţ.							·
Lot 5	Citywide Facilities	1.1.3	Parking	Resurface stalls where deteriorating	\$2,800.00	each	1	\$2,800.00	2	Staff to investigate completion status
				Reconfigure accessible stalls to avoid requiring						
Parking Facilities	0, 1, 5, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,			pedestrians to cross vehicular way, in the	4007.50			4007.50	•	
Lot 5	Citywide Facilities	1.1.4	Parking	alternative, leave as is with striped crosswalk Create two or more 8' accessible parking stalls.	\$367.50	each	1	\$367.50	2	Staff to investigate completion status
Parking Facilities				with one 5' adjacent access aisle, with proper						
Lot 6	Citywide Facilities	1.1.1	Parking	signage and striping	\$1,589.00	each	2	\$3,178.00	2	STAFF WILL INVESTIGATE
Parking Facilities - Lot 6	Citywide Facilities	1.2.1	Kiosk	Repair slope in CFS of kiosk operable parts to max 2.08%	\$122.50	sq ft	12	\$1,470.00	2	STAFF WILL INVESTIGATE



			Type of	_		unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
				Replace kiosk control panel with one having						
				tactile controls, tactile input buttons, speech						
				enabled feature, adding a "clear" or "correct" key						
Parking Facilities				and assure numbers are arranged in a 12-key ascending or descending layout with the 5 key						
Lot 6	Citvwide Facilities	1.2.2	Kiosk	tactilely discernable from the others	\$11.000.00	each	1	\$11.000.00	2	Staff to investigate technical feasibility
Parking Facilities	Oitywide i aciiilles	1.2.2	NOSK	Repaint stalls and access aisles to be 8' and 5'	ψ11,000.00	Cacii	-	ψ11,000.00		Stan to investigate technical reasibility
Lot 7	Citywide Facilities	1.1.1	Parking	each where faded or incorrect in width	\$73.50	each	4	\$294.00	2	To be completed in FY22
D				Barrain and a surrant of a surficient and a surficient an						
Parking Facilities - Lot 7	Citywide Facilities	1.1.2	Parking	Repair or correct slope of parking spaces and access aisles to max 2.08% in any direction	\$3,062.50	each	8	\$24,500.00	2	Staff to investigate technical feasibility
Parking Facilities	Citywide Facilities	1.1.2	Parking	access aisies to max 2.06% in any direction	\$5,062.50	staff	0	φ24,500.00		Stail to investigate technical leasibility
Lot 7	Citywide Facilities	1.1.3	Parking	Maintain accessible stalls to be free of debris	\$0.00	time	0	\$0.00	2	On-going
				Add one van parking sign to van accessible stall	-					<u> </u>
Parking Facilities -				and assure stall and access aisle are 11' and 5' or						
Lot 7	Citywide Facilities	1.1.4	Parking	8' and 8'	\$283.50	each	1	\$283.50	2	To be completed in FY22
				Make below corrections to the kiosk closest to the						
Parking Facilities	6., =		12: 1	accessible stalls; if stalls are dispersed, correct	**	,		**	•	0. 5
Lot 7	Citywide Facilities	1.2.1	Kiosk	both Repair slope in CFS of kiosk operable parts to	\$0.00	n/a	0	\$0.00	2	Staff to investigate technical feasibility
Parking Facilities - Lot 7	Citywide Facilities	1.2.2	Kiosk	max 2.08%	\$122.50	sq ft	12	\$1,470.00	2	Staff to investigate technical feasibility
LOT 1	Citywide Facilities	1.2.2	KIUSK		φ122.30	Sq It	12	φ1,470.00		Stail to investigate technical reasibility
				Replace kiosk control panel with one having						
				tactile controls, tactile input buttons, speech						
				enabled feature, adding a "clear" or "correct" key						
				and assure numbers are arranged in a 12-key						
				ascending or descending layout with the 5 key						
Parking Facilities				tactilely discernable from the others and assure						
Lot 7	Citywide Facilities	1.2.3	Kiosk	top control in max 48" above the ground	\$11,000.00	each	1	\$11,000.00	2	Staff to investigate technical feasibility
Parking Facilities	0,, 1, 5, 1,,,	404	12: 1	B	011 000 00			044.000.00	0	0. " "
Lot 7	Citywide Facilities	1.2.4	Kiosk	Replace screens with ones providing less glare	\$11,000.00	each	1	\$11,000.00	2	Staff will investigate completion status
Parking Facilities				Create two or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper						
Lot 8	Citywide Facilities	1.1.1	Parking	signage and striping	\$1,589.00	each	2	\$3,178.00	2	Staff will investigate completion status
Parking Facilities	Citywide i dollides	1.1.1	ranking	Repair surface of AR to kiosk to be firm and	ψ1,000.00	Cuon		ψο, 17 0.00	_	Cian will invodigate completion status
Lot 8	Citywide Facilities	1.2.1	Kiosk	stable	\$50.50	sq ft	24	\$1,212.00	2	To be completed in FY22
Parking Facilities										·
Lot 8	Citywide Facilities	1.2.2	Kiosk	Correct CIL and gap in CFS of kiosk	\$96.25	each	1	\$96.25	2	To be completed in FY22
Parking Facilities				Repair slope in CFS of kiosk operable parts to		_				
Lot 8	Citywide Facilities	1.2.3	Kiosk	max 2.08%	\$122.50	sq ft	12	\$1,470.00	2	Staff to investigate technical feasibility



					I	1	1			
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Oite	1100 Bist	Oite	Correction	Recommendation	1 Tice/ dilic	type	units	Total cost	1 11436	Notes
				Replace kiosk control panel with one having						
				tactile controls, tactile input buttons, speech						
				enabled feature, adding a "clear" or "correct" key						
				and assure numbers are arranged in a 12-key						
				ascending or descending layout with the 5 key						
Parking Facilities				tactilely discernable from the others and assure						
Lot 8	Citywide Facilities	1.2.4	Kiosk	top control in max 48" above the ground	\$11,000.00	each	1	\$11,000.00	2	Staff to investigate technical feasibility
Parking Facilities				Repair or correct slope of parking spaces and						
Lot 9	Citywide Facilities	1.1.1	Parking	access aisles to max 2.08% in any direction	\$3,062.50	each	7	\$21,437.50	2	Staff to investigate technical feasibility
Parking Facilities -	Oitywide i dointies	1.1.1	ranking	Relocate north stall and ramp stall to a location	ψ0,002.00	Cuon	'	Ψ21,401.00		Otali to investigate teorimeal reasibility
Lot 9	Citywide Facilities	1.1.2	Parking	without a drain	\$73.50	each	2	\$147.00	2	To be completed in FY22
Parking Facilities -	•			Remove ramp from shared access aisle and	·					
Lot 9	Citywide Facilities	1.1.3	Parking	create a curb ramp	\$6,510.00	each	1	\$6,510.00	2	Staff to investigate technical feasibility
Parking Facilities -				Raise existing accessible parking signs so lowest		staff				
Lot 9	Citywide Facilities	1.1.4	Parking	end of bottom sign is min 60" aff	\$0.00	time	0	\$0.00	2	To be completed in FY22
Parking Facilities	0, 1, 5, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,		10. 1	Repair slope in CFS of kiosk operable parts to	*****		40	* 4 4 7 0 00		0. 5
Lot 9	Citywide Facilities	1.2.1	Kiosk	max 2.08%	\$122.50	sq ft	12	\$1,470.00	2	Staff to investigate technical feasibility
				Replace kiosk control panel with one having						
				tactile controls, tactile input buttons, speech						
				enabled feature, adding a "clear" or "correct" key						
				and assure numbers are arranged in a 12-key						
				ascending or descending layout with the 5 key						
Parking Facilities -				tactilely discernable from the others and assure						
Lot 9	Citywide Facilities	1.2.2	Kiosk	top control in max 48" above the ground	\$11,000.00	each	1	\$11,000.00	2	Staff to investigate technical feasibility
Dayleing Facilities				Create three or more 8' accessible parking stalls,						
Parking Facilities - Lot 10	Citywide Facilities	1.1.1	Parking	with one 5' adjacent access aisle, with proper signage and striping	\$1,589.00	each	3	\$4,767.00	2	Staff to investigate technical feasibility
Lot 10	Oitywide i aciiilles	1.1.1	raiking	and striping	ψ1,303.00	Cacii		ψ+,707.00		otali to investigate technical reasibility
Parking Facilities				Correct CIL in CFS of kiosk and maintain to be						
Lot 10	Citywide Facilities	1.2.1	Kiosk	free of debris	\$96.25	each	1	\$96.25	2	To be completed in FY22
Parking Facilities	07 11 5 777	400	le: I	Repair slope in CFS of kiosk operable parts to	0400 50		40	04 470 00	0	T
Lot 10	Citywide Facilities	1.2.2	Kiosk	max 2.08%	\$122.50	sq ft	12	\$1,470.00	2	To be completed in FY22
				Replace kiosk control panel with one having						
				tactile controls, tactile input buttons, speech						
				enabled feature, adding a "clear" or "correct" key						
				and assure numbers are arranged in a 12-key						
				ascending or descending layout with the 5 key						
Parking Facilities	a =			tactilely discernable from the others and assure						2. 2
Lot 10	Citywide Facilities	1.2.3	Kiosk	top control in max 48" above the ground	\$11,000.00	each	1	\$11,000.00	2	Staff to investigate technical feasibility



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Parking Facilities				Repair or correct slope of parking spaces and						
Lot 15	Citywide Facilities	1.1.1	Parking	access aisles to max 2.08% in any direction	\$3,062.50	each	6	\$18,375.00	2	Staff to investigate technical feasibility
B 11 E 1111						. "				
Parking Facilities - Lot 15	Citywide Facilities	1.1.2	Parking	Maintain stalls to be free of debris	\$0.00	staff time	0	\$0.00	2	On-going
	•							·		<u> </u>
Parking Facilities				Reconfigure accessible stalls to avoid requiring pedestrians to cross vehicular way, in the						
Lot 15	Citywide Facilities	1.1.3	Parking	alternative, leave as is with striped crosswalk	\$367.50	each	1	\$367.50	2	Staff to investigate technical feasibility
				Create a curb ramp to be max running slope						
				8.33%, max cross slope 2.08%, having a top landing as wide as the ramp and 36" deep and						
				side flares with a max slope 10% for access to pay						
Parking Facilities	Cityanida Facilitias	101	Visak	station and create required 30" by 48" CFS at	¢4 407 F0	b	4	¢4 407 50	0	Ctaff to investigate to shair all face in ility
Lot 15	Citywide Facilities	1.2.1	Kiosk	kiosk	\$1,487.50	each	1	\$1,487.50	2	Staff to investigate technical feasibility
Parking Facilities				Repair slope in CFS of kiosk operable parts to						
Lot 15	Citywide Facilities	1.2.2	Kiosk	max 2.08%	\$122.50	sq ft	12	\$1,470.00	2	Staff to investigate technical feasibility
				Replace kiosk control panel with one having						
				tactile controls, tactile input buttons, speech						
				enabled feature, adding a "clear" or "correct" key						
				and assure numbers are arranged in a 12-key ascending or descending layout with the 5 key						
Parking Facilities				tactilely discernable from the others and assure						
Lot 15	Citywide Facilities	1.2.3	Kiosk	top control in max 48" above the ground	\$11,000.00	each	1	\$11,000.00	2	Staff to investigate technical feasibility
Parking Facilities				Create one or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper						
Lot 16	Citywide Facilities	1.1.1	Parking	signage and striping	\$1,589.00	each	1	\$1,589.00	2	Staff to investigate technical feasibility
5 5				_ , , , , , , , , , , , , , , , , , , ,						
Parking Facilities - Lot 16	Citywide Facilities	1.1.2	Parking	Repair or correct slope of parking spaces and access aisles to max 2.08% in any direction	\$3,062.50	each	3	\$9,187.50	2	Staff to investigate technical feasibility
20110	Oilywide I dollides	1.1.2	ranning	decess distes to max 2.56 % in any direction	ψ0,002.00	Cuon	0	ψο, τον .σο		Stan to investigate technical reasistinty
Parking Facilities				Raise existing accessible parking signs so lowest		staff				
Lot 16	Citywide Facilities	1.1.3	Parking	end of bottom sign is min 60" aff Replace kiosk control panel with one having	\$0.00	time	0	\$0.00	2	To be completed in FY22
				tactile controls, tactile input buttons, speech						
				enabled feature, adding a "clear" or "correct" key						
Parking Facilities - Kiosks - Front				and assure numbers are arranged in a 12-key ascending or descending layout with the 5 key						
Street	Citywide Facilities	1.1.1	Kiosk	tactilely discernable from the others	\$11,000.00	each	1	\$11,000.00	2	N/A



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Parking Facilities - Kiosks - Park Avenue	Citywide Facilities	1.1.1	Kiosk	Leave as is, kiosk 03 and make corrections to 05 and 06 same block	\$0.00	n/a	0	\$0.00	2	N/A
Parking Facilities - Kiosks - Park			12: 1	Repair cross slope of route to kiosk 05 to max	0400.50		40			OTAFFAMILL INN/FOTIOATE
Avenue Parking Facilities - Kiosks - Park	Citywide Facilities	1.1.2	Kiosk	2.08% Repair slope in CFS of kiosk operable parts to max 2.08%; choose either 04 or 02 based on	\$122.50	sq ft	12	\$1,470.00	2	STAFF WILL INVESTIGATE
Avenue Parking Facilities - Kiosks - Park	Citywide Facilities	1.1.3	Kiosk	addition of accessible parking on the block Replace kiosk control panel with one having tactile controls, tactile input buttons, speech enabled feature, adding a "clear" or "correct" key and assure numbers are arranged in a 12-key ascending or descending layout with the 5 key	\$122.50	sq ft	12	\$1,470.00	2	STAFF WILL INVESTIGATE
Avenue Parking Facilities - Kiosks - Placer	Citywide Facilities	1.1.4	Kiosk	tactilely discernable from the others	\$11,000.00	each	2	\$22,000.00	2	Staff to investigate technical feasibility
Avenue Parking Facilities - Kiosks - Placer Avenue	Citywide Facilities Citywide Facilities	1.1.1	Kiosk Kiosk	Resurface AR to kiosk to be firm and stable Replace kiosk control panel with one having tactile controls, tactile input buttons, speech enabled feature, adding a "clear" or "correct" key and assure numbers are arranged in a 12-key ascending or descending layout, the 5 key tactilely discernable from others	\$2,800.00 \$11,000.00	each	1	\$2,800.00 \$11,000.00	2	Staff to investigate technical feasibility Staff to investigate technical feasibility
Parking Facilities - Kiosks - Lawrence Street	Citywide Facilities	1.1.1	Kiosk	Leave as is, kiosk 02 and assure kiosk 01 becomes accessible	\$0.00	n/a	0	\$0.00	2	N/A
Parking Facilities - Kiosks - Lawrence Street	Citywide Facilities	1.1.2	Kiosk	Replace kiosk control panel on kiosk 01 with one having tactile controls, tactile input buttons, speech enabled feature, adding a "clear" or "correct" key and assure numbers are arranged in a 12-key ascending or descending layout with the 5 key tactilely discernable from the others	\$11,000.00	each	1	\$11,000.00	2	Staff to investigate technical feasibility
Parking Facilities - Kiosks - 6th Avenue	Citywide Facilities	1.1.1	Kiosk	Provide required 30" by 48" CFS at kiosk 02	\$67.25	sq ft	12	\$807.00	2	Staff to investigate technical feasibility



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit	# of units	Total cost	Phase	Notes
Site	ncc bist	Cite	correction	Recommendation	FIICE/ UIIIL	type	uiiits	i otai cost	Filase	Notes
Parking Facilities										
Kiosks - 6th				Repair slope in CFS of pay kiosk operable parts						
Avenue	Citywide Facilities	1.1.2	Kiosk	to max 2.08%	\$122.50	sq ft	12	\$1,470.00	2	Staff to investigate technical feasibility
				Replace kiosk control panel with one having tactile controls, tactile input buttons, speech						
				enabled feature, adding a "clear" or "correct" key						
				and assure numbers are arranged in a 12-key						
Parking Facilities - Kiosks - 6th				ascending or descending layout with the 5 key tactilely discernable from the others and assure						
Avenue	Citywide Facilities	1.1.3	Kiosk	top row is max 48" aff	\$11,000.00	each	1	\$11,000.00	2	Staff to investigate technical feasibility
					,					, ,
D 1: E 399										
Parking Facilities - Kiosks -				Repair slope in CFS of pay kiosk operable parts						
Broadway Street	Citywide Facilities	1.1.1	Kiosk	to max 2.08%	\$122.50	sq ft	12	\$1,470.00	2	Staff to investigate technical feasibility
				Replace kiosk control panel with one having						
				tactile controls, tactile input buttons, speech enabled feature, adding a "clear" or "correct" key						
Parking Facilities				and assure numbers are arranged in a 12-key						
Kiosks -				ascending or descending layout with the 5 key						
Broadway Street	Citywide Facilities	1.1.2	Kiosk	tactilely discernable from the others	\$11,000.00	each	1	\$11,000.00	2	Staff to investigate technical feasibility
Parking Facilities										
Kiosks - Fuller				Repair slope in CFS of pay kiosk operable parts						
Avenue	Citywide Facilities	1.1.1	Kiosk	to max 2.08%	\$122.50	sq ft	12	\$1,470.00	2	Staff to investigate technical feasibility
Parking Facilities										
Kiosks - Fuller				Leave as is, kiosks 08, 02 and 05 and assure						
Avenue	Citywide Facilities	1.1.2	Kiosk	other kiosks on the block become accessible	\$0.00	n/a	0	\$0.00	2	N/A
				Replace kiosk control panel with one having tactile controls, tactile input buttons, speech						
				enabled feature, adding a "clear" or "correct" key						
Parking Facilities				and assure numbers are arranged in a 12-key						
Kiosks - Fuller				ascending or descending layout with the 5 key						
Avenue	Citywide Facilities	1.1.3	Kiosk	tactilely discernable from the others	\$11,000.00	each	6	\$66,000.00	2	Staff to investigate technical feasibility
Parking Facilities										
Kiosks - Last				Repair slope in CFS of pay kiosk operable parts						
Chance Gulch	Citywide Facilities	1.1.1	Kiosk	to max 2.08%	\$122.50	sq ft	24	\$2,940.00	2	Staff to investigate technical feasibility
Parking Facilities										
Kiosks - Last				Leave as is, kiosks 08, 02 and 05 and assure						
Chance Gulch	Citywide Facilities	1.1.2	Kiosk	other kiosks on the block become accessible	\$0.00	n/a	0	\$0.00	2	N/A



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Oite	1100 Bist	Oite	Correction	Replace kiosk control panel with one having	T TICE/ UTIL	туре	units	Total cost	1 Hase	110.63
				tactile controls, tactile input buttons, speech enabled feature, adding a "clear" or "correct" key						
Parking Facilities				and assure numbers are arranged in a 12-key						
Kiosks - Last	Ohanida Farilikia	440	IX:I-	ascending or descending layout with the 5 key	¢44.000.00			#00.000.00	2	Chaff has in the standard has also in all face the life.
Chance Gulch	Citywide Facilities	1.1.3	Kiosk	tactilely discernable from the others	\$11,000.00	each	9	\$99,000.00	2	Staff to investigate technical feasibility
				Create or repair a curb ramp to be max running						
Parking Facilities -				slope 8.33%, max cross slope 2.08%, having a top landing as wide as the ramp and 36" deep and						
Kiosks - Jackson Street	Citywide Facilities	1.1.1	Kiosk	side flares with a max slope 10% for access to sidewalk from accessible stall at kiosk 07 and 03	\$1,487.50	each	2	\$2,975.00	2	Staff to investigate technical feasibility
Sileet	Citywide Facilities	1.1.1	NIUSK	Sidewaik Hoffi accessible stall at klosk 07 and 03	φ1,407.30	eacii		φ2,973.00	2	Stan to investigate technical leasibility
Parking Facilities - Kiosks - Jackson				Repair slope in CFS of pay kiosk operable parts						
Street	Citywide Facilities	1.1.2	Kiosk	to max 2.08%	\$122.50	sq ft	24	\$2,940.00	2	Staff to investigate technical feasibility
Parking Facilities										
Kiosks - Jackson				Leave as is, kiosks 04, 06 and 02 and assure						
Street	Citywide Facilities	1.1.3	Kiosk	other kiosks on the block become accessible Replace kiosk control panel with one having	\$0.00	n/a	0	\$0.00	2	N/A
				tactile controls, tactile input buttons, speech						
				enabled feature, adding a "clear" or "correct" key and assure numbers are arranged in a 12-key						
Parking Facilities				ascending or descending layout with the 5 key						
Kiosks - Jackson Street	Citywide Facilities	1.1.4	Kiosk	tactilely discernable from the others assuring top row of controls are max 48" aff	\$11,000.00	each	4	\$44,000.00	2	Staff to investigate technical feasibility
Davida a Facilitia				M/h	,			· ,		, ,
Parking Facilities - Meters - Front				When street or sidewalk projects are planned, correct issues with route and clear floor space at		staff				Will be addressed with sidewalk
Street	Citywide Facilities	1.1.1	Meters	meters as noted Lower meter controls to max 48" to the top	\$0.00	time	0	\$0.00	2	reconstruction
Parking Facilities				operable part and display screen is visible from a						Complete
Meters - Front Street	Citywide Facilities	1.1.2	Meters	point located 40" max above the center of the CFS in front of the machine	\$0.00	staff time	0	\$0.00	2	Complete
	Oitywide Facilities	1.1.2	INICIGIS		ψ0.00	unie	U	φυ.υυ	2	
Parking Facilities - Meters - Park				When street or sidewalk projects are planned, correct issues with route and clear floor space at		staff				Will be addressed with sidewalk
Avenue	Citywide Facilities	1.1.1	Meters	meters as noted	\$0.00	time	0	\$0.00	2	reconstruction
Parking Facilities -				Lower meter controls to max 48" to the top operable part and display screen is visible from a						
Meters - Park				point located 40" max above the center of the CFS	40.55	staff		40.55		Complete
Avenue	Citywide Facilities	1.1.2	Meters	in front of the machine	\$0.00	time	0	\$0.00	2	



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Parking Facilities -				When street or sidewalk projects are planned,						
Meters - Placer				correct issues with route and clear floor space at		staff				Will be addressed with sidewalk
Avenue	Citywide Facilities	1.1.1	Meters	meters as noted	\$0.00	time	0	\$0.00	2	reconstruction
5 II 5 III				Lower meter controls to max 48" to the top						
Parking Facilities - Meters - Placer				operable part and display screen is visible from a point located 40" max above the center of the CFS		staff				Complete
Avenue	Citywide Facilities	1.1.2	Meters	in front of the machine	\$0.00	time	0	\$0.00	2	
7.17.011.00	onymus i dominos			THE THE STATE OF T	Ψ0.00			ψο.οο	_	
Parking Facilities				When street or sidewalk projects are planned,						
Meters - Lawrence Street	Cityavida Eggilitica	111	Meters	correct issues with route and clear floor space at meters as noted	\$0.00	staff time	0	\$0.00	2	Will be addressed with sidewalk
Lawrence Street	Citywide Facilities	1.1.1	Meters	Interes as noted	\$0.00	ume	0	φυ.υυ		reconstruction
				Lower meter controls to max 48" to the top						
Parking Facilities -				operable part and display screen is visible from a						Complete
Meters -				point located 40" max above the center of the CFS		staff				
Lawrence Street	Citywide Facilities	1.1.2	Meters	in front of the machine	\$0.00	time	0	\$0.00	2	
Parking Facilities				When street or sidewalk projects are planned,						
Meters - 6th				correct issues with route and clear floor space at		staff				Will be addressed with sidewalk
Avenue	Citywide Facilities	1.1.1	Meters	meters as noted	\$0.00	time	0	\$0.00	2	reconstruction
				Lower meter controls to max 48" to the top						
Parking Facilities				operable part and display screen is visible from a		, ,,				Complete
Meters - 6th Avenue	Citywide Facilities	1.1.2	Meters	point located 40" max above the center of the CFS in front of the machine	\$0.00	staff time	0	\$0.00	2	·
Avenue	Citywide i aciities	1.1.2	Meters	Lower meter controls to max 48" to the top	ψ0.00	unie	0	ψ0.00		
Parking Facilities				operable part and display screen is visible from a						Complete
Meters - Fuller				point located 40" max above the center of the CFS		staff				Complete
Avenue	Citywide Facilities	1.1.1	Meters	in front of the machine	\$0.00	time	0	\$0.00	2	
Parking Facilities				When street or sidewalk projects are planned,						
Meters - Cruse				correct issues with route and clear floor space at		staff				Will be addressed with sidewalk
Street	Citywide Facilities	1.1.1	Meters	meters as noted	\$0.00	time	0	\$0.00	2	reconstruction
				Lower meter controls to max 48" to the top						
Parking Facilities				operable part and display screen is visible from a		at-#				Complete
Meters - Cruse Street	Citywide Facilities	1.1.2	Meters	point located 40" max above the center of the CFS in front of the machine	\$0.00	staff time	0	\$0.00	2	·
Olifoti	•	1.1.2	Wickers	Create one or more 8' accessible parking stalls,	ψ0.00	unic	3	ψ0.00		
Peanut Park	Helena Citizens	1.1.1	Parking	with one 5' adjacent access aisle, with proper	\$1,135.00	each	1	\$1,135.00	СО	Complete
	Council District 3			signage and striping						•
	Helena Citizens		Exterior	Create AR with crushed and compacted stone or						
Peanut Park	Council District 3	1.2.1	Accessible	similar outdoor material from parking or sidewalk	\$48.00	lin ft	100	\$4,800.00	CO	Complete
			Route	to site amenities						



							I			
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Peanut Park	Helena Citizens Council District 3	1.10.1	Park Site	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, and locate along new AR as a smart practice	\$115.00	each	1	\$115.00	со	Complete
Performance Square	Helena Citizens Council District 1	1.2.1	Exterior Accessible Route	Repair, bevel, or ramp CIL along AR	\$68.75	each	1	\$68.75	1	Complete
Performance Square	Helena Citizens Council District 1	1.2.2	Exterior Accessible Route	Correct or fill gaps along AR	\$20.00	sq ft	25	\$500.00	1	Complete
Performance Square	Helena Citizens Council District 1	1.2.1	Ramp	Reconfigure last flight of stairs to provide required 60" landing at ramp	\$4,042.50	each	1	\$4,042.50	1	Incomplete
Performance Square	Helena Citizens Council District 1	1.2.2	Ramp	Install handrails on both sides of the ramp	\$700.00	each	1	\$700.00	1	Incomplete
Performance Square	Helena Citizens Council District 1	1.2.1	Stairs	Correct riser heights on stairs so they are a consistent height between 4" to 7"; leave as is if technically infeasible	\$288.75	each	21	\$6,063.75	1	Incomplete
Performance Square	Helena Citizens Council District 1	1.2.2	Stairs	Correct tread depth on stairs so they are 11" minimum and consistent, leave as is if technically infeasible	\$288.75	each	20	\$5,775.00	1	Incomplete
Performance Square	Helena Citizens Council District 1	1.2.3	Stairs	Install kick plates on all stairs or replace with ones having closed risers	\$60.00	each	21	\$1,260.00	1	Incomplete
Performance Square	Helena Citizens Council District 1	1.2.4	Stairs	Provide contrast on leading 2" of each tread	\$20.00	each	20	\$400.00	1	Incomplete
Performance Square	Helena Citizens Council District 1	1.2.5	Stairs	Install detectable warning strip on top tread of each stairway as a smart practice	\$150.00	each	1	\$150.00	1	Incomplete
Performance Square	Helena Citizens Council District 1	1.2.6	Stairs	Replace handrails on both sides of stairway, mounted 34" to 38" aff with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max	\$700.00	each	1	\$700.00	1	Incomplete
Performance Square	Helena Citizens Council District 1	1.10.1	Park Site	See recommendations 1.2.1 and 1.2.2 for ramp corrections to performance stage	\$0.00	n/a	0	\$0.00	1	N/A
Ramey Park	Helena Citizens Council District 6	1.1.1	Parking	Resurface stalls and access aisles to eliminate depressions, gaps, and cracks	\$2,000.00	each	1	\$2,000.00	3	N/A School District property
Ramey Park	Helena Citizens Council District 6	1.1.2	Parking	Repair or correct slope of parking space and access aisle to max 2.08% in any direction	\$2,187.50	each	1	\$2,187.50	3	N/A School District property
Ramey Park	Helena Citizens Council District 6	1.2.1	Exterior Accessible Route	Create a curb ramp to be max running slope 8.33%, max cross slope 2.08%, having a top landing as wide as the ramp and 36" deep and side flares with a max slope 10%	\$1,062.50	each	1	\$1,062.50	3	N/A School District property
Ramey Park	Helena Citizens Council District 6	1.2.2	Exterior Accessible Route	Repair, bevel, or ramp CIL along AR	\$68.75	each	1	\$68.75	3	N/A School District property



Site	HCC Dist	Cite	Type of	Becommendation	Price/ unit	unit	# of	Total cost	Dhoos	Notes
Site	HCC DIST	Cite	correction	Recommendation	Price/ unit	type	units	l otal cost	Phase	Notes
Ramey Park	Helena Citizens Council District 6	1.2.3	Exterior Accessible Route	See 1.10 below for AR to site elements	\$0.00	n/a	0	\$0.00	3	N/A School District property
Ramey Park	Helena Citizens Council District 6	1.3.1	Playground Entry	Acquire and install intended user signage and mount at designated entry as a smart practice	\$150.00	each	1	\$150.00	со	N/A School District property
Ramey Park	Helena Citizens Council District 6	1.4.1	Playground Surface	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs	\$7,500.00	each	1	\$7,500.00	2	N/A School District property
Ramey Park	Helena Citizens Council District 6	1.4.2	Playground Surface	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces	\$0.00	staff time	0	\$0.00	СО	N/A School District property
Ramey Park	Helena Citizens Council District 6	1.4.3	Playground Surface	Establish protocols for regular and frequent inspection and maintenance of accessible playground surface	\$0.00	staff time	0	\$0.00	CO	N/A School District property
Ramey Park	Helena Citizens Council District 6	1.5.1	Transfer System	Consider adding second transfer system as a smart practice	\$3,550.00	each	1	\$3,550.00	со	N/A School District property
Ramey Park	Helena Citizens Council District 6	1.5.2	Transfer System	Lower platform on transfer system to 11" to 18" aff, in the alternative, add and maintain surface fill level to achieve the same	\$250.00	each	1	\$250.00	co	N/A School District property
Ramey Park	Helena Citizens Council District 6	1.7.1	EPCs	Lower entry to crawl tunnels to max 8" aff	\$250.00	each	2	\$500.00	со	N/A School District property
Ramey Park	Helena Citizens Council District 6	1.7.2	EPCs	Adjust height of platform decks to max 8" for access to EPCs, in the alternative, install compliant transfer steps	\$1,000.00	each	2	\$2,000.00	со	N/A School District property
Ramey Park	Helena Citizens Council District 6	1.7.3	EPCs	Leave as is, remaining EPCs as the above correction will meet 50%	\$0.00	n/a	0	\$0.00	со	N/A School District property
Ramey Park	Helena Citizens Council District 6	1.8.1	GLPCs	See recommendation 1.4.1 for surface corrections	\$0.00	n/a	0	\$0.00	со	N/A School District property
Ramey Park	Helena Citizens Council District 6	1.8.2	GLPCs	Add one more type of GLPC such as swing, spinner or rocker, to meet incentive scoping	\$2,000.00	each	1	\$2,000.00	со	N/A School District property
Ramey Park	Helena Citizens Council District 6	1.10.1	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to ball fields	\$48.00	lin ft	100	\$4,800.00	3	N/A School District property
Ramey Park	Helena Citizens Council District 6	1.10.2	Park Site	Leave as is ball field 1 and designate ball field 2	\$0.00	n/a	0	\$0.00	3	N/A School District property
Ramey Park	Helena Citizens Council District 6	1.10.3	Park Site	Replace <u>drinking fountain</u> with a hi-lo bowl fountain	\$3,998.75	each	1	\$3,998.75	3	N/A School District property
Ramey Park	Helena Citizens Council District 6	1.10.4	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the drinking fountain	\$48.00	lin ft	50	\$2,400.00	3	N/A School District property
Ramey Park	Helena Citizens Council District 6	1.10.5	Park Site	Relocate 20% of garbage cans to be along AR	\$0.00	staff time	0	\$0.00	3	N/A School District property



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Ramey Park	Helena Citizens Council District 6	1.10.6	Park Site	Extend AR to grill	\$48.00	lin ft	50	\$2,400.00	3	N/A School District property
Ramey Park	Helena Citizens Council District 6	1.10.7	Park Site	Relocate bike rack to be along the AR	\$0.00	staff time	0	\$0.00	3	N/A School District property
Ramey Park	Helena Citizens Council District 6	1.10.8	Park Site	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, install at least one armrest and locate along an AR as a smart practice	\$115.00	each	1	\$115.00	3	N/A School District property
Ramey Park	Helena Citizens Council District 6	1.10.9	Park Site	Replace or add one <u>picnic table</u> with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table as a smart practice	\$800.00	each	1	\$800.00	3	N/A School District property
Robinson Park	Helena Citizens Council District 6	1.1.1	Parking	Repaint stalls and access aisles to be 8' and 8' each	\$52.50	each	2	\$105.00	СО	Staff will invesitigate feasibility of on- street designated ADA spaces
Robinson Park	Helena Citizens Council District 6	1.1.2	Parking	Add one van parking sign to one accessible stall and repaint stall and access aisle to 11' and 5' or 8' and 8'	\$202.50	each	2	\$405.00	СО	N/A
Robinson Park	Helena Citizens Council District 6	1.1.3	Parking	Repair or correct slope of parking space and access aisle to max 2.08% in any direction	\$2,187.50	each	2	\$4,375.00	СО	N/A
Robinson Park	Helena Citizens Council District 6	1.1.4	Parking	Mount no parking signage to prevent cars from parking and blocking curb ramp	\$150.00	each	2	\$300.00	СО	N/A
Robinson Park	Helena Citizens Council District 6	1.2.1	Exterior Accessible Route	Create lined cross walk where pedestrian pathway crosses through vehicular traffic as a smart practice	\$262.50	each	1	\$262.50	CO	Incomplete
Robinson Park	Helena Citizens Council District 6	1.2.2	Exterior Accessible Route	Create a level landing at the top of the curb ramp, 36" deep and as wide as ramp	\$87.50	sq ft	32	\$2,800.00	со	Complete
Robinson Park	Helena Citizens Council District 6	1.2.3	Exterior Accessible Route	Correct slope of curb ramp side flares to max 10%	\$725.00	each	1	\$725.00	CO	Incomplete
Robinson Park	Helena Citizens Council District 6	1.2.4	Exterior Accessible Route	Correct curb ramp slope to max 8.33%	\$725.00	each	3	\$2,175.00	со	Incomplete
Robinson Park	Helena Citizens Council District 6	1.2.5	Exterior Accessible Route	Install compliant detectable warning at curb ramps as a smart practice	\$235.00	each	3	\$705.00	со	Incomplete
Robinson Park	Helena Citizens Council District 6	1.2.6	Exterior Accessible Route	Repair, bevel, or ramp CIL along AR	\$68.75	each	2	\$137.50	со	Complete
Robinson Park	Helena Citizens Council District 6	1.2.7	Exterior Accessible Route	Correct or fill gaps along AR	\$68.75	each	2	\$137.50	СО	Complete



						l	l			
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Robinson Park	Helena Citizens Council District 6	1.2.8	Exterior Accessible Route	See 1.10 below for AR to site elements	\$0.00	n/a	0	\$0.00	со	N/A
Robinson Park	Helena Citizens Council District 6	1.10.1	Park Site	Relocate garbage can to be along AR	\$0.00	staff time	0	\$0.00	со	Complete
Robinson Park	Helena Citizens Council District 6	1.10.2	Park Site	Enlarge pads at least 36" by 48" adjacent to 20% of benches as a smart practice	\$115.00	each	1	\$115.00	со	Incomplete
Robinson Park	Helena Citizens Council District 6	1.10.3	Park Site	Raise bench seat to 17" to 19" aff as a smart practice	\$250.00	each	1	\$250.00	со	Complete
Robinson Park	Helena Citizens Council District 6	1.10.4	Park Site	Acquire and install at least one armrest to 20% of existing benches as a smart practice	\$70.00	each	1	\$70.00	СО	Complete
Robinson Park	Helena Citizens Council District 6	1.11.1	Shelters	Replace 20% of the picnic tables with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around the table as a smart practice	\$800.00	each	1	\$800.00	со	Complete
Robinson Park	Helena Citizens Council District 6	1.11.2	Shelters	Create AR with crushed and compacted stone or similar outdoor material from sidewalk to shelter	\$48.00	lin ft	100	\$4,800.00	СО	To be completed in FY23
Robinson Park	Helena Citizens Council District 6	1.11.3	Shelters	Repair, bevel or ramp CIL at shelter entry	\$68.75	each	1	\$68.75	со	To be completed in FY23
Robinson Park	Helena Citizens Council District 6	1.11.4	Shelters	Relocate garbage to be along the AR	\$0.00	staff time	0	\$0.00	со	Complete
Selma Held Park	Helena Citizens Council District 7	1.3.1	Playground Entry	Fill and compact crushed stone surface so that it maintains its accessibility characteristics	\$5,000.00	each	1	\$5,000.00	3	Complete
Selma Held Park	Helena Citizens Council District 7	1.4.1	Playground Surface	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs	\$5,000.00	each	1	\$5,000.00	2	Complete
Selma Held Park	Helena Citizens Council District 7	1.5.1	Transfer System	Consider adding second transfer system as a smart practice	\$3,550.00	each	1	\$3,550.00	3	Complete
Selma Held Park	Helena Citizens Council District 7	1.8.1	GLPCs	See recommendation 1.4.1 for surface corrections	\$0.00	n/a	0	\$0.00	3	Complete
Selma Held Park	Helena Citizens Council District 7	1.9.1	Sand Box	Lower play table surface to max 31" aff	\$250.00	each	1	\$250.00	3	Complete
Selma Held Park	Helena Citizens Council District 7	1.10.1	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the gardens	\$48.00	lin ft	100	\$4,800.00	2	Complete
Selma Held Park	Helena Citizens Council District 7	1.10.2	Park Site	Consider providing raised garden beds for use by patrons with disabilities	\$500.00	each	2	\$1,000.00	2	Complete
Selma Held Park	Helena Citizens Council District 7	1.10.3	Park Site	Replace one spigot with one operable without a tight pinch or grasp	\$367.50	each	1	\$367.50	2	Complete
Selma Held Park	Helena Citizens Council District 7	1.10.4	Park Site	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, install at least one armrest and locate along an AR as a smart practice	\$115.00	each	1	\$115.00	2	Incomplete



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Selma Held Park	Helena Citizens Council District 7	1.10.5	Park Site	Replace one picnic table with one having knee and toe clearance and place on an AR as a smart practice	\$800.00	each	1	\$800.00	2	Complete
Sixth Ward Park	Helena Citizens Council District 6			Under Construction at time of assessment				\$0.00	1	Complete
Sixth Ward Park	Helena Citizens Council District 6			Under Construction at time of assessment				\$0.00	1	Complete
Sixth Ward Park	Helena Citizens Council District 6			Under Construction at time of assessment				\$0.00	1	Complete
Sixth Ward Park	Helena Citizens Council District 6			Under Construction at time of assessment				\$0.00	1	Complete
Sixth Ward Park	Helena Citizens Council District 6			Under Construction at time of assessment				\$0.00	1	Complete
Sixth Ward Park	Helena Citizens Council District 6			Under Construction at time of assessment				\$0.00	1	Complete
Sixth Ward Park	Helena Citizens Council District 6			Under Construction at time of assessment				\$0.00	1	Complete
Sixth Ward Park	Helena Citizens Council District 6			Under Construction at time of assessment				\$0.00	1	Complete
Sixth Ward Park	Helena Citizens Council District 6			Under Construction at time of assessment				\$0.00	1	Complete
Skelton Park	Helena Citizens Council District 5	1.2.1	Exterior Accessible Route	Create lined cross walk where pedestrian pathway crosses through vehicular traffic as a smart practice	\$262.50	each	1	\$262.50	СО	Incomplete
Skelton Park	Helena Citizens Council District 5	1.2.2	Exterior Accessible Route	Correct curb ramp landing slope to max 2.08%	\$87.50	sq ft	32	\$2,800.00	СО	Incomplete
Skelton Park	Helena Citizens Council District 5	1.2.3	Exterior Accessible Route	Correct slope of curb ramp side flares to max 10%	\$725.00	each	4	\$2,900.00	СО	Incomplete
Skelton Park	Helena Citizens Council District 5	1.2.4	Exterior Accessible Route	Resurface curb ramp where deteriorating	\$725.00	each	1	\$725.00	со	Incomplete
Skelton Park	Helena Citizens Council District 5	1.2.5	Exterior Accessible Route	Correct curb ramp slope to max 8.33%	\$725.00	each	1	\$725.00	со	Incomplete
Skelton Park	Helena Citizens Council District 5	1.2.6	Exterior Accessible Route	Correct curb ramp cross slope to max 2.08%	\$725.00	each	1	\$725.00	СО	Incomplete
Skelton Park	Helena Citizens Council District 5	1.2.7	Exterior Accessible Route	Install compliant detectable warning at curb ramps as a smart practice	\$235.00	each	4	\$940.00	СО	Incomplete
Skelton Park	Helena Citizens Council District 5	1.2.8	Exterior Accessible Route	Correct or fill gaps along AR	\$68.75	each	2	\$137.50	со	Complete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Skelton Park	Helena Citizens Council District 5	1.2.9	Exterior Accessible Route	Repair, bevel, or ramp CIL along AR	\$68.75	each	1	\$68.75	со	Complete
Skelton Park	Helena Citizens Council District 5	1.2.10	Exterior Accessible Route	See 1.10 below for AR to site elements	\$0.00	n/a	0	\$0.00	СО	Complete
Skelton Park	Helena Citizens Council District 5	1.3.1	Playground Entry	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to new designated entry	\$48.00	lin ft	50	\$2,400.00	СО	Complete
Skelton Park	Helena Citizens Council District 5	1.3.2	Playground Entry	Create designated entry by removing 60" portion of play area boundary as a smart practice	\$500.00	each	1	\$500.00	СО	Complete
Skelton Park	Helena Citizens Council District 5	1.4.1	Playground Surface	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs	\$7,500.00	each	1	\$7,500.00	2	Complete
Skelton Park	Helena Citizens Council District 5	1.4.2	Playground Surface	Frequently inspect and regularly maintain accessible portions of play area surface that are comprised of loose fill such as EWF so that surface is level with other surfaces	\$0.00	staff time	0	\$0.00	со	Complete
Skelton Park	Helena Citizens Council District 5	1.4.3	Playground Surface	Establish protocols for regular and frequent inspection and maintenance of accessible playground surface	\$0.00	staff time	0	\$0.00	СО	Complete
Skelton Park	Helena Citizens Council District 5	1.5.1	Transfer System	Consider adding second transfer system as a smart practice	\$3,550.00	each	1	\$3,550.00	СО	Complete
Skelton Park	Helena Citizens Council District 5	1.8.1	GLPCs	Lower entry point for seat swing to 11" to 24" aff	\$0.00	staff time	0	\$0.00	СО	Complete
Skelton Park	Helena Citizens Council District 5	1.8.2	GLPCs	See recommendation 1.4.1 for surface corrections	\$0.00	n/a	0	\$0.00	СО	Complete
Skelton Park	Helena Citizens Council District 5	1.8.3	GLPCs	Leave as is, remaining GLPCs as the above correction will meet incentive scoping	\$0.00	n/a	0	\$0.00	СО	Complete
Skelton Park	Helena Citizens Council District 5	1.10.1	Park Site	Replace surface at fitness stations with EWF, crushed and compacted stone, or similar outdoor material	\$10,000.00	each	2	\$20,000.00	СО	Incomplete
Skelton Park	Helena Citizens Council District 5	1.10.2	Park Site	Relocate garbage can to be along AR	\$0.00	staff time	0	\$0.00	СО	Complete
Skelton Park	Helena Citizens Council District 5	1.10.3	Park Site	Replace or add one <u>picnic table</u> with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table as a smart practice	\$800.00	each	1	\$800.00	со	Complete
Waukesha Park	Helena Citizens Council District 4	1.2.1	Exterior Accessible Route	Correct slope of curb ramp side flares to max 10%	\$725.00	each	1	\$725.00	2	Incomplete
Waukesha Park	Helena Citizens Council District 4	1.2.2	Exterior Accessible Route	Install compliant detectable warning at transitions from walkways to vehicular ways as a smart practice	\$235.00	each	1	\$235.00	2	Incomplete



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Waukesha Park	Helena Citizens Council District 4	1.4.1	Playground Surface	Fill and compact EWF surface so that it maintains its accessibility characteristics	\$5,000.00	each	1	\$5,000.00	2	Complete
Waukesha Park	Helena Citizens Council District 4	1.4.2	Playground Surface	Establish protocols for regular and frequent inspection and maintenance of accessible playground surface	\$0.00	staff time	0	\$0.00	1	Complete
Waukesha Park	Helena Citizens Council District 4	1.5.1	Transfer System	Consider adding second transfer system as a smart practice	\$3,550.00	each	1	\$3,550.00	1	Complete
Waukesha Park	Helena Citizens Council District 4	1.5.2	Transfer System	Lower platform on transfer system to 11" to 18" aff, in the alternative, add and maintain surface fill level to achieve the same	\$250.00	each	1	\$250.00	1	Complete
Waukesha Park	Helena Citizens Council District 4	1.8.1	GLPCs	See recommendation 1.4.1 for surface corrections	\$0.00	n/a	0	\$0.00	1	Complete
Waukesha Park	Helena Citizens Council District 4	1.8.2	GLPCs	Lower entry point for seat swing to 11" to 24" aff	\$0.00	staff time	0	\$0.00	1	Complete
Waukesha Park	Helena Citizens Council District 4	1.8.3	GLPCs	Leave as is, remaining GLPCs as the above correction will meet incentive scoping and one of each type accessible	\$0.00	n/a	0	\$0.00	1	Complete
Waukesha Park	Helena Citizens Council District 4	1.10.1	Park Site	Correct or repair slope at gardens doorway landing to max 2.08% in any direction for level CFS	\$2,187.50	each	1	\$2,187.50	2	Incomplete
Waukesha Park	Helena Citizens Council District 4	1.10.2	Park Site	Repair, bevel, or ramp CIL at garden door entry to max .25"	\$68.75	each	1	\$68.75	2	Incomplete
Waukesha Park	Helena Citizens Council District 4	1.10.3	Park Site	Extend a pathway away from the <u>garden</u> building for emergency egress	\$48.00	lin ft	75	\$3,600.00	2	Incomplete
Waukesha Park	Helena Citizens Council District 4	1.10.4	Park Site	Replace operable parts in <u>garden</u> with ones operable without a tight pinch or grip	\$367.50	each	1	\$367.50	2	Complete
Waukesha Park	Helena Citizens Council District 4	1.10.5	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to and through the garden	\$48.00	lin ft	200	\$9,600.00	2	Complete
Waukesha Park	Helena Citizens Council District 4	1.10.6	Park Site	Consider providing raised garden beds for patrons with disabilities	\$500.00	each	2	\$1,000.00	2	Incomplete
Waukesha Park	Helena Citizens Council District 4	1.10.7	Park Site	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, add at least one armrest and locate along an AR as a smart practice	\$185.00	each	1	\$185.00	2	Incomplete
Waukesha Park	Helena Citizens Council District 4	1.10.8	Park Site	Replace one picnic table with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table as a smart practice	\$800.00	each	1	\$800.00	2	Complete
Wesleyan Park	Helena Citizens Council District 5	1.2.1	Exterior Accessible Route	Install compliant detectable warning at curb ramps as a smart practice	\$235.00	each	1	\$235.00	СО	Incomplete
Wesleyan Park	Helena Citizens Council District 5	1.2.2	Exterior Accessible Route	Repair, bevel, or ramp CIL along AR	\$68.75	each	5	\$343.75	со	Incomplete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Wesleyan Park	Helena Citizens Council District 5	1.2.3	Exterior Accessible Route	Correct or fill gaps along AR	\$68.75	each	2	\$137.50	СО	To be completed in FY22
Wesleyan Park	Helena Citizens Council District 5	1.2.4	Exterior Accessible Route	Correct or repair sidewalk cross slope along AR to max 2.08%	\$87.50	sq ft	25	\$2,187.50	со	Incomplete
Wesleyan Park	Helena Citizens Council District 5	1.2.5	Exterior Accessible Route	See 1.10 below for AR to site elements	\$0.00	n/a	0	\$0.00	со	Complete
Wesleyan Park	Helena Citizens Council District 5	1.3.1	Playground Entry	Acquire and install intended user signage and mount at designated entry as a smart practice	\$150.00	each	1	\$150.00	СО	Complete
Wesleyan Park	Helena Citizens Council District 5	1.4.1	Playground Surface	Replace existing surface with an accessible surface such as EWF, PIP or tiles, with compliant slopes and CILs	\$50,000.00	each	1	\$50,000.00	со	Complete
Wesleyan Park	Helena Citizens Council District 5	1.5.1	Transfer System	Install transfer system on play structure with access to 50% of the EPCs, if feasible	\$3,550.00	each	1	\$3,550.00	СО	Complete
Wesleyan Park	Helena Citizens Council District 5	1.7.1	EPCs	See recommendation 1.4.1 for surface corrections	\$0.00	n/a	0	\$0.00	со	Complete
Wesleyan Park	Helena Citizens Council District 5	1.7.2	EPCs	See recommendation 1.5.1 for transfer corrections	\$0.00	n/a	0	\$0.00	СО	Complete
Wesleyan Park	Helena Citizens Council District 5	1.7.3	EPCs	Adjust entry height of tunnel to max 8"	\$250.00	each	1	\$250.00	со	Complete
Wesleyan Park	Helena Citizens Council District 5	1.7.4	EPCs	Leave as is, remaining EPCs as the above correction will meet 50%	\$0.00	n/a	0	\$0.00	со	Complete
Wesleyan Park	Helena Citizens Council District 5	1.8.1	GLPCs	Add two GLPCs of two different types to meet incentive scoping	\$2,000.00	each	2	\$4,000.00	со	Complete
Wesleyan Park	Helena Citizens Council District 5	1.10.1	Park Site	Relocate garbage can to be along AR	\$0.00	staff time	0	\$0.00	со	Complete
Wesleyan Park	Helena Citizens Council District 5	1.10.2	Park Site	Replace or add one <u>picnic table</u> with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table as a smart practice	\$800.00	each	1	\$800.00	со	Complete
Women's Park	Helena Citizens Council District 3	1.2.1	Exterior Accessible Route	Create a level landing at the top of the curb ramp, 36" deep and as wide as ramp	\$625.00	each	1	\$625.00	3	Complete
Women's Park	Helena Citizens Council District 3	1.2.2	Exterior Accessible Route	Correct slope of curb ramp side flares to max 10%	\$725.00	each	2	\$1,450.00	3	Complete
Women's Park	Helena Citizens Council District 3	1.2.3	Exterior Accessible Route	Correct curb ramp slope to max 8.33%	\$725.00	each	1	\$725.00	3	Complete
Women's Park	Helena Citizens Council District 3	1.2.4	Exterior Accessible Route	Correct curb ramp cross slope to max 2.08%	\$725.00	each	1	\$725.00	3	Complete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Women's Park	Helena Citizens Council District 3	1.2.5	Exterior Accessible Route	Install compliant detectable warning at curb ramps as a smart practice	\$235.00	each	1	\$235.00	3	Complete
Women's Park	Helena Citizens Council District 3	1.2.6	Exterior Accessible Route	See 1.10 below for AR to site elements	\$0.00	n/a	0	\$0.00	3	N/A
Women's Park	Helena Citizens Council District 3	1.10.1	Park Site	Relocate 20% of garbage cans to be along AR	\$0.00	staff time	0	\$0.00	3	Complete
Women's Park	Helena Citizens Council District 3	1.10.2	Park Site	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to the performance area	\$48.00	lin ft	25	\$1,200.00	3	N/A no performance area designated at park
Women's Park	Helena Citizens Council District 3	1.10.3	Park Site	Construct firm, stable, and slip resistant pads at least 36" by 48" adjacent to 20% of benches, add at least one armrest and locate along an AR as a smart practice	\$115.00	each	2	\$230.00	3	Complete
Women's Park	Helena Citizens Council District 3	1.10.4	Park Site	Replace or add one <u>picnic table</u> with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table as a smart practice	\$800.00	each	1	\$800.00	3	Complete
Charles Van Hook Wetlands	Helena Citizens Council District 4	1.2.1	Exterior Accessible Route	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to wetlands	\$48.00	lin ft	100	\$4,800.00	СО	Complete
City Shop	Citywide Facilities	1.1.1	Parking	Raise existing accessible parking signs so lowest end of bottom sign is min 60" aff	\$0.00	staff time	0	\$0.00	3	To be completed in FY22
City Shop	Citywide Facilities	1.2.1	Stairs - Exterior	Leave exterior stairs as is due to infeasibility of changing	\$0.00	n/a	0	\$0.00	3	N/A
City Shop	Citywide Facilities	1.3.1	Exterior Signage	Mount signage at inaccessible entrances directing patrons in wheelchairs to accessible entrance	\$150.00	each	1	\$150.00	3	To be completed in FY22
City Shop	Citywide Facilities	1.3.2	Exterior Signage	Mount signage at entrance designating it as accessible	\$150.00	each	1	\$150.00	3	To be completed in FY22
City Shop	Citywide Facilities	1.4.1	Exterior Doors	For all doors along the public circulation route, repair, bevel, or ramp CIL at door entries to max .25"	\$68.75	inch	6	\$412.50	3	To be completed in FY22
City Shop	Citywide Facilities	1.4.2	Exterior Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	5	\$1,837.50	3	To be completed in FY22
City Shop	Citywide Facilities	1.4.3	Exterior Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice	\$0.00	staff time	0	\$0.00	3	On-going
City Shop	Citywide Facilities	1.4.4	Exterior Doors	Upon renovation ; make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	3	N/A
City Shop	Citywide Facilities	1.6.1	Interior Doors	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	5	\$6,250.00	3	Incomplete



			Type of			unit	# of			
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
City Shop	Citywide Facilities	1.6.2	Interior Doors	For all doors along the public circulation route, replace door with one having 32" clear width	\$1,980.00	each	7	\$13,860.00	3	Incomplete
City Shop	Citywide Facilities	1.6.3	Interior Doors	For all doors along the public circulation route, repair, bevel, or ramp CILs at door entries to max .25"	\$68.75	inch	1	\$68.75	3	Incomplete
City Shop	Citywide Facilities	1.6.4	Interior Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	22	\$8,085.00	3	Incomplete
City Shop	Citywide Facilities	1.6.5	Interior Doors	For all doors along the public circulation route, <i>inspect, adjust, and maintain</i> 5 lbf to open interior doors	\$0.00	staff time	0	\$0.00	3	On-going
City Shop	Citywide Facilities	1.6.6	Interior Doors	For employee only doors; make above corrections upon renovation	\$0.00	n/a	0	\$0.00	3	N/A
City Shop	Citywide Facilities	1.7.1	Interior Accessible Route	Lower operating mechanisms along the interior AR to max 48" aff to the highest operable part	\$250.00	each	1	\$250.00	3	Incomplete
City Shop	Citywide Facilities	1.7.2	Interior Accessible Route	Replace drinking fountain with hi-lo bowl	\$3,998.75	each	1	\$3,998.75	3	Incomplete
City Shop	Citywide Facilities	1.7.3	Interior Accessible Route	Replace exit sign with illuminated exit sign	\$150.00	each	1	\$150.00	3	To be completed in FY22
City Shop	Citywide Facilities	1.7.4	Stairs - Interior	Install handrails on both sides of stairway, mounted 34" to 38" aff with top and bottom extensions and having a 1.25" – 2" in diameter, or a non-circular grip that has a perimeter dimension of 4"- 6.25" max	\$700.00	each	4	\$2,800.00	3	To be completed in FY23
City Shop	Citywide Facilities	1.9.1	Employee Spaces	Employee only areas permit approach, entry, and exit, relocate obstacles to create AR and turning space of 60" in fleet office	\$0.00	staff time	0	\$0.00	3	On-going
City Shop	Citywide Facilities	1.9.2	Employee Spaces	For all other deficits, <i>leave as is</i> , employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	3	N/A
City Shop	Citywide Facilities	1.11.1	Restrooms	Provide one men's and one women's accessible rest room	\$17,806.25	each	2	\$35,612.50	3	To be completed in FY23
City Shop	Citywide Facilities	1.13.1	Locker Rooms	Leave as is, existing employee only locker room and shower; modify policy allowing employee with a disability to use public locker area or make renovations to existing locker area	\$0.00	n/a	0	\$0.00	3	N/A
City Shop	Citywide Facilities	1.15.1	Interior Signage	Create template for signs that addresses height of sign, size of characters, location of Braille, and other requirements	\$0.00	staff time	0	\$0.00	3	To be completed in FY22



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
City Shop	Citywide Facilities	1.15.2	Interior Signage	Implement a sign revision program throughout the building, discriminating between directional signs and signs for permanent spaces	\$0.00	staff time	0	\$0.00	3	To be completed in FY22
City Shop	Citywide Facilities	1.15.3	Interior Signage	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door	\$150.00	each	4	\$600.00	3	To be completed in FY22
Comstock Hill	Helena Citizens Council District 7	1.2.1	Exterior Accessible Route	Leave as is until site is developed	\$0.00	n/a	0	\$0.00	СО	N/A
Cruse Park	Helena Citizens Council District 3	1.2.1	Exterior Accessible Route	Repair, bevel, or ramp CIL along AR	\$68.75	each	3	\$206.25	СО	Complete
Cruse Park	Helena Citizens Council District 3	1.2.2	Exterior Accessible Route	Repaint marked crossing to include flares	\$262.50	each	1	\$262.50	со	Complete
Cruse Park	Helena Citizens Council District 3	1.2.3	Exterior Accessible Route	Install compliant detectable warning at curb ramps and transitions from walkways to vehicular ways as a smart practice	\$235.00	each	2	\$470.00	СО	Complete
Cruse Park	Helena Citizens Council District 3	1.2.4	Exterior Accessible Route	Correct or repair sidewalk running slope along AR to max 5%	\$87.50	sq ft	25	\$2,187.50	со	Incomplete
Cruse Park	Helena Citizens Council District 3	1.10.1	Park Site	Acquire and install at least one armrest to 20% of existing benches as a smart practice	\$70.00	each	1	\$70.00	со	N/A benches have been removed
Cruse Park	Helena Citizens Council District 3	1.13.1	Signage	Replace existing signage with signage having compliant character heights and placed within proper viewing distance of the AR	\$150.00	each	1	\$150.00	СО	Incomplete
Crystal Springs Wetlands	Helena Citizens Council District 4	1.2.1	Exterior Accessible Route	Correct or repair sidewalk cross slope along AR to max 2.08%	\$87.50	sq ft	25	\$2,187.50	СО	Staff to investigate completion status
Crystal Springs Wetlands	Helena Citizens Council District 4	1.2.2	Exterior Accessible Route	Install compliant detectable warning at curb ramps as a smart practice	\$235.00	each	1	\$235.00	СО	Staff to investigate completion status
Dale Harris Park	Helena Citizens Council District 1	1.2.1	Exterior Accessible Route	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to trail sign	\$48.00	lin ft	100	\$4,800.00	СО	Staff to investigate completion status
Dale Harris Park	Helena Citizens Council District 1	1.3.1	Trails	Mount signage at all trail heads indicating length of accessible trail segment, surface type, typical and min. tread width, typical and max. running slope, typical and max. cross slope as a smart practice	\$150.00	each	1	\$150.00	СО	Staff to investigate completion status



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Dale Harris Park	Helena Citizens Council District 1	1.3.2	Trails	Create template for signs that addresses height of sign, size of characters, and other requirements	\$0.00	staff time	0	\$0.00	СО	Staff to investigate completion status
East Side Fire Station	Citywide Facilities	1.1.1	Parking	Install parking space to meet accessible standards	\$1,135.00	each	1	\$1,135.00	3	Incomplete
East Side Fire Station	Citywide Facilities	1.2.1	Exterior Accessible Route	Create lined cross walk where pedestrian pathway crosses through vehicular traffic as a smart practice	\$262.50	each	1	\$262.50	3	Incomplete
East Side Fire Station	Citywide Facilities	1.3.1	Exterior Signage	Mount signage at inaccessible entrances directing patrons in wheelchairs to accessible entrance	\$150.00	each	1	\$150.00	3	Incomplete
East Side Fire Station	Citywide Facilities	1.3.2	Exterior Signage	Mount signage at entrance designating it as accessible	\$150.00	each	1	\$150.00	3	Incomplete
East Side Fire Station	Citywide Facilities	1.4.1	Exterior Doors	Relocate coke machine to create 60" maneuvering space around door	\$0.00	staff time	0	\$0.00	3	Employee-only access
East Side Fire Station	Citywide Facilities	1.4.2	Exterior Doors	Correct or repair slope at doorway landing to max 2.08% in any direction for level CFS at east entry and west entry	\$2,187.50	each	2	\$4,375.00	3	Incomplete
East Side Fire Station	Citywide Facilities	1.4.3	Exterior Doors	Replace hardware with lever hardware at east entry and west entry	\$367.50	each	2	\$735.00	3	Incomplete
East Side Fire Station	Citywide Facilities	1.4.4	Exterior Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice	\$0.00	staff time	0	\$0.00	3	On-going
East Side Fire Station	Citywide Facilities	1.4.5	Exterior Doors	Install kick plates on push side of doors with glass	\$100.00	each	2	\$200.00	3	Incomplete
East Side Fire Station	Citywide Facilities	1.4.6	Exterior Doors	Upon renovation ; make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	3	N/A
East Side Fire Station	Citywide Facilities	1.6.1	Interior Doors	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	6	\$7,500.00	3	On-going
East Side Fire Station	Citywide Facilities	1.6.2	Interior Doors	For all doors along the public circulation route, replace door with one having 32" clear width	\$1,980.00	each	1	\$1,980.00	3	Incomplete will be addressed during renovation
East Side Fire Station	Citywide Facilities	1.6.3	Interior Doors	For all doors along the public circulation route, replace threshold at interior doors with ADA thresholds	\$181.25	each	1	\$181.25	3	Incomplete will be addressed during renovation
East Side Fire Station	Citywide Facilities	1.6.4	Interior Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	13	\$4,777.50	3	Incomplete will be addressed during renovation
East Side Fire Station	Citywide Facilities	1.6.5	Interior Doors	Inspect, adjust, and maintain 5 lbf to open interior doors	\$0.00	staff time	0	\$0.00	3	On-going
East Side Fire Station	Citywide Facilities	1.6.6	Interior Doors	<i>Install</i> kick plate on door #10 and door #11	\$100.00	each	2	\$200.00	3	Incomplete
East Side Fire Station	Citywide Facilities	1.6.7	Interior Doors	For employee only doors; make above corrections <i>upon renovation</i>	\$0.00	n/a	0	\$0.00	3	N/A



			ı							
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
East Side Fire Station	Citywide Facilities	1.7.1	Interior Accessible Route	Provide an AR to all public areas required to be accessible	\$31,165.00	each	1	\$31,165.00	3	Employee-only access
East Side Fire Station	Citywide Facilities	1.7.2	Interior Accessible Route	Correct or repair cross slope of AR to max 2.08%	\$87.50	sq ft	25	\$2,187.50	3	Staff to investigate technical feasibility
East Side Fire Station	Citywide Facilities	1.7.3	Interior Accessible Route	Replace floor grate	\$100.00	each	1	\$100.00	3	Incomplete
East Side Fire Station	Citywide Facilities	1.7.4	Interior Accessible Route	Lower operating mechanisms along the interior AR to max 48" aff to the highest operable part	\$250.00	each	1	\$250.00	3	Employee-only operated
East Side Fire Station	Citywide Facilities	1.7.5	Stairs	Tread risers and depth on stairs should be uniform and a maximum of 7" and a minimum of 11" deep, <i>leave as is</i> due to infeasibility of making depth and risers consistent	\$0.00	n/a	0	\$0.00	3	N/A technically infeasible
East Side Fire Station	Citywide Facilities	1.9.1	Employee Spaces	For all other deficits, <i>leave as is</i> , employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	3	N/A
East Side Fire Station	Citywide Facilities	1.11.1	Restrooms	Provide one accessible restroom and mount signage at the other directing staff to the accessible restroom	\$17,806.25	each	1	\$17,806.25	3	To be completed in FY23
East Side Fire Station	Citywide Facilities	1.12.1	Kitchen	Remove base cabinet and lower sink height to max 34" aff	\$2,485.00	each	1	\$2,485.00	3	To be completed in FY23
East Side Fire Station	Citywide Facilities	1.12.2	Kitchen	Replace oven with one having controls on the front panel	\$2,000.00	each	1	\$2,000.00	3	Complete
East Side Fire Station	Citywide Facilities	1.12.3	Kitchen	Replace table with smaller one for CFS at dishwasher	\$800.00	each	1	\$800.00	3	Complete
East Side Fire Station	Citywide Facilities	1.13.1	Locker Rooms	Designate 5% or no less than 1 locker as accessible, mounting signage having the access symbol and hooks and operating mechanisms max 48" aff	\$300.00	each	1	\$300.00	3	To be completed in FY23
East Side Fire Station	Citywide Facilities	1.13.2	Locker Rooms	Replace locker hardware with ADA compliant hardware on designated lockers	\$300.00	each	1	\$300.00	3	To be completed in FY23
East Side Fire Station	Citywide Facilities	1.13.3	Locker Rooms	Replace bench in dressing area with one having a seat depth of 20" to 24" deep, 42" long, affixed to the wall or having a back and mounted 17" to 19" aff	\$600.00	each	1	\$600.00	3	To be completed in FY23
<u>Grandstreet</u> <u>Theatre</u>	Citywide Facilities	1.1.1	Parking	Create one or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping	\$1,135.00	each	1	\$1,135.00	3	Complete
Grandstreet Theatre	Citywide Facilities	1.2.1	Exterior Accessible Route	Correct or repair sidewalk cross slope along AR to max 2.08%	\$87.50	sq ft	25	\$2,187.50	3	Incomplete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Grandstreet Theatre	Citywide Facilities	1.2.2	Exterior Accessible Route	Relocate mailbox or install bollard to warn of protrusion	\$0.00	staff time	0	\$0.00	3	Incomplete
Grandstreet Theatre	Citywide Facilities	1.3.1	Exterior Signage	Mount signage at inaccessible entrances directing patrons in wheelchairs to accessible entrance	\$150.00	each	1	\$150.00	3	Staff to investigate completion status
Grandstreet Theatre	Citywide Facilities	1.3.2	Exterior Signage	Mount signage at entrance designating it as accessible	\$150.00	each	1	\$150.00	3	Staff to investigate completion status
Grandstreet Theatre	Citywide Facilities	1.4.1	Exterior Doors	For all doors along the public circulation route, widen pathway approaching entry to extend 18" beyond latch side of door for maneuvering clearance	\$1,250.00	each	2	\$2,500.00	3	Staff to investigate technical feasibility
Grandstreet Theatre	Citywide Facilities	1.4.2	Exterior Doors	For all doors along the public circulation route, replace thresholds at exterior doors with ADA thresholds	\$181.25	each	1	\$181.25	3	Staff to investigate technical feasibility
Grandstreet Theatre	Citywide Facilities	1.4.3	Exterior Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	1	\$367.50	3	Incomplete
Grandstreet Theatre	Citywide Facilities	1.4.4	Exterior Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice	\$0.00	staff time	0	\$0.00	3	On-going
Grandstreet Theatre	Citywide Facilities	1.4.5	Exterior Doors	For all doors along the public circulation route, inspect, adjust, and maintain closing speed on door closers	\$0.00	staff time	0	\$0.00	3	On-going
Grandstreet Theatre	Citywide Facilities	1.4.6	Exterior Doors	Upon renovation ; make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	3	N/A
Grandstreet Theatre	Citywide Facilities	1.5.1	Lift	Standby power, leave as is , the manual lowering device is enabled	\$0.00	n/a	0	\$0.00	3	N/A
Grandstreet Theatre	Citywide Facilities	1.5.2	Lift	30" angled kick plate, leave as is , provides safety barrier for threshold	\$0.00	n/a	0	\$0.00	3	N/A
Grandstreet Theatre	Citywide Facilities	1.6.1	Interior Doors	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	11	\$13,750.00	3	Staff to investigate technical feasibility
Grandstreet Theatre	Citywide Facilities	1.6.2	Interior Doors	For all doors along the public circulation route, replace doors with doors having 80" overhead clearance and 32" clear width	\$1,980.00	each	5	\$9,900.00	3	Staff to investigate technical feasibility
Grandstreet Theatre	Citywide Facilities	1.6.3	Interior Doors	For all doors along the public circulation route, repair, bevel, or ramp CILs at door entries to max .25"	\$68.75	inch	3	\$206.25	3	Staff to investigate technical feasibility
Grandstreet Theatre	Citywide Facilities	1.6.4	Interior Doors	For all doors along the public circulation route, replace threshold at interior doors with ADA thresholds	\$181.25	each	1	\$181.25	3	Incomplete
Grandstreet Theatre	Citywide Facilities	1.6.5	Interior Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	4	\$1,470.00	3	Staff to investigate technical feasibility



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Grandstreet Theatre	Citywide Facilities	1.6.6	Interior Doors	For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors	\$0.00	staff time	0	\$0.00	3	On-going
Grandstreet Theatre	Citywide Facilities	1.6.7	Interior Doors	For all doors along the public circulation route, <i>inspect, adjust, and maintain</i> closing speed on door closers	\$0.00	staff time	0	\$0.00	3	On-going
Grandstreet Theatre	Citywide Facilities	1.6.8	Interior Doors	For employee only doors; make above corrections upon renovation	\$0.00	n/a	0	\$0.00	3	N/A
Grandstreet Theatre	Citywide Facilities	1.7.1	Interior Accessible Route	Correct or repair running slope of AR to max 5%	\$87.50	sq ft	25	\$2,187.50	3	Staff to investigate technical feasibility
Grandstreet Theatre	Citywide Facilities	1.7.2	Interior Accessible Route	Mount compliant signage at all doors along the egress route	\$150.00	each	3	\$450.00	3	Staff to investigate completion status
Grandstreet Theatre	Citywide Facilities	1.7.3	Service Counter	Lower 36" wide segment of service counter to max 36" aff, in the alternative, train staff to come out from around the counter to provide customer service	\$785.00	each	1	\$785.00	3	Staff to investigate technical feasibility
Grandstreet Theatre	Citywide Facilities	1.7.4	Stairs	Correct riser heights on stairs to consistent height between 4" to 7", leave as is if technically infeasible	\$288.75	each	28	\$8,085.00	3	Staff to investigate technical feasibility
Grandstreet Theatre	Citywide Facilities	1.7.5	Stairs	Provide visual contrast on front 2" of each tread	\$20.00	each	28	\$560.00	3	Incomplete
Grandstreet Theatre	Citywide Facilities	1.7.6	Stairs	Install detectable warning strip on top tread of each stairway as a smart practice	\$150.00	each	2	\$300.00	3	Incomplete
Grandstreet Theatre	Citywide Facilities	1.7.7	Stairs	Replace handrails with compliant handrails	\$700.00	each	5	\$3,500.00	3	Incomplete
Grandstreet Theatre	Citywide Facilities	1.7.8	Ramp	Shorten ramp run to max 30' or a max of 30" rise	\$155.00	inch	10	\$1,550.00	3	Staff to investigate technical feasibility
Grandstreet Theatre	Citywide Facilities	1.7.9	Ramp	Correct slope of ramp to max 8.33%	\$87.50	sq ft	270	\$23,625.00	3	Staff to investigate technical feasibility
Grandstreet Theatre	Citywide Facilities	1.7.10	Ramp	Correct ramp cross slope to max 2.08%	\$87.50	sq ft	270	\$23,625.00	3	Staff to investigate technical feasibility
Grandstreet Theatre	Citywide Facilities	1.7.11	Ramp	Create a level landing along the ramp every 30'	\$1,250.00	each	6	\$7,500.00	3	Staff to investigate technical feasibility
Grandstreet Theatre	Citywide Facilities	1.7.12	Ramp	Install handrails on both sides of the ramp	\$700.00	each	3	\$2,100.00	3	Staff to investigate technical feasibility
Grandstreet Theatre	Citywide Facilities	1.8.1	Public Spaces	Lower 36" wide segment of the service counter to max 36" aff, in the alternative, train staff to come out from around the counter to provide customer service	\$785.00	each	1	\$785.00	3	Staff to investigate technical feasibility
Grandstreet Theatre	Citywide Facilities	1.9.1	Employee Spaces	Leave as is, employee work areas pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	3	N/A



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Grandstreet Theatre	Citywide Facilities	1.10.1	Assembly Area	Provide a retractable arm and designation signage at accessible aisle seats	\$240.00	each	2	\$480.00	3	Incomplete
Grandstreet Theatre	Citywide Facilities	1.10.2	Assembly Area	Provide required number of wheel chairs seats and companion seats	\$449.50	each	2	\$899.00	3	Incomplete
Grandstreet Theatre	Citywide Facilities	1.11.1	Restrooms	Adjust stall door to be self-closing and install exterior hardware that is operable without a tight pinch or grasp	\$100.00	each	2	\$200.00	3	Incomplete
Grandstreet Theatre	Citywide Facilities	1.11.2	Restrooms	Relocate or recess tampon dispenser and light fixture to not interfere with general circulation path, protrusions can't be greater than 4"	\$250.00	each	1	\$250.00	3	Incomplete
Grandstreet Theatre	Citywide Facilities	1.15.1	Interior Signage	Create template for signs that addresses height of sign, size of characters, location of Braille, and other requirements	\$0.00	staff time	0	\$0.00	3	Incomplete
Grandstreet Theatre	Citywide Facilities	1.15.2	Interior Signage	Implement a sign revision program throughout the building, discriminating between directional signs and signs for permanent spaces	\$0.00	staff time	0	\$0.00	3	Incomplete
Grandstreet Theatre	Citywide Facilities	1.15.3	Interior Signage	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door	\$150.00	each	10	\$1,500.00	3	Incomplete
Kessler Park	Helena Citizens Council District 6	1.2.1	Exterior Accessible Route	Create a level landing at the top of the curb ramp, 36" deep and as wide as ramp	\$87.50	sq ft	16	\$1,400.00	CO	Incomplete
Kessler Park	Helena Citizens Council District 6	1.2.2	Exterior Accessible Route	Correct slope of adjacent street surfaces to max 5%	\$87.50	sq ft	50	\$4,375.00	СО	Incomplete
Kessler Park	Helena Citizens Council District 6	1.2.3	Exterior Accessible Route	Correct slope of curb ramp slide flares to max 10%	\$725.00	each	2	\$1,450.00	CO	Incomplete
Kessler Park	Helena Citizens Council District 6	1.2.4	Exterior Accessible Route	Create a curb ramp to be max running slope 8.33%, max cross slope 2.08%, having a top landing as wide as the ramp and 36" deep and side flares with a max slope 10%	\$1,062.50	each	1	\$1,062.50	СО	Incomplete
Kessler Park	Helena Citizens Council District 6	1.2.5	Exterior Accessible Route	Repair, bevel, or ramp CIL along AR	\$68.75	each	4	\$275.00	СО	Incomplete
Kessler Park	Helena Citizens Council District 6	1.2.6	Exterior Accessible Route	Install compliant detectable warning at transitions from walkways to vehicular ways as a smart practice	\$235.00	each	2	\$470.00	СО	Incomplete
Kessler Park	Helena Citizens Council District 6	1.10.1	Park Site	Relocate 20% of garbage cans to be along AR	\$0.00	staff time	0	\$0.00	СО	Complete



		l	1							
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Kessler Park	Helena Citizens Council District 6	1.10.2	Park Site	Replace one picnic table with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table as a smart practice	\$800.00	each	1	\$800.00	со	Complete
Main Fire Station	Citywide Facilities	1.1.1	Parking	Create one or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping	\$1,135.00	each	1	\$1,135.00	2	Staff to investigate technical feasibility
Main Fire Station	Citywide Facilities	1.2.1	Exterior Accessible Route	Create AR with lined cross walk where pedestrian pathway crosses through vehicular traffic as a smart practice	\$262.50	each	1	\$262.50	3	Staff to investigate technical feasibility
Main Fire Station	Citywide Facilities	1.3.1	Exterior Signage	Mount signage at inaccessible entrances directing patrons in wheelchairs to accessible entrance	\$150.00	each	1	\$150.00	3	Incomplete
Main Fire Station	Citywide Facilities	1.3.2	Exterior Signage	Mount signage at entrance designating it as accessible	\$150.00	each	1	\$150.00	3	Incomplete
Main Fire Station	Citywide Facilities	1.4.1	Exterior Doors	For all doors along the public circulation route, replace doors with ones having 32" clear width	\$1,980.00	each	1	\$1,980.00	3	Staff to investigate technical feasibility
Main Fire Station	Citywide Facilities	1.4.2	Exterior Doors	For all doors along the public circulation route, replace thresholds at exterior doors with ADA thresholds	\$181.25	each	1	\$181.25	3	Incomplete
Main Fire Station	Citywide Facilities	1.4.3	Exterior Doors	For employee only doors; make above corrections <i>upon renovation</i>	\$0.00	n/a	0	\$0.00	3	N/A
Main Fire Station	Citywide Facilities	1.6.1	Interior Doors	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	9	\$11,250.00	3	Staff to investigate technical feasibility
Main Fire Station	Citywide Facilities	1.6.2	Interior Doors	For all doors not along the public circulation route <i>leave as is,</i> correction is may be technically infeasible	\$0.00	n/a	0	\$0.00	3	N/A
Main Fire Station	Citywide Facilities	1.6.3	Interior Doors	No maneuvering clearance at door due to stairs, <i>leave as is,</i> correction is technically infeasible	\$0.00	n/a	0	\$0.00	3	N/A
Main Fire Station	Citywide Facilities	1.6.4	Interior Doors	For all doors along the public circulation route, replace door with one having 32" clear width	\$1,980.00	each	8	\$15,840.00	3	Staff to investigate technical feasibility
Main Fire Station	Citywide Facilities	1.6.5	Interior Doors	For all doors along the public circulation route, <i>fill</i> and maintain gaps at doorways to max .5"	\$68.75	each	1	\$68.75	3	Incomplete
Main Fire Station	Citywide Facilities	1.6.6	Interior Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated, mounted 34" to 48" aff	\$367.50	each	22	\$8,085.00	3	Incomplete
Main Fire Station	Citywide Facilities	1.6.7	Interior Doors	For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors	\$0.00	staff time	0	\$0.00	3	On-going



			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Main Fire Station	Citywide Facilities	1.6.8	Interior Doors	For all doors along the public circulation route, replace doors with ones having sidelight viewing windows max 43" aff	\$990.00	each	6	\$5,940.00	3	Staff to investigate technical feasibility
Main Fire Station	Citywide Facilities	1.6.9	Interior Doors	For employee only doors; make above corrections upon renovation	\$0.00	n/a	0	\$0.00	3	N/A
Main Fire Station	Citywide Facilities	1.7.1	Interior Accessible Route	Provide an AR to all public areas required to be accessible	\$31,165.00	each	1	\$31,165.00	2	Staff to investigate technical feasibility
Main Fire Station	Citywide Facilities	1.7.2	Interior Accessible Route	Lower thermostat and microphone	\$250.00	each	2	\$500.00	2	Incomplete
Main Fire Station	Citywide Facilities	1.7.3	Stairs	Stairs only to upper level dayroom, kitchen, locker- room and sleeping rooms, <i>leave as is</i> , employee area only; reassign duties if an employee with a disability requires access here	\$0.00	n/a	0	\$0.00	3	N/A
Main Fire Station	Citywide Facilities	1.8.1	Public Spaces	Remove or relocate movie player	\$250.00	each	1	\$250.00	2	Incomplete
Main Fire Station	Citywide Facilities	1.8.2	Public Spaces	Lower thermostat to max 48" aff	\$250.00	each	1	\$250.00	2	Incomplete
Main Fire Station	Citywide Facilities	1.9.1	Employee Spaces	Employee only area permit approach, entry, and exit, relocate obstacles to create AR through rooms listed	\$0.00	staff time	0	\$0.00	2	On-going
Main Fire Station	Citywide Facilities	1.9.2	Employee Spaces	For all other deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	2	N/A
Main Fire Station	Citywide Facilities	1.11.1	Restrooms	Acquire and mount signage, including access symbol at both	\$150.00	each	2	\$300.00	2	Incomplete
Main Fire Station	Citywide Facilities	1.11.2	Restrooms	Relocate or recess towel dispenser to not interfere with general circulation path, protrusions can't be greater than 4"	\$250.00	each	2	\$500.00	2	Incomplete
Main Fire Station	Citywide Facilities	1.12.1	Kitchen	For all deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	2	N/A
Main Fire Station	Citywide Facilities	1.13.1	Locker Rooms	For all deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	2	N/A
Meatloaf Hill	Helena Citizens Council District 2	1.2.1	Exterior Accessible Route	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to trail sign	\$48.00	lin ft	200	\$9,600.00	СО	Staff to investigate completion status



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Meatloaf Hill	Helena Citizens Council District 2	1.2.2	Exterior Accessible Route	Create a curb ramp to be max running slope 8.33%, max cross slope 2.08%, having a top landing as wide as the ramp and 36" deep and side flares with a max slope 10%	\$1,062.50	each	3	\$3,187.50	СО	Staff to investigate completion status
Meatloaf Hill	Helena Citizens Council District 2	1.3.1	Trails	Mount signage at all trail heads indicating length of accessible trail segment, surface type, typical and min. tread width, typical and max. running slope, typical and max. cross slope as a smart practice	\$150.00	each	5	\$750.00	СО	Staff to investigate completion status
Meatloaf Hill	Helena Citizens Council District 2	1.3.2	Trails	Create template for signs that addresses height of sign, size of characters, and other requirements	\$0.00	staff time	0	\$0.00	СО	Staff to investigate completion status
Nob Hill Open Lands	Helena Citizens Council District 7	1.2.1	Exterior Accessible Route	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to trailhead	\$48.00	lin ft	50	\$2,400.00	со	Staff to investigate completion status
Nob Hill Open Lands	Helena Citizens Council District 7	1.2.2	Exterior Accessible Route	Create a curb ramp to be max running slope 8.33%, max cross slope 2.08%, having a top landing as wide as the ramp and 36" deep and side flares with a max slope 10%	\$1,062.50	each	2	\$2,125.00	00	Staff to investigate completion status
Nob Hill Open Lands	Helena Citizens Council District 7	1.3.1	Trails	Replace one picnic table with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table as a smart practice	\$915.00	each	1	\$915.00	00	Staff to investigate completion status
Nob Hill Open Lands	Helena Citizens Council District 7	1.3.2	Trails	Mount signage at all trail heads indicating length of accessible trail segment, surface type, typical and min. tread width, typical and max. running slope, typical and max. cross slope as a smart practice	\$150.00	each	2	\$300.00	со	Staff to investigate completion status
Nob Hill Open Lands	Helena Citizens Council District 7	1.3.3	Trails	Create template for signs that addresses height of sign, size of characters, and other requirements	\$0.00	staff time	0	\$0.00	СО	Staff to investigate completion status
Nob Hill Park	Helena Citizens Council District 7	1.2.1	Exterior Accessible Route	Create a level landing at the top of the curb ramp, 36" deep and as wide as ramp	\$87.50	sq ft	16	\$1,400.00	СО	Staff to investigate completion status
Nob Hill Park	Helena Citizens Council District 7	1.2.2	Exterior Acccessible Route	Repair, bevel, or ramp CIL along AR	\$68.75	each	1	\$68.75	СО	Staff to investigate completion status
Nob Hill Park	Helena Citizens Council District 7	1.2.3	Exterior Acccessible Route	Correct slope of curb ramp slide flares to max 10%	\$725.00	each	1	\$725.00	СО	Staff to investigate completion status
Nob Hill Park	Helena Citizens Council District 7	1.2.4	Exterior Acccessible Route	Correct curb ramp cross slope to max 2.08%	\$725.00	each	1	\$725.00	со	Staff to investigate completion status



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit	# of units	Total cost	Phase	Notes
Site	HCC DIST	Cite		Recommendation	Price/ unit	type	units	Total cost	Filase	Notes
Nob Hill Park	Helena Citizens Council District 7	1.2.5	Exterior Acccessible Route	Establish protocols for regular and frequent inspection and maintenance of surface from AR	\$0.00	staff time	0	\$0.00	со	Staff to investigate completion status
Nob Hill Park	Helena Citizens Council District 7	1.2.6	Exterior Acccessible Route	Correct or fill 2.5" gap along AR	\$68.75	each	1	\$68.75	со	Staff to investigate completion status
Nob Hill Park	Helena Citizens Council District 7	1.2.7	Exterior Acccessible Route	Correct or repair sidewalk cross slope along AR to max 2.08%	\$87.50	sq ft	100	\$8,750.00	со	Staff to investigate completion status
Nob Hill Park	Helena Citizens Council District 7	1.2.8	Exterior Acccessible Route	Correct or repair sidewalk running slope along AR to max 5%	\$87.50	sq ft	75	\$6,562.50	со	Staff to investigate completion status
Nob Hill Park	Helena Citizens Council District 7	1.2.9	Exterior Acccessible Route	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to bridge	\$48.00	lin ft	100	\$4,800.00	со	Staff to investigate completion status
Nob Hill Park	Helena Citizens Council District 7	1.2.10	Exterior Acccessible Route	Create a curb ramp to be max running slope 8.33%, max cross slope 2.08%, having a top landing as wide as the ramp and 36" deep and side flares with a max slope 10%	\$1,062.50	each	1	\$1,062.50	со	Staff to investigate completion status
Nob Hill Park	Helena Citizens Council District 7	1.2.11	Exterior Acccessible Route	Repair, bevel, or ramp CIL along AR	\$68.75	each	2	\$137.50	со	Staff to investigate completion status
<u>Pioneer Village</u>	Helena Citizens Council District 4	1.2.1	Exterior Accessible Route	Correct slope of adjacent street surfaces to max 5%	\$87.50	sq ft	25	\$2,187.50	со	Incomplete
Pioneer Village	Helena Citizens Council District 4	1.10.1	Park Site	Relocate 20% of garbage cans to be along AR	\$0.00	staff time	0	\$0.00	со	Complete
Pioneer Village	Helena Citizens Council District 4	1.10.2	Park Site	Replace one <u>picnic table</u> with one with knee and toe clearance, 19" deep at 27" high and 24" deep at 9" high, with a 36" AR around table as a smart practice	\$800.00	each	1	\$3.00	со	Complete
Police 24x7	Citywide Facilities	1.1.1	Parking	Repaint stalls and access aisles to be 8' and 5' each	\$52.50	each	1	\$52.50	3	Property sold
Police 24x7	Citywide Facilities	1.1.2	Parking	Correct or fill 1" gap along AR	\$68.75	each	1	\$68.75	3	Property sold
Police 24x7	Citywide Facilities	1.2.1	Exterior Accessible Route	Correct or fill 1" gap along AR	\$68.75	each	1	\$68.75	3	Property sold
Police 24x7	Citywide Facilities	1.2.2	Exterior Accessible Route	Create lined cross walk where pedestrian pathway crosses through vehicular traffic as a smart practice	\$262.50	each	1	\$262.50	3	Property sold
Police 24x7	Citywide Facilities	1.3.1	Exterior Signage	Mount signage at inaccessible entrances directing patrons in wheelchairs to accessible entrance	\$150.00	each	1	\$150.00	3	Property sold



			.							
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Police 24x7	Citywide Facilities	1.3.2	Exterior Signage	Mount signage at entrance designating it as accessible	\$150.00	each	1	\$150.00	3	Property sold
Police 24x7	Citywide Facilities	1.4.1	Exterior Doors	For all doors along the public circulation route, <i>install</i> kick plate on east entry	\$100.00	each	1	\$100.00	3	Property sold
Police 24x7	Citywide Facilities	1.4.2	Exterior Doors	For all doors along the public circulation route, <i>inspect, adjust, and maintain</i> 8.5 lbf to open exterior doors	\$0.00	staff time	0	\$0.00	3	Property sold
Police 24x7	Citywide Facilities	1.4.3	Exterior Doors	Upon renovation ; make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	3	Property sold
Police 24x7	Citywide Facilities	1.6.1	Interior Doors	For all doors along the public circulation route, replace doors with doors having 80" overhead clearance	\$1,980.00	each	1	\$1,980.00	3	Property sold
Police 24x7	Citywide Facilities	1.6.2	Interior Doors	For employee only doors; make above corrections <i>upon renovation</i>	\$0.00	n/a	0	\$0.00	3	Property sold
Police 24x7	Citywide Facilities	1.7.1	Interior Accessible Route	Lower 36" wide segment of service counter to max 36" aff, in the alternative, train staff to come out from around the counter to provide customer service	\$785.00	each	1	\$785.00	3	Property sold
Police 24x7	Citywide Facilities	1.7.2	Interior Accessible Route	Provide 80" overhead clearance if feasible, in the alternative, pad the obstruction to prevent injury	\$220.00	each	1	\$220.00	3	Property sold
Police 24x7	Citywide Facilities	1.7.3	Interior Accessible Route	Relocate objects to provide access to exit signage	\$0.00	staff time	0	\$0.00	3	Property sold
Police 24x7	Citywide Facilities	1.9.1	Employee Spaces	For all deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	3	Property sold
Police 24x7	Citywide Facilities	1.11.1	Restrooms	Remount rear grab bar to behind the toilet, 12" to one side of center and 24" to the other and 33" to 36" aff	\$281.25	each	1	\$281.25	2	Property sold
Police 24x7	Citywide Facilities	1.11.2	Restrooms	Remount vertical grab bar so that bottom is between 39" and 41" aff and the centerline is between 39" and 41" from rear wall	\$281.25	each	1	\$281.25	2	Property sold
Police 24x7	Citywide Facilities	1.11.3	Restrooms	Replace toilet tank with one having flush mechanism on the open side, in the alternative, install an auto flush unit	\$211.25	each	1	\$211.25	2	Property sold
Police 24x7	Citywide Facilities	1.11.4	Restrooms	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	\$0.00	staff time	0	\$0.00	2	Property sold
Police 24x7	Citywide Facilities	1.11.5	Restrooms	Lower sink to max 34" aff to front of rim	\$1,700.00	each	1	\$1,700.00	2	Property sold
Police 24x7	Citywide Facilities	1.11.6	Restrooms	Install additional coat hook(s) or lower existing to 40"-48" max	\$0.00	staff time	0	\$0.00	2	Property sold



			Tymo of			unit	# of			
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Police 24x7	Citywide Facilities	1.11.7	Restrooms	Replace door with one having 80" overhead and 32" clear width	\$1,980.00	each	1	\$1,980.00	2	Property sold
Police 24x7	Citywide Facilities	1.15.1	Interior Signs	Create template for signs that addresses height of sign, size of characters, location of Braille, and other requirements	\$0.00	staff time	0	\$0.00	3	Property sold
Police 24x7	Citywide Facilities	1.15.2	Interior Signs	Implement a sign revision program throughout the building, discriminating between directional signs and signs for permanent spaces	\$0.00	staff time	0	\$0.00	3	Property sold
Police 24x7	Citywide Facilities	1.15.3	Interior Signs	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door	\$150.00	each	3	\$450.00	3	Property sold
Reber Park	Helena Citizens Council District 1	1.2.1	Exterior Accessible Route	Re-cut or re-pour curb ramp to be max running slope 8.33%, max cross slope 2.08%, having a top landing as wide as the ramp and 36" deep and side flares max slope 10%	\$725.00	each	1	\$725.00	CO	Incomplete
Reber Park	Helena Citizens Council District 1	1.2.2	Exterior Accessible Route	Install compliant detectable warning at curb ramps and transitions from walkways to vehicular ways as a smart practice	\$235.00	each	1	\$235.00	СО	Incomplete
Reber Park	Helena Citizens Council District 1	1.2.3	Exterior Accessible Route	Maintain AR clearance of min. 80" overhead and 36" wide	\$0.00	staff time	0	\$0.00	СО	Complete
Reber Park	Helena Citizens Council District 1	1.2.4	Exterior Accessible Route	Correct or fill gaps along AR	\$68.75	each	2	\$137.50	СО	Complete
Reber Park	Helena Citizens Council District 1	1.3.1	Trails	Establish protocols for regular and frequent inspection and maintenance of accessible trail surface as a smart practice	\$0.00	staff time	0	\$0.00	СО	Complete
Reber Park	Helena Citizens Council District 1	1.3.2	Trails	Frequently maintain trail running slope to assure it does not exceed 8.33% slope for 200' max, 10% for 30' max or 12.5% for 10' with resting spaces on the trail as a smart practice	\$0.00	staff time	0	\$0.00	CO	On-going
Reber Park	Helena Citizens Council District 1	1.3.3	Trails	Frequently maintain trail cross slope to assure it does not exceed 5% for surfaces other than concrete, boards or asphalt as a smart practice	\$0.00	staff time	0	\$0.00	CO	On-going
Scale House	Citywide Facilities	1.1.1	Parking	Create one or more 8" accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping	\$1,135.00	each	1	\$1,135.00	3	Staff to investigate technical feasibility



			I			l	l			
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Scale House	Citywide Facilities	1.2.1	Exterior Accessible Route	Create lined cross walk where pedestrian pathway crosses through vehicular traffic as a smart practice	\$262.50	each	1	\$262.50	3	Staff to investigate technical feasibility
Scale House	Citywide Facilities	1.2.2	Exterior Accessible Route	Create a curb ramp to be max running slope 8.33%, max cross slope 2.08%, having a top landing as wide as the ramp and 36" deep and side flares with a max slope 10%	\$1,062.50	each	1	\$1,062.50	3	Incomplete
Scale House	Citywide Facilities	1.3.1	Exterior Signage	Mount signage at inaccessible entrances directing patrons in wheelchairs to accessible entrance	\$150.00	each	1	\$150.00	3	Incomplete
Scale House	Citywide Facilities	1.3.2	Exterior Signage	Mount signage at entrance designating it as accessible	\$150.00	each	1	\$150.00	3	Incomplete
Scale House	Citywide Facilities	1.4.1	Exterior Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	1	\$367.50	3	Incomplete
Scale House	Citywide Facilities	1.4.2	Exterior Doors	For all doors along the public circulation route, <i>inspect, adjust, and maintain</i> 8.5 lbf to open exterior doors as a smart practice	\$0.00	staff time	0	\$0.00	3	On-going
Scale House	Citywide Facilities	1.4.3	Exterior Doors	Upon renovation ; make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	3	N/A
Scale House	Citywide Facilities	1.6.1	Interior Doors	No maneuvering clearance at Mechanical room door due to sink, <i>leave as is,</i> correction is technically infeasible	\$0.00	n/a	0	\$0.00	3	N/A
Scale House	Citywide Facilities	1.6.2	Interior Doors	For all doors along the public circulation route, widen doors to 32" for any doors indicated	\$1,980.00	each	1	\$1,980.00	3	Staff to investigate technical feasibility
Scale House	Citywide Facilities	1.6.3	Interior Doors	<i>Inspect, adjust, and maintain</i> 5 lbf to open interior doors	\$0.00	staff time	0	\$0.00	3	On-going
Scale House	Citywide Facilities	1.6.4	Interior Doors	Upon renovation ; make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	3	N/A
Scale House	Citywide Facilities	1.7.1	Interior Accessible Route	Inspect, adjust, and maintain 5 lbf to open interior doors	\$0.00	staff time	0	\$0.00	3	On-going
Scale House	Citywide Facilities	1.9.1	Employee Spaces	Employee only area, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	3	N/A
Scale House	Citywide Facilities	1.11.1	Restrooms	Acquire and mount signage, including Braille and access symbol mounted on wall, latch side of door, 48" to baseline of lowest character and 60" to baseline of highest character	\$150.00	each	1	\$150.00	3	Incomplete
Scale House	Citywide Facilities	1.11.2	Restrooms	Remount toilet to 16" to 18" from the side wall to centerline	\$1,306.00	each	1	\$1,306.00	3	Staff to investigate technical feasibility
Scale House	Citywide Facilities	1.11.3	Restrooms	Lower mirror so reflective surface is max 40" aff	\$0.00	staff time	0	\$0.00	3	Staff to investigate technical feasibility



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Scale House	Citywide Facilities	1.11.4	Restrooms	Insulate exposed pipes under sink	\$55.00	each	1	\$55.00	3	Incomplete
Scale House	Citywide Facilities	1.11.5	Restrooms	Replace toilet seat, or re-set or replace toilet to 17" to 19" aff	\$1,306.00	each	1	\$1,306.00	3	Staff to investigate technical feasibility
Scale House	Citywide Facilities	1.11.6	Restrooms	<i>Install</i> grab bar behind the toilet, 12" to one side of center and 24" to the other and 33" to 36" aff	\$281.25	each	1	\$281.25	3	Staff to investigate technical feasibility
Scale House	Citywide Facilities	1.11.7	Restrooms	<i>Install</i> side grab bar with a 42" long grab bar, mounted max 12" from the rear wall and 33" to 36" aff	\$281.25	each	1	\$281.25	3	Staff to investigate technical feasibility
Scale House	Citywide Facilities	1.11.8	Restrooms	Relocate or recess First Aid Kit and hand dryer to not interfere with general circulation path	\$250.00	each	1	\$250.00	3	Incomplete
Scale House	Citywide Facilities	1.15.1	Interior Signage	Create template for signs that addresses height of sign, size of characters, location of Braille, and other requirements	\$0.00	staff time	0	\$0.00	3	Complete
Scale House	Citywide Facilities	1.15.2	Interior Signage	Implement a sign revision program throughout the building, discriminating between directional signs and signs for permanent spaces	\$0.00	staff time	0	\$0.00	3	Complete
Scale House	Citywide Facilities	1.15.3	Interior Signage	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door	\$150.00	each	4	\$600.00	3	Incomplete
Skelton Common Area	Helena Citizens Council District 5	1.2.1	Exterior Accessible Route	Install compliant detectable warning at curb ramps and transitions from walkways to vehicular ways as a smart practice	\$235.00	each	1	\$235.00	со	Staff to investigate completion status
Solid Waste Admin Office	Citywide Facilities	1.2.1	Exterior Accessible Route	<i>Install</i> detectable warning strip on top tread of each stairway as a smart practice	\$150.00	each	1	\$150.00	3	Incomplete
Solid Waste Admin Office	Citywide Facilities	1.2.2	Exterior Accessible Route	Correct ramp cross slope to max 2.08%	\$87.50	sq ft	90	\$7,875.00	3	Incomplete
Solid Waste Admin Office	Citywide Facilities	1.3.1	Exterior Signage	Mount signage at inaccessible entrances directing patrons in wheelchairs to accessible entrance	\$150.00	each	1	\$150.00	3	Incomplete
Solid Waste Admin Office	Citywide Facilities	1.3.2	Exterior Signage	Mount signage at entrance designating it as accessible	\$150.00	each	1	\$150.00	3	Incomplete
Solid Waste Admin Office	Citywide Facilities	1.4.1	Exterior Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior east entry door	\$0.00	staff time	0	\$0.00	3	On-going
Solid Waste Admin Office	Citywide Facilities	1.4.2	Exterior Doors	Upon renovation ; make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	3	N/A



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Solid Waste Admin Office	Citywide Facilities	1.6.1	Interior Doors	No maneuvering clearance at door due to door opening into storage area, <i>leave as is</i> , correction is technically infeasible	\$0.00	n/a	0	\$0.00	3	N/A
Solid Waste Admin Office	Citywide Facilities	1.6.2	Interior Doors	For employee only doors; make above corrections upon renovation	\$0.00	n/a	0	\$0.00	3	N/A
Solid Waste Admin Office	Citywide Facilities	1.9.1	Employee Spaces	Employee only area permit approach, entry, and exit, relocate obstacles to create AR and turning space through mechanical room	\$0.00	staff time	0	\$0.00	3	To be completed in FY22
Solid Waste Admin Office	Citywide Facilities	1.9.2	Employee Spaces	For all other deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	3	N/A
Solid Waste Admin Office	Citywide Facilities	1.11.1	Restrooms	Relocate toilet paper dispensers 7" min and 9" max in front of the toilet measured to the center line of the dispenser and 15"-48" aff	\$0.00	staff time	0	\$0.00	3	Staff to investigate completion status
Solid Waste Admin Office	Citywide Facilities	1.11.2	Restrooms	Lower coat hooks at between 40"-48" max	\$0.00	staff time	0	\$0.00	3	Staff to investigate completion status
Solid Waste Admin Office	Citywide Facilities	1.15.1	Interior Signage	Create template for signs that addresses height of sign, size of characters, location of Braille, and other requirements	\$0.00	staff time	0	\$0.00	3	Complete
Solid Waste Admin Office	Citywide Facilities	1.15.2	Interior Signage	Implement a sign revision program throughout the building, discriminating between directional signs and signs for permanent spaces	\$0.00	staff time	0	\$0.00	3	Complete
Solid Waste Admin Office	Citywide Facilities	1.15.3	Interior Signage	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door	\$150.00	each	3	\$450.00	3	Staff to investigate completion status
Solid Waste Truck Storage	Citywide Facilities	1.1.1	Parking	Create one or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping	\$1,135.00	each	1	\$1,135.00	3	Incomplete
Solid Waste Truck Storage	Citywide Facilities	1.3.1	Exterior Signage	Mount signage at inaccessible entrances directing patrons in wheelchairs to accessible entrance	\$150.00	each	1	\$150.00	3	Incomplete
Solid Waste Truck Storage	Citywide Facilities	1.3.2	Exterior Signage	Mount signage at entrance designating it as accessible	\$150.00	each	1	\$150.00	3	Incomplete
Solid Waste Truck Storage	Citywide Facilities	1.4.1		For all doors along the public circulation route, replace doors with doors having 80" overhead clearance	\$1,980.00	each	3	\$5,940.00	3	Incomplete will be addressed during renovation
Solid Waste Truck Storage	Citywide Facilities	1.4.2		For all doors along the public circulation route, <i>repair, bevel, or ramp CIL</i> at door entries to max .25"	\$68.75	each	1	\$68.75	3	Incomplete will be addressed during renovation



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Solid Waste Truck Storage	Citywide Facilities	1.4.3	Exterior Doors	For all doors along the public circulation route, replace hardware with lever hardware where indicated	\$367.50	each	2	\$735.00	3	Incomplete
Solid Waste Truck Storage	Citywide Facilities	1.4.4	Exterior Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice	\$0.00	staff time	0	\$0.00	3	On-going
Solid Waste Truck Storage	Citywide Facilities	1.4.5	Exterior Doors	Upon renovation ; make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	3	N/A
Solid Waste Truck Storage	Citywide Facilities	1.6.1	Interior Doors	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	2	\$2,500.00	3	Incomplete
Solid Waste Truck Storage	Citywide Facilities	1.6.2	Interior Doors	For all doors along the public circulation route, replace doors with doors having 80" overhead clearance	\$1,980.00	each	4	\$7,920.00	3	Incomplete will be addressed during renovation
Solid Waste Truck Storage	Citywide Facilities	1.6.3	Interior Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice	\$0.00	staff time	0	\$0.00	3	On-going
Solid Waste Truck Storage	Citywide Facilities	1.6.4	Interior Doors	For employee only doors; make above corrections <i>upon renovation</i>	\$0.00	n/a	0	\$0.00	3	N/A
Solid Waste Truck Storage	Citywide Facilities	1.7.1	Stairs	Leave stairs as is, lack of AOR on second floor; this floor is not accessible	\$0.00	n/a	0	\$0.00	3	N/A
Solid Waste Truck Storage	Citywide Facilities	1.9.1	Employee Spaces	Employee only areas permit approach, entry, and exit, relocate obstacles to create turning space of 60" in parts room	\$0.00	staff time	0	\$0.00	3	On-going
Solid Waste Truck Storage	Citywide Facilities	1.9.2	Employee Spaces	For all other deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	3	N/A
Solid Waste Truck Storage	Citywide Facilities	1.11.1	Restrooms	Lower sinks to max 34" aff to front of rim	\$1,700.00	each	2	\$3,400.00	3	Staff to investigate technical feasibility
Solid Waste Truck Storage	Citywide Facilities	1.11.2	Restrooms	Remount toilets to 16" to 18" from the side wall to centerline	\$1,306.00	each	2	\$2,612.00	3	Staff to investigate technical feasibility
Solid Waste Truck Storage	Citywide Facilities	1.11.3	Restrooms	Adjust stall door to be self-closing	\$0.00	staff time	0	\$0.00	3	Incomplete
Solid Waste Truck Storage	Citywide Facilities	1.11.4	Restrooms	Remount side grab bar to max 12" from the rear wall at the close end and 33" to 36" aff	\$281.25	each	2	\$562.50	3	Incomplete
Solid Waste Truck Storage	Citywide Facilities	1.11.5	Restrooms	Remount coat hook to a max. of 48"	\$0.00	staff time	0	\$0.00	3	Incomplete
Solid Waste Truck Storage	Citywide Facilities	1.13.1	Locker Rooms	Leave as is, existing employee only locker room and shower; modify policy allowing employee with a disability to use public locker area or make renovations to existing locker area	\$0.00	n/a	0	\$0.00	3	N/A



Oite	UGO Diat	0:4-	Type of	December detice	Dui and somit	unit	# of	Total and	Dhara	Notes
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Solid Waste Truck Storage	Citywide Facilities	1.15.1	Interior Signage	Create template for signs that addresses height of sign, size of characters, location of Braille, and other requirements	\$0.00	staff time	0	\$0.00	3	Complete
Solid Waste Truck Storage	Citywide Facilities	1.15.2	Interior Signage	Implement a sign revision program throughout the building, discriminating between directional signs and signs for permanent spaces	\$0.00	staff time	0	\$0.00	3	Complete
Solid Waste Truck Storage	Citywide Facilities	1.15.3	Interior Signage	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted at 60" to the middle of the sign and on the latch side of the door	\$150.00	each	4	\$600.00	3	Incomplete
Stone Meadows	Helena Citizens Council District 4	1.2.1	Exterior Accessible Route	Correct slope of adjacent street surfaces to max 5%	\$87.50	sq ft	50	\$4,375.00	со	Staff to investigate completion status
Stone Meadows	Helena Citizens Council District 4	1.2.2	Exterior Accessible Route	Correct slope of curb ramp slide flares to max 10%	\$725.00	each	1	\$725.00	со	Staff to investigate completion status
Stone Meadows	Helena Citizens Council District 4	1.2.3	Exterior Accessible Route	Correct curb ramp slope to max 8.33%	\$725.00	each	1	\$725.00	со	Staff to investigate completion status
Transfer Station Break Room 2	Citywide Facilities	1.1.1	Parking	Create one or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping	\$1,135.00	each	1	\$1,135.00	3	Staff to investigate technical feasibility
Transfer Station Break Room 2	Citywide Facilities	1.2.1	Exterior Accessible Route	Create exterior accessible route to accessible entry door	\$48.00	lin ft	200	\$9,600.00	3	Staff to investigate technical feasibility
Transfer Station Break Room 2	Citywide Facilities	1.3.1	Exterior Signage	Mount signage at entrance designating it as accessible	\$150.00	each	1	\$150.00	3	Incomplete
Transfer Station Break Room 2	Citywide Facilities	1.4.1	Exterior Doors	Inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice	\$0.00	staff time	0	\$0.00	3	On-going
Transfer Station Break Room 2	Citywide Facilities	1.4.2	Exterior Doors	Upon renovation; make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	3	N/A
Transfer Station Break Room 2	Citywide Facilities	1.6.1	Interior Doors	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	2	\$2,500.00	3	Incomplete
Transfer Station Break Room 2	Citywide Facilities	1.6.2	Interior Doors	For all doors along the public circulation route, inspect, adjust, and maintain 5 lbf to open interior doors	\$0.00	staff time	0	\$0.00	3	On-going
Transfer Station Break Room 2	Citywide Facilities	1.6.3	Interior Doors	For employee only doors; make above corrections upon renovation	\$0.00	n/a	0	\$0.00	3	N/A



			1							
Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Transfer Station Break Room 2	Citywide Facilities	1.7.1	Interior Accessible Route	Relocate protruding objects along the interior AR or place cane detectable warning or bollard at foot of the time clock (TS57), first aid kit (TS58, TS59), and shelf	\$250.00	each	1	\$250.00	3	Incomplete will be addressed during renovation
Transfer Station Break Room 2	Citywide Facilities	1.7.2	Interior Accessible Route	Lower thermostat operating mechanism in break room to max 48" aff to highest operable part; leave as is if employee only operated	\$250.00	each	1	\$250.00	3	Incomplete will be addressed during renovation
Transfer Station Break Room 2	Citywide Facilities	1.11.1	Restrooms - Multiple Users	Lower mirror so reflective surface is max 40" aff	\$0.00	staff time	0	\$0.00	3	Incomplete will be addressed during renovation
Transfer Station Break Room 2	Citywide Facilities	1.11.2	Restrooms - Multiple Users	Insulate exposed pipes under sink in locker area	\$55.00	each	1	\$55.00	3	Incomplete will be addressed during renovation
Transfer Station Break Room 2	Citywide Facilities	1.11.3	Restrooms - Multiple Users	Remount toilet to 16" to 18" from the side wall to centerline	\$1,306.00	each	1	\$1,306.00	3	Incomplete will be addressed during renovation
Transfer Station Break Room 2	Citywide Facilities	1.11.4	Restrooms - Multiple Users	Adjust stall door to be self-closing	\$0.00	staff time	0	\$0.00	3	Incomplete
Transfer Station Break Room 2	Citywide Facilities	1.11.5	Restrooms - Multiple Users	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff	\$281.25	each	1	\$281.25	3	Incomplete will be addressed during renovation
Transfer Station Break Room 2	Citywide Facilities	1.11.6	Restrooms - Multiple Users	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to one side of center and 24" to the other and 33" to 36" aff	\$281.25	each	1	\$281.25	3	Incomplete will be addressed during renovation
Transfer Station Break Room 2	Citywide Facilities	1.11.7	Restrooms - Multiple Users	Lower hook in accessible stalls to max 48" aff	\$0.00	staff time	0	\$0.00	3	Incomplete will be addressed during renovation
Transfer Station Break Room 2	Citywide Facilities	1.11.8	Restrooms - Multiple Users	Relocate or recess hand dryer to not interfere with general circulation path, protrusions can't be greater than 4"	\$250.00	each	1	\$250.00	3	Incomplete will be addressed during renovation
Transfer Station Break Room 2	Citywide Facilities	1.11.1	Restrooms - Single Users	Remove or relocate locker storage at fixtures and operable parts	\$0.00	staff time	0	\$0.00	3	Incomplete will be addressed during renovation
Transfer Station Break Room 2	Citywide Facilities	1.11.2	Restrooms - Single Users	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff	\$281.25	each	1	\$281.25	3	Incomplete will be addressed during renovation
Transfer Station Break Room 2	Citywide Facilities	1.11.3	Restrooms - Single Users	Replace rear grab bar with one 36" long, mounted behind the toilet, 12" to one side of center and 24" to the other and 33" to 36" aff	\$281.25	each	1	\$281.25	3	Incomplete
Transfer Station Break Room 2	Citywide Facilities	1.11.4	Restrooms - Single Users	Install vertical or swing-up grab bar at correct distances aff	\$281.25	each	1	\$281.25	3	Incomplete
Transfer Station Break Room 2	Citywide Facilities	1.11.5	Restrooms - Single Users	Remount toilet paper dispenser max 7" to 9" from front of toilet, 15" to 48" aff and min 12" above or 1.5" below grab bar	\$0.00	staff time	0	\$0.00	3	Staff to investigate completion status



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Transfer Station Break Room 2	Citywide Facilities	1.11.6	Restrooms - Single Users	Lower mirror so reflective surface is max 40" aff	\$0.00	staff time	0	\$0.00	3	Staff to investigate technical feasibility
Transfer Station Break Room 2	Citywide Facilities	1.11.7	Restrooms - Single Users	Insulate exposed pipes under sink	\$55.00	each	1	\$55.00	3	Incomplete will be addressed during renovation
Transfer Station Break Room 2	Citywide Facilities	1.11.8	Restrooms - Single Users	Relocate or recess towel dispenser and hand dryers to not interfere with general circulation path, protrusions can't be greater than 4"	\$250.00	each	1	\$250.00	3	Incomplete will be addressed during renovation
Transfer Station Break Room 2	Citywide Facilities	1.13.1	Locker Rooms	Leave as is, existing employee only locker room and shower; modify policy allowing employee with a disability to use public locker area or make renovations to existing locker area	\$0.00	n/a	0	\$0.00	3	N/A
Transfer Station Break Room 2	Citywide Facilities	1.15.1	Interior Signage	Create template for signs that addresses height of sign, size of characters, location of Braille, and other requirements	\$0.00	staff time	0	\$0.00	3	Complete
Transfer Station Break Room 2	Citywide Facilities	1.15.2	Interior Signage	Implement a sign revision program throughout the building, discriminating between directional signs and signs for permanent spaces	\$0.00	staff time	0	\$0.00	3	Complete
Transfer Station Break Room 2	Citywide Facilities	1.15.3	Interior Signage	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door	\$150.00	each	4	\$600.00	3	Incomplete
<u>Triangle Park</u>	Helena Citizens Council District 1	1.1.1	Parking	Create one or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping	\$1,135.00	each	1	\$1,135.00	со	Staff to investigate completion status
Triangle Park	Helena Citizens Council District 1	1.2.1	Exterior Accessible Route	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk around park	\$48.00	lin ft	100	\$4,800.00	СО	Staff to investigate completion status
Triangle Park	Helena Citizens Council District 1	1.2.2	Exterior Accessible Route	Create curb ramps to be max running slope 8.33%, max cross slope 2.08%, having a top landing as wide as the ramp and 36" deep and side flares with a max slope 10%	\$1,062.50	each	1	\$1,062.50	СО	Staff to investigate completion status
<u>Utility</u> <u>Maintenance</u>	Citywide Facilities	1.1.1	Parking	Repair or correct slope of parking space and access aisle to max 2.08% in any direction	\$2,187.50	each	1	\$2,187.50	3	Staff to investigate technical feasibility
Utility Maintenance	Citywide Facilities	1.2.1	Exterior Accessible Route	Correct slope of curb ramp side flares to max 10%	\$725.00	each	1	\$725.00	3	Staff to investigate technical feasibility



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
Utility Maintenance	Citywide Facilities	1.2.2	Exterior Accessible Route	Re-cut or re-pour curb ramp to be max running slope 8.33%, max cross slope 2.08%, having a top landing as wide as the ramp and 36" deep and side flares max slope 10%	\$725.00	each	1	\$725.00	3	Staff to investigate technical feasibility
Utility Maintenance	Citywide Facilities	1.3.1	Exterior Signage	Mount signage at inaccessible entrances directing patrons in wheelchairs to accessible entrance	\$150.00	each	1	\$150.00	3	Incomplete
Utility Maintenance	Citywide Facilities	1.3.2	Exterior Signage	Mount signage at entrance designating it as accessible	\$150.00	each	1	\$150.00	3	Incomplete
Utility Maintenance	Citywide Facilities	1.4.1	Exterior Doors	For all doors along the public circulation route, relocate storage, furniture, and other obstacles to create 60" maneuvering space around doors	\$0.00	staff time	0	\$0.00	3	Staff to investigate completion status
Utility Maintenance	Citywide Facilities	1.4.2	Exterior Doors	For all doors along the public circulation route, replace grate in maneuvering clearance with one having openings max .5"	\$100.00	each	1	\$100.00	3	Incomplete
Utility Maintenance	Citywide Facilities	1.4.3	Exterior Doors	For all doors along the public circulation route, inspect, adjust, and maintain 8.5 lbf to open exterior doors as a smart practice	\$0.00	staff time	0	\$0.00	3	On-going
Utility Maintenance	Citywide Facilities	1.4.4	Exterior Doors	Upon renovation; make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	3	N/A
Utility Maintenance	Citywide Facilities	1.6.1	Interior Doors	For all doors along the public circulation route, provide required maneuvering clearance on push and pull side of doors	\$1,250.00	each	5	\$6,250.00	3	N/A technically infeasible
Utility Maintenance	Citywide Facilities	1.6.2	Interior Doors	No maneuvering clearance at door due to counter, <i>leave as is</i> , correction is technically infeasible	\$0.00	n/a	0	\$0.00	3	N/A
Utility Maintenance	Citywide Facilities	1.6.3	Interior Doors	Remove laundry soap	\$0.00	staff time	0	\$0.00	3	Staff to investigate completion status
Utility Maintenance	Citywide Facilities	1.6.4	Interior Doors	For all doors along the public circulation route, <i>inspect, adjust, and maintain</i> 8.5 lbf to open exterior doors as a smart practice	\$0.00	staff time	0	\$0.00	3	On-going
Utility Maintenance	Citywide Facilities	1.6.5	Interior Doors	For employee only doors; make above corrections <i>upon renovation</i>	\$0.00	n/a	0	\$0.00	3	N/A
Utility Maintenance	Citywide Facilities	1.7.1	Service Counter	Lower 36" wide segment of service counter to max 36" aff, in the alternative, train staff to come out from around the counter to provide customer service	\$785.00	each	1	\$785.00	3	Staff to investigate technical feasibility
Utility Maintenance	Citywide Facilities	1.7.2	Interior Accessible Route	Relocate protruding objects along the interior AR or place cane detectable warning or bollard at foot of lights	\$250.00	each	1	\$250.00	3	Staff to investigate completion status
Utility Maintenance	Citywide Facilities	1.7.3	Interior Accessible Route	Replace drinking fountain with hi-lo bowl	\$3,998.75	each	1	\$3,998.75	3	Staff to investigate technical feasibility



			1			1				
			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
Utility Maintenance	Citywide Facilities	1.7.4	Stairs	Leave stairs as is correction is technically infeasible	\$0.00	n/a	0	\$0.00	3	N/A
Utility Maintenance	Citywide Facilities	1.9.1	Employee Spaces	Employee only areas permit approach, entry, and exit, relocate obstacles to create turning space of 60" in hazmat room	\$0.00	staff time	0	\$0.00	3	Staff to investigate completion status
Utility Maintenance	Citywide Facilities	1.9.2	Employee Spaces	For all other deficits, <i>leave as is,</i> employee work area pursuant to 2010 Standards 106.5 Defined Terms, until an employee with a disability works here	\$0.00	n/a	0	\$0.00	3	N/A
Utility Maintenance	Citywide Facilities	1.11.1	Restrooms	Lower mirror so reflective surface is max 40" aff	\$0.00	staff time	0	\$0.00	3	Staff to investigate technical feasibility
Utility Maintenance	Citywide Facilities	1.11.2	Restrooms	Replace urinal with one having a 13.5" min depth mounted at max 17" to rim with flush controls max 48" aff	\$2,127.50	each	1	\$2,127.50	3	Staff to investigate technical feasibility
Utility Maintenance	Citywide Facilities	1.11.3	Restrooms	Remount napkin dispenser and coat hook between 40"-48" max	\$250.00	each	1	\$250.00	3	Employee-only access
Utility Maintenance	Citywide Facilities	1.13.1	Locker Rooms	Leave as is, existing employee only locker room and shower; modify policy allowing employee with a disability to use public locker area or make renovations to existing locker area	\$0.00	n/a	0	\$0.00	3	N/A
Utility Maintenance	Citywide Facilities	1.14.1	Alarms	Upon renovation <i>install audible and visual</i> alarms in all rooms and spaces	\$407.50	each	3	\$1,222.50	3	N/A - No fire alarm system
Utility Maintenance	Citywide Facilities	1.15.1	Interior Signage	Create template for signs that addresses height of sign, size of characters, location of Braille, and other requirements	\$0.00	staff time	0	\$0.00	3	Complete
Utility Maintenance	Citywide Facilities	1.15.2	Interior Signage	Implement a sign revision program throughout the building, discriminating between directional signs and signs for permanent spaces	\$0.00	staff time	0	\$0.00	3	Complete
Utility Maintenance	Citywide Facilities	1.15.3	Interior Signage	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted 48" to baseline of lowest character and 60" to the baseline of the highest character sign and on the latch side of the door	\$150.00	each	3	\$450.00	3	Staff to investigate completion status
WWTP Interpretive Center	Citywide Facilities	1.1.1	Parking	Create one or more 8' accessible parking stalls, with one 5' adjacent access aisle, with proper signage and striping	\$1,135.00	each	1	\$1,135.00	3	Staff to investigate technical feasibility
WWTP Interpretive Center	Citywide Facilities	1.2.1	Exterior Accessible Route	Create AR with crushed and compacted stone or similar outdoor material from parking or sidewalk to accessible building entrance	\$48.00	lin ft	200	\$9,600.00	3	Incomplete
WWTP Interpretive Center	Citywide Facilities	1.3.1	Exterior Signage	Mount signage at entrance designating it as accessible	\$150.00	each	1	\$150.00	3	Incomplete



						l	1			
			Type of			unit	# of			
Site	HCC Dist	Cite	correction	Recommendation	Price/ unit	type	units	Total cost	Phase	Notes
WWTP Interpretive Center	Citywide Facilities	1.4.1	Exterior Doors	For all doors along the public circulation route, replace doors with ones having 32" clear width	\$1,980.00	each	1	\$1,980.00	3	Incomplete will be addressed during renovation
WWTP Interpretive Center	Citywide Facilities	1.4.2	Exterior Doors	Upon renovation ; make above corrections to employee only doors	\$0.00	n/a	0	\$0.00	3	N/A
WWTP Interpretive Center	Citywide Facilities	1.6.1	Interior Doors	For all doors along the public circulation route, relocate fire extinguisher	\$0.00	staff time	0	\$0.00	3	Staff to investigate completion status
WWTP Interpretive Center	Citywide Facilities	1.6.2	Interior Doors	No maneuvering clearance at door due to wall, leave as is, correction is technically infeasible	\$0.00	n/a	0	\$0.00	3	N/A
WWTP Interpretive Center	Citywide Facilities	1.6.3	Interior Doors	Door width not 32", <i>leave as is,</i> correction is technically infeasible	\$0.00	n/a	0	\$0.00	3	N/A
WWTP Interpretive Center	Citywide Facilities	1.6.4	Interior Doors	For employee only doors; make above corrections upon renovation	\$0.00	n/a	0	\$0.00	3	Incomplete will be addressed during renovation
WWTP Interpretive Center	Citywide Facilities	1.8.1	Public Spaces	Lower operating mechanisms along the interior AR to max 48" aff to the highest operable part	\$250.00	each	1	\$250.00	3	Incomplete
WWTP Interpretive Center	Citywide Facilities	1.8.2	Public Spaces	Relocate protruding objects along the interior AR or place cane detectable warning or bollard at foot of TV	\$250.00	each	1	\$250.00	3	Incomplete
WWTP Interpretive Center	Citywide Facilities	1.11.1	Restrooms	Centerline of toilet is 19" from wall, should not exceed 18", <i>leave as is</i>	\$0.00	n/a	0	\$0.00	3	Staff to investigate technical feasibility
WWTP Interpretive Center	Citywide Facilities	1.11.2	Restrooms	Replace or re-set toilet to 17" to 19" aff	\$1,306.00	each	2	\$2,612.00	3	Staff to investigate technical feasibility
WWTP Interpretive Center	Citywide Facilities	1.11.3	Restrooms	Remount side grab bar to max 12" from the rear wall at the close end and min 54" on the far end, and 33" to 36" aff	\$281.25	each	2	\$562.50	3	Staff to investigate technical feasibility
WWTP Interpretive Center	Citywide Facilities	1.11.4	Restrooms	Install vertical grab bar to accessibility standards	\$281.25	each	2	\$562.50	3	Staff to investigate technical feasibility
WWTP Interpretive Center	Citywide Facilities	1.11.5	Restrooms	Lower mirror so reflective surface is max 40" aff	\$0.00	n/a	0	\$0.00	3	Staff to investigate technical feasibility
WWTP Interpretive Center	Citywide Facilities	1.15.1	Interior Signage	Create template for signs that addresses height of sign, size of characters, location of Braille, and other requirements	\$0.00	staff time	0	\$0.00	3	Complete



Site	HCC Dist	Cite	Type of correction	Recommendation	Price/ unit	unit type	# of units	Total cost	Phase	Notes
WWTP Interpretive Center	Citywide Facilities	1.15.2	Interior Signage	Implement a sign revision program throughout the building, discriminating between directional signs and signs for permanent spaces	\$0.00	staff time	0	\$0.00	3	Complete
WWTP Interpretive Center	Citywide Facilities	1.15.3	Interior Signage	Mount signage at all permanent rooms/spaces having Braille and the international symbol of accessibility, mounted at 60" to the middle of the sign and on the latch side of the door	\$150.00	each	4	\$600.00	3	Incomplete
Yund Park	Helena Citizens Council District 3	1.2.1	Exterior Accessible Route	Repair, bevel, or ramp CIL along AR	\$68.75	each	1	\$68.75	СО	Complete
Yund Park	Helena Citizens Council District 3	1.2.2	Exterior Accessible Route	Correct slope of curb ramp slide flares to max 10%	\$725.00	each	2	\$1,450.00	со	Incomplete
Yund Park	Helena Citizens Council District 3	1.2.3	Exterior Accessible Route	Correct slope of ramp to max 8.33%	\$725.00	each	1	\$725.00	со	Incomplete
Yund Park	Helena Citizens Council District 3	1.2.4	Exterior Accessible Route	Install compliant detectable warning at curb ramp as a smart practice	\$235.00	each	3	\$705.00	СО	Incomplete
Yund Park	Helena Citizens Council District 3	1.2.5	Exterior Accessible Route	Create lined cross walk where pedestrian pathway crosses through vehicular traffic as a smart practice	\$262.50	each	1	\$262.50	СО	Incomplete
Yund Park	Helena Citizens Council District 3	1.13.1	Signage	Replace existing signage with signage having compliant character heights and placed within proper viewing distance of the AR	\$150.00	each	1	\$150.00	СО	Incomplete