

REPORT TO THE CITY OF HELENA

Section: Crystal Springs Wetlands

September 16, 2015

Legend of Abbreviations

aff...	Above the finished ground
AR...	Accessible Route
CIL...	Change in Level
CFS...	Clear Floor Space
CGS...	Clear Ground Space
EPC...	Elevated Play Component
GLPC...	Ground Level Play Component

Background

The Helena Parks and Rec staff visited Crystal Springs Wetlands Park to conduct an access audit. The findings are below.

1.1 Parking – not applicable

1.2 Exterior Accessible Route - [[CHECKLIST](#)] 2.4% cross slope along Willowbrook [CSW4](#), [CSW5](#); no detectable warning on closest curb ramp [CSW6](#)

Recommendations (in the alternative, leave as is and designate other sites in the City as accessible):

1.2.1 **Correct or repair** sidewalk cross slope along AR to max 2.08% (CSW4, CSW5)

1.2.2 **Install** compliant detectable warning at curb ramps as a smart practice (CSW6)

Responsible Employee	Progress Towards Completion	Recommended Phase
Amy Teegarden Director 406/447-8462	(insert periodic notes regarding steps taken or work completed)	CITY OPTION

1.3 Playground Designated Entry – not applicable

1.4 Playground Surface/Accessible Route within – not applicable

1.5 Transfer System – not applicable

1.6 Ramps – not applicable

1.7 Elevated Play Components – not applicable

1.8 Ground Level Play Components – not applicable

1.9 Sand box/Play tables – not applicable

1.10 Park Site – not applicable

1.11 Shelters/Picnic Areas – not applicable

1.12 Park Buildings – not applicable

1.13 Other – not applicable